



VIC

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 85527540

Estimate : ES006857

Date : 02/12/2019
Vehicle Num. : XD8401T
Make/Model : MAN TGM 18.280 4X2 BB-2013
Chassis/Eng# : WMAN08ZZ7DY296490/21834545853
Accident Date : 30/11/2019
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

- 1. 1 SPECIAL NETT ITEMS :
- 2. 1 TAIL LAMP L/H *500*
- 3. 1 TAIL LAMP BRACKET L/H *42*
- 4. 1 TAIL LAMP BRACKET REFLECTOR *ca*
- 4. 1 VERDEGRO SYSTEM US-100K (TMA'S) TRUCK MOUNT ATTENUATORS (PASS NCHRP350 STS LEVEL 3) C/W *pac* HYDRAULIC LIFT

Special Nett Total S\$:

LABOUR :
CHANGE TAILLAMP AND CHECK WIRING
TO DISMANTLE CARRIAGE, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME, RE-ALIGN BODY AND RUST PROOFING
LABOUR CHARGE TO INSTALL, REMOVE/DISPOSE DAMAGE TMA

Labour Total S\$:

42,000

Resur by 900000

3 days

P/P 1000

Resur before repair

3 days / P/P

395.00
228.60
36.80
<u>59,800.00</u> <i>? 1000</i>
60,460.40
<u>120.00</u> <i>60</i>
<u>1,200.00</u> <i>x</i>
<u>1,000.00</u> <i>600</i>
2,320.00

42,000

1000

43,000

SingDollars Sixty-Two Thousand Seven Hundred Eighty & Cents Forty Only

Total S\$: 62,780.40

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: