

INS. CASE OWNER:

CHOR HENG

CC 4/AIG1902 1216

LKK:

IDAC:

Surveyor:

PNSU

DOI:

7/11/19

Date / Time:

2/11/19

Registered in Merimen:

2/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFN 132H

Claim No.:

2A10773235 9G

Name of Insured:

TAN AI LING

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A:

70/11/19

Place of Accident:

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) (YES) NO

OI GIA REPORT:

(YES) NO

TP GIA REPORT:

(YES) NO

Insured Liability:

%

Final ? Yes / No

XD 8401 T



INSRS:

WSP:

Tel:

Liability:

RMKS:

complete
VMS

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting hr (1st):	
	Non-Reporting hr (2nd):	
	Non-Reporting hr (Final):	
	Notification hr (if non-pickup):	
	Call OI:	
	After call hr to OI:	11/12/19 - JIC
11/12/19	Documentation Check List: Handler Typist	
	Notification hr (if non-pickup)	
	After call hr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA/GIA:	
	Medical Bill:	
	PDR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others: TMA DOCS	
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: P/P	S\$ 43,000.00 3 days) Reduction: 22 %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 10/03/2020	Confirm with: LLY	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 24	If NO or B 28, Ass. Lia:
Repair Cost: (w/gst)	S\$ 46,010.00	OI: 2012-ENDED TP
Loss of Rental (LOR):	S\$ - (days)	
Loss of Use (LOU):	S\$ 540.00/180 x 3 days)	
Loss of Income (LOI):	S\$ - (\$ x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐ [Tick only one]	
GIA/LTA Search	S\$ 7.45	
Medical:	S\$ -	
Disbursement:	S\$ - (e.g. Tow/ Independent)	
Legal Cost	S\$ -	
Total:	S\$ 46,557.45 Global Sum S\$: 46,500.00	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$ 46,500.00 Name 1: COMPLETE VMS PTE LTD	
Payee 2: (Strike if N.A.)	S\$ - Name 2: -	
Payee 3: (Strike if N.A.)	S\$ - Name 3: -	

COPY SENT
10/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: 4320.00



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 85527540

Estimate : ES006857

Date : 02/12/2019
Vehicle Num. : XD8401T
Make/Model : MAN TGM 18.280 4X2 BB-2013
Chassis/Eng# : WMAN08ZZ7DY296490/21834546853
Accident Date : 30/11/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|---|--|--|
| 1. | 1 | SPECIAL NETT ITEMS : | | |
| 2. | 1 | TAIL LAMP L/H <i>brw</i> | | |
| 3. | 1 | TAIL LAMP BRACKET L/H <i>lt</i> | | |
| 4. | 1 | TAIL LAMP BRACKET REFLECTOR <i>ca</i> | | |
| | | VERDEGRO SYSTEM US-100K (TMA'S) TRUCK MOUNT | | |
| | | ATTENUATORS (PASS NCHRP350 STS LEVEL 3) C/W <i>me</i> | | |
| | | HYDRAULIC LIFT <i>pass</i> | | |

Special Nett Total S\$:

LABOUR :
CHANGE TAILLAMP AND CHECK WIRING
TO DISMANTLE CARRIAGE, KNOCK AND STRAIGHTEN REAR
CHASSIS FRAME, RE-ALIGN BODY AND RUST PROOFING
LABOUR CHARGE TO INSTALL, REMOVE/DISPOSE DAMAGE TMA

Labour Total S\$:

42,000

395.00
228.60
36.80
<i>59,800.00</i>
<i>60,460.40</i>

From Hy 90000

<i>120.00</i>
<i>1,200.00</i>
<i>1,000.00</i>
<i>2,320.00</i>

3 days
P/P 1000

42,000
1000
43,000

Resurvey before paper

3 days
1 P/P

SingDollars : Sixty-Two Thousand Seven Hundred Eighty & Cents Forty Only

Total S\$: 62,780.40

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

L&K Auto Consultants hence notify the Repairs of the following:
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairs

Signature

Date



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 85527540

Estimate : ES006857

Date : 02/12/2019
Vehicle Num. : XD8401T
Make/Model : MAN TGM 18.280 4X2 BB-2013
Chassis/Eng# : WMAN08ZZ7DY296490/21834545853
Accident Date : 30/11/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	SPECIAL NETT ITEMS :		
2.	1	TAIL LAMP L/H <i>bro</i>		395.00
3.	1	TAIL LAMP BRACKET L/H <i>bt</i>		228.60
4.	1	TAIL LAMP BRACKET REFLECTOR <i>ca</i>		36.80
		VERDEGRO SYSTEM US-100K (TMA'S) TRUCK MOUNT		
		ATTENUATORS (PASS NCHRP350 STS LEVEL 3) C/W <i>pre</i>		
		HYDRAULIC LIFT <i>prze?</i>		
		Special Nett Total S\$:		59,800.00 <i>1.02</i>
				60,460.40
		LABOUR :		
		CHANGE TAILLAMP AND CHECK WIRING		
		TO DISMANTLE CARRIAGE, KNOCK AND STRAIGHTEN REAR		
		CHASSIS FRAME, RE-ALIGN BODY AND RUST PROOFING		
		LABOUR CHARGE TO INSTALL, REMOVE/DISPOSE DAMAGE TMA		
		Labour Total S\$:		120.00 <i>60</i>
				3 day
				1,200.00 <i>X</i>
				1,000.00 <i>800</i>
				2,320.00

Resurvey before repair

End

SingDollars : Sixty-Two Thousand Seven Hundred Eighty & Cents Forty Only

Total S\$: 62,780.40

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

Link to Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature

Date

Your password will expire in 10 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – XD8401T vs SFN132H (OI) on D.O.A.: 30/11/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chan, Jennifer-WM, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divya
Sent: 12/2/2019 10:21:28 AM

Hi,

Please refer to the enclosed request from **Complete VMS PTE LTD.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours.

If you have any queries/concerns, please let us know.

Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

10:36am @ 2/12/19

P. Li Hui

v. IN.

Address: 14 Tampines
Ind. Drive,
528530

Li Hui arrange survey
on 3/12/19

From: lihui@completevms.com.sg [mailto:lihui@completevms.com.sg]

Sent: Monday, December 02, 2019 10:16 AM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Chan, Jennifer-WM; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; lihui@completevms.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFN132H AND XD8401T ON 30/11/2019

Without Prejudice

Dear OIC,

Please arrange Mr Adrian Ling (LKK Auto Consultants Pte Ltd) to conduct survey.

Thank you & Best Regards,
Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

From: Hor, Yinnul

Sent: Mon, 2 Dec 2019 01:33:04 +0000

To: lihui@completevms.com.sg

Cc: Fong, Andy-SY, Chan, Jennifer-WM, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFN132H AND XD8401T ON 30/11/2019

Without Prejudice

Your Reference : XD8401T
Our Reference : SFN132H

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206558 | Ext: 1002208
YinRui.Hor@aig.com | www.aig.as

From: Gan Li Hui [mailto:lihui@completevms.com.sg]
Sent: Saturday, November 30, 2019 10:38 AM
To: ClaimsDocManagement
Subject: [EXTERNAL] NOTICE OF ACCIDENT: XD8401T Your ref: SFN132H

This message is from an external sender; be cautious with links and attachments.

Without Prejudice

Dear Sir,

ACCIDENT INVOLVING XD8401T AND SFN132H ON 30/11/2019 ALONG PIE TOWARDS TUAS AFTER ENG NEO AT ABOUT 01:05 HRS.

We act for **CLEANING TECHNOLOGY MANAGEMENT PTE LTD** owner of vehicle no. XD8401T with instruction to repair the vehicle.

Please be informed that the said vehicle can be inspected at:-

Venue Complete VMS Pte Ltd

176, Sin Ming Drive,

#03-14,

Singapore 575721

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you. Please note that there will also be a storage charge of \$60 per

day on the 2 day notice period commencing from the date of this letter.

Thank you & Best Regards,

Gan Li Hui (Ms)

Complete VMS PTE LTD

Block 176 Sin Ming Drive, #03-14

Sin Ming Autocare Complex, Singapore 575721

Tel: 6455 0012 Fax: 6554 0012

Print Received Message

This mail is associated with :

***XD8401T (3420773235SG)**
[SFN132H]
TP
CLEANING TECHNOLOGY MANAGEMENT PTE LTD
Nov 30 2019 12:00AM
[TAN AI LING]
COMPLETE VMS PTE LTD

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/03/2020 14:03 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$46557.45) - XD8401T - Claim Handler: Loh, Chee-Heng

Approved:46557.45:COR: \$46010 LOU: \$450-540 LTA: \$7.45 Subj to Final Repair Bill, LTA Search Bill and supporting delivery / shipping order docs furnished and in order

(REFERENCE CASE)



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Seletar Drive, #01-14, Seletar Aerospace Complex, Singapore 817221
(Tel) 6455 0112 (Fax) 6754 0112 (Web) www.completevms.com.sg

Cecilia

Email: darrin@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHYE THIAM MAINTENANCE PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention: THE OWNER
Contact: 64819588 83518539

Estimate: ES006704

Date: 17/06/2019
Vehicle Num: AE320R
Make/Model: NISSAN CB54CL PHIN 2006
Chassis/Eng: CB54CLP00006GE 133343738
Accident Date: 17/06/2019
Claim No:
Reference:
Policy No:

S/N Quantity Particular

Unit Price Amount S\$

LABOUR
TO SUPPLY AND INSTALL VERDEGRO US-100K (TMA'S) TRUCK
MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3) CW
HYDRAULIC LIFT UP
TO DISMANTLE CARRIAGE KNOCK AND STRAIGHTEN REAR CHASSIS
FRAME, RE-ALIGN BODY AND RUST PROOFING

Labour Total S\$

7/1/2019
42,000.00
59,000.00
1/000 2,000.00
62,000.00


Rasul
Hp 90010068

5 days

P/P

17/06/19 @ 1430

Reay new parts



Agreed/Not Agreed: Not Agreed

Total S\$ 62,000.00

COMPLETEVMS PTE LTD

This is only an estimate based on our preliminary inspection and may involve additional parts and labour time which may be required after the work has begun.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2019 Edit Reg		02 Dec 2019 00:00 Edit Adj Rpt	S\$43,000.00 Edit Estimates	S\$43,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN AI LING, ID: S78337241		
Main Claimant:	CLEANING TECHNOLOGY MANAGEMENT PTE LTD, Co. Reg. No.: 200101562H		
Vehicle Reg. No.:	XDB401T	Date of Loss:	30/11/2019 00:00 - :59 [71 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3420773235SG	Policy/Cover Note No.:	1800085566 (Comprehensive)
Vehicle Reg. No. (Insured):	SFN132H	Policy No. (Claimant):	5108283142
		Excess:	
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (06/03/2020): Alert - Adj Mandate Approved (S\$46557.45) - XDB401T - Claim Handler: Loh, Chee-H...
- AIG_SG (03/12/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD8401T (3420773235SG)
[SFN132H]

TP

CLEANING TECHNOLOGY MANAGEMENT PTE LTD

Nov 30 2019 12:00AM

[TAN AI LING]

COMPLETE VMS PTE LTD

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/12/19 13:54	Video - Accident From: OD - Reg. No: SFN132H, Claimant: TAN AI LING		Load AVI	
2	04/12/19 13:54	Video - Accident From: OD - Reg. No: SFN132H, Claimant: TAN AI LING		Load AVI	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/12/19 14:08	Odometer Reading		Load JPG	
2	11/12/19 14:08	Chassis Number		Load JPG	
3	11/12/19 14:09	General View		Load JPG	
4	11/12/19 14:09	General View		Load JPG	
5	11/12/19 14:09	General View		Load JPG	
6	11/12/19 14:09	General View		Load JPG	
7	11/12/19 14:09	General View		Load JPG	
8	11/12/19 14:09	General View		Load JPG	
9	11/12/19 14:09	General View		Load JPG	
10	11/12/19 14:09	General View		Load JPG	
11	11/12/19 14:09	General View		Load JPG	
12	11/12/19 14:09	General View		Load JPG	
13	11/12/19 14:09	General View		Load JPG	
14	11/12/19 14:09	General View		Load JPG	
15	11/12/19 14:09	General View		Load JPG	
16	11/12/19 14:09	General View		Load JPG	
17	11/12/19 14:09	General View		Load JPG	
18	11/12/19 14:09	General View		Load JPG	
19	11/12/19 14:09	General View		Load JPG	
20	11/12/19 14:09	General View		Load JPG	
21	11/12/19 14:09	General View		Load JPG	
22	11/12/19 14:09	General View		Load JPG	
23	11/12/19 14:09	General View		Load JPG	
24	11/12/19 14:09	General View		Load JPG	
25	11/12/19 14:09	General View		Load JPG	
26	11/12/19 14:09	General View		Load JPG	
27	11/12/19 14:09	General View		Load JPG	
28	11/12/19 14:09	General View		Load JPG	
29	11/12/19 14:09	General View		Load JPG	
30	11/12/19 14:09	General View		Load JPG	
31	11/12/19 14:09	General View		Load JPG	
32	11/12/19 14:09	General View		Load JPG	
33	04/03/20 14:48	Reinspection Photo		Load JPG	
34	04/03/20 14:48	Reinspection Photo		Load JPG	

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
35	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
36	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
37	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
38	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
39	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
40	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
41	04/03/20 14:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/12/19 15:10	EMAIL FROM AIG DD 02122019	 Load PDF	
2	04/12/19 16:52	TP ESTIMATE- MARKED	 Load PDF	
3	11/12/19 13:55	EMAIL FROM AIG	 Load PDF	
4	11/12/19 14:07	EMAIL TO OI	 Load PDF	
5	11/12/19 14:07	LETTER TO OI	 Load PDF	
6	12/02/20 13:26	LTA SEARCH	 Load PDF	
7	12/02/20 13:26	LOD	 Load PDF	
8	10/03/20 12:10	TMA SUPPORTING DOCUMENTS	 Load PDF	
9	10/03/20 14:30	EMAIL FROM AIG	 Load PDF	
10	10/03/20 14:54	EMAIL FROM TP	 Load PDF	
11	12/03/20 10:52	WORKSHOP INVOICE	 Load PDF	
12	12/03/20 10:52	AUTHORISATION TO ACT FORM	 Load PDF	
13	12/03/20 10:52	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/12/19 15:57	OI GIA REPORT	 Load PDF	
2	04/12/19 13:54	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFN132H (Insd veh)	Model:	MAN TGM 18.280 6.9 D 4X2
	XD8401T (TP veh)		BB (M)
Date of Accident:	30/11/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	67,175.03
Final Repair Cost	:	\$	46,500.00
Loss of Use	:	\$	3.00 days at \$180.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	46,500.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	COMPLETE VMS PTE LTD	:	\$ 46,500.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

12 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021216/R1HS3Q2

Date: 12/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800085566
 Claimant: XD8401T Insured Vehicle No: SFN132H
 Vehicle No: XD8401T
 Date of Loss: 30/11/2019 Nature of Claim: TP Claim No: 3420773235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD8401T
 Make & Model: MAN TGM 18.280, 6.9 D 4X2 BB (M) Engine No: 21834545853460
 Reg. Date: 10/12/2013 (Man. Year: 2013) Chassis No: WMAN08ZZ7DY296490
 Colour: Yellow Odometer: 80516 km
 Engine Capacity: 6871 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
 Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
 Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,460.40	42,000.00	18,460.40	30.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,000.00	1,320.00	56.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	62,780.40	43,000.00	19,780.40	31.51
+ GST 7.00/7.00% (S\$)	4,394.63	3,010.00	1,384.63	31.51
Nett Amount (S\$)	67,175.03	46,010.00	21,165.03	31.51
+ Loss of Use (3.0 x S\$180.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		46,557.45		
Global Sum Settlement (S\$)		46,500.00		

INSPECTION

Date of Assignment: 02/12/2019
 Date Inspected: 03/12/2019 Inspected At: 14, Tampines ind drive
 Repairer: COMPLETE VMS PTE LTD (HQ)
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP L/H }	Broken	395.00 FS	*42,000.00 FS
2	1		*TAIL LAMP BRACKET L/H }	Bent	228.60 FS	*- FS
3	1		*TAIL LAMP BRACKET REFLECTOR }	Cracked	36.80 FS	*- FS
4	1		*VERDEGRO SYSTEM US-100K (TMAS) TRUCK MOUNT ATTENUATORS (PASS NCHRP350 STS LEVEL 3) C/W HYDRAULIC LIFT }	Necessary	59,800.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 60,460.40 42,000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHANGE TAIL LAMP AND CHECK WIRING }	New	120.00	1,000.00
2	TO DISMANTLE CHARRIAGE ,KNOCK AND STRAIGHTEN REAR CHASSIS FRAME ,RE-ALIGN BODY AND RUST PROOFING }	New	1,200.00	0.00
3	LABOUR CHARGE TO INSTALL REMOVE /DISPOSE DAMAGE TMA }	New	1,000.00	0.00
Gross Labour Cost (\$\$)			2,320.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >