From (Person Estimated Co	Gubriel wee	of III		Date/Time: A	12/1903.58	3pm
OD PP / V	STTP RES / OD RES / E	Bill to VA/INV/MV/CS				
to Inspect V	chicle No:	SLQ SISTS Hup Motor		98154	ree	
f	Blkanna	Tampingo al.	93 #01 -	20	093	
ohey No: um Insured:	DIAM DC00020	32 Clai	m No:	(4.00	6 400.00	-
lake of Veh		E	kcess: 78	D.O.A. 26	Stulla	-
1.				3  2  4 H.O.D. Endorsemen		Meiner
\	REP. / REV 24 HRS			TI-A-TA THREADDRESSED	No.	1000
\	SpmOplo 19	erson Contacted:	Sovid v	chicle IN OUT		- He
ate/Time;	Action/Instruction	male 1	Sould v	ehicle INCOUT		- Hu"
ate/Time;	Spomo of 12/19	male 1	Jouid v	Phicle INCOUT		- pu"
CA (REV) Date/Time; 2	Action/Instruction	male 1	Sould v	ehicle INCOUT		- He

Date / Time	Action / Instruction	
	LTA 41637 140.72h.	
ulala	Royert Via Merimon	
4/12/19	Revert, Via Merimen Approval Mandake by Calitha Sout to Authorise to, Hup Motor \$1460.96 confind who Don'd	
9/12/19	Sout to Authorise to, Hup Motor	
2/13	\$ 1460.96 confund who Dourd	(Red \$ 2356-00, 61%)
· //		,
	DECEIVED	0040

From

Insured

Policy No

Claims No.

Sum Insured:

Make of Veh:

(Client's Record)

(Policy Condition)

Bal, or Market Value:

IDAC Accident Roort:

LPR Seen:

REV

Est. Repairs:

Lum Sum:

Date:

Estimated Cost

To Inspect Vehicle No:

		REC	EIVED 2 7 DEC 20	19	
Date/Time, File Pass to?	: Prell. Report	. Da	ys Of Repair: 3		
1) ElekeTime, File Rokum to?	: Final Report	Re	survey No. of Trip: 2	Survey Fee:	240
27/2/19 Ty	pist	Add Fee:	: Site Insp (\$	)8+RSSI	
1 /	,		: Interview (\$	) Fholos	
Peport Format:			:Tech, Invs (8	) Others	n
Lump Sum / LEJ: (a			: Weetend (8		
PIP \$14	60-96			TOTAL	261

#### Yvonne Wong (LKK Auto)

From:

Yvonne Wong (LKK Auto)

Sent:

Wednesday, December 04, 2019 1:19 PM

To:

hupmotor@gmail.com

Cc:

SUR

Subject:

RE: RE : REVERT OD CLAIMS FOR CLIENT'S VEHICLE : SLQ 5157 S, UNDER POLICY NO :

D19MPC0002932, DOA: 26/11/19, INVOLVING: JKS 8222, ALONG CHANGI SOUTH ST

2, OPEN CAR PARK

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SLQ5157S (excess \$600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <a href="mailto:yvonnewong@lkkauto.com">yvonnewong@lkkauto.com</a> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Monday, December 02, 2019 3:58 PM

To: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: David Ang <hupmotor@gmail.com>

Subject: RE: RE: RE : REVERT OD CLAIMS FOR CLIENT'S VEHICLE : SLQ 5157 S, UNDER POLICY NO : D19MPC0002932, DOA :

26/11/19, INVOLVING: JKS 8222, ALONG CHANGI SOUTH ST 2, OPEN CAR PARK

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711

Tel: 6347 6100, Ext - 248

From: Motor Claim - III

Sent: 02 December, 2019 2:45 PM

To: 'David Ang' < hupmotor@gmail.com >

Subject: RE: RE: RE : REVERT OD CLAIMS FOR CLIENT'S VEHICLE : SLQ 5157 S, UNDER POLICY NO : D19MPC0002932, DOA :

26/11/19, INVOLVING: JKS 8222, ALONG CHANGI SOUTH ST 2, OPEN CAR PARK

Dear Sir/Mdm,

Please conduct an OD survey on our vehicle SLQ5157S and let us have your report urgently.

This claim will be handled by Lalitha.

\*Kindly create OD claim & upload this survey request email to merimen.

Thank You.

#### Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711

Tel: 6347 6100, Ext – 248

From: David Ang [mailto:hupmotor@gmail.com]

Sent: 02 December, 2019 2:22 PM

To: Motor Claim - III < motorclaim@iii.com.sg>
Cc: Lalitha Krishnan - III < lalitha@iii.com.sg>

Subject: RE: REVERT OD CLAIMS FOR CLIENT'S VEHICLE: SLQ 5157 S, UNDER POLICY NO: D19MPC0002932, DOA:

26/11/19, INVOLVING: JKS 8222, ALONG CHANGI SOUTH ST 2, OPEN CAR PARK

Dear Sirs,

Attach our estimate bill, Client's NRIC, Driving Licence, insurance certificate & log card for your reference & attention, Kindly assign your panel surveyor (LKK or LBS) to survey client's damaged vehicle under own damage claims On: 03/12/19 (at 10am to 1pm) as owner request,

As third party JKS 8222 (Malaysia Truck) insurer was not reply & respond our email request for survey under PRI & liability for client's third party claims,

We will assist & revert client's recovery claims against third party insurer (Zurich General Insurance Malaysia Bhd) after we had complete the repair work,

Best Regards
David Ang
Tel: 6784 0039, Fax: 6784 0076, HP: 9815 4655
Mailing Address:
Hup Motor Trading & Service
Blk 9004 Tampines St 93
#01-120
Singapore 528838

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

#### Nivitha (LKK Auto)

From:

Motor Claim - III < motorclaim@iii.com.sg>

Sent:

Monday, 2 December 2019 3:58 PM

To:

'sur@lkkauto.com'; Admin-D (LKKAuto)

Cc:

David Ang

Subject:

RE: RE: REVERT OD CLAIMS FOR CLIENT'S VEHICLE: SLQ 5157 S, UNDER POLICY NO: D19MPC0002932, DOA: 26/11/19, INVOLVING: JKS 8222, ALONG CHANGI

SOUTH ST 2, OPEN CAR PARK

#### Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Motor Claim - III

Sent: 02 December, 2019 2:45 PM

To: 'David Ang' <hupmotor@gmail.com>

Subject: RE: RE: REVERT OD CLAIMS FOR CLIENT'S VEHICLE: SLQ 5157 S, UNDER POLICY NO: D19MPC0002932, DOA

: 26/11/19, INVOLVING : JKS 8222, ALONG CHANGI SOUTH ST 2, OPEN CAR PARK

Dear Sir/Mdm,

Please conduct an OD survey on our vehicle SLQ5157S and let us have your report urgently.

This claim will be handled by Lalitha.

\*Kindly create OD claim & upload this survey request email to merimen.

Thank You.

#### Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711 Tel: 6347 6100, Ext – 248 From: David Ang [mailto:hupmotor@gmail.com]

Sent: 02 December, 2019 2:22 PM

To: Motor Claim - III < motorclaim@iii.com.sg>
Cc: Lalitha Krishnan - III < lalitha@iii.com.sg>

Subject: RE: REVERT OD CLAIMS FOR CLIENT'S VEHICLE: SLQ 5157 S, UNDER POLICY NO: D19MPC0002932, DOA:

26/11/19, INVOLVING: JKS 8222, ALONG CHANGI SOUTH ST 2, OPEN CAR PARK

Dear Sirs,

Attach our estimate bill, Client's NRIC, Driving Licence, insurance certificate & log card for your reference & attention, Kindly assign your panel surveyor (LKK or LBS) to survey client's damaged vehicle under own damage claims On: 03/12/19 (at 10am to 1pm) as owner request,

As third party JKS 8222 (Malaysia Truck) insurer was not reply & respond our email request for survey under PRI & liability for client's third party claims,

We will assist & revert client's recovery claims against third party insurer (Zurich General Insurance Malaysia Bhd) after we had complete the repair work,

Best Regards David Ang

Tel: 6784 0039, Fax: 6784 0076, HP: 9815 4655

Mailing Address : Hup Motor Trading & Service Blk 9004 Tampines St 93

#01-120

Singapore 528838

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

India International Insurance Pte Ltd

64 Cecil Street #04-00 IOB Building Singapore 049711

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Lalitha Krishnan

Date:

03 Dec 2019

#### **Preliminary Advice**

Vehicle No

: SLQ5157S

Accident Date

: 26/11/2019

Make

: HONDA VEZEL

Policy No.

: D19MPC0002932

Assignment Date

: 02/12/2019

Excess

: \$\$0.00

Date of Inspection

: 03/12/2019

Est. Duration of Repair

: 3.00

Inspection At

: HUP MOTOR TRADING & SERVICE (HQ)

BLK 9004 TAMPINES STREET 93, #01-120

SINGAPORE 528838

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,816.96
Revised Amount	:S\$	1,460.96
Check Items (Estimated)	:S\$	278.72
Total	:S\$	1,739.68

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

Margin for Repair

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	37,887.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,113.00

#### Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
	have your authorisation.

( )	The ve	hicle is	uneconomical	to	be	repaired,	you are	advised	to	invite	tender	for	the	wrec	;k
-----	--------	----------	--------------	----	----	-----------	---------	---------	----	--------	--------	-----	-----	------	----

Other comments:

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	26/11/2019 17:10
Date Of Accident	26/11/2019 11:00
Exact Location Of Accident	CHANGI SOUTH ST 2 UNTI :01-01/02 S (486596)
Country/State of Loss	SINGAPORE
	Control of the Contro

Charles in Party of the Control	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLQ5157S
Insured/Policyholder	
Name Of Registered Owner	TAN KOK HOW
NRIC No	S8578961I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97369179
Alternative Phone No	OTHERS-97369179
Vehicle Particulars	

Temole i diticulars	
Manufacturer-	HONDA
TV: 7.7	

Model VEZEL-1.5 HYBRID X (A)

Exact Purpose for which vehicle was being used at PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

Type Of Coverage

Fleet Policy

INDIA INTERNATIONAL INSURANCE PTE LTD

COMPREHENSIVE

NO

Policy Number D19MPC0002932

Cover Note Number

 Driver
 TAN KOK HOW

 NRIC No
 \$8578961I

 Date Of Birth
 07/08/1985

 Occupation
 INDOOR

 Date Of Driving Pass
 17/01/2009

Driving Experience 10 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97369179

Fax Number

Contact Number OTHERS-97369179

EMail Address NOEMAIL

Address

BLK 127 PASIR RIS STREET 11 #10-387

Postcode

510127

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JKS8222 (COMMERCIAL VEHICLE)

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN & POLICE REPORT NO. T/20191126/7019

Attachment(s)

Are accident photos available for attachment?

YES YES

Was there any video captured by Car Camera?

FILE WITH INSURED

Remarks/ Reasons: Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

JKS8222

Vehicle Make/Model/Colour

LORRY

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

0167109727

Address

Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

2

Passenger 1

NAME:

GENDER:

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 3/ 14/1 / 2016

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

GIARMC skatenHanform\_V3

#### Sketch Plan #2 Pg. 1

	Okcient fan #2 r g.	
KETCH PLAN		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
111111111		
SCRIBE CIRCUMSTANCES		
		*
		<del></del>
3		
		1.0
		*
CLARATION	ulana ann Anna In-Anna In-Anna In-	
re declare the foregoing partic	ulars are true in every respect.	
HOL		
000		
licyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature

Date & Time: 26/11/2019
49:45 pm

(If driver is not the policyholder) Date & Time:

Name: NRIC/FIN No.:





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20191126/7019

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/11/2019 16:05			Vide Report No.:	Station Diary No.:			
Informa	nt's Partic	ulars					
Name of TAN KO	Informant: K HOW		Address: 127 PASIR RIS STREET 11	#10-387 SINGAPORE 510127			
ID Type NRIC NO	/ ID No.: D / S85789	611	Contact No.: Home/Office:	Mobile: 97369179			
National MALAYS	ity: SIAN		Email: KOKHOWBE85@GMAIL.CC	PM			
Sex: Male	Age: 34	Date of Birth: 07/08/1985	Type of Informant: Driver				
Race: Chinese			Language: Institution / School National English				
Occupation: Sales and related associate professional nec			Driving Licence Information: Class: 3 Date of Expiry:				

General Inform	nation of the Accident			
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 100 26/11/2019 03-44	Type of Location: Car Park
Location:				omes NPC
CHANGI SOL	JTH STREET 2, 01-01/0	2 Singapore 486596	16	apore 529682 1800-5871999
Weather: Clear		Road Surface:	F	Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collis Moving Vehic	ion: le Against - Parked Vehi	cle	8	Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
JKS 8222	Lorry			White	No Damage	1
SLQ 5157 S	Car	HONDA	Vezel Hybrid	Black	Slightly Damaged	0

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
SLQ 5157 S	INDIA INTERNATIONAL INSURANCE PTE LTD	D19MPC0002932	13/07/2019	12/07/2020		





1/20191126/7019

2 of 3

Report No. T/20191126/7019

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

#### CONTINUATION OF REPORT

<b>Details of Perso</b>	n Involved			CALCULA !		
Any Pedestrian In	nvolved: No					
No. of Pedestrian	s Injured: NIL		Use of Pe	destriar	Cross	ing: NA
Driver						
Name	TAN KOK HOW			ID No		S8578961I
Related Vehicle	SLQ 5157 S (Car)			Contact No.		97369179
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	fInjury	NIL	

#### Brief Details.

My car is parked, and the lorry reversing and accidentally hit the right back of my car, causing my back light broken and bumper slightly came out. The lorry is a from Malaysia, car plate no. JKS 8222. Under the name of company, Sin Wah Bee Transport Co. Sdn Bhd





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20191126/7019

CONTINUATION OF REPORT

Sketch Plan

NP168

Informant is not able to provide sketch plan

Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/11/2019 16:05
Officer In Charge Of Case: TP / TPHQ / SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172	Classification Of Case:



### INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. MZ-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711

Office (65) 63476100 Fax (65) 62244174

Email insure@iii.com.sg Website www.iil.com.sg

COVER: COMPREHENSIVE

# CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

CERTIFICATE NO.: D19MPC0002932

**SLQ5157S** 

1. Index Mark and Registration Number of Vehicle

RU31244315

Chassis No

TAN KOK HOW

2. Name of Policyholder

13 Jul 2019

3 Effective date of Insurance 4. Expiry date of Insurance

12 Jul 2020

Persons or Classes of Persons entitled to drive\*

(a) The Policyholder

The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her

employer or his/her partner.

(b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6. Limitations as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

#### The Policy does not cover

a) Use for hire or reward.

b) Use for racing, pace-making, reliability trial, speed-testing.

Use for the carriage of goods other than samples in connection with any trade or business.

Use for any purpose in connection with the Motor Trade.

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Insured and Named Drivers Excess Sect I: SGD600.00

Unnamed Drivers Excess Sect I

: SGD1,100.00

Windscreen Excess

: SGD100.00

Hire Purchase Company

N.A

FOR DRIVERS BELOW 21 YEARS OR ABOVE 65 YEARS OF AGE &/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, ADDITIONAL EXCESS OF \$2500/-ON SECTION I WILL BE APPLICABLE.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agent/Broker

: A000038/M Plus Consultancy

Date of Issue

: 06/06/2019 14:23:17

MX1-Private Car (Insured Driving)

For India International Insurance Pte Ltd

Authorised Signatory

Vehicle Details	
Vehicle No.:	SLQ5157S
Make / Model:	HONDA / VEZEL HYBRID 1.5X AUTO
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme :	Normal
Chassis No. :	RU31244315
Propellant:	Petrol-Electric
Engine No. :	LEB5944335
Motor No.:	H12349204
Engine Capacity:	1496 cc
Power Rating:	22.0 kW
Maximum Power Output:	112.0 kW (150 bhp)
Maximum Laden Weight:	1555 kg
Unladen Weight:	1280 kg
Year Of Manufacture :	2017
Original Registration Date :	13 Jul 2017
Lifespan Expiry Date :	<b>-</b> 0
COE Category:	E - Open - all except motorcycle
Quota Premium :	\$49,899.00
COE Expiry Date :	12 Jul 2027
Road Tax Expiry Date :	12 Jul 2020
PARF Eligibility Expiry Date :	12 Jul 2027
Inspection Due Date :	12 Jul 2020
Intended Transfer Date :	26 Nov 2019
CO2 Emission :	94.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$22,450.00
CO Emission :	-
HC Emission :	-
NOx Emission :	
PM Emission :	-)

Fees To Be Paid For Transfer	
Transfer Fees	\$25.00

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	9611
Vehicle No.:	SLQ5157S
Vehicle to be Exported:	No
ntended Deregistration Date:	03 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5944335
Chassis No.:	RU31244315
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,321.00
Original Registration Date:	13 Jul 2017
First Registration Date:	13 Jul 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jul 2027
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00
COE Expiry Date:	12 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,899.00
COE Rebate Amount:	\$37,887.00
Total Rebate Amount:	\$41,637.00

The information contained herein is correct as at 03 Dec 2019

OK

GCARMART.COM

Sign up Login

**New Cars** 

12/3/2019 . . '

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum





# Toyota Alphard

The ultimate family car! Supreme road presence with space for the whole family and much more.



Post an Advertisement Sell it yourself! Advertise it at just

\$58 until it's SOLD!

2019 Toyota Dyna 3.0m At Offer Price \$66,800!



Offer Ends At 31/12/2019! Cheapest In The Marketl Grab Your Workhorse Naw! Net Link Partners StarAd



rowse by Category

Post an Ad

Advertiser Login ٠

Make

Ways of Selling

Model

« Back (12) Next »

Sort by Date Posted

24 vehicles

Vezel Hybrid 1.5A

Price

Depreciation

Reg Date

Eng Cap

Advanced Search Mileage

Veh Type

Search Selection

Vezel Hybrid 1.5A

Any

2017

Any

Anv

Anv

Honda Vezel Hybrid 1.5A X

\$74,800

\$9,440 /yr

31-Jul-2017

1,496 cc

37,066 km

SUV



We Assure You Its Non Private Hire/Leasing Car! Elegant Pearl White Vezel 1.5A, Hybrid Model. Genuine Low Mileage Done 37066km. As Good As New, See To Believe. New Car Number. New Paintwork. Road Tax Till Jul 20. 100% Accident Free. Price Negotiable. Call Now!

Lake View Credit Pte Ltd

Posted: 01-Dec-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda Vezel, Vezel, Used Honda



Honda Vezel Hybrid 1.5A X

\$75,800

\$9,800 /yr

25-May-2017

1,496 cc

36,158 km

SUV

1 Owner, Low Mileage With Immaculate Condition, Powerful And Smooth Transmission, Low Fuel Consumption And Low Maintenances. New Road Tax Till May 2020. Call/SMS/Watsapp For Viewing

Republic Auto

Posted: 01-Dec-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X **Honda Sensing** 

\$74,388

\$9,050 /yr

10-Nov-2017

1,496 cc

36,000 km

SUV

1 Owner.Low Interest At 2.28%, Original Paint And Condition. Safety Honda Sensing Functions With Auto Lane Departure Warning.Most Popular Compact SUV. Act Fast And Call Now For Viewing Before It Gone.

Cycle & Carriage.Fulco Motor Dealer

Posted: 01-Dec-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda Vezel, Vezel, Used Honda



Honda Vezel Hybrid 1.5A X

\$69,800

\$9,420 /yr

24-Jan-2017

1,496 cc

50,000 km

SUV

**Honda Sensing** 

Low Depreciation! Hot Favourite SUV On The Road. Powerful, Reliable, Yet Fuel Efficient Equipped With Hybrid Technology And Honda Sensing. Only 1 Previous Owner. Non PHV Unit. Accident Free. Car In Original Condition. Flexible Loan Available With Attractive Interest...

AL Autocar Pte Ltd

Posted: 30-Nov-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda Vezel, Used Honda



Door Visor

Honda Vezel Door Visor / Honda HRV Door Visor

about this product

# 哈汽車貿易服務 HUPMOTOR TRADING & SERVICE

9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076	Email: hupmotor@	gmail.c	om Reg. No.	378091/00W
Ref:TP 2972/11/19 Your Ref:	Date:	7th	NOV 2019	
MR TAN KOK HOW BLK 127, #10-387 PASIR RIS STREET 11 SINGAPORE 5101:7				
Estimate cost of repair to HONDA VEZEL 1.5% (	A) Hybrid S	/Wgn	- SIQ 5	157 S
1 pc o/s tail lamp assy CM 2 pcs o/s tail lamp clips & stopper MM & \$ 1 pc tail gate door o/s reflecter AA 1 pc rear bumper o/s side pad DA 1 pc rear bumper o/s side pad side retainer 1 pc rear bumper o/s side pad top retainer 14 pcs rear bumper top & low clips AA 1 pc rear o/s fender 8 pcs rear o/s fender inner trim board clips 1 pc rear o/s fender wheel guard shield AA 10 pcs rear o/s fender wheel guard clips stop	3.90 3.6.50	1	463.90 13.00 272.30 284.50 26.00 42.00 46.80 709.80 52.00 263.40 85.00	" X X X X X X X X X X X X X X X X X X X
	Less 20,5		2,258.70 451.74	
	SGD	S\$ 4	1,806.96	SGD
To wiring check up for affected wiring system.			50.00	20
To remove & refix carpet, floor mat, garnish, cover, fender inner shield & necessary parts, repair rear o/s fender, tail lamp panel & necessary	to enable		150.00	00
To respray Tuff-Kote on all affected accident	parts.	11	60.00	X
Labour charge to remove & cut out damaged part straighten & knocking out rear o/s fender, o/s panel & necessary parts, to weld, renew & alig	e toil lowe		750.00	280
To putty & respray painting on all affected as	ccident par	ts. 1	,000.00	400
	SGD :	S\$ 3	,816.96	(SGD)
Singapore Dollars : Three Thousand Eight Hundr	red Sixteen	Doll	ars And	07/
LKK Auto Consultants hence notify the Repairer of the following: *To resurvey before after spray painting *To dispiHUP MOTOR TRADING & SERVICS *Parts prime are subject to continuation *The dispination are subject to continuation	+ Ali	1	, ,	700.9
* Through the state of a Water Prejudice basis  No in the state of the	Thephy	1 31	eperp-	27.
Signature:  Plan 5/5.	30	7	3	600

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted	d Ins Auth'ed	Sta	Status	
Main	03 Dec 2019 Edit Reg		02 Dec 2019 00:00 Edit Adj Rpt	S\$1,460. Edit Esti	1	S\$1,460.96 View Rpt		Re	nding for port Cancel Case	Survey
	Main	R	eference	CI	aim Deta	nils	Docum	ents	٦.	Show All
CLAIM S	UBFOLDER DE	TAILS	Contraction of the last			[Create	ed by adjuster	1		
Insured:	TAN KOK	HOW, ID: S857	8961I							
Vehicle Re No.:	SLQ515	75			Date of L		2019 00:00 - :59 on this and <b>13</b> Days	From LTA	Reg Date (	Man Yr)]
Claim Typ	pim Type: OD / MPC2019D0001526 Policy/Cover Note No.: D19MPC0002932 (Comprehensive)									
	Excess: S\$600.00									
Repairer:	Hup Moto	or Trading & Ser	vice (HQ) Blk 9004	Tampines St	reet 93,	#01-120, 528	838 Tampines - 1	rel: 678400	39/981546	55
Handling Insurer:	India Int	ernational Insur	ance Pte Ltd (HQ)	- Tel: 63476	100 [1	Handled by <b>La</b>	litha Krishnan	- 6347 613	9]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	Handled	by MARCUS	CHUA] [Fina	I Rpt due	11/12/2	019]
ASSOCIA	ATED MAIL RE	CEIVED						View All	Compose	e Case Mail
			date Approved (S\$ date Approved (S\$							
ALL ASS	OCIATED TAS	SKS <sup>=</sup>				View All	Search Tasks	Create N	lew Task	Complete
Due Da		Type Task	Group Subjec	t Handle	er As	ssigned By	Completed	On C	reated On	Done

#### Claim Documents

# \*SLQ5157S (MPC2019D0001526) OD Nov 26 2019 12:00AM [TAN KOK HOW] Hup Motor Trading & Service

=		load Photos Compose New Letter	View View		
	essment Reports	I was a second of the second o	1 per page	V	₩.
Vo L	Finalized On 04/12/19 09:02	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice		nbnail HTM	Prin
_	04/12/15 05:02	Adjuster similediate Advice	0 200		
Pho	otos/Images		3 per page	V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		nbnail	Prin
1	04/12/19 09:01	General View			V
2	04/12/19 09:01	General View	0		Ø
3	04/12/19 09:01	General View	0	<b>.</b>	V
4	04/12/19 09:01	General View	0		V
5	04/12/19 09:01	General View	0	Tip	V
5	04/12/19 09:01	General View	0		V
7	04/12/19 09:01	General View	0	3	V
8	04/12/19 09:01	General View	0		V
9	04/12/19 09:01	General View	0	2	V
10	04/12/19 09:01	General View	0	3	V
11	04/12/19 09:01	General View	0	5	V
12	04/12/19 09:01	General View	0		V
13	04/12/19 09:01	General View	0	學	V
14	04/12/19 09:01	General View	0		V
15	04/12/19 09:01	General View	0		V
16	04/12/19 09:01	General View	0	1	V
17	04/12/19 09:01	General View	0	1	V
18	04/12/19 09:01	General View	0		V
19	04/12/19 09:01	General View	0		V
20	04/12/19 09:01	General View	0	Q	Ø
21	04/12/19 09:01	General View	0	i i	V
22	04/12/19 09:01	General View	6		V
23	04/12/19 09:01	General View	6		V

Ass	essment Reports		1 per p	age 🗸	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
24	04/12/19 09:01	General View	0		Ø
25	04/12/19 12:57	Reinspection Photo	0	0	Ø
26	04/12/19 12:57	Reinspection Photo	0	国意	Ø
27	04/12/19 12:57	Reinspection Photo	6	1100	Ø
28	04/12/19 12:57	Reinspection Photo	0	9	Ø
29	04/12/19 12:57	Before Repair Photo	0		Ø
30	04/12/19 12:57	Before Repair Photo	0		Ø
31	04/12/19 12:57	Before Repair Photo	9		Ø
Do	cumentation		1 per p	age 🔻	$\mathbf{\nabla}$
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/19 08:59	GIA	0	Load PDF	
2	04/12/19 08:59	ESTIMATE	6	Load PDF	
3	04/12/19 09:00	Certificate of Insurance	0	Load PDF	
4	04/12/19 09:00	Driver's Driving License	0	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	03/12/19 08:31	Singapore Accident Statement	0	Load PDF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			-
			~
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

#### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd

64 Cecil Street, #04-00 IOB Building

Singapore 049711

Our File No:

CS/III19021240/UYD3E2

Date:

30/12/2019

REFERENCE

Insured/Claimant: Date of Loss:

TAN KOK HOW

26/11/2019

Policy No:

D19MPC0002932

Nature of Claim:

OD

Claim No: MPC2019D0001526

LEB5944335

RU31244315

92834 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

Colour:

**SLQ5157S** 

Make & Model: HONDA VEZEL, 1.5 X (A) Reg. Date:

13/07/2017 (Man. Year: 2017)

Black

Engine Capacity: Market Value/New Car Price: S\$64,000.00

1496 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Engine No:

Odometer:

Chassis No:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Pre-accident Condition: No

Front Tyre Size: Front Left Side:

215/60 R16 Michelin 6 mm Rear Tyre Size: Rear Left Side:

215/60 R16 Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,806.96	700.96	1,106.00	61.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	760.00	1,250.00	62.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,816.96	1,460.96	2,356.00	61.72
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	3,216.96	860.96	2,356.00	73.24

INSPECTION

Date of Assignment:

02/12/2019

Date Inspected:

03/12/2019 Inspected At:

Hup Motor Trading & Service (HQ)

Blk 9004 Tampines Street 93, #01-120

Singapore 528838

Estimated Period of Repair:

3.0 days

Adjuster: MARCUS CHUA Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

Referen	ce		
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)	
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLQ5157S)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running pagnumbers with the END OF ESTIMATES marker on the last estimate page		
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.	

# Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*O/S TAIL LAMP ASSY	Cracked	463.90 FL	*463.90 FL
2	2	*O/S TAIL LAMP CLIPS & STOPPER	Necessary	13.00 FL	*13.00 FL
3	1	*TAIL GATE DOOR O/S REFLECTOR	Not Necessary	272.30 FL	*-FL
4	1	*REAR BUMPER O/S SIDE PAD	Dented	284.50 FL	*284.50 FL
5	1	*REAR BUMPER O/S SIDE PAD SIDE RETAINER	Bent	26.00 FL	*26.00 FL
6	1	*REAR BUMPER O/S SIDE PAD TOP RETAINER	Bent	42.00 FL	*42.00 FL
7	1	*REAR BUMPER TOP & LOW CLIPS (14PCS)	Necessary	46.80 FL	*46.80 FL
8	1	*REAR O/S FENDER	Repair	709.80 FL	*-FL
9	8	*REAR O/S FENDER INNER TRIM BOARD CLIPS	Not Necessary	52.00 FL	*-FL
10	1	*REAR O/S FENDER WHEEL GUARD SHIELD	Not Necessary	263.40 FL	*-FL
11	10	*REAR O/S FENDER WHEEL GUARD CLIPS STOPPER	Not Necessary	85.00 FL	*-FL
F=Fra	anchise	part. L=ListItemDisc.	Sub Total (S\$)		876.20
		- List Item Discount on L Items 20.	.00/20.00% (S\$)	451.74	175.24
		i i	Total Parts (S\$)	1,806.96	700.96
		Report was unsubmitted during this print-	-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, FENDER INNER SHIELD & NECESSARY PARTS, TO ENABLE REPAIR REAR O/S FENDER, TAIL LAMP PANEL & NECESSARY PARTS	New	150.00	60.00
3	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	60.00	0.00
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAF O/S FENDER, O/S TAIL LAMP PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New R	750.00	280.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,000.00	400.00
	Gross Labour Cost (S\$)		2,010.00	760.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >