

ASS. REC. BY:

REF: CS/FC1 K104201 / A4f302

Special instruction:

(CWS)

Surveyor

Admission

ASSIGNMENT (Office)

From (Person): Jason Tsa Chui tiat

of FC1

Date/Time: 3.12.19 12.06 p.m

Estimated Cost

Bill 100

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SMN 1284R

Insured: SHC 2269T

at Workshop m/s Sin Hwa motor

Tel: 97666672

of BIK 3023A Ubi Rd 1 #01-59

Policy No.

Claim No: D19007618mFSH

Sum Insured:

Excess

Make of Veh:

D.O.A. 29.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

$$Vr_{up}''$$

Date/Time: 3.12.2019 1.02p.m

Person Contacted:

Khi m

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMN 1284R -
	SH(22691 - (C3/ FI1509574/ LUK 2 DOA - 4/11/2015

ASSIGNMENT

SMD1284R. 2018 August.

UD / TP / WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle File

at Workshop File

Insured

Policy No.

Client's

Own Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	OIS

Est. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repair: days Rep. Yes or No

Loss Sum: % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted

Truck / Trailer

Make

Mercedes Benz C180 1595

Color

Grey.

AXX Insured / Std / NI / NA

Sp. Reading

21313.

T-AXX Insured / Std / NI / NA

EngNo

City

WDD2050402 R398/54

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt

Brake: Inorder / Jammed / Leaked / Burnt

Mod: Nil / S/Rim / STD A/Rim

Tyre Size

F: 225/50R17.

R: 225/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Continental

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A

D.O.A

03/12/19

Survey held at

Sin Hwee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP 1st Cap.

4/12/19 Sent E-Mail to Insurance (Pending Estimate)

20/1/20 Sent e-mail to Insurance

MV:

PV:

Nett:

RECEIVED 20 JAN 2020

17/1/20 P/P \$3639-50 (Red \$1275-50, 25%)

Cons/Time File Form

☐

: Preli. Report

☐

: Final Report

Cons/Time File Form

20/1/20 Typist

Days Of Repair:

3

Resurvey No. of Trip:

3

Adm Fee:

☐

See form

☐

Intercom

☐

Intercom

☐

Intercom

☐

Intercom

Survey Fee

Transport

Intercom

Intercom

Intercom

Intercom

Intercom

135

50

50+50

34

34

34

34

319

P/P \$3639-50



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007618MFSH

Date: 20 Jan 2020

Our Ref: CS/FCI19021291/Ayf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD1284R.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/12/2019 at the premises of M/s SIN HWEE MOTOR.PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ 4,915.00
Revised Estimate Amount	: S\$ 3,639.50
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Adrian Ling
Licensed Appraiser

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, January 20, 2020 2:36 PM
To: 'CWS Motor Claims'
Cc: SUR
Subject: SURVEY ASSESSMENT - D19007618MFSH/1
Attachments: SMD1284R DOA 29112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SMD1284R
Date of survey : 03/12/2019
Number of days : 3 days
Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne Wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne Wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, December 04, 2019 5:23 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007618MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle SMD1284R on 03/12/2019.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Tuesday, 3 December, 2019 12:06 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007618MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, December 04, 2019 5:23 PM
To: 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19007618MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle SMD1284R on 03/12/2019.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Tuesday, 3 December, 2019 12:06 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007618MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

MOTOR SURVEY ASSIGNMENT

Date	02-12-2019	Our Ref No. D19007618MFSH
Accident Date	29-11-2019	Claim Type. Third Party
Insured Vehicle	SHC2269T	Third Party Vehicle. SMD1284R
Survey Location	BLK 3023A UBI ROAD 1 #01-59	
Contact Person.	KHIM HP	
Contact No.	67455783/ 97666672	Fax No. 67449582
Survey Type	WITHOUT PREJUDICE: NO ESTIMATE. WE CAN AGREE TO DS IF THERE IS ESTIMATE AND VEHICLE TO BE SURVEYED A	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN HWEE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

MR JASON CHUA PO TIONG

TP1st Cap.
Xonne.

DATE	2/12/2019
VEHICLE NO:	SMD 1284 R
MAKE:	MERCEDE
MODEL:	C180

WIN 2052+02 R398154

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	REAR BUMPER - NETT <i>del</i>	1,780.00	1,780.00 <i>1590</i>
1 PC	REAR BUMER LOWER GARNISH - NETT <i>del</i>	350.00	350.00
1 PC	LOWER GARNISH CHROME - NETT <i>ut</i>	295.00	295.00
1 PC	REINFORCEMENT - NETT <i>newer part</i>	745.00	745.00 <i>682</i>
2 PCS	REVERSE SENSOR - NETT <i>1 piece damaged 2x Bays</i>	190.00	380.00 <i>150</i>
1 PC	<i>Simple Lower Bumper 1/4 - NOT needed</i>	<i>158.00</i>	<i>✓</i>
	----- SUBTOTAL		3,550.00
LESS 10%	----- LESS 10%	-10.00%	-355.00
			<i>3355</i>
			<i>3019.50</i>
-	TO KNOCK INNER PANEL AND BRACKETS TO REPLACE AND ALIGN ABOVE ITEMS	750.00	750.00 <i>250</i>
-	TO REPLACE REVERSE SENSORS AND CARRY OUT MANAGEMENT SCAN / RESET FAULT CODES	250.00	250.00 <i>120</i>
-	TO SPRAY PAINT REAR BUMPER AND INNER PANEL	600.00	600.00 <i>250</i>
-	TO SUPPLY AND TUFF KOTE ON AFFECTED AREA.	120.00	120.00 <i>x</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
P/P 03/12/19
03 Days

total 3639.50

CP/P)

Tel: 6745 5783 Fax: 6744 9582

Email: sinhweemotor@gmail.com

Website: www.sinhweemotor.com

TOTAL \$4,915.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19021291/Ayf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2269T	Veh. Inspected	SMD 1284R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007618MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	03/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2050402R398154	Colour	GREY	
Odometer	21313	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2019	Inspection Date	03/12/2019	
Survey held at	SIN HWEE MOTOR PTE LTD BLK 3023-A UBI ROAD 1 #01-59 SINGAPORE 408717			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1284R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	DEFORMED	1,780.00	1,590.00
1	REAR BUMPER LOWER GARNISH (N)	DEFORMED	350.00	350.00
1	LOWER GARNISH CHROME (N)	CUT	295.00	295.00
1	REINFORCEMENT (N)	BENT	745.00	682.00
2	REVERSE SENSOR @\$190.00 (N)	DAMAGED	380.00	380.00
1	BUMPER LOWER BRACKET L/H (N)	CRACKED	58.00	58.00
	LESS 10% DISCOUNT		-360.80	-335.50
			3,247.20	3,019.50
LABOUR				
	TO KNOCK INNER PANEL AND BRACKETS TO REPLACE AND ALIGN ABOVE ITEMS.		750.00	250.00
	TO REPLACE REVERSE SENSORS AND CARRY OUT MANAGEMENT SCAN/RESET FAULT CODES.		250.00	120.00
	TO SPRAY PAINT REAR BUMPER AND INNER PANEL.		600.00	250.00
	TO SUPPLY AND TUFF KOTE ON AFFECTED AREA.	NOT NECESSARY	120.00	-
			1,720.00	620.00
GRAND TOTAL			4,967.20	3,639.50
RECOMMENDED COST OF REPAIRS				3,639.50

Report Ref No. CS/FC119021291/Ayf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M,MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.