

ASS. REC. BY:

REF: CS/AG 1021332 / Ust327

Special Instruction:

SUMMARY

meimer

MORUE

## ASSIGNMENT (Office)

From (Person):

Jennifer Chan

of

AIG

Date/Time:

3.12.19 10.24.17

Estimated Cost:

Bill to:

OB / TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Report Vehicle No:

SLK 88436

Insured:

at Workshop m/s

Autolux Industrial

Tel:

96450079

of

19 Ubi Road 4

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Brand)

D.O.A. 30.11.2019

4.12.2019

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3.12.2019 4.07.17

Person Contacted:

Hamzah

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 88436 - CCB / AIG 19011012 / LPA 372 D.O.A. - 20/11/2019

04/12/19

@ 17:46 pm revised PA to Azlan Spazardine via meimer

04/12/19

@ 17:51 pm mandate requested authorisation report to AIG via meimer.

05/12/19

@ 16:35 pm mandate approved by # Kofe Chong

ASS. REC. BY:

REF: A14

## ASSIGNMENT

From:

Date: 4/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 8843G

at Workshop m/s: Autolution

of 19 Ubi Road 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: TBA \$0/-

(Client's Record)

Make of Veh:

10:30am (waiting)

Hamzah

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 66k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 1.51 % 3 Val.: Yes or No

CA (REV) / REP. / 24 HRS

147F

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 8843G

Yr Regn: 2, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Nissan Qashqai c.c. 1197

Colour: Blue AC: Insured / Std / NI / NA

Sp. Reading: 50613 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFEAJ1U1812328

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 60 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 30/11/19

D.O.I. 4/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Ref.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12/19 LTA 46723 Rep Airs Spatrim scratched  
 @ 18:06 pm inform cl to Hamzah via email.  
 No other rep - photo taken from repairer  
 AIG Comments: Front Bumper to be repair & repaint instead of replacement.  
 20/2/20 \$1631.64 confirmed with hamzah.  
 C\$ 1,575.68 Red - 49%

RECEIVED 1 FEB 2020

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 4

1) 21/02/20

☒ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2

Add Fee: ☐ : Site Insp (\$)

Survey Fee: 200

Transportation: 3 + RS 84

Photos

Others: 11

TOTAL

211

Report Format:

Lump Sum (LE) G \$1,631.64 Rep

☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Wheel end (\$)

Your password will expire in 9 days. [Click here to change it.](#)





- SLK8843G - survey arrangement

From: AIG SGP, Claims-Survey

To: Admin A. assignments

Cc: Fong, Andy-SY, Fan, Winnie-LW

Sent: Tuesday, 3 December, 2019 10:24:47 AM

Attachments:  [slk8843g-cl expiry feb 2020.tif](#)  [slk8843g-estimate 301119.pdf](#)  [slk8843g-owner icdl 301119.tif](#)  [slk8843g-sas 301119.PDF](#)

Hi LKK,

Kindly assist to survey.

Thanks & regards  
Jennifer Chan

---

**From:** Hamzah [mailto:hamzah\_saad@tanchong.com]

**Sent:** Monday, 2 December, 2019 4:57 PM

**To:** AIG SGP, Claims-Survey

**Subject:** [EXTERNAL] SLK8843G - survey arrangement

This message is from an external sender; be cautious with links and attachments.

Dear Survey Team,

Kindly arrange for survey tomorrow morning at 10.00 am.

Owner waiting.

Kindly revert.

Hamzah Sa'ad  
Service Supervisor  
Autolution Industrial Pte Ltd  
19 Ubi Road 4  
S408623  
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483  
Hp: +65 96450079 Email: hamzah\_saad@tanchong.com

P: Hamzah  
T: 10:32a.m 3.12.19  
V: Out  
E: ✓

96450079  
Hamzah

9116 5199

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	147F
<b>Vehicle Details</b>	
Vehicle No.:	SLK8843G
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	HRA2348528A
Chassis No.:	SJNFEAJ11U1812328
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	02 Feb 2017
First Registration Date:	02 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$13,725.00 6P6L
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2027
PARF Rebate Amount:	\$10,293.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	01 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$36,430.00
<b>Total Rebate Amount:</b>	<b>\$46,723.00</b>

The information contained herein is correct as at 04 Dec 2019

OK

THE MAZDA CX-3.  
NOW FROM \$89,888.  
CX-3 SP variant is featured



CLICK HERE



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

New 5 Years Renewal COE Toyota Wish 1.8A



2.88% P.A. \$0 Admin, Monthly  
From \$688, 2 Years Warranty.  
Engine And Gearbox.  
GV Credit. [StarAd](#)

ABWIN

ONE-STOP



Post an Ad Advertiser Login Ways of Selling

Browse by Category






« Back ( 1 2 ) Next »

Sort by Date Posted

33 vehicles

nissan gas

Advanced Search

Model	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	nissan gas	Any	Any	2017	Any	Any	Any
	<b>Nissan Qashqai 1.2A DIG-T Premium</b> Well Maintained By A Single Owner. Low Depreciation, High Loan Available. Good Fuel Consumption. Bad Credit Also Can Apply. Allmotoring.sg Posted: 03-Dec-2019 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan	<b>\$73,000</b>	<b>\$8,470 /yr</b>	<b>31-Aug-2017</b>	<b>1,197 cc</b>	<b>44,000 km</b>	<b>SUV</b>
	<b>Nissan Qashqai 1.2A DIG-T</b> Graded <b>A</b> by <b>STP</b> Offer 1.98% Interest Rate! Purchase From An Award Winning Dealership! STA Certified Accident Free Quality Pre-Owned With Low Mileage And Agent Service History For Peace Of Mind. 100% Loan Approval With Our In House Financing. View Today! Cosmo Automobiles Posted: 03-Dec-2019 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan	<b>\$69,800</b>	<b>\$8,730 /yr</b>	<b>18-Feb-2017</b>	<b>1,197 cc</b>	<b>47,339 km</b>	<b>SUV</b>
	<b>Nissan Qashqai 2.0A Premium Moonroof</b> 1 Owner Unit, Well Maintained, Spacious And Powerful With Comfortable Interior, Practical For Daily Use. Low On Maintenance! High Trade In Available. Call Our Friendly Salesman Now For An Viewing Appointment Today! Don't Miss! Mayfair Motoring Posted: 02-Dec-2019 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan	<b>\$77,800</b>	<b>\$8,990 /yr</b>	<b>29-Jun-2017</b>	<b>1,997 cc</b>	<b>40,086 km</b>	<b>SUV</b>
	<b>Nissan Qashqai 1.2A DIG-T Premium</b> Driven By 1 Mature Owner Who Service This Qashqai With Agent On Time! With Documents To Prove! Still Under Agent Warranty! Selling At The Same Deprecation With A Vezel And You Get To Enjoy Much Refinement From The Face Lifted Model With Updated Interiors, Lea... Posted: 01-Dec-2019 Tags: 2017 Nissan Qashqai, 2017 nissan qashqai, Nissan Qashqai, nissan qashqai, Nissan, Qashqai, qashqai, Used Nissan	<b>\$75,800</b>	<b>\$8,560 /yr</b>	<b>30-Nov-2017</b>	<b>1,197 cc</b>	<b>34,520 km</b>	<b>SUV</b>
	<b>SCT Auto Services Pte Ltd - Repair &amp; Servicing</b> SCT Auto Services is a one-stop repair centre with expertise in vehicle servicing, repairs, and spray painting. More info about this shop						
Compare	an Qashqai 1.2A DIG-T	\$69,800	\$8,540 /yr	20-Apr-2017	1,197 cc	61,000 km	SUV 1/4

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Thursday, 5 December 2019 6:06 pm  
**To:** Hamzah Saad / TCMS  
**Cc:** SUR  
**Subject:** SLK 8843G OD (AIG) Date of Loss: 30/11/2019

Hi Hamzah,

As instructed by our client, please proceed to repair the insured vehicle **SLK 8843G (Excess S TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

**Please refer below AIG comments,**

**Front Bumper to be repair and repaint instead of replacement. Resurvey for checked / hidden and supplementary items require.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*SLK8843G (11179888165G)**

OD

Nov 30 2019 11:00PM

[STEPHANIE SHAINA LEE HER LING]

Autolution Industrial Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 05/12/2019 16:35 PM,

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$2349.32) - SLK8843G - Claim Handler: Azlan, Syazairdina

Approved:2349.32:Front Bumper to be repair and repaint instead of replacement. Please resurvey for checked / hidden and supplementary items if required and upload photos in Merimen.

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: **AIG Asia Pacific Insurance Pte. Ltd.**  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: **LKK Auto Consultants Pte Ltd**  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: **Azian, Syazairdina**Date: **04 Dec 2019****Preliminary Advice**

Vehicle No	: SLK8843G	Accident Date	: 30/11/2019
Make	: NISSAN QASHQAI	Policy No.	: 2100499757
Assignment Date	: 03/12/2019	Excess	: S\$0.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 4 days
Inspection At	: Autolution Industrial Pte Ltd (HQ) 19 UBI ROAD 4 Singapore 408623		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,207.32
Revised Amount	:S\$	2,177.96
Check Items (Estimated)	:S\$	171.36
Total	:S\$	2,349.32
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	46,723.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,277.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2019 12:37
Date Of Accident	30/11/2019 23:00
Exact Location Of Accident	STRAITS VIEW
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8843G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	STEPHANIE SHAINA LEE HER LING
NRIC No	S8520147F
Email Address	LEE.SHAINA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92708209
Alternative Phone No	OFFICE-90612848

### Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100499757-02
Cover Note Number	

### Driver

Name of Driver	STEPHANIE SHAINA LEE HER LING
NRIC No	S8520147F
Date Of Birth	08/07/1985
Occupation	INDOOR
Date Of Driving Pass	29/05/2006
Driving Experience	13 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92708209
Fax Number	
Contact Number	OFFICE-90612848

Address	18 BEDOK RISE, #09-57
Postcode	465410
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SARA MAY GENDER: : FEMALE
Passenger 2	NAME: : PALOMA JIMENEZ GENDER: : FEMALE
Passenger 3	NAME: : KIM MIN JUNG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer attachment.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG423X
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS/BLUE
Details Of Properties	RH SIDE
Vehicle Category	PRIVATE HIRE
Name of Driver	SIAM CHOON PENG WILLIAM

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 2/12/2019  
11:20 pm


Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name: Hafizah  
NRIC/FIN No.: SXXXX434B

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my vehicle 'A' (SLK8843A) along Marina Boulevard. Upon reaching the junction of Straits View, I activated my left hand indicator to turn left into Straits View. I stopped my vehicle 'A' at the junction to ask <sup>the ASCO officer</sup> about the road closures around Marina Bay. Thereafter, I proceeded down Lane 1 of Straits View. As I was driving forward, vehicle 'B' (SKG 428X) made a left turn from Marina Boulevard into Straits View. He overtook to his right into my lane and collided into the front left-hand side of my vehicle 'A'.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 2/12/2019  
1:20 pm

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: Hamzah  
NRIC/FIN No.: SXXXX434B



# CERTIFICATE OF INSURANCE

## NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Stephanie Shaina Lee Her Ling  
 Period of Insurance : 02 Feb 2019 To 01 Feb 2020  
 Engine No. : HRA2348528A  
 Chassis No. : SJNFEAJ11U1812328

Vehicle No. : SLK8843G  
 Policy No. : 2100499757-02  
 Endorsement No. :  
 Issued Date : 18 Jan 2019

### ABOUT THE COVER

Make/Model : NISSAN QASHQAI 1.2 DIG-TURBO  
 Engine Capacity/Tonnage : 1,197.00 CC  
 Driver Restriction : NA  
 Person or Classes of Persons Entitled to Drive\* :  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2017  
 Insuring with COE/PAF : Yes

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$2,000 as "Inexperienced Driver Excess" (IDR) if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1600cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

#### Section 2

Property Damage - \$0

Windscreens : \$100

Named Driver and Excess (where applicable)

Stephanie Shaina Lee Her Ling - \$500 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC Auto Clinic Add: No. 1, South Lok Yang Road Singapore 628098 63622212
2. Autohub Industrial Add: 18 UM Road 4 Singapore 408623 64029596
3. TC Auto Clinic Add: 25 Lang Kee Road Singapore 158087 67038511 67038512 67038513
4. Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 589623 64994091 64994092 64994093
5. Tan Chong Motor Sales Add: 17 Lorong 6 Tee Payoh Singapore 315254 63570753 63570754

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance refers is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0500810050

TAN CHONG CREDIT PTE LTD

911 BUKIT TIMAH ROAD

SINGAPORE 589622 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Signature*

AIG Asia Pacific Insurance Pte. Ltd.  
 AUTHORIZED REPRESENTATIVE

8825AN

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 5490 9565 FAX: 5348 7

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0598/19  
DATE : 02-DEC-2019

ADD ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-15 AIG BLDG  
S(079120)  
TEL : 64191891  
FAX : 68357416  
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : M/S STEPHANIE SHAINA LEE HER LING  
ADDRESS : 10 EASTWOOD ROAD  
#03-04  
S(486364)  
TELEPHONE NO : 90612948 MR LEE

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM  
POLICY NO : Z100499757-02  
VEHICLE NO : SLK8843G  
MODEL CODE : FRLAR8ZJ11UEA-A-  
MODEL/YEAR : NISSAN QASHQAI 1.3  
ENGINE NO : 18X2348529A  
CHASSIS NO : SJNFEA111U1812328  
MILEAGE : 50535 KM  
DATE IN : 02/12/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HAMZAH  
ACCIDENT DATE : 30/11/2019

- 96450079

Estimate Consultants hence notify the Receiver of the following:  
1. The vehicle is not for sale during the repair period.  
2. The vehicle is not for sale during the repair period.  
3. The vehicle is not for sale during the repair period.  
4. The vehicle is not for sale during the repair period.  
5. The vehicle is not for sale during the repair period.  
6. The vehicle is not for sale during the repair period.  
7. The vehicle is not for sale during the repair period.  
8. The vehicle is not for sale during the repair period.  
9. The vehicle is not for sale during the repair period.  
10. The vehicle is not for sale during the repair period.

Authorised by Receiver

Signature:

Date:

not allowed  
LH Marcus  
the photo before party  
4/12/19  
Excess \$ ?  
4 by.

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLK8843G

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR BONNET, RENEW FRONT BUMPER AND LH FRONT FENDER.	650.00	490
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	750.00	600
3 ZZ/003	CHECK LIGHT SYSTEM AND FOCUS.	48.00	✓
4 ZZ/004	REMOVE AND INSTALL FRONT BUMPER SENSOR.	55.00	✓
TOTAL LABOUR CHARGES		1503.00	



## MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SLK88436

## DAMAGED PARTS &amp; PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN		11	50.00	X
2	L/F FENDER ARC MOLD	63811-4EAD4	S/R 540.50	—		
3	L/F FENDER PROTECTOR COVER	63843-HH00A	an 128.30	X		
4	FENDER-FRONT LH	F3101-4EAMB	n 665.00	X		
5	FRT BUMPER SIDE BRKT LH	62223-4EAD4	11 23.40	X		
6	CLIP FRONT BUMPER @ \$1.30 EACH	01553-05933	ser 7.80	—		
7	FRONT BUMPER FASCIA	62022-4EAD4	R 582.90	X		
SUB TOTAL			2067.90	0.00	50.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			413.58	0.00	0.00	
GRAND TOTAL			1654.32	0.00	50.00	
OVERALL TOTAL			1704.32			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLK8M436

TOTAL LABOUR CHARGES	1503.00
TOTAL SPARE PARTS CHARGES	1704.32
GRAND TOTAL:	3207.32 *

\* ALL charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*inmate*

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/W/0598/19  
DATE : 02-DEC-2019

AIG ASIA PACIFIC INSURANCE PTE LTD  
7B SHENTON WAY  
#07-16 AIG BLDG  
S1079126  
TEL : 64191891  
FAX : 68357418  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S STEPHANIE SHAINA LEE HER LING  
ADDRESS : 38 BEDOK RISE  
#09-57  
S14654101  
TELEPHONE NO : 90612940 MR LEE

4 days

TYPE OF CLAIM : DO OR GO RECOVERY CLAIM  
POLICY NO : Z100499757-02  
VEHICLE NO : SLK88K3G  
MODEL CODE : FRLA8ZJ11UFA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRAZ348528A  
CHASSIS NO : SJNFEAJ11U181232B  
MILEAGE : 51215 KM  
DATE IN : 02/12/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HANZAH  
ACCIDENT DATE : 30/11/2019

96450079

LABOUR CHARGES FOR ACCIDENT VEHICLE RESIN NO SLKBBK30

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 22/001	LABOUR CHARGES TO REPAIR BONNET, FRONT BUMPER AND LH FRONT FENDER.	850.00	490.00
2 22/002	CHARGES TO SPRAY PAINTING SAME.	750.00	600.00
3 22/003	CHECK LIGHT SYSTEM AND FOCUS.	48.00	48.00
4 22/004	REMOVE AND INSTALL FRONT BUMPER SENSOR.	55.00	55.00
	TOTAL LABOUR CHARGES	1503.00	1193.00

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLK88438

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT.	LIST.	S/NETT	REMARKS
1	SUNRISES	99R			50.00	X
2	L/F FENDER ARC MOLD	63811-42A0A	540.30			OK
3	L/F FENDER PROTECTOR COVER	63843-HV00A	128.30			X
4	FENDER-FRONT LH	73101-4CAME	685.00			X
5	FRT BUMPER SIDE BRKT LH	62023-42A0A	23.40			X
6	CLIP FRONT BUMPER W 11.30 EACH	01563-0W033	7.80			OK
7	FRONT BUMPER FASCIA	62022-42A0A	682.90			X
SUB TOTAL			548.30	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-20.00%, S/NETT-0.00%)			109.66	0.00	0.00	
GRAND TOTAL			438.64	0.00	0.00	
OVERALL TOTAL			438.64			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO 3UKBB43G

NETT ITEM	548.70
LESS 20.00%	-109.66
NETT AMOUNT	438.64
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	3193.00
TOTAL SPARE PARTS CHARGES	438.64
TOTAL CHARGES	1831.64
ADD J & GST	114.21
GRAND TOTAL	1745.85

# SATISFACTORY NOTE

TAN CHONG MOTOR SALES PTE LTD (TCMS)  
AUTOLUTION INDUSTRIAL PTE LTD (AIPL)  
TC AUTOCLINIC PTE LTD (TCAC)

☐  
☒  
☐

DATE:

16/12/2019

OWNER NAME:

Stephanie Shaina Lee Her Ling

NRIC NO.:

ADDRESS:

18 Bedok Rise, #09-57  
Singapore 465410

TYPE OF CLAIM:

☒ OWN DAMAGE (OD)  
☒ OWN DAMAGE (OD) & UNINSURED LOSS (EXCESS & LOSS OF USAGE) VIA TCMS / AIPL / TCAC  
☐ THIRD PARTY THROUGH TCMS / AIPL / TCAC  
☐ THIRD PARTY - OWNER DIRECT CLAIM AGAINST THIRD PARTY INSURANCE  
☐ WINDSCREEN / GLASS (W/S)

VEHICLE MODEL:

Nissan Qashqai

REGN. NO.:

SLK 8843G

CHASSIS NO.:

SJNFEAJ11U1812328

INSURANCE CO.:

Alfa Asia Pacific Insurance Pte Ltd

CLAIM NO.:

POLICY NO.:

2150499757-02

DATE OF ACCIDENT:

30/11/2019

DATE RECEIVED:

16/12/2019

DATE COMPLETED:

19/12/2019

We / I hereby confirmed that the accident repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd and that all necessary repairs as resulted of the accident of the above vehicle have been completed to our / my satisfaction and that We / I have no further claim whatsoever against the above Company in respect thereof. Terms and Conditions as stipulated in the overleaf applies.

We / I have taken delivery of my car after all necessary repair carried out by Tan Chong Motor Sales Pte Ltd / Autolution Industrial Pte Ltd / TC AutoClinic Pte Ltd on\* 20/12/2019

Note: In the event of an Own Damage Claim, your Insurance Company may under policy terms & conditions, or as standard Industrial Practice, increase the loading on your premium during Insurance Policy renewal. Your NCD [Non Claim Discount] may also be affected, subject to business policy of respective Insurance Company.

STEPHANIE SHAINA LEE HER LING  
(NAME / SIGNATURE OF INSURED)

## FOOTNOTE:

☐ TCMS / AIPL / TCAC\* WILL CLAIM ON BEHALF OF OWNER THROUGH TCMS'S LEGAL AID  
☐ OWNER WILL MAKE CLAIM AGAINST THIRD PARTY INSURANCE COMPANY  
☐ TCMS / AIPL / TCAC\* WILL CLAIM ON BEHALF OF OWNER UNINSURED LOSS (EXCESS PAYMENT & LOSS OF USAGE)

☐ DEPOSIT PAID BY OWNER  
☐ DOCUMENTS RETURNED TO OWNER

**AUTOLUTION INDUSTRIAL PTE LTD**

In Association with Tan Chong Motor Sales Pte Ltd  
19 UBI ROAD 4 SINGAPORE 408623 TEL: 64909666/67038680 FAX: 68467483  
Business Reg. No.: 199500871W  
GST Reg. No.: M2-8920338-9



**TAX INVOICE**

GST REG: M2-8920338-9

NAME : AIG ASIA PACIFIC INSURANCE PTE LTD  
ADDRESS : 78 SHENTON WAY  
TELEPHONE : #07-16 AIG BLDG S(079120)  
MODEL : 64191891  
ENGINE NO : FRLARBZJ11UEA--A--  
CHASSIS NO : HRA2348528A  
VEHICLE NO : SJNFEAJ11U1812328  
SLK8843G

INVOICE NO : W32147894  
INVOICE DATE : 12-FEB-2020  
TERMS : CREDIT  
DATE REC'D : 09-DEC-2019  
SA / SE : HAMZAH  
JOB NO : HG816409  
MILEAGE : 051215  
YOUR REFERENCE : 2100499757-02

ITEMS	JOB DESCRIPTION	AMOUNT
1	LABOUR	
1	LABOUR CHARGES TO REPAIR BONNET, FRONT BUMPER AND LH FRONT FENDER.	490.00
2	CHARGES TO SPRAY PAINTING SAME.	600.00
3	CHECK LIGHT SYSTEM AND FOCUS.	48.00
4	REMOVE AND INSTALL FRONT BUMPER SENSOR.	55.00
	SUBTOTAL :	1193.00
	PARTS	
1	CLIP FRONT BUMPER @ \$1.30 EACH	6.24
	Qty:6 @ \$1.30 each (Disc:20.00% After Disc:\$6.24each)	
2	L/F FENDER ARC MLDG	432.40
	Qty:1 @ \$540.50 each (Disc:20.00% After Disc:\$432.40each)	
	SUBTOTAL :	438.64
	Insurance Co : AIG ASIA PACIFIC INSURANCE PTE LTD	
	Policy No....: 2100499757-02	
	Claim Type ...: OD OR OD RECOVERY CLAIM	
	DOA.....: 30-NOV-2019	
	Our Ref.....: INS/IC/H/0598/19	
	Surveyor.....: SURVEYOR FROM INSURANCE CO	
	LABOUR :	1193.00
	PARTS :	438.64
	SUBTOTAL :	1631.64
	TOTAL :	1631.64
	GST(7%) :	114.21
	AMOUNT DUE :	1745.85

(NB : NC=No Charge;P=Included in Package;W=Warranty;G=Goodwill)

DOLLARS: ONE THOUSAND SEVEN HUNDRED FORTY FIVE AND CENTS EIGHTY FIVE ONLY.

*Mohd LG*  
WORKSHOP MANAGER

The General Terms and Conditions of Service (the "Conditions") printed overleaf or attached to this Invoice shall apply to all Services set out above. Any claims relating the Services shall be subject to the Conditions. Any objections to the charges in this Invoice must be made within seven (7) days from the date of this Invoice, otherwise it shall be assumed that this Invoice has been accepted as correct and conclusive.

CUSTOMER

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE

TIME

VEHICLE NO : SLK8843G (HG816409/W32147894)

RELEASED BY 2019

15:21:34

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD

SIGNATURE



## ...CLAIM SUBFOLDER...(Pending for Survey Report)




















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Dec 2019		03 Dec 2019 16:30 <a href="#">Edit Adj Rpt</a>	<b>S\$1,631.64</b> <a href="#">Edit Estimates</a>	<b>S\$1,631.64</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>






















Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	STEPHANIE SHAINA LEE HER LING, ID: S8520147F, Tel: +6592708209, Email: lee.shaina@gmail.com								
Vehicle Reg. No.:	SLK8843G	Date of Loss:	30/11/2019 23:00 - :59 [33 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1117988816SG	Policy/Cover Note No.:	(Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Autolution Industrial Pte Ltd (HQ) 19 UBI ROAD 4, 408623 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... <b>[Final Rpt due 12/12/2019]</b>								
Driver/Custodian:	STEPHANIE SHAINA LEE HER LING (34 / Female), NRIC: S8520147F, Tel: +6592708209 Email: lee.shaina@gmail.com								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (09/12/2019): SLK8843G / OD / 30/11/2019 / Coverage &amp; Excess update</li> <li>AIG_SG (05/12/2019): Alert - Adj Mandate Approved (S\$2349.32) - SLK8843G - Claim Handler: Azlan, Syaz...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLK8843G (1117988816SG)  
 OD  
 Nov 30 2019 11:00PM  
 [STEPHANIE SHAINA LEE HER LING]  
 Autolution Industrial Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Video</b>				
			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	02/12/19 13:28	<b>Video - Accident</b> [Linked Accident Report Documents]	 Load MP4	
<b>Assessment Reports</b>				
			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 17:46	<b>Adjuster Immediate Advice</b>	 Load HTM	
<b>Photos/Images</b>				
			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 12:10	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
2	04/12/19 12:10	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
3	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	04/12/19 12:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				
			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 17:48	<b>SLK 8843G GIA.pdf</b>	 Load PDF	
2	04/12/19 17:48	<b>DRIVING &amp; CI.pdf</b>	 Load PDF	
3	04/12/19 17:48	<b>ESTIMATE.pdf</b>	 Load PDF	
4	24/02/20 16:34	<b>Workshop Invoice</b>	 Load PDF	
5	24/02/20 16:34	<b>Discharge Voucher</b>	 Load PDF	

## Linked Accident Report Documents

			View	View in Browser
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	02/12/19 13:28	Video - Accident	 Load MP4	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	06/12/19 19:40	Accident Statement	 Load HTM	
2	06/12/19 19:43	Accident Statement	 Load HTM	
3	06/12/19 19:45	Accident Statement	 Load HTM	
4	06/12/19 19:46	Accident Statement	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	02/12/19 13:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	02/12/19 13:03	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
11	02/12/19 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	02/12/19 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	02/12/19 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	02/12/19 13:58	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	02/12/19 13:53	Sketch Plan	 Load TIF	
2	02/12/19 13:53	Sketch Plan #2	 Load TIF	
3	02/12/19 13:53	Driving License	 Load TIF	
4	02/12/19 13:53	CI	 Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG19021332/USF3E2

Date: 24/02/2020

### REFERENCE

Insured/Claimant: STEPHANIE SHAINA LEE HER LING

Policy No:

Date of Loss: 30/11/2019

Nature of Claim: OD Claim No: 1117988816SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK8843G

Make &amp; Model: NISSAN QASHQAI, 1.2 DIG-T (A)

Engine No: HRA2348528A

Reg. Date: 02/02/2017 (Man. Year: 2016)

Chassis No: SJNFEAJ11U1812328

Colour: Blue

Odometer: 50613 km

Engine Capacity: 1197 cc

Market Value/New Car Price: S\$66,000.00

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,704.32	438.64	1,265.68	74.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,503.00	1,193.00	310.00	20.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,207.32</b>	<b>1,631.64</b>	<b>1,575.68</b>	<b>49.13</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>224.51</b>	<b>114.21</b>	<b>110.30</b>	<b>49.13</b>
<b>Nett Amount (S\$)</b>	<b>3,431.83</b>	<b>1,745.85</b>	<b>1,685.98</b>	<b>49.13</b>

### INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 04/12/2019 Inspected At:

Autolution Industrial Pte Ltd (HQ)  
19 UBI ROAD 4  
Singapore 408623

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
2	1		*L/F FENDER ARC MLDG	Scratched	540.50 FN	*540.50 FN
3	1		*L/F FENDER PROTECTOR COVER	Not Necessary	128.30 FN	*- FN
4	1		*FENDER-FRONT LH	Repair	685.00 FN	*- FN
5	1		*FRT BUMPER SIDE BRKT LH	Not Necessary	23.40 FN	*- FN
6	6		*CLIP FRONT BUMPER	Necessary	7.80 FN	*7.80 FN
7	1		*FRONT BUMPER FASCIA	Repair	682.90 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	2,117.90	548.30
- Nett Item Discount on N Items 20.00/20.00% (S\$)	413.58	109.66
Total Parts (S\$)	1,704.32	438.64

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR BONNET, RENEW FRONT BUMPER AND LH FRONT FENDER	New	650.00	490.00
2	CHARGES TO SPRAY PAINTING SAME	New	750.00	600.00
3	CHECK LIGHT SYSTEM AND FOCUS	New	48.00	48.00
4	REMOVE AND INSTALL FRONT BUMPER SENSOR	New	55.00	55.00
Gross Labour Cost (S\$)			1,503.00	1,193.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >