

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095

Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : GENERAL INSURANCE**Estimate No: EST0001075**

Date: 24 Dec 2019

Veh Reg No: **SDR811J**Make/Model: VOLKSWAGEN JETTA
GP 1.4 TSI 90A

Chassis No: WWWZZZ16ZFM032937

Engine No: CAXF52727

Reg. Date: 30/07/2015

ATTN: Motor Claim Department

Your Ref No: SDR811J

Claim Type: Third Party

Accident Date: 22.11.19

Estimate Repair Cost to Vehicle No :SDR811J

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 Rear Bumper / Re	1,123.80	1 PC	1,123.80	✓
2 Rear Bumper Lower Spoiler / GA	540.00	1 PC	540.00	✓
3 Rear Bumper Top Beam ✓ BR	164.20	1 PC	164.20	124.2
4 Rear Bumper Reinforcement X NN	640.00	1 PC	640.00	
5 Rear End Panel X NN	962.50	1 PC	962.50	
6 Front Bumper X repair.	890.00	1 PC	890.00	1788
			4,320.50	1609.2
	Less 10%		432.05	3,888.45
Special Net				
7 Rear Bumper Sensor / on	300.00	1 SET	300.00	200
8 Front Number Plate / cut	50.00	1 PC	50.00	40
			350.00	350.00
Labour				
9 Panel Beating 3-4 Days.	950.00	1 PC	950.00	400
10 Rust Proofing	60.00	1 PC	60.00	X NN
11 Spray Painting lump sum repair.	850.00	1 PC	850.00	400
After repair photos.			1,860.00	1,860.00
			Total	SS 6,098.45

LKK Auto Consultants hence notify the Repairer of the following:

TOTAL SINGAPORE DOLLAR SIX THOUSAND NINETY EIGHT AND CENTS FORTY FIVE ONLY

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For FOCUS AUTO PTE LTD

2649.2

20%: 2100

AUTHORISED SIGNATURE