

ASS. REC. BY:

REF:

TMI/ (C3/TMI 19021382/Kyf3n2)

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HI= 727K Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude c.c 1995

Colour

h. white / h.

A/C: Insured / Std / NI / NA

Sp. Reading

346111

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VI-1 ABL 15 AUG 28 1194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Bailun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

26/11/19

D.O.I.

3/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to SHC 727K - X

SJK 1903 L - X

8220h (Red \$26746-53, 99%)

16/12 Sent Preli to Insurance Co (E-Mail)

RECEIVED 18 FEB 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

18/2/20 Typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

P/P \$220K

250

11

261



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref:

Date: 13 Dec 2019

Our Ref: CC3/TMI19021382/Kyf3

The Motor Claims Department  
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHF727K.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/12/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>26,966.53</u>
Revised Estimate Amount	: S\$ <u>220.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the o/s front.



Yours faithfully

KENNETH KONG SENG CHEONG  
Licensed Appraiser

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHF727K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002345
Chassis No.:	VF1ABL15AUC281194
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Dec 2014
First Registration Date:	31 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2022
PARF Rebate Amount:	\$9,373.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$19,965.00
<b>Total Rebate Amount:</b>	<b>\$29,338.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Nov 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/11/2019 13:44
Date Of Accident	26/11/2019 22:10
Exact Location Of Accident	GEYLANG LORONG 27A
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF727K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	NG CHAN HENG
NRIC No	S0674939I
Date Of Birth	19/07/1949
Occupation	OUTDOOR
Date Of Driving Pass	10/10/1969
Driving Experience	50 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90995295
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 192A RIVERVALE DRIVE #09-930
Postcode	541192
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20191127/2109

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK1903L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature		Reporting Centre Personnel's Signature
Date & Time:	Driver's Signature (If driver is not the policyholder)	Name:
	Date & Time:	NRIC/FIN No.:

Hand-drawn sketch map of the Geylang area. The map shows a vertical road labeled 'Geylang' and a horizontal road labeled 'Geylang'. At the intersection, there are two small rectangular buildings labeled 'A' and 'B'. To the right of the intersection, there is a large rectangular area labeled 'A SHF 727K' and 'B SJR 1903L'. An arrow points upwards from the bottom of the vertical road.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature:  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20191127/2109

1 of 3

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

Report No. T/20191127/2109

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/11/2019 15:19		Vide Report No.:		Station Diary No.: 102	
<b>Informant's Particulars</b>					
Name of Informant: NG CHAN HENG			Address: APT BLK 192A RIVERVALE DRIVE #09-930 SINGAPORE 541192		
ID Type / ID No.: NRIC NO / S0674939I			Contact No.: Home/Office: Mobile: 90995295		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 70	Date of Birth: 19/07/1949	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Relief Taxi Driver			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 26/11/2019 22:10	Type of Location:
Location: Along Road 1 LORONG 27A GEYLANG				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHF727K	Taxi				Slightly Damaged	0
SJK1903L	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





**SINGAPORE  
POLICE FORCE**



T/20191127/2109

2 of 3

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

Report No. T/20191127/2109

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	NG CHAN HENG	ID No.	S0674939I
Related Vehicle	SHF727K (Taxi)	Contact No.	90995295
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	Lim Kim Chai	ID No.	S1803248A
Related Vehicle	SJK1903L (Car)	Contact No.	98599588
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 26/11/2019 at about 2210hrs, I was travelling straight along Geylang Lorong 27A. There was a motorcycle on my left so I slowed my taxi down to let the motorcycle pass me. Suddenly, I felt an impact on my taxi's right portion. Vehicle B (SJK1903L) has moved from stationary position beside me and hit onto my taxi's front right portion. Both Vehicles B Driver and I alighted from our vehicle and the driver wrote a note and asked me to sign it. I did not understand what is it as I do not understand English. The driver then refused to let me go and won't return my IC that I had passed to him to take photo earlier until I have signed the note and I signed it in the end. The contents of the note was not explained to me by the driver. My IC was then subsequently returned back to me.

I have in-car camera.



**SINGAPORE  
POLICE FORCE**



T/20191127/2109

3 of 3

Report No. T/20191127/2109

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 TEO JIA HAO, KENNETH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/Time:

27/11/2019 15:19

Classification Of Case:

SN 085

Authentication Stamp

NP168



Signature

Singapore Police Force

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 727K****AAD1911-221***Not Notified**44 Day @ 220p*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHF 727K**

VF1ABL15AUC281194

RENAULT

LATITUDE

26.11.19

**NTUC Income***Tokio*

31/12/2014

<b>PART</b>	
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER BRACKET FRT RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	BONNET INSULATOR
1	BONNET STRUT RH

**LIST**

\$	<i>R</i>	747.20	<i>R</i>
\$	<i>Sm</i>	344.70	<i>Sm</i> <i>X</i>
\$	<i>Sm</i>	394.68	
\$	<i>Sm</i>	101.40	
\$	<i>Sm</i>	10.70	
\$	<i>Sm</i>	292.50	
\$	<i>"</i>	147.00	
\$		207.21	
\$		663.70	
\$		743.60	
\$		128.30	
\$		437.10	
\$		191.40	
\$		11.80	
\$		106.40	
\$		66.30	
\$		60.90	
\$		177.22	
\$		969.90	
\$		225.36	
\$		686.00	
\$		592.70	
\$		41.60	
\$		1,312.70	
\$		294.30	
\$		53.30	

**Trans-cab Auto Services Pte Ltd**

AAD1911-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 727K**

1	BONNET HINGE RH	\$	237.40
1	BONNET LOCK	\$	152.80
1	BONNET CABLE	\$	55.20
1	BONNET CABLE COVER	\$	80.60
1	BONNET SEAL OUTER	\$	83.20
1	BONNET SEAL INNER	\$	70.10
1	LOWER ARM RH L70Y	\$	192.70
1	KNUCKLE ARM RH L70Y	\$	481.50
1	ABSORBER FRT RH L70Y	\$	203.50
1	DRIVESHAFT RH	\$	1,355.70
1	STABILIZER BAR FRT	\$	427.90
1	WIPER RESERVOIR MOTOR	\$	82.60
1	WIPER RESERVOIR	\$	179.60
1	WIPER RESERVOIR NECK	\$	29.30

*Sn*  
*X*

<b>TOTAL</b>	<b>\$</b>	<b>12,640.07</b>
<b>10%</b>	<b>\$</b>	<b>1,264.01</b>
	<b>\$</b>	<b>11,376.06</b>

**Special Nett**

1	BUMPER CLIP FRT	\$	<i>nn</i> 66.00
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50
1	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00
1	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50
1	FRONT RIGHT TYRE	\$	<i>Sn</i> 300.00
1	FRONT RIGHT TYRE RIM	\$	<i>Sn</i> 380.00
1	FRONT RIGHT TYRE RIM COVER	\$	<i>Sn</i> 50.00
1SET	Front licence plate with holder	\$	<i>Sn</i> 80.00
1SET	RADIATOR GRILLE SCREW	\$	<i>nn</i> 16.00
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>nn</i> 52.00
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85

*X*

**Trans-cab Auto Services Pte Ltd**

AAD1911-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 727K

2	BONNET CABLE CLIP L70Y	\$	nn 6.31	X
---	------------------------	----	---------	---

TOTAL	\$	1,210.47
-------	----	----------

TOTAL PARTS	\$	12,586.53
-------------	----	-----------

**LABOUR**

Putty and spray painting of the affected portion.	\$	6,000.00	2201
---	----	----------	------

To Check Electrical Lighting Concerned.	\$	170.00	X
---	----	--------	---

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	nn 6,000.00	X
---	----	-------------	---

To rust-proofing of the affected areas.	\$	↷ 170.00	X
---	----	----------	---

To transfer of front fender fittings, attachment and perform water seepage test.	\$	↷ 170.00	X
--	----	----------	---

To transfer of bonnet fittings, attachment and perform water seepage test.	\$	↷ 170.00	X
--	----	----------	---

To check steering geometry and computer wheel alignment	\$	↷ 220.00	X
---	----	----------	---

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	↷ 380.00	X
---	----	----------	---

To transfer of front bumper fittings, attachment and perform water seepage test.	\$	↷ 170.00	X
--	----	----------	---

To transfer of tire, rim and on wheel balancing.	\$	↷ 170.00	X
--	----	----------	---

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 727K****AAD1911-221**

To remove and refit interior fittings, trimmings,  
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle  
on jig bench, to facilitate repair.

\$ *nn* 380.00 X**TOTAL \$ 14,380.00****Over All Total \$ 26,966.53****LUMP SUM (REPAIR DAY)****20 DAYS***1 day*

L&K Auto Consultants hence notify  
the Repairer of the following:

- To resurvey & estimate spray painting
- To display damaged panel during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No legal endorsement is given
- Supplementary Survey may be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19021382/KYF3N2  
 Date: 18/02/2020

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000249  
 Claimant Vehicle No: SHF727K Insured Vehicle No: SJK1903L  
 Date of Loss: 26/11/2019 Nature of Claim: TP Claim No: M1909294

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHF727K  
 Make & Model: RENAULT ATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C002345  
 Reg. Date: 31/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC281194  
 Colour: Metallic White/Red Odometer: 546111 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm  
 Front Right Side: Sailun 9 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,586.52	0.00	12,586.52	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,380.00	220.00	14,160.00	98.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>26,966.52</b>	<b>220.00</b>	<b>26,746.52</b>	<b>99.18</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,887.66</b>	<b>15.40</b>	<b>1,872.26</b>	<b>99.18</b>
<b>Nett Amount (S\$)</b>	<b>28,854.18</b>	<b>235.40</b>	<b>28,618.78</b>	<b>99.18</b>

## INSPECTION

Date of Assignment: 16/12/2019  
 Date Inspected: 03/12/2019 Inspected At: Trans Cab Auto Services Pte Ltd - Amk (HQ)  
 Singapore 569111  
 Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2020)

Parts: 143 RENAULT ATTITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF727K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER FRT	Repair	747.20 FL	-	*-FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	-	*-FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	-	*-FL
4	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	-	*-FL
5	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	-	*-FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	-	*-FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	-	*-FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	-	*-FL
9	1		*BUMPER BEAM FRT	Serviceable	663.70 FL	-	*-FL
10	1		*HEADLAMP RH	Serviceable	743.60 FL	-	*-FL
11	1		*HEADLAMP PANEL FRT RH	Serviceable	128.30 FL	-	*-FL
12	1		*FENDER PANEL FRT RH	Serviceable	437.10 FL	-	*-FL
13	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	-	*-FL
14	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	-	*-FL
15	1		*FENDER BRACKET FRT RH	Serviceable	106.40 FL	-	*-FL
16	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	-	*-FL
17	1		*TOW COVER FRT	Serviceable	60.90 FL	-	*-FL
18	1		*FRONT BRACE PANEL	Serviceable	177.22 FL	-	*-FL
19	1		*RADIATOR GRILLE	Serviceable	969.90 FL	-	*-FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	-	*-FL
21	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	-	*-FL
22	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	-	*-FL
23	1		*FRAME FULL SUPPORT BRACKET	Serviceable	41.60 FL	-	*-FL
24	1		*BONNET	Serviceable	1,312.70 FL	-	*-FL
25	1		*BONNET INSULATOR	Serviceable	294.30 FL	-	*-FL
26	1		*BONNET STRUT RH	Serviceable	53.30 FL	-	*-FL
27	1		*BONNET HINGE RH	Serviceable	237.40 FL	-	*-FL
28	1		*BONNET LOCK	Serviceable	152.80 FL	-	*-FL
29	1		*BONNET CABLE	Serviceable	55.20 FL	-	*-FL
30	1		*BONNET CABLE COVER	Serviceable	80.60 FL	-	*-FL
31	1		*BONNET SEAL OUTER	Serviceable	83.20 FL	-	*-FL
32	1		*BONNET SEAL INNER	Serviceable	70.10 FL	-	*-FL
33	1		*LOWER ARM RH L70Y	Serviceable	192.70 FL	-	*-FL
34	1		*KNUCKLE ARM RH L70Y	Serviceable	481.50 FL	-	*-FL
35	1		*ABSORBER FRT RH L70Y	Serviceable	203.50 FL	-	*-FL
36	1		*DRIVESHAFT RH	Serviceable	1,355.70 FL	-	*-FL
37	1		*STABILIZER BAR FRT	Serviceable	427.90 FL	-	*-FL
38	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	-	*-FL
39	1		*WIPER RESERVOIR	Serviceable	179.60 FL	-	*-FL
40	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	-	*-FL
41	1		*BUMPER CLIP FRT	Not Necessary	66.00 FS	-	*-FS
42	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	-	*-FS
43	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	-	*-FS
44	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	-	*-FS
45	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	-	*-FS
46	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	-	*-FS

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
47	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	-	*- FS
48	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	-	*- FS
49	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	-	*- FS
50	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	-	*- FS
51	1		*FRONT RIGHT TYRE RIM COVER	Serviceable	50.00 FS	-	*- FS
52	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	-	*- FS
53	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	-	*- FS
54	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	-	*- FS
55	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	-	*- FS
56	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	-	*- FS
57	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,850.53</b>	<b>0.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,264.01</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>12,586.52</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	0.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
9	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>14,380.00</b>	<b>220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >