

CS REC BY:

REF: CS/MSG19021405/Qsf3³²

Special Instruction:

Surveyor: Sun Pin

ASSIGNMENT (Office)

From (Person): Jeannie cheng Jin Rong of MSG

Date/Time: 4.12.19 1209 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 7993C

Insured:

at Workshop m/s Systematic Air conditioning

Tel: 64847188

of 29 smoko way

Policy No: 29099690

Claim No: 613169

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 29.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 4.12.19 1.08 p.m

Person Contacted:

shah

9010 6946

H.O.D. Endorsement:

I bon / wei ming

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

GBG 7993C - X

05/12/19 @ 14:59 pm revised PA to Jeannie cheng V.A merimen

05/12/19 @ 16:22 pm mandate requested authorize repair to

Jeannie via merimen.

6/12/19

Rece approved from Kenny Ong by merimen

ASS. REC. BY: Sun Pin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: \$500/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 79K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: G1B97993C Yr Regn: 30/Oct/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toyota Dyna 150

c.c

2982Colour: White

A/C:

Insured / Std / NI / NA

Sp. Reading: 594.10

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35YX0K209205

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

145 R15C- Yoko

R:

155 R12C- Fireenza

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5

mm

R/Bal. 5

mm

L/Bal. 5

mm

L/Bal. 5

mm

D.O.A. 29/11/2019

D.O.I.

04/12/2019

Survey held at

Systematic AirconditioningDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/12/19 @ 4.07pm Spoken to Jannie aware vehicle repair on LS. basis

6/12/19 Informed Shah. CIA on LS repair ex \$500 by email

MV: 79K.

Sun Pin

RECEIVED 04 MAR 2020

PLS see meL/S \$ 7,150/- @ 6 daysC\$ 2,280.00 Red 24%

Date/Time, File Pass to?



: Prel. Report

1) 04/03/20

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.E.I.:

\$ 7,150/- USDays Of Repair: 6Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee: 150

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2019		04 Dec 2019 12:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	Artisan Fine Foods Pte. Ltd., Co. Reg. No.: 201006219C		
Vehicle Reg. No.:	GBG7993C	Date of Loss:	29/11/2019 15:00 - :59 [24 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 613169	Policy/Cover Note No.:	29099690 (Comprehensive) Coverage: 23/11/2019 - 22/11/2020
		Excess:	S\$500.00
Repairer:	Systematic Airconditioning Pte Ltd (HQ) 29 Senoko Way, 758059 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jeannie Cheng Jin Rong - 6594 2537]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/12/2019]		
Driver/Custodian:	Yusnizam Bin Yunos (52 / Male) , NRIC: S1826961I, Tel: +6586428913 Email:		
Adj Asg. Remarks:	Car in. Manual assigned to LKK via email on 04/12/19. Survey and revert. Please revert. Thank you.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

pls Reply the email
as well.
got assign in email too.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Wednesday, 4 December 2019 11:33 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: 04122019112618.pdf

Importance: High

ACCIDENT INVOLVING GBG7993C ON 29 Nov 2019

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the e-mail and do not copy, distribute or disclose its contents.

Shirley Hiew (LKK Auto)

From: shah@systematicaircon.com
Sent: Tuesday, 3 March 2020 1:16 pm
To: Shirley Hiew (LKK Auto)
Cc: Oi Sun Pin (LKK Auto); SUR
Subject: RE: GBG7993C

Hi Shirley,

We will re sent to MSIG.

Thank you
Sha

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 3 March, 2020 10:58 AM
To: shah@systematicaircon.com
Cc: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: GBG7993C

Hi Shah,

Kindly inform the repair cost is before excess \$ 500/- & GST.

Please do re-amend your final invoice & all relevant document, re-sent to MSIG insurance.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: shah@systematicaircon.com <shah@systematicaircon.com>
Sent: Tuesday, 3 March 2020 10:52 am
To: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: GBG7993C

Hi Sun Pin,

We agreed to COR at \$7,150.00 before gst.

Should you have any enquiries, please do not hesitate to contact us at 64847188 or via this mail.

Thank you.

Sha

Systematic Airconditioning Pte Ltd

29 Senoko Way, Singapore 758059

Tel No. : +(65) 6484 7188

Fax No. : +(65) 6484 1334

Email : shah@systematicaircon.com

Website : www.systematicaircon.com



From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Friday, 28 February, 2020 9:13 AM
To: shah@systematicaircon.com
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: GBG7993C

Hi Sha,

WITHOUT PREJUDICE

Kindly refer the finalize amount COR: \$7,150 before GST @ 6 repair days under lump sum repair.
If agree please update.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: shah@systematicaircon.com [<mailto:shah@systematicaircon.com>]
Sent: Tuesday, 25 February, 2020 4:27 PM
To: SUR; Oi Sun Pin (LKK Auto)
Subject: FW: GBG7993C

Hi Sur,

Kindly refer as attached

Should you have any enquiries, please do not hesitate to contact us at 64847188 or via this mail.

Thank you.

Ska

Systematic Airconditioning Pte Ltd

29 Senoko Way, Singapore 758059

Tel No. : +(65) 6484 7188

Fax No. : +(65) 6484 1334

Email : shah@systematicaircon.com

Website : www.systematicaircon.com



Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 6 December 2019 4:29 PM
To: SUR; shah@systematicaircon.com
Subject: RE: GBG 7993C-DOA:29/11/2019 (MSIG OD)

Dear Shah,

As instructed by our client , please proceed to repair the **insured vehicle GBG 7993C on Lump Sum Repair, (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBG7993C (613169)**

OD

Nov 29 2019 3:00PM

[Artisan Fine Foods Pte. Ltd.]

Systematic Airconditioning Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/02/2020 17:19 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$7150.00) - GBG7993C - Claim Handler: Jeannie Cheng Jin Rong

Approved:7150.00:a if c lump sum \$7150

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***GBG7993C (613169)**

OD

Nov 29 2019 3:00PM

[Artisan Fine Foods Pte. Ltd.]

Systematic Airconditioning Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 06/12/2019 15:53 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$8500.00) - GBG7993C - Claim Handler: Jeannie Cheng Jin Rong

Approved:8500.00:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co,Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 26 Feb 2020

Preliminary Advice

Vehicle No	: GBG7993C	Accident Date	: 29/11/2019
Make	: TOYOTA DYNA 150	Policy No.	: 29099690
Assignment Date	: 04/12/2019	Excess	: S\$500.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 6 days
Inspection At	: Systematic Airconditioning Pte Ltd (HQ) 29 Senoko Way Singapore 758059		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,430.00
Revised Amount	:S\$	8,950.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,950.00

Lump Sum Repair	:S\$	7,150.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	27,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,196.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 06 Dec 2019

Preliminary Advice

Vehicle No	: GBG7993C	Accident Date	: 29/11/2019
Make	: TOYOTA DYNA 150	Policy No.	: 29099690
Assignment Date	: 04/12/2019	Excess	: S\$500.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 6 days
Inspection At	: Systematic Airconditioning Pte Ltd (HQ) 29 Senoko Way Singapore 758059		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,430.00
Revised Amount	:S\$	8,500.00
Check Items (Estimated)	:S\$	850.00
Total	:S\$	9,350.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	27,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,196.00

Remarks

- (X) The vehicle is economical for repair. Repairer repair the vehicle on lump sum basis.
- () The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 05 Dec 2019

Preliminary Advice

Vehicle No	: GBG7993C	Accident Date	: 29/11/2019
Make	: TOYOTA DYNA 150	Policy No.	: 29099690
Assignment Date	: 04/12/2019	Excess	: S\$500.00
Date of Inspection	: 04/12/2019	Est. Duration of Repair	: 6 days
Inspection At	: Systematic Airconditioning Pte Ltd (HQ) 29 Senoko Way Singapore 758059		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,430.00
Revised Amount	:S\$	8,580.00
Check Items (Estimated)	:S\$	850.00
Total	:S\$	9,430.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	27,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,196.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

MKKH19158081 / K Kim Hin Auto Pte Ltd - HQ
ENTRY DATE & TIME: 30/11/2019 13:58
SUBMITTED BY: Chou Wei Kiat, Jerome

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/11/2019 13:58
Date Of Accident 29/11/2019 15:30
Exact Location Of Accident CLEMENTI WEST STREET 2 CAR PARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG7993C

Insured/Policyholder

Name Of Registered Owner ARTISAN FINE FOODS PTE. LTD.
Co Reg No 201006219C
Email Address LOGISTICS@ARTISANFINEFOODS.COM
Mobile Phone No
Alternative Phone No Office-62767716

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA 1.5T-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number B29099690MKC
Cover Note Number

Driver

Name of Driver YUSNIZAM BIN YUNOS
NRIC No S18269611
Date Of Birth 29/08/1967
Occupation INDOOR
Date Of Driving Pass 24/03/2008
Driving Experience 11 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-86428913

Fax Number

Contact Number

Email Address

NOEMAIL

Address

BLK 372 BUKIT BATOK STREET 31 #04-376

Postcode

650372

Was driver an employee of the Insured's Company

YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLIDED INTO PROPERTY

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

1

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO


Sketch Plan


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

30/11/19 011.30am


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

✓ At about 3.30 pm, it was raining heavily. I was about to exit the car park, as I was driving out turning right I step on my brake but it was too late as the top of the vehicle has hit the metal gantry.

* OD claim other workshop *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	219C
Vehicle Details	
Vehicle No.:	GBG7993C
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2752738
Chassis No.:	JTFAT35YX0K209205
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	30 Oct 2017
First Registration Date:	30 Oct 2017
Transfer Count:	1
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,205.00
COE Rebate Amount:	\$27,804.00
Total Rebate Amount:	\$27,804.00

The information contained herein is correct as at 05 Dec 2019

OK

SELL YOUR CAR TODAY

List car till sold & let us handle the paperwork.

[POST AN AD NOW!](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Toyota Wish 2.0A. \$19,800.



Superb Condition. No
Consignement.
Direct Owner. StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

16 vehicles

Toyota Dyna

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Dyna	Any	Any	2017	Any	Any	Any	Available
	Toyota Dyna 150 3.0M	\$48,800	\$6,310 /yr	29-Aug-2017	2,982 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In The Market! Vehicle Still Under Warranty So Buy With A Peace Of Mind! 1 Owner Only! No Repair Needed! View To Believe! High Trade... Cheapest In The Market! Vehicle Still Under Warranty And In Tip Top Condition! Net Link Partners Pte Ltd Posted: 05-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna Dump	\$82,000	\$11,380 /yr	16-Feb-2017	4,009 cc	10,000 km	Truck	Available
Fuel Type: Diesel Posted: 15-Oct-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$47,800	\$6,510 /yr	06-Apr-2017	2,982 cc	-	Truck	Available
Fuel Type: Diesel Previous Owner From Big Company, Change New Lorry Every 3 Years. Excellent Condition As They Could Not Afford Any Vehicle Break Down In Their Business. Servicing All Done. Full Loan 6 Years No Problem. Monthly Only 700. Trade-in Get More Discount. Call To View... ABWIN Bus Pte Ltd Posted: 04-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$52,500	\$7,160 /yr	06-Apr-2017	2,982 cc	-	Truck	Available
Fuel Type: Diesel Box As Good As New! 1 Owner! Good Condition! Low Cost Maintenance! Most Reliable Lorry In The Market! High Loan Available! Offer Highest Trade In For Your Used! Call Us To Find Out More Details. Call Now, Please Call For Appointment. QIFei Auto Pte Ltd Posted: 21-Nov-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Tyre Valve Cap (TRD)							
Unique and comes with a keychain wrench. More info about this product								
	Toyota Dyna 150 3.0M	\$48,800	\$6,630 /yr	13-Apr-2017	2,982 cc	-	Truck	Available
Fuel Type: Diesel Good Condition! 10 Feet Lorry With Full Canopy. 100% Loan Available. In-House Loan Available. Fast Approval And Delivery. Call Now For Appointment. ABWIN (1994) Pte Ltd Posted: 01-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$50,800	\$6,750 /yr	13-Jun-2017	2,982 cc	29,000 km	Truck	Available
Fuel Type: Diesel High Trade In/Loan Available, 1 Owner, Toyota Dyna Comes With Excellent Fuel Efficiency And A Spacious Cabin To Fulfill Your Business Needs, Still Under Borneo Motors Warranty, Price Negotiable,. Please Call /WhatsApp Now To Arrange A Viewing Appointment. BKW Automobile Pte Ltd Posted: 12-Nov-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								

Compare



Toyota Dyna 150 3.0M

\$50,048

\$6,540 /yr

31-Jul-2017

2,982 cc

43,575 km

Truck

Available

Fuel Type: Diesel

1 Owner, Super Low Mileage & Still Under Warranty. High COE Amt Unit. Box Condition Nearly New. Ex-owner Sold Due To Under Usage. Yet Lorry + Box Cheaper Than New Lorry Depreciation. Call Now For View.

PREMIUM AD

ABWIN Bus Pte Ltd

Posted: 04-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$56,800

\$7,420 /yr

31-Jul-2017

2,982 cc

53,000 km

Truck

Available

Fuel Type: Diesel

Warranty From Borneo Motor, Palfinger Tailgate Load 750KG. 1 Owner, Smooth Engine, High Box. Good For Small Delivers For Your Company Needs. Partition Door To Separate Your Goods Door Step Viewing Is Available.

PREMIUM AD

Ezy-1 Pte Ltd

Posted: 29-Nov-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$51,800

\$6,750 /yr

07-Aug-2017

2,982 cc

51,000 km

Truck

Available

Fuel Type: Diesel

Well Maintained By Previous Owner. Call Our Friendly Sales Team For Viewing Now. In House Loan Available.

Hui Hua Credit Pte Ltd

Posted: 28-Nov-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$53,800

\$7,010 /yr

08-Aug-2017

2,982 cc

-

Truck

Available

Fuel Type: Diesel

1 Careful Owner. Very Well Maintained. With 7 Foot Box 3 Door. 100% Loan. Hurry. Don't Miss. Good Buy. Not Much In The Market.

Index Credit

Posted: 30-Nov-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Free Valuation for your Car

Find out how much your car is worth today! Protect yourself from lowballing buyers with an accurate Free Valuation.

Find out more!



Toyota Dyna 150 3.0M

\$50,800

\$6,600 /yr

15-Aug-2017

2,982 cc

49,500 km

Truck

Available

Fuel Type: Diesel

Most Reliable 10 Feet Lorry! Brand Speaks For Itself! Retractable Canopy And Fresh Paintwork Done Up Just For You! All Trade In And High Loan Arrangements Can Be Made. How Can We Be Of Service! Kindly Contact Our Friendly Yet Entertaining Sales Consultant For M...

PREMIUM AD

Car (S) Pte Ltd

Posted: 04-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$51,800

\$6,730 /yr

17-Aug-2017

2,982 cc

57,000 km

Truck

Available

Fuel Type: Diesel

One Owner, Still Under Warranty! Most Reliable Lorry In The Market, Feel Free To Call Our Friendly Sales To Arrange For Viewing.

Posted: 30-Nov-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$49,900

\$6,460 /yr

25-Aug-2017

2,982 cc

42,000 km

Truck

Available

Fuel Type: Diesel

Powerful Engine And Reliable Performance. The Best 10 Feet Light Goods Vehicle In The Market, Still Under Warranty And Service By Borneo, High Loan Available, Call For Inquiry!

DIRECT OWNER

Posted: 05-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

-

N.A

30-Oct-2017

2,982 cc

105,757 km

Truck

Available

Fuel Type: Diesel**Auction Closing Time:** 10th Dec 2019 at 11:00 PM

Non GST Registered. 1 Key Available. Road Tax Expiry On 29/10/2019. Mileage Of 105757Km. Toyota Dyna 150 5MT, Maximum Laden Weight: 3500 Kg. Financing Up To 90% Possible Subject To Credit Approval. Call Us To Enquire. Interested Bidders Are Advised To View...

AUCTION VEN

Posted: 04-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$82,000 / \$10,370 /yr

30-Oct-2017 /

2,982 cc

21,000 km

Truck

Available

Fuel Type: Diesel

Excellent Original Condition Refrigerated Dyna With Low Mileage. Reliable And Under Warranty. Call Now For Viewing.

DIRECT OWNER

Posted: 27-Oct-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M

\$52,800

\$6,610 /yr

29-Nov-2017

2,982 cc

80,000 km

Truck

Available

Fuel Type: Diesel

Cheapest In Market. New Side Wooden Railing, Aluminium Checkered Plate. Perfect Condition. High Loan And High Trade In. Welcome To Viewing And Testing.

ABWIN (1994) Pte Ltd

Posted: 04-Dec-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Systematic Airconditioning Pte Ltd

29 Senoko Way Singapore 758059 Tel : 64847188 Fax : 64841334
UEN : 199800703G

Winnie - 65942556

REG/CS/PAY/FA

04 DEC 2019

Carin ✓ Leanne (PIC)
put

QUOTATION

Motor Claims Dept
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore
Tel : 68272742

email: motor_survey@msig.com.sg
6205 T402
Fax : 68277809

Date : 29/11/2019
Quotation No : SAPL/2019/0249
Validity :
Terms :

1Hs Full

4/12/19

RE : Repair for GBG7993C - Toyota 10'

Thank you for your Invitation to quote, we are pleased to offer our best price as follows :

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT (SGD)
1	REF_CONDENSERUNIT REFRIGERATION SYSTEM (accident damage) Supply and replace one (1) set New Condenser Unit Assy	1	.	7,800.00	7,800.00
2	REF TRUCK BOX REF TRUCK BOX (accident damage) (Bulkhead) Repair and retrofit Ref Truck Box Parts and Fixtures Supply and install one (1) lot Stainless Steel Plate to re- inforce front Bulk head (outside) c/w sealant Supply and install one (1) lot Stainless Steel plate to re- inforce inside Ref. Box c/w Sealant Supply and replace one (1) lot Bolt and nuts XPS Foam and Fiberglass repair on Freezer Box damage area and make good	1	.	850.00	850.00
3	REF TRUCK BOX REF TRUCK BOX Supply Labour and Services to done above job Supply labour and Services to check and realign Ref. Box	1	.	780.00	780.00
4	SER-IV-0000-004 EXCESS	1	.	-500.00	-500.00
5	SER-IV-0000-004 TRANSPORTS AWLLOWANCE	10	.	50.00	500.00

Trust that the above quotation is in order and look forward to your favourable reply. kindly acknowledge and place your company stamp and signature below and fax a copy for our action

SUB TOTAL : 9,430.00
ADD 7% GST : 660.10
TOTAL AMOUNT : 10,090.10

Thanks and Regards

4/p e 11/8am: shah confirmed car in.

CUSTOMER'S CONFIRMATION

Signature, Stamp and Date



Systematic Airconditioning Pte Ltd

29 Senoko Way Singapore 758059 Tel : 64847188 Fax : 64841334
UEN : 199800703G

Winnie - 65942556

QUOTATION

Motor Claims Dept
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore
Tel : 68272742

Fax : 68277809

email: motor_survey@
60251402 sq. msig
asia.com

Date : 29/11/2019
Quotation No : SAPL/2019/0249
Validity :
Terms :

RE : Repair for GBG7993C - Toyota 10'

Thank you for your invitation to quote, we are pleased to offer our best price as follows :

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT (SGD)
1	REF_CONDENSERUNIT - need invoice REFRIGERATION SYSTEM (accident damage) Supply and replace one (1) set New Condenser Unit Assy	1	.	7,800.00	7,800.00
2	REF TRUCK BOX REF TRUCK BOX (accident damage) (Bulkhead) Repair and retrofit Ref Truck Box Parts and Fixtures Supply and install one (1) lot Stainless Steel Plate to re- inforce front Bulk head (outside) c/w sealant Supply and install one (1) lot Stainless Steel plate to re- inforce inside Ref. Box c/w Sealant Supply and replace one (1) lot Bolt and nuts XPS Foam and Fiberglass repair on Freezer Box damage area and make good	1	.	850.00	850.00
3	REF TRUCK BOX REF TRUCK BOX Supply Labour and Services to done above job Supply labour and Services to check and realight Ref. Box	1	.	780.00	780.00
4	SER-IV-0000-004 EXCESS	1	.	-500.00	-500.00
5	SER-IV-0000-004 TRANSPORTS AWLLOWANCE	10	X	50.00	500.00

Sun Pin (LKK)
04/12/2019.

Excess - \$500

REV.

Repair day - 6 days.

L/S Repair

After paint photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Trust that the above quotation is in order and look forward to your favourable reply. kindly acknowledge and place your company stamp and signature below and fax a copy for our action

Thanks and Regards

Sunpin@lkkauto.com

86612627.

L/S \$7,150

N { 7,800
450

L = 700

8,950

L/S - 20%

7,160

SUB TOTAL 9,430.00
ADD 7% GST 660.10
TOTAL AMOUNT 10,090.10

CUSTOMER'S CONFIRMATION

Signature, Stamp and Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2019		04 Dec 2019 12:09 Edit Adj Rpt	S\$7,150.00 Edit Estimates	S\$7,150.00 View Rpt		Pending for Survey Report Cancel Case




Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Artisan Fine Foods Pte. Ltd., Co. Reg. No.: 201006219C								
Vehicle Reg. No.:	GBG7993C	Date of Loss:	29/11/2019 15:00 - :59 [24 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 613169	Policy/Cover Note No.:	29099690 (Comprehensive) Coverage: 23/11/2019 - 22/11/2020						
		Excess:	S\$500.00						
Repairer:	Systematic Airconditioning Pte Ltd (HQ) 29 Senoko Way, 758059 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jeannie Cheng Jin Rong - 6594 2537]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 03/01/2020]								
Driver/Custodian:	Yusnizam Bin Yunus (52 / Male) , NRIC: S1826961I, Tel: +6586428913 Email:								
Adj Asg. Remarks:	Car in. Manual assigned to LKK via email on 04/12/19. Survey and revert. Please revert. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (27/02/2020): Alert - Adj Mandate Approved (S\$7150.00) - GBG7993C - Claim Handler: Jeannie Che... MSIG_SG (06/12/2019): Alert - Adj Mandate Approved (S\$8500.00) - GBG7993C - Claim Handler: Jeannie Che... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
































Claim Documents

***GBG7993C (613169)**
OD
Nov 29 2019 3:00PM
[Artisan Fine Foods Pte. Ltd.]
Systematic Airconditioning Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/19 14:59	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>
2	06/12/19 11:44	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>
3	26/02/20 16:33	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/19 09:56	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	05/12/19 09:57	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/12/19 09:57	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	05/12/19 09:57	General View		<input checked="" type="checkbox"/>
34	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
35	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
36	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
37	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
38	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
39	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
40	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
41	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
42	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
43	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
44	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
45	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
46	16/12/19 09:37	Dismantled Parts		<input checked="" type="checkbox"/>
47	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
48	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
49	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
50	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
51	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
52	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
53	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
54	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
55	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
56	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
57	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
58	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
59	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
60	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
61	16/12/19 09:37	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/12/19 14:48	PARF COE		<input checked="" type="checkbox"/>
2	03/12/19 14:48	Transfer Fee Details		<input checked="" type="checkbox"/>
3	04/12/19 11:57	Estimate + Accident Statement + CI + The Schedule		<input checked="" type="checkbox"/>
4	04/12/19 11:57	Email to arrange survey		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	04/12/19 12:05	Survey Request - Manual Assigned		<input checked="" type="checkbox"/>
2	04/12/19 12:08	Outsource Instruction		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/19 14:44	GBG 7993C GIA.pdf		<input checked="" type="checkbox"/>
2	05/12/19 14:44	ESTIMATE.pdf		<input checked="" type="checkbox"/>
3	26/02/20 16:31	ESTIMATE MARKED .pdf		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	06/12/19 19:43	Accident Statement		<input checked="" type="checkbox"/>
2	06/12/19 19:44	Accident Statement		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
3	06/12/19 19:46	Accident Statement	 Load HTM	
4	06/12/19 19:48	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	30/11/19 14:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	30/11/19 14:04	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19021405/QSF3S2

Date: 04/03/2020

REFERENCE

Insured/Claimant: Artisan Fine Foods Pte. Ltd.
Date of Loss: 29/11/2019

Policy No: 29099690
Nature of Claim: OD Claim No: 613169

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG7993C**
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)
Reg. Date: 30/10/2017 (Man. Year: 2017)
Colour: White
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$79,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2752738
Chassis No: JTFAT35YX0K209205
Odometer: 59410 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
Front Left Side: Yokohama 5 mm Rear Left Side: Firenza 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,650.00	8,250.00	400.00	4.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	1,200.00	80.00	6.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,930.00	9,450.00	480.00	4.83
Approved Total (Overridden) (S\$)		7,150.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	9,430.00	6,650.00	2,780.00	29.48
+ GST 7.00/7.00% (S\$)	660.10	465.50	194.60	29.48
Nett Amount (S\$)	10,090.10	7,115.50	2,974.60	29.48

INSPECTION

Date of Assignment: 04/12/2019

Date Inspected: 04/12/2019 Inspected At:

Systematic Airconditioning Pte Ltd (HQ)
29 Senoko Way
Singapore 758059

Estimated Period of Repair: 6.0 days

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=892992&extid=324872&CFID=68136243&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Mar 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG7993C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET NEW CONDENSER UNIT ASSY	Crushed	7,800.00 F	*7,800.00 F
2	2		*LOT STAINLESS STEEL PLATE TO RE-INFORCE FRONT BULK HEAD (OUSIDE) C/W SEALANT	Necessary	850.00 F	*450.00 F
3	1		*LOT BOLT AND NUTS XPS FOAM AND FIBERGLASS REPAIR ON FREEZER BOX DAMAGE AREA AND MAKE GOOD		0.00 F	*- F
Total Parts (S\$)						8,650.00 8,250.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY LABOUR AND SERVICES TO DONE ABOVE JOB. SUPPLY LABOUR AND SERVICES TO CHECK AND REALIGN REF. BOX.	New	780.00	700.00
2	TRANSPORTS ALLOWANCE.	New	500.00	500.00
Gross Labour Cost (S\$)			1,280.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >