

QCL.

NS/INC 19021418/Gvf302

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Comfort Lorry  
 of \_\_\_\_\_  
 Insured: FBR 2598R  
 Policy No: 5112087425 (23/06/2019/2103P20)  
 Claims No: MT | 1074122-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMA 4779K in Perm 19 Apr 2012  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Sonata CC 1991  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 625253 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KM1GT41VMCA 822903  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Modi: OK / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Hankook  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 1/12/19 D.O.I. 03-12-19  
 Survey field at w/s 4:20pm  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Rear n/s  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMA 4779K - X
	FBR 2598R - X
<u>11/12/19</u>	<u>LS \$ 1400 confirmed by email (Red 2637.92, 659)</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 Days Of Repair: 4  
 Resurvey No. of Trip: 1  
 Date/Time, File Return to? 11/12 - typist  
 Add Fee:  Site Insp: 15  
 Interview: 15  
 Tech Insp: 15  
 Disposal: 15  
 Survey Fee: 160  
 Transportation: \_\_\_\_\_  
 TP  
 LS \$ 1400/2  
 160

## Veron Chen (LKKAuto)

---

**From:** MTCL@income.com.sg  
**Sent:** Wednesday, 11 December 2019 11:07 AM  
**To:** Veron Chen (LKKAuto)  
**Subject:** RE: REQUEST FOR CLAIM NUMBER

Dear Sir/Mdm,

We have registered the claim.

Please refer below

Please allow the claim officer 2-3 working days to respond to your case.

We appreciate if you do not respond to this email. Thank you

Best regards

**Diana Tay**  
Senior Admin Assistant  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)



---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Wednesday, 11 December 2019 9:20 AM  
**To:** MTCL@income.com.sg  
**Subject:** REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1074122-002	COMFORT TRANSPORTATION PTE LTD	SHA 4779K	FBQ 2598I
2	MT/1074312-002	COMFORT TRANSPORTATION PTE LTD	SHD 6588R	SCY 9018J

D.O.A	Time of Accident	Estimate	Tentative repair cost
1/12/2019	18:45	\$4,037.92	\$1,400.00
2/12/2019	08:20	\$5,364.34	\$1,100.00

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)
[Change Password](#)
[Log Out](#)

[My Desktop](#)  
[Notice of Loss](#)

**Policy Query**

Policy No.  Date of Accident   
 Vehicle No.(For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5112087425		CHIN CHENG LEONG	S7968865G	GMC	Third Party, Fire & Theft	FBQ2598R	FBQ2598R	23/08/2019	22/08/2020

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA4779K
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	D4EAB935639
Chassis No.:	KMHET41VMCA822903
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,622.00
Original Registration Date:	19 Apr 2012
First Registration Date:	19 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$14,622.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2020
PARF Rebate Amount:	\$8,773.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$42,384.00
COE Rebate Amount:	\$1,972.00
<b>Total Rebate Amount:</b>	<b>\$10,745.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Dec 2019

OK

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**SHA4779K**

Make / Model  
**HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO**

Vehicle Type :  
**H10 - Public Transport Taxi (Motor Car)**

Vehicle Attachment 1 :  
**Air-Con (Taxi)**

Vehicle Scheme :  
**Taxi (Company)**

Chassis No. :  
**KMHET41VMCA822903**

Propellant :  
**Diesel**

Engine No. :  
**D4EAB935639**

Motor No. :  
**-**

Engine Capacity :  
**1991 cc**

Power Rating :  
**-**

Maximum Power Output :  
**110.0 kW (147 bhp)**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2019 15:21
Date Of Accident	01/12/2019 18:45
Exact Location Of Accident	BUKIT TIAMH ROAD TWDS UPP BUKIT TIMAH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4779K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	POH KENG HUAT
NRIC No	S0058591B
Date Of Birth	13/06/1954
Occupation	OUTDOOR
Date Of Driving Pass	19/11/1982
Driving Experience	37 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91859291
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	685C 04-200 CHOA CHU KANG CRESCENT
Postcode	683685
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CHOA CHU KANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBQ2598R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	CHIN CHENG LEONG
NRIC/Passport Number	
Contact Number	97508217
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**


Name	CHIN CHENG LEONG
Approximate Age	
Injuries Sustain	LEG
Injured person in which vehicle?	FBQ2598R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

**DETAILS OF INJURED PERSON 2**

Name	POH KENG HUAT
Approximate Age	65
Injuries Sustain	BACK
Injured person in which vehicle?	SHA4779K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached police report.

T/20191202 / 2000

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. LTD.  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Loke Viet Yiang  
NRIC/FIN No.:

RAAFRMC Seru/Ref/Ins/Comp/203



**SINGAPORE  
POLICE FORCE**



T/20191202/2000

1 of 3

Report No. T/20191202/2000

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 02/12/2019 00:03	Vide Report No.: E/20191201/0145	Station Diary No.: 1
--	-------------------------------------	-------------------------

**Informant's Particulars**

Name of Informant: POH KENG HUAT		Address: APT BLK 685C CHOA CHU KANG CRESCENT #04-200 SINGAPORE 683685	
ID Type / ID No.: NRIC NO / S0058591B		Contact No.: Home/Office:	Mobile: 91859291
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 65	Date of Birth: 13/06/1954	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/12/2019 18:45	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH ROAD				
TOWARDS UPP BUKIT TIMAH				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBQ2598R	Motorcycle				Slightly Damaged	0
SHA4779K	TAXI				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE  
POLICE FORCE**



T/20191202/2000

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

2 of 3

Report No. T/20191202/2000

## CONTINUATION OF REPORT

Driver			
Name	POH KENG HUAT	ID No.	S0058591B
Related Vehicle	NIL	Contact No.	91859291
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Rider			
Name	CHIN CHENG LEONG	ID No.	S7968865G
Related Vehicle	NIL	Contact No.	97508217
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 01/12/2019 at 1815hrs, along Bukit Timah Road towards Upp Bukit Timah, near to SPC, a motorcycle bearing registration number FBQ2598R hit onto the rear of my taxi. The rider claimed that he hit onto my taxi. The rider was indecisive as to settle privately or report police. At first the rider wanted to settle privately. I then decided to call Traffic Police directly. Ambulance also came to the scene. Rider was conveyed to TTSH. Traffic Police then advised me to lodge a Road Traffic Accident Report.



SINGAPORE  
POLICE FORCE



T/20191202/2000

3 of 3

Report No. T/20191202/2000

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
J /

Sr Staff Sgt ANG MAGDELENE



Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
02/12/2019 00:03


SIGNATURE


Officer In Charge Of Case:  
TP / GIT /

Classification Of Case:

Contact No.:

Authentication Stamp  
NP168





**Workshops**

Team: ARC Repair TP(CLS0)1

### JOB CARD

Sales Order:

JC NO.: 305358515

OMER

IS COMFORT TRANSPORTATION PTE LTD  
 OMER NO. 7010045  
 ADDRESS 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 (R) 65508755 (O)  
 (P)


REGN NO.: <b>SHA4779K</b>	MILEAGE
MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
MODEL <b>SONATA</b>	DATE/TIME IN <b>02.12.2019 13:05</b>
YR OF MANU. <b>19.04.2012</b>	TARGET DATE
CHASSIS CODE <b>KMHET41VMCA822903</b>	COMPLETION DATE/TIME:

IDENTIFICATION CARD NO.

JOB DESCRIPTION

Accident Date: 01.12.2019  
 NATURE: 3P 01.12.2019

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No.: **SHA4779K**      **CHIANG**

Vehicle No.: **SHA4779K**

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

**COMFORTDELGRO ENGINEERING PTE LTD**

VEHICLE NO : SHA 4779K

DATE 3/12/2019 9:50

MAKE :

MODEL : HYUNDAI SONATA

*change*  
*afmc*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper / <i>TV</i>			\$ 578.40
	Rear Bumper Clip / <i>MC</i>			\$ 22.00
	Rear Bumper Protector (LH) / <i>scr</i>			\$ 38.00
	Tail Lamp (RH) / <i>cut</i>			\$ 344.00
	Rear Fender (RH) <i>X repair</i>			\$ 1,935.90
	Rear Fender Inner Lining (RH) <i>X</i> <del>LN</del> <i>NN</i>			\$ 74.10
	Rear Windscreen Moulding <i>X</i>			\$ 60.00
	<b>SUB TOTAL</b>		<i>982.4</i>	\$ 3,052.40
	<b>LESS 20%</b>			\$ 610.48
	<b>DISCOUNTED TOTAL</b>		<i>785.92</i>	\$ 2,441.92
	Rear Windscreen Sealant <i>X NN</i>			\$ 46.00
	<b>Labour Charge</b>			
	Panel Beating <i>(240)</i>			\$ 560.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>		<i>1785.52</i>	\$ 1,550.00
	<b>ESTIMATE TOTAL</b>		<i>20% : 400</i>	\$ 4,037.92

*/*  
*/*  
*/*  
*/*  
*X*  
*X*  
*X*

Nett

*480*  
*400*  
*20*  
*X NN*  
*60*  
*X NN*  
*40.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Musta*  
*4/12/19*

*cupan repair.*  
*After repair photos*  
*Eric Qiang - 8288 0282*  
*4pm 4 Days.*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 11 December 2019 9:21 AM  
**To:** 'Chiang Liat Choon'  
**Subject:** RE: PENDING FINALISE-SHA 4779K

Dear Mr Chiang,

Noted with thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chiang Liat Choon <chianglc@cdge.com.sg>  
**Sent:** Wednesday, 11 December 2019 9:19 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Re: PENDING FINALISE-SHA 4779K

Confirm.

Best Regards  
Chiang Liat Choon  
Taxi Crash Repair ComfortDelGro Engineering Pte Ltd  
Off: 62148314 Fax: 65468156



Think Before Printing

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 11 December 2019 9:17 AM  
**To:** Chiang Liat Choon <chianglc@cdge.com.sg>  
**Subject:** FW: PENDING FINALISE-SHA 4779K

Dear Mr Chiang,

WITHOUT PREJUDICE

Please confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 10 December 2019 8:40 AM  
**To:** Chiang Liat Choon <chianglc@cdge.com.sg>  
**Subject:** RE: PENDING FINALISE-SHA 4779K

Dear Mr Chiang,

WITHOUT PREJUDICE

Offer Lump Sum \$1400 @ 4 working days.

Please check and confirm

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


---

**From:** Chiang Liat Choon <chianglc@cdge.com.sg>  
**Sent:** Monday, 9 December 2019 6:05 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Re: PENDING FINALISE

Hi VERON,

My finalise with guoqiang & photo after paint.

Best Regards  
Chiang Liat Choon  
Taxi Crash Repair ComfortDelGro Engineering Pte Ltd  
Off: 62148314 Fax: 65468156



---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Monday, 9 December 2019 4:47 PM  
**To:** Lim Kwok Eng <limke@cdge.com.sg>; Chiang Liat Choon <chianglc@cdge.com.sg>  
**Subject:** PENDING FINALISE

Dear Mr Lim/Mr Chiang,

WITHOUT PREJUDICE

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

1. SHA 4779K-DOA: 1/12/2019
2. SHD 6588R-DOA: 2/12/19

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19021418/Gvf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 19-12-2019
Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>	
Insured Veh. FBQ 2598R	Veh. Inspected SHA 4779K
Policy No. 5112087425	Coverage (\$) 0.00
Claim No. MT/1074122-002	Excess (\$) 0.00
Assign From	Assign Date 03/12/2019
<b>2. Vehicle Particulars &amp; Condition</b>	
Make & Model HYUNDAI SONATA	c.c 1991
Engine No. HIDDEN	Year of Reg. 2012
Chassis No. KMHET41VMCA822903	Colour BLUE
Odometer 625253	Steering IN ORDER
Brakes IN ORDER	Modification NIL
General GOOD	
<b>3. Conditions of Tyres</b>	
	Size Make Balance
R/H Front Tyre	215/60 R16 HANKOOK 5 mm
L/H Front Tyre	215/60 R16 HANKOOK 5 mm
R/H Rear Tyre	215/60 R16 HANKOOK 5 mm
L/H Rear Tyre	215/60 R16 HANKOOK 5 mm
<b>4. Description of Damages</b>	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.	
<b>5. General Information</b>	
Accident Date 01/12/2019	Inspection Date 03/12/2019
Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969	
<b>5a. Remarks</b>	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
<b>5b. Estimate Days of Repair</b>	
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4779K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TORN	578.40	578.40
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER PROTECTOR (LH)	SCRATCHED	38.00	38.00
1	TAIL LAMP (RH)	CUT	344.00	344.00
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	1,935.90	-
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	74.10	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
	LESS 20% DISCOUNT		-610.48	-196.48
			2,441.92	785.92
<b>SPECIAL NETT ITEMS</b>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			46.00	-
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER (RH).		560.00	480.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	60.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
			1,550.00	1,000.00
<b>GRAND TOTAL</b>			<b>4,037.92</b>	<b>1,785.92</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,400.00</b>

Report Ref No. NS/INC19021418/Gvf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.