


SKETCH PLAN

A) YP2554A

B) YP6587D

Changi Airport Terminal 3

B's driver assistant



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/05/19 @ 10:00 at about 6:20pm I parked my vehicle at Changi Airport Terminal 3. I heard engine Vehicle B's driver assistant came down off vehicle B to assist my vehicle. From left mirror on vehicle B was trying to reverse and park into a lot beside my vehicle. My vehicle left side mirror is broken. No one is injured.

Diels

DECLARATION

Regards

x

Isaac Ng Cheng Long | Goldbell Leasing Pte Ltd
Senior Executive, Operations Admin (FIM)


DID: +65 6494 2897 | Tel: +65 6861 0007 | Fax: +65 6807 0431 |
Mobile: +65 9829 8836 |

x

Sketch Plan #2

SKETCH PLAN

A-YP 25344



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/12/2011 around 0530hrs, I was driving my vehicle YP25344 along old temporary road while driving I did not notice my vehicle was going side ways. Suddenly felt an impact on my left portion of my vehicle where I have collided onto the road shoulder. No body was injured.

DECLARATION

We declare the foregoing particulars are true in every respect.

Koh Liang Bo

For accident on 31.05.19