

# COMFORTDELGRO ENGINEERING

Our Ref : 305358709

Date : 03.12.2019

Time of Fax : 1650w

ALG

Via Fax : email

Your Insured : SJG 1505 Z

Date of Acc : 02.12.2019

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Attn : Motor Claims Dept.

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO** SHA 2306 E

Loyang  
59 Loyang Drive  
Singapore 508969  
Fax no. 6546 8156

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
  - I) Our initial estimate of repairs of the damaged vehicle.
  - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811

Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305

Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006

Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176

Larry Ng Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

 Larry Ng

for Vice President  
Crash Repairs & Claims Recovery

A member of

**COMFORTDELGRO**



**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 2306E

DATE : 3.12.2019

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	<b>Labour Charge</b>				
	Spray Painting Charge- Frt Bumper			\$ 250.00	
	<b>TOTAL LABOUR</b>			<b>\$ 250.00</b>	
	Rear Bumper			\$ 459.40	
	Rear Bumper Reinforcement			\$ 294.80	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 138.10	\$ 276.20	
	Rear Bumper Centre Moulding Assy			\$ 451.25	
	Rear Bumper Lower Centre Moulding Assy			\$ 155.00	
	Rear Bumper Stay			\$ 138.10	
	Rear Bumper Side Bracket (LH/RH)		\$ 33.10	\$ 66.20	
	Rear Bumper Cover Clips			\$ 22.00	
	<b>SUB TOTAL</b>			<b>\$ 1,862.95</b>	
	<b>LESS 20%</b>			<b>\$ 372.59</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,490.36</b>	
	Rear No.Plates			\$ 25.00	Nett
	Rear No.Plates Trim Cover			\$ 30.00	Nett
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
				<b>\$ 240.70</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 250.00	
	Wiring Charge			\$ 50.00	
	Remove/Refix Reverse Sensor			\$ 120.00	
	<b>TOTAL LABOUR</b>			<b>\$ 770.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,751.06</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate** as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/12/2019 15:03
Date Of Accident	02/12/2019 20:20
Exact Location Of Accident	MERCHANT ROAD >> AYE TUNNEL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA2306E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	FOO YONG WEE
NRIC No	S7240283I
Date Of Birth	27/10/1972
Occupation	OUTDOOR
Date Of Driving Pass	12/06/1998
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81832733
Fax Number	
Contact Number	
EMail Address	THOMASKGN@HOTMAIL.COM

Address	BLK 345 CLEMENTI AVENUE 5 #12-80
Postcode	120345
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

PLS REFER TO ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG1505Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PIETER LUIT DE RIDDER
NRIC/Passport Number	
Contact Number	96158327
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Nature Of Damage FRT

No. Qf Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLN6431J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver YEW CHOON SENG

NRIC/Passport Number

Contact Number 87555587

Address

Postcode

Insurance Company Name

Nature Of Damage REAR

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:03-Dec-2019@12:15hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



A-SHA 2306E

B-SJG 1505Z

C-SLN 6431J

Along Merchant Road Twds AYE Tunnel

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

02.12.2019 at about 20:20hrs.I was travelling along Merchant Road towards AYE Tunnel.
With 01 female passenger on board.
I was travelling straight on the right lane.As the cars in front were slowed down,I applied e-brake.
Suddenly I felt an impact from behind and came to know that veh (B) hit my taxi (A) rear portion.
I assessed the damages to my taxi (A) and come to know that there were 3 vehicles involved in the chain accident.
No injury in this accident.
I have a CCTV footage and scene photos to support my claims.
The parties involved in the accident are :
A-SHA 2306E
B-SJG 1505Z Mr Pieter Luit De Ridder.S 2750721B.Hp no: 9615 8327.
C-SLN 6431J Mr Yew Choon Seng (You ChunCheng).S 7823319B.Hp no: 8755 5587.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 03-Dec-2019@12:15hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: