

ASS. REC. BY:

REF: 653 | CT119021483 | Gsf302 | Special Instruction:

Surveyor: GiaASSIGNMENT (Office)From (Person): Ben Tang of CTI Date/Time: 05/12/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 46634 Insured: SBW 3218Aat Workshop in/s HIAP L&C Tel: 9660 1347 Han Weiof 160 S/M DRIVE #05-17 S/M. AUTO CITYPolicy No: _____ Claim No: CNM190205751

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07/12/19
(Client's Record)CA / REV / REP. / REV 24 HRS 'PR5' H.O.D. Endorsement: _____Date/Time: 05/12/19 @ 17.06pm Person Contacted: Han Wei Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>Johnnie (X)</u>
	<u>SLB 46634 - X</u>
	<u>SBW 3218A - X</u>

ASS. REC BY: ad. | CT:


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s Hiaplek.
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLB 4663H Yr Regn: 08 Apr 2016
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Vezel c.c. 1496
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 186738 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: RW1110737
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 215/55 R17
R: 11

(Policy Condition)



Remark: **The veh had commenced its repair at the time of inspection.**

BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

Front 6 mm R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. _____ D.O.I. 05-12-19

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at wk
Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$1000 - \$200</u>

Date/Time, File Pass to? 06/2/19
1) Typist
Date/Time, File Return to? _____

Days Of Repair: 3
Resurvey No. of Trip: 1

2) _____
Report Format: PRS
Lump Sum / H.R. (\$) _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Wheel end (\$)

Survey Fee:	<u>190</u>
Transportation:	_____
S + RS + SI	_____
Photos	_____
Others:	_____
TOTAL	<u>190</u>

Nivitha (LKK Auto)

From: PRI Cpaglar <pri@cpaglar.com.sg>
Sent: Thursday, 5 December 2019 10:32 AM
To: Ben Tang
Cc: assignments
Subject: Re: OUR REF: SNM19D205751/SBW3218A/BEN- OUR REF: CP/PRI/SLB4663/19/NA (SF) YOUR REF: SBW 3218A NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC ACCIDENT ON 2ND DECEMBER 2019
Attachments: FORM 3 PRI SCAN_20191205_095226648_12052019_094446.pdf

Dear Sirs,

Please find attached.

Artika
C Paglar & Co

On Thu, Dec 5, 2019 at 9:54 AM Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:
WITHOUT PREJUDICE

Dear Sirs

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

XGB
H
(in)
PRS
Han Wei
05/12/2019

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: PRI Cpaglar <pri@cpaglar.com.sg>
Sent: Wednesday, December 4, 2019 5:58 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205751/SBW3218A/BEN- OUR REF: CP/PRI/SLB4663/19/NA (SF)
YOUR REF: SBW 3218A NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC
ACCIDENT ON 2ND DECEMBER 2019

Dear Sirs,

Please find attached.

Artika

C Paglar & Co

On Wed, Dec 4, 2019 at 11:21 AM Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING

Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, December 4, 2019 11:15 AM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; PRI@CPAGLAR.COM.SG

Subject: OUR REF: SNM19D205751/SBW3218A/BEN- OUR REF: CP/PRI/SLB4663/19/NA (SF)
YOUR REF: SBW 3218A NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC
ACCIDENT ON 2ND DECEMBER 2019

Dear Ben,

Please conduct PRS for SLB4663.

Note : officer in charge – Ben Tang 63896175.

****** Kindly quote our reference number when replying.***

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: PRI Cpaglar [mailto:pri@cpaglar.com.sg]
Sent: Tuesday, 3 December, 2019 4:15 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Constance Paglar <constance@cpaglar.com.sg>
Subject: OUR REF: CP/PRI/SLB4663/19/NA (SF) YOUR REF: SBW 3218A NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC ACCIDENT ON 2ND DECEMBER 2019 INVOLVING MOTOR VEHICLE NO. SLB 4663H AND SBW 3218A ALONG CAUSEWAY BETWEEN SINGAPORE TO JB AT ABOUT 1445 HOURS. PURSUAN...

Dear Sirs,

Enclose is a copy of our letter dated 3rd December 2019 for your attention.

Regards,
Shu Fong
For and on behalf of
Messrs C Paglar & Co
50 Chin Swee Road
#05-03 Thong Chai Building
Singapore 169874
Tel: 6536 5456
Fax: 6536 8706

GST Registration Number: M90371275

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

CPc

C PAGLAR & CO

ADVOCATES & SOLICITORS

UEN NO. 53130985A

GST REGISTRATION NO. M90371275E

50 Chin Swee Road
#05-03 Thong Chal Building
Singapore 169874

Telephone: (65) 6536 5456

Facsimile: (65) 6836 2195

Email: pri@cpaglar.com.sg

SERVICE OF COURT DOCUMENTS BY FACSIMILE WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SBW 3218A
Our Reference: CP/PRI/SLB4663/19.na

Date : 5th December 2019

CHINA TAIPING INSURANCE SINGAPORE PTE LTD
ATTN: MOTOR CLAIMS DEPT

BY EMAIL

Dear Sirs,

CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES

We refer to your email dated 5th December 2019.

Please note that the said vehicle can be inspected at:

HIAP LEK AUTOMOBILE TRADING
160 Sin Ming Drive
#05-17 Sin Ming Autocity
Singapore 575722
Contact No.: 9660-1347 (Hanwei)
(Please call the contact person within the next 2 days in advance)

KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

Yours faithfully,


C PAGLAR & CO

cc. [Client by Fax 6266-8605 Only] – (SLB 4663H)

FOR SURVEYOR

Please initial here after completion of
pre-repair inspection.
Thank you

.....
Appointed Surveyor (Name & Signature)

.....
Date & Time of Inspection Form 3

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2019 17:22
Date Of Accident	02/12/2019 14:45
Exact Location Of Accident	CAUSEWAY BETWEEN SINGAPORE TO JB
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4663H
Insured/Policyholder	
Name Of Registered Owner	TT TRANS
Co Reg No	52937394K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97303395
Alternative Phone No	OFFICE-97303395

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090438382-02 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	TAN LYE WAH
NRIC No	S1547680Z
Date Of Birth	14/08/1962
Occupation	OUTDOOR
Date Of Driving Pass	13/04/1985
Driving Experience	34 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97303395
Fax Number	
Contact Number	OTHERS-97303395
Email Address	NOEMAIL

Address	BLK 699 #16-11 HOUGANG STREET 52
Postcode	530699
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE PROPRIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBW3218A
Vehicle Make/Model/Colour	JAGUAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:





 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

03 DEC 2019


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the causeway towards JB from Woodlands Customs. Due to heavy traffic, front vehicles slowed down and stopped, I stopped too. After a while I felt a bump from behind and realised a car SBW3218A had hit onto the rear of my car.


I was alone at the time of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

03 DEC 2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	394K
Vehicle No.:	SLB4663H
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4030740
Chassis No.:	RU11110737
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,648.00
Original Registration Date:	08 Apr 2016
First Registration Date:	08 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$9,648.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2026
PARF Rebate Amount:	\$7,236.00
COE Expiry Date:	07 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,009.00
COE Rebate Amount:	\$29,164.00
Total Rebate Amount:	\$36,400.00

The information contained herein is correct as at 05 Dec 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2019 17:39		11 Dec 2019 14:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	TAN LYE WAH		
Vehicle Reg. No.:	SLB4663H	Date of Loss:	02/12/2019 00:00 - :59 [43 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SBW3218A	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/12/2019]		
Adj Asg. Remarks:	Please arrange for PRS survey of TP vehicle SLB4663H.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SLB4663H
[SBW3218A]
TP
TAN LYE WAH
Dec 2 2019 12:00AM
[-]
Hiap Lek Automobile Trading

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
2	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
3	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
4	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
5	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
6	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
7	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
8	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
9	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
10	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
11	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
12	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
13	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
14	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
15	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
16	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
17	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
18	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
19	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
20	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
21	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
22	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
23	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
24	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
25	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
26	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
27	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
28	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
29	12/12/19 17:43	General View		Load JPG	<input checked="" type="checkbox"/>					
30	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
31	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
32	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
33	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
34	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
35	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
36	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
37	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
38	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
39	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
40	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
41	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
42	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					
43	12/12/19 17:50	Photographs of Damaged Items		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
45	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
46	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
47	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
48	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
49	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
50	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
51	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
52	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
53	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
54	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
55	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
56	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
57	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
58	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
59	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
60	12/12/19 17:50	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
61	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	12/12/19 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119021483/GSF3E2

Date: 12/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:
Claimant	
Vehicle No : SLB4663H	Insured Vehicle No : SBW3218A
Date of Loss: 02/12/2019	Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4663H	Engine No:	L15B4030740
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11110737
Reg. Date:	08/04/2016 (Man. Year: 2015)	Odometer:	186738 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	11/12/2019	
Date Inspected:	05/12/2019 Inspected At:	160 SIN MING DRIVE # 05-17 Repairer : Hiap Lek Automobile Trading
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 -\$2,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4663H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >