

INS. CASE OWNER:

wynn

CC 4 ASM
AXA1902 1912, G 1239LKK:
IDAC:

Surveyor:

Guo Arian

DOI:

ASSIGNMENT

Date / Time:

5/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGS 5470K

Claim No.:

S9m028 LG / 150 V48

Name of Insured:

CHEE LEE CHIANG

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$S

D.O.A.:

26/11/19

Place of Accident:

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) (YES) / NO

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

Final ? Yes / No

SJU 7021M



INSRS:

WSP:

Tel:

Liability:

RMKS:

NBS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

DIP

SS

1150.00

(3

days)

Reduction:

5253.97

%

69

Email

Call

FINAL SETTLEMENT

Date/Time:

3/1/2020

Confirm with

Fullynn

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

4A

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1150.00

Loss of Rental (LOR):

SS

-

(360

x 3

days)

Loss of Use (LOU):

SS

180.00

(360

x 3

days)

Loss of Income (LOI):

SS

-

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

1337.45

Global Sum \$S:

FINAL PAYMENT

Date/Time:

3/1/2020

Confirm with:

Fullynn

Email

Call

Payee 1:

SS

1337.45

Name 1:

NBS Motorsport Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

X GIA

Car. | AXA.

9

ASSIGNMENT

(-2019)

From _____ Date _____
 Estimated Cost _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s NGS Motorsport
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SSU 793 / M or Regn: 28 Dec 2009
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Vios c.c. 1497
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 261475 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053HY930 5134467
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ S/Rim / STD A/Rim or
 Tyre Size: F: 185/60 R15
 R: 1
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hifly
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 05-12-19
 Survey held at w/s 5:30 pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>COB: 6472</u>
<u>05/12</u>	<u>Finalized \$1150 with Boss (Red. \$2513.97 / 69.1)</u>

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
☐ : Other (\$ _____)

Survey Fee: _____

Transportation: _____

3) \$ = PS. \$ _____

4) Flares _____

5) Other _____

TOTAL

Report Format: _____

Long Form / Mobile: _____

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel : 9695 5547 Fax: 6481 5727 e-mail : ngs motorsportpteltd@gmail.com

Reg No: 201812604N

05/12/2019

AXA Ins Singapore Pte Ltd

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 28/11/2019 @14:10HRS
INVOLVING VEH NO.: SJU7931M & SGS5470K
CLAIMS AGAINST SGS5470K
CLAIM REF: S9M028LGMC/LK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts: Ty Vios

1	Rear Bumper	Repair	\$	385.32
1	Rear Bumper Retainer	X NN	\$	59.84
1	Rear Fender RH	X Repair	\$	935.38
1	Rear Rim RH- Repair	X Repair	\$	200.00
1	Rear Door RH- Repair	X Repair	\$	789.62
1	Rear Door Protector RH	/ MC	\$	83.14
			\$	2,453.30
		Less 25%	\$	613.33
			\$	1,839.97
6	Clips, Fender Lining @\$4.00	X S.Nett	\$	24.00
1	Rear Tyre RH	X S.Nett	\$	150.00

To remove all damaged parts with all necessary component/attachment
straighten chassis member, cut & weld panel, repair/reshape dented body panel,
replace damaged parts, refit into position

Spray Painting

Check wiring/proper function on lights and etc.

Any other parts which necessitate repair or renewal will incur additional charged.

Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully,

NGS MOTORSPORT PTE LTD

EVELYN NG

3 Days - 05/12/19
P/P After repair photos
Gno Qiap - 82880282
Gno Qiang @ LKK Auto. Com

1150

100

50 (SAV)

400

600

NN

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	700D
Vehicle No.:	SJU7931M
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	1NZX984523
Chassis No.:	MR053HY9305134467
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	29 Dec 2009
First Registration Date:	29 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$12,717.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2019
PARF Rebate Amount:	\$6,358.00
COE Expiry Date:	28 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$114.00
Total Rebate Amount:	\$6,472.00

The information contained herein is correct as at 05 Dec 2019

OK



Service Request Details

Claim

S9M028LG

Reference

None

Loss Date

November 28, 2019

Report Date

Dec 5, 2019 9:31:00 AM

Request Date

December 5, 2019

Due Date

December 12, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Sungor. G&G

P. Evelyn Ng

T: 11.344.44 5. 12. 19

V: 14

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJU7931M



Model
VIO S E AUTO

Service Address

...

Primary Contact/Insured

CHEE LEE CHIANG
8A CHEMPAKA AVENUE, 349621, Singapore

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

5

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

Summer Lee (LKK Auto)

From: ngs motorsport <ngsmotorsportpteltd@gmail.com>
Sent: Thursday, 5 December, 2019 10:27 AM
To: KADRI Mateen
Subject: [EXTERNAL] Re: Your Ref : SJU7931M Our Ref : S9M028LGMC/LK

Hi,

Appoint LKK Auto, pls note car in already.

Evelyn Ng
DID HP 9695 5547

NGS MOTORSPORT PTE LTD
Blk 10 Ang Mo Kio Ind Park 2a
#02-01 AMK AutoPoint
Singapore 568047

On Thu, Dec 5, 2019 at 9:47 AM KADRI Mateen <mateen.kadri@axa.com.sg> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir,

We want to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list below to conduct the joint pre-repair survey as a Single Joint Expert.

List of our motor surveyors:	
1.	LKK Auto Consultants Pte Ltd
2.	Infiniti Appraisal Services
3.	Priority Services Pte Ltd
4.	AXA in house surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert. Meanwhile, please furnish us with estimate quotation in order for our surveyor to complete the pre repair survey.

If there be any injury claims by your client, please combine it in one Letter of Demand in light of one cause of action, save as to costs and expenses.

Regards,

Mateen Kadri



From: ngs motorsport [mailto:ngsmotorsportpteltd@gmail.com]
Sent: Wednesday, December 04, 2019 4:35 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: [EXTERNAL] Notification Of Accident For Our Veh SJU7931M

Dear Sir/Madam,

RE: Accident on 28/11/2019 @14:10hrs

Along Junction Of Desker Rd & Kg Kapor Rd

Involving SJU7931M & SGS5470K

Claims Againts Veh SGS5470K (AXA)

Vehicle SJU7931M (In workshop)

Kindly be informed that an accident involving my/our vehicle no. **SJU7931M** and vehicle(s) no. **SGS5470K** had taken place at/along **Junction Of Desker Rd & Kg Kapor Rd** on date **28/11/2019** at time **14:10** hours.

Please let us/me know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If I/we did not hear from you within 2 working days, I/we shall proceed to repair the vehicle without further notice and I/we shall claim for the additional loss of use arising from the giving of this notification to you.

Kindly let us have your claims reference, officer in charge of this case and please let us have your clients advice on quantum and liability.

Warmest Regards,

Evelyn Ng

DID HP 9695 5547

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Ind Park 2a

#02-01 AMK AutoPoint

Singapore 568047

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/01/2020

Survey Details:

Date of loss	28-Nov-19
Date of appointment	5-Dec-19
Date of survey	5-Dec-19
Location of survey	NGS TRADING

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJU 7931M
Make and Model	TOYOTA VIOS E A
Date of registration	29/12/2009
Excess	
Market Value	\$28,000
Parf Rebate	\$6,472
Nett Loss	\$21,528

Repair details:

Initial Estimate	\$ 3,663.97
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 150.00
Check items (estimate)	\$ -
Labour	\$ 1,000.00
Total	\$ 1,150.00
Lump Sum(if applicable)	\$ -
Number of days for repair	3



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

03 RECOMMENDED REPAIR DAYS + 1PRS = 4DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	1,150.00
Loss of use	\$	240.00 4days x \$60
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	7.45
Others	\$	-
Proposed Total	\$	1,397.45

 <MANDATE IA> - S9M028LG {ACCIDENT INVOLVING
SGS 5470K (OI) & SJU 7931M (TP) ON 28/11/2019}

Type

 Question

Message

LIABILITY: 100% BOLA S4a - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1397.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 17/01/2020

[Reply](#)

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

HP : 9695 5547 Fax: 6481 5772 e-mail: ngsmotorsportpteltd@gmail.com

Reg No. 201812604N

Messrs : AXA Insurance Singapore Pte Ltd
143 Cecil Street
#01-01 GB Building
Singapore 069542
Attn: Motor Claim Dept

Bill No.: IV20180445

Date : 26/12/2019

Qty	Description	Unit Price	Amount
	Your Ref: S9M028LGMC/LK Accident On Junction Of Desker Rd & Kg Kapor Rd Involving SJU7931M & SGS5470K Claims Against SGS5470K Lump Sum Repair Survey By: Guo Qiang (LKK)		\$ 1,150.00
Grand Total			\$ 1,150.00

Goods sold are not refundable

NGS MOTORSPORT PTE LTD



E.&O.E



VEHICLE LEASE AGREEMENT

Agreement Date: 18 Oct 2019

Referrer Name: Carro sell

NRIC: _____

Car plate no.: _____

Company **Maric Marketing Pte Ltd**
Having its registered office at:
9 Tagore Lane #03-04, Singapore 787472
(hereinafter known as "The Owner")

Rental Begins on: 11 Nov 2019

Time Out & Sign: 11.45 AM

Office No: **6452 4300**

Office hour: **10 am - 7 pm**

Date & Time In: 4 Dec 2019

Signed by Staff: 1435 PM

Hirer's Name: Kalaivanan s/o R Ramasamy IC: S1507977

Address: Blk 25 Telok Wangah Crescent #03-01 SL 090025

(hereinafter known as "the Hirer")

hereby agrees that the Owner shall let and the Hirer shall take the vehicle described below or a replacement vehicle provided by the Owner (hereinafter known as "the Vehicle") upon the terms and conditions hereinafter appearing.

1. DESCRIPTION OF VEHICLE

- a. Make & Model : Toyota UES
b. Registration No : SA11 7931 M
c. Mileage : _____
d. Contact No : 9069 2770
e. Bank Account : _____
f. Email : _____

25-1 Dec = \$350

2-4 Dec = \$125

= \$475

Tax = \$50

\$525

Reduced deposit - \$500 → 1/11 (N)

= \$225

11/12/19 will Made payment

2. RENTAL PERIOD: 2 ^{days} month

3. DEPOSIT AMOUNT: 4300

4. FIRST WEEK RENTAL STARTS ON _____ AMOUNT _____

5. RENTAL FEE : \$5 50 ^{day} per week

20/11 - Return

a. Rental Fee includes the following items:

- Unlimited mileage;
- Service and maintenance;
- Road Tax and Radio License;
- Motor Insurance Coverage (Excess applicable);
- 24-hours breakdown and emergency service (in Singapore only); and

Hirer's Initial	Owner's Initial



Re:<MANDATE IA> - S9M028LG {ACCIDENT INVOLVING
SGS 5470K (OI) & SJU 7931M (TP) ON 28/11/2019}

Type

🔗 Question

Message

Dear CCL, proceed. However, to offer at 3days first. Thanks

Reply

Cecilia Chong (LKK Auto)

From: ngs motorsport <ngsmotorsportpteltd@gmail.com>
Sent: Thursday, 2 January 2020 3:33 PM
To: Cecilia Chong (LKK Auto)
Subject: LOD For Our Insured Veh SJU7931M
Attachments: Authorise To Act.pdf; IV20180445.pdf; SGS5470K LTA Search.pdf; SJU7931M Driver Contract.pdf; SJU7931M SAS Report.pdf

Dear Sir,

RE: VEH INVOLVING SJU7931M/SGS5470K ON 28/11/2019

We understand that you are the insurer of SGS5470K vehicle.

I/We wish to inform you that my/our vehicle SJU7931M have been completed repairs to my/our satisfaction by M/s NGS Motorsport Pte Ltd. I/We therefore propose to claim from you as follow:-

a) Cost of Repair	\$1150.00
b) LOU 4days @\$60.00	\$ 240.00 (Include Sunday)
c) LTA Search	<u>\$ 7.45</u>
	<u>\$1397.45</u>

A copy each of the following supporting documents is attached

- a) Authorise to act
- b) Cert of insurance
- c) Our bill M/S NGS MotorSport Pte Ltd
- d) LTA Search
- e) SJU7931M SAS Report
- f) Driver Contract

Your early reply to the above claims would therefore be much appreciated.

Your faithfully,

Evelyn Ng
DID HP 9695 5547

NGS MOTORSPORT PTE LTD
Blk 10 Ang Mo Kio Ind Park 2a
#02-01 AMK AutoPoint
Singapore 568047

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19021512/Gga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:LYNN

Date : 14-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 5470K	Veh. Inspected	SJU 7931M
Policy No.	GA330525/1	Coverage (\$)	0.00
Claim No.	S9M028LG	Excess (\$)	0.00
Assign From		Assign Date	05/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305134467	Colour	BLUE
Odometer	261475	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	HIFLY	5 mm
L/H Front Tyre	185/60 R15	HIFLY	5 mm
R/H Rear Tyre	185/60 R15	HIFLY	5 mm
L/H Rear Tyre	185/60 R15	HIFLY	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/11/2019	Inspection Date	05/12/2019
Survey held at	NGS MOTORSPORT PTE LTD BLK 10 AMK IND PK 2A #02-01 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 7931M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	385.32	-
1	REAR BUMPER RETAINER (CONSISTENT)	NOT NECESSARY	59.84	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	935.38	-
1	REAR DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	789.63	-
	LESS 25% DISCOUNT		-542.54	-
			1,627.63	-
1	REAR RIM RH (SN)(CONSISTENT)	DAMAGED	200.00	100.00
1	REAR DOOR PROTECTOR RH (SN)(CONSISTENT)	NECESSARY	83.14	50.00
	LESS 25% DISCOUNT		-70.79	-
			212.35	150.00
SPECIAL NETT ITEMS				
6	CLIPS ,FENDER LINER @\$4.00 (SN)(CONSISTENT)	NOT NECESSARY	24.00	-
1	REAR TYRE RH (SN)(CONSISTENT)	NOT NECESSARY	150.00	-
			174.00	-
LABOUR				
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT STRAIGHTEN CHASSIS MEMBER ,CUT & WELD PANEL ,REPAIR /RESHAPE DENTED BODY PANEL,REPLACE DAMAGED PARTS ,REFIT INTO POSITION.		800.00	400.00
	SPRAY PAINTING.		800.00	600.00
	CHECK WIRING /PROPER FUNCTION ON LIGHTS AND ETC.	NOT NECESSARY	50.00	-
			1,650.00	1,000.00
GRAND TOTAL			3,663.98	1,150.00
RECOMMENDED COST OF REPAIRS				1,150.00

Report Ref No. CC4/ASM19021512/Gga3q2



Report Ref No. CC4/ASM19021512/Gga3q2

A handwritten signature in black ink, consisting of a stylized 'X' followed by a loop and a vertical stroke.

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

A handwritten signature in black ink, featuring a stylized 'H' and 'L' with a small mark at the end.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

59M02BLG

Reference

CC4/ASM19021512/Cgpl3a2

Loss Date

28 November 2019

Report Date

5 Dec 2019 9:31:00 AM

Request Date

5 December 2019

Due Date

Vendor Name

L&K AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SJU7931M

Make

TMVO TOYOTA

Model

VIOS E AUTO

Service Address

...

Primary Contact/Insured

CHEE LEE CHIANG

BA CEMPAKA AVENUE, 349621, Singapore

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

1

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1_111.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
LKXAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2020
TAX INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
TIRD LEASE AGREEMENT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
ATA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
MANDATE IA DO 17012020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LTA SEARCH INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 PAIRF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
 TP-IA 7924.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2019
 EMAIL.png	Letters and Correspondence	Workshop	KADRI Mateen	5 December 2019
 GA330525-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	KADRI Mateen	5 December 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PRG).png	Letters and Correspondence	Workshop	KADRI Mateen	5 December 2019
 TP-GIA SJU7931M.pdf	Reports & Statement	GIA Report	KADRI Mateen	5 December 2019
 SJU7931M TP VIDEO.AVI	Evidence	Videos	KHONG Lynn	5 December 2019