

ASS. REC. BY:

REF:

CS/111 19021565 / GSF302

Special Instruction:

Surveyor

GA

ASSIGNMENT (Office)

From (Person):

Gabriel W

of

III

Date/Time:

6.12.19 12pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S12 3253 L

Insured:

SHC 8335 X

at Workshop m/s

Em Solution

Tel:

91018302

of

160 San my Drw 402-17/19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A

3.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

6.12.19

12pm

Person Contacted:

Bernard

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 8335 X CC4022190 13283 / AUTH 362 DEP: 06/12/2019

S12 3253 L X

10/12/19

@ 12:04 pm checked with Bernard, don't want proceed direct settlement

III

SJZ 3253L 21 sep 2010

Front Rear

R.Bal. 6 mm R.Bal. 6 mm

L.Bal. 6 mm L.Bal. 6 mm

D.O.A. D.O.I. 06-12-19

Survey held at w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/C / UIC / Rooftop

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: 15/12/19
 Type: ☒ Prelim. Report
☒ Final Report
 Days Of Repair: 4
 Resurvey No. of Trip: 2
 Survey Fee: 300
 Trip Expenses: 11
 361
 Trip Fee: 45
 Interview: 45
 Transport: 45
 Fuel: 45
 \$ 3,000/- 45

Summer Lee (LKK Auto)

From: Gabriel Wee <Gabriel@iii.com.sg>
Sent: Friday, 6 December, 2019 1:21 PM
To: Nivitha (LKK Auto)
Subject: RE: OUR REF.: E21-112311.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

Yes,

Forward you the email.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: 06 December, 2019 12:37 PM
To: Gabriel Wee <Gabriel@iii.com.sg>
Subject: RE: OUR REF.: E21-112311.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

Dear Gabriel,

Kindly check below assignment is it assign to us?

Best Regards

Shiau Chan

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: EM Auto [mailto:emautosolution@singnet.com.sg]
Sent: Friday, 6 December 2019 12:33 PM
To: assignments@lkkauto.com
Subject: FW: OUR REF.: E21-112311.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Wednesday, 4 December, 2019 12:24 PM

To: Sally Chong <sallychong@visionlawllc.com>; Manivel Priyadarshini <manivel@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>

Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; Andrew Lim <Andrew@iii.com.sg>; derekkeh@singnet.com.sg; Tanvin13@yahoo.com.sg

Subject: RE: OUR REF.: E21-112311.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJZ3253L and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]

Sent: 04 December, 2019 11:12 AM

To: Motor Claim - III <motorclaim@iii.com.sg>; Manivel Priyadarshini <manivel@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>

Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; Andrew Lim <Andrew@iii.com.sg>; derekkeh@singnet.com.sg; Tanvin13@yahoo.com.sg

Subject: RE: OUR REF.: E21-112311.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: FOO HAI HWE
ACCIDENT INVOLVING SJZ 3253L & SHC 8335X ON 3 DEC 2019 ALONG WEST GATE DROPOFF POINT AT ABOUT 11:57 HRS

Thank you for your email of even date below with your list of surveyors.

Our client confirms the appointment of **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

| | | |
|---------|---|--|
| Venue | : | E M SOLUTION PTE LTD 160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722 |
| Contact | : | Mr. Bernard (Tel.: 6456-0226 / 9101-8302) |

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Wednesday, 4 December, 2019 9:14 AM

To: Sally Chong; Manivel Priyadarshini; Gabriel Wee

Cc: 'EM Solution Pte Ltd'; Andrew Lim

Subject: RE: OUR REF.: E21-MISC.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: 03 December, 2019 3:46 PM

To: Motor Claim - III <motorclaim@iii.com.sg>; Manivel Priyadarshini <manivel@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>

Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; Andrew Lim <Andrew@iii.com.sg>

Subject: OUR REF.: E21-MISC.19 (SJZ 3253L @ 03/12/2019) III'S REF NO : SHC 8335X

Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: FOO HAI HWEE

ACCIDENT INVOLVING SJZ 3253L & SHC 8335X ON 3 DEC 2019 ALONG WEST GATE DROPOFF POINT AT ABOUT 11:57 HRS

We are instructed by FOO HAI HWEE to notify you of a road traffic accident ON 3 DEC 2019 ALONG WEST GATE DROPOFF POINT AT ABOUT 11:57 HRS involving our client's vehicle registration number SJZ 3253L and vehicle registration number SHC 8335X driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL: 6534-2811 (ext 115)

FAX: 6535-6802

C.c.: VEHICLE OWNER OF SHC 8335X
COMFORT TRANSPORTATION PTE LTD
383, Sin Ming Drive,
GAS BUILDING,
Singapore 575717

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



This email has been checked for viruses by AVG antivirus software.

www.avg.com

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------|--------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 305E |
| Vehicle No.: | SJZ3253L |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 08 Dec 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | ESTIMA HYBRID 2.4X A |
| Primary Colour: | Purple |
| Manufacturing Year: | 2010 |
| Engine No.: | 2AZH549575 |
| Chassis No.: | AHR207049742 |
| Maximum Power Output: | 110.0 kW (147 bhp) |
| Open Market Value: | \$47,044.00 |
| Original Registration Date: | 21 Sep 2010 |
| First Registration Date: | 21 Sep 2010 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$28,227.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 20 Sep 2020 |
| PARF Rebate Amount: | \$14,113.00 |
| COE Expiry Date: | 20 Sep 2020 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| QP Paid: | \$35,909.00 |
| COE Rebate Amount: | \$2,812.00 |
| Total Rebate Amount: | \$16,925.00 |

The information contained herein is correct as at 08 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT | |
|--|--|
| Date Of Report | 04/12/2019 11:09 |
| Date Of Accident | 03/12/2019 11:55 |
| Exact Location Of Accident | WEST GATE DROP-OFF POINT |
| Country/State of Loss | SINGAPORE |
| DETAILS OF OWN VEHICLE | |
| Vehicle Registration Number | SJZ3253L |
| Insured/Policyholder | |
| Name Of Registered Owner | FOO HAI HWEE |
| NRIC No | S1518305E |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-88669646 |
| Alternative Phone No | OFFICE-88669646 |
| Vehicle Particulars | |
| Manufacturer | TOYOTA |
| Model | ESTIMA |
| Exact Purpose for which vehicle was being used at time of accident | WORK PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |
| Insurance Company | |
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5101045420-01 |
| Cover Note Number | |
| Driver | |
| Name of Driver | FU WANNI |
| NRIC No | S8531621D |
| Date Of Birth | 29/09/1985 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 28/09/2009 |
| Driving Experience | 10 YEARS AND 2 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-88669646 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|--|
| Address | BLK 619 BUKIT PANJANG RING ROAD #04-812 SINGAPORE |
| Postcode | 670619 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | CHILDREN |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : MUHAMMAD AMIRUL BIN ANUAR GENDER: : MALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER ATTACHED

Attachment(s)

| | |
|---|---------------------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | VIDEO FOOTAGE WILL SEND TO NTUC |
| Was there any audio recorded? | NO |


DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-----------------|
| Vehicle Registration Number | SHC8335X |
| Vehicle Make/Model/Colour | |
| Details Of Properties | REFER ATTACHED |
| Vehicle Category | TAXI |
| Name of Driver | LEONG CHOY THIM |
| NRIC/Passport Number | S6838394C |
| Contact Number | 86868394 |
| Address | |
| Postcode | |
| Insurance Company Name | |

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 3/12/19 at about 11:57 AM I was driving my vehicle - STZ 3253 L along West GATE Drop-off point. As I was driving into the drop-off out of a sudden - a taxi SHC 8335 X from the left side of the TAXI STAND lot swerved over to my lane and collided onto my vehicle left-side door. FYI, during the material time of accident my vehicle was slow moving, after the impact, I stopped my vehicle and exchange my particulars with taxi driver. I reporting this incident for T/party claim against SHC 8335 X for my damages. The taxi driver informed me to lodge a report against him for my damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------------|
| Date Of Report | 04/12/2019 11:09 |
| Date Of Accident | 03/12/2019 11:55 |
| Exact Location Of Accident | WEST GATE DROP-OFF POINT |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJZ3253L |
| Insured/Policyholder | |
| Name Of Registered Owner | FOO HAI HWEE |
| NRIC No | S1518305E |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-88669646 |
| Alternative Phone No | OFFICE-88669646 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | TOYOTA |
| Model | ESTIMA |
| Exact Purpose for which vehicle was being used at time of accident | WORK PURPOSE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5101045420-01 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | FU WANNI |
| NRIC No | S8531621D |
| Date Of Birth | 29/09/1985 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 28/09/2009 |
| Driving Experience | 10 YEARS AND 2 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-88669646 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|--|
| Address | BLK 619 BUKIT PANJANG RING ROAD #04-812 SINGAPORE |
| Postcode | 670619 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | CHILDREN |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : MUHAMMAD AMIRUL BIN ANUAR GENDER: : MALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER ATTACHED

Attachment(s)


| | |
|---|---------------------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | VIDEO FOOTAGE WILL SEND TO NTUC |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-----------------|
| Vehicle Registration Number | SHC8335X |
| Vehicle Make/Model/Colour | |
| Details Of Properties | REFER ATTACHED |
| Vehicle Category | TAXI |
| Name of Driver | LEONG CHOY THIM |
| NRIC/Passport Number | S6838394C |
| Contact Number | 86868394 |
| Address | |
| Postcode | |
| Insurance Company Name | |

| No. | Nature Of Damage |
|-----|-------------------------------------|
| | No. Of Passenger (Including Driver) |

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 3/12/19 at about 11:57 AM I was driving my vehicle - STZ 3253 L along Wool Gate Drop-off point. As I was driving into the Drop-off but of a sudden - a taxi SHC 8335 X from the left side of the TAXI STAND lot SWERVED over to my lane and collided onto my vehicle left-side door. FYI, during the material time of accident my vehicle was slow moving, after the impact, I stopped my vehicle and exchange my particulars with taxi driver. I reporting this incident for T/property claim against SHC 8335 X for my damages. The taxi driver informed me to lodge a report against him for my damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

Foo Hai Hwee

For Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for 14 days
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

06.11.2019

REPAIR ESTIMATE FOR TOYOTA ESTIMA - SJZ 3253 L

| | | | | |
|----------|--------------------------------------|------------|----------|--------|
| 1 pc. | LH front fender | X Repair | 542.70 | X |
| 1 pc. | LH front fender inner shield | X NN | 298.10 | X |
| 1 pc. | LH front fender lower garnish | / Cut | 266.50 | / |
| 1 pc. | LH front door | / Full | 1,339.40 | / |
| 2 pcs. | LH front door hinges | 1 pc - BT. | 96.20 / | 192.40 |
| 1 pc. | LH front door stopper | X NN | 144.80 | |
| 1 pc. | LH front door lower garnish | / Mts. | 538.20 | / |
| 1 pc. | LH front door mirror assy | X | 762.30 | |
| 1 pc. | LH front door outer handle | X | 94.90 | |
| 1 pc. | LH front door inner lock | X | 543.50 | |
| 1 pc. | LH front door rubber | X | 470.80 | |
| 1 pc. | LH front door inner lower trim | X | 136.20 | |
| 1 pc. | LH front door gear regulator w motor | X | 455.30 | |
| 1 pc. | LH front door channel felt | X | 178.80 | |
| 1 pc. | LH front door inner trim | X | 786.20 | |
| 1 pc. | LH rear door | X Repair | 1,339.40 | |
| 1 pc. | LH rear door lower garnish | / Cut | 525.60 | / |
| 1 pc. | LH rear door rubber | X NN | 470.80 | |
| 1 pc. | LH side skirt panel | X Repair | 482.40 | |
| 1 pc. | LH side skirt panel rubber trim | X NN | 105.20 | |
| | | | 9,673.50 | 2765.9 |
| Less 25% | | | 2,418.38 | |
| | | | 7,255.13 | 274.42 |

| | | | | |
|-------|-------------------------------------|---|-------|----|
| 1 set | LH front door inner trim clips | / | 45.00 | SN |
| 1 set | LH front door lower garnish clips | / | 30.00 | SN |
| 1 set | LH rear door lower garnish clips | / | 30.00 | SN |
| 1 set | LH front fender lower garnish clips | / | 30.00 | SN |

- 1) Check electrical wirings. 60.00 X NN
- 2) Transfer LH front and doors mechanisms. 200.00 60
- 3) Repair accident damages and renew above parts. 1,100.00 400.
- 4) Spray paint on accident affected portions. 1,100.00 700
- 5) Rust proofing on accident affected portions. 140.00 X NN

\$ 9,990.13 1060

4 Days - 06/12/19.
 Warnings Repair
 After repair photos.
 Gino Gino - 82880282

3740.44 13692.46
 w.g.: 3000

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

07.12.2019

Foo Hai Hwee

SUPPLEMENTARY REPAIR ESTIMATE FOR TOYOTA ESTIMA - SJZ 3253 L

| | | | | |
|-------|---|----------|--------------------|--------|
| 1 pc. | LH front shock absorber | X | 485.70 | A |
| 1 pc. | LH front knuckle arm | X | 552.45 | A |
| 1 pc. | LH front wheel bearing | / | 174.70 | A |
| 1 pc. | LH front drive shaft | X | 1,830.25 | A |
| | | | 3,043.10 | |
| | | Less 25% | 760.78 | 131.02 |
| | | | <u>2,282.33</u> | |
| 1 pc | LH front sport rim | / | 580.00 | SN A |
| 1 pc | LH front tyre | X | 380.00 | SN A |
| | | | | |
| 1) | Lower front suspension to facilitate repair | 80 | 360.00 | A |
| 2) | Computerize wheel alignment | 60 | 100.00 | A |
| | | | <u>\$ 3,702.33</u> | |

381.02

3610.44

20% : 2850 3000

...CLAIM SUBFOLDER...(Pending for Survey Report)












































CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|--|---------------|--|--|--|------------|---|
| Main | 20 Dec 2019 13:59 Edit Reg | | 06 Dec 2019 00:00 Edit Adj Rpt | S\$3,000.00 Edit Estimates | S\$3,000.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: +, Co. Reg. No.: - | | | | | | | | | |
| Main Claimant: FOO HAI HWEE , ID: S1518305E | | | | | | | | | |
| Vehicle Reg. No.: SJZ3253L | | Date of Loss: 03/12/2019 00:00 - :59 [110 Months and 12 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP | | Policy/Cover Note No.: | | | | | | | |
| Vehicle Reg. No. (Insured): SHC8335X | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel: | | | | | | | | | |
| Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/12/2019] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SJ23253L
[SHC8335X]
TP
FOO HAI HWEE
Dec 3 2019 12:00AM
[-]
Em Solution Pte Ltd (160 Sin Ming)

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|------------------|-----------------------------------|--|-------------------------------------|
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/ Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 10/12/19 09:38 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 10/12/19 09:38 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 10/12/19 09:38 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 10/12/19 09:38 | Dismantled Parts |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|---|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 44 | 11/12/19 10:41 | After Repair Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 11/12/19 10:41 | After Repair Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 11/12/19 10:41 | After Repair Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 06/12/19 14:22 | ASSIGNMENT FROM III |  | Load PDF | |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 10/12/19 08:37 | Singapore Accident Statement |  | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured. | | | |
| <div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> ^ v </div> </div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19021565/GSF3E2

Date: 20/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : SJZ3253L

Insured Vehicle No : SHC8335X

Date of Loss: 03/12/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ3253L

Make & Model: TOYOTA ESTIMA, 2.4 (A)

Engine No: 2AZH549575

Reg. Date: 21/09/2010 (Man. Year: 2010)

Chassis No: AHR207049742

Colour: Silver

Odometer: 279607 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 10,632.45 | 2,440.45 | 8,192.00 | 77.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,060.00 | 1,300.00 | 1,760.00 | 57.52 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 13,692.45 | 3,740.45 | 9,952.00 | 72.68 |
| Approved Total (Overridden) (S\$) | | 3,000.00 | | |
| (S\$) | 13,692.45 | 3,000.00 | 10,692.45 | 78.09 |
| + GST 7.00/7.00% (S\$) | 958.47 | 210.00 | 748.47 | 78.09 |
| Nett Amount (S\$) | 14,650.92 | 3,210.00 | 11,440.92 | 78.09 |

INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 06/12/2019 Inspected At:

Em Solution Pte Ltd (160 Sin Ming)
(HQ)
160 Sin Ming Drive, #03-19 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 20 Dec 2019) |
| Parts: | M1-MPV | TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJZ3253L) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|--|-----------------|-------------|--------------|
| 1 | 1 | *LH FRONT FENDER | Repair | 542.70 FL | *- FL |
| 2 | 1 | *LH FRONT FENDER INNER SHIELD | Not Necessary | 298.10 FL | *- FL |
| 3 | 1 | *LH FRONT FENDER LOWER GARNISH | Cut | 266.50 FL | *266.50 FL |
| 4 | 1 | *LH FRONT DOOR | Buckled | 1,339.40 FL | *1,339.40 FL |
| 5 | 1 | *LH FRONT DOOR HINGES (2PCS) | Bent (1Pc Only) | 192.40 FL | *96.20 FL |
| 6 | 1 | *LH FRONT DOOR STOPPER | Not Necessary | 144.80 FL | *- FL |
| 7 | 1 | *LH FRONT DOOR LOWER GARNISH | Missing | 538.20 FL | *538.20 FL |
| 8 | 1 | *LH FRONT DOOR MIRROR ASSY | Not Necessary | 762.30 FL | *- FL |
| 9 | 1 | *LH FRONT DOOR OUTER HANDLE | Not Necessary | 94.90 FL | *- FL |
| 10 | 1 | *LH FRONT DOOR INNER LOCK | Not Necessary | 543.50 FL | *- FL |
| 11 | 1 | *LH FRONT DOOR RUBBER | Not Necessary | 470.80 FL | *- FL |
| 12 | 1 | *LH FRONT DOOR INNER LOWER TRIM | Not Necessary | 136.20 FL | *- FL |
| 13 | 1 | *LH FRONT DOOR GEAR REGULATOR W MOTOR | Not Necessary | 455.30 FL | *- FL |
| 14 | 1 | *LH FRONT DOOR CHANNEL FELT | Not Necessary | 178.80 FL | *- FL |
| 15 | 1 | *LH FRONT DOOR INNER TRIM | Not Necessary | 786.20 FL | *- FL |
| 16 | 1 | *LH REAR DOOR | Repair | 1,339.40 FL | *- FL |
| 17 | 1 | *LH REAR DOOR LOWER GARNISH | Cut | 525.60 FL | *525.60 FL |
| 18 | 1 | *LH REAR DOOR RUBBER | Not Necessary | 470.80 FL | *- FL |
| 19 | 1 | *LH SIDE SKIRT PANEL | Repair | 482.40 FL | *- FL |
| 20 | 1 | *LH SIDE SKIRT PANEL RUBBER TRIM | Not Necessary | 105.20 FL | *- FL |
| 21 | 1 | *SET LH FRONT DOOR INNER TRIM CLIPS | Necessary | 45.00 FS | *45.00 FS |
| 22 | 1 | *SET LH FRONT DOOR LOWER GARNISH CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 23 | 1 | *SET LH REAR DOOR LOWER GARNISH CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 24 | 1 | *SET LH FRONT FENDER LOWER GARNISH CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 25 | 1 | *LH FRONT SHOCK ABSORBER | Not Necessary | 485.70 FL | *- FL |
| 26 | 1 | *LH FRONT KNUCKLE ARM | Not Necessary | 552.45 FL | *- FL |
| 27 | 1 | *LH FRONT WHEEL BEARING | Necessary | 174.70 FL | *174.70 FL |
| 28 | 1 | *LH FRONT DRIVE SHAFT | Not Necessary | 1,830.25 FL | *- FL |
| 29 | 1 | *LH FRONT SPORT RIM (LOCAL REPAIR) | Scratched | 580.00 FS | *100.00 FS |
| 30 | 1 | *LH FRONT TYRE | Not Necessary | 380.00 FS | *- FS |

F=Franchise part. S=SpcNettl. L=ListItemDisc.

Sub Total (\$\$) 13,811.60 3,175.60
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,179.15 735.15

Total Parts (\$\$) 10,632.45 2,440.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | CHECK ELECTRICAL WIRINGS | New | 60.00 | 0.00 |
| 2 | TRANSFER LH FRONT AND DOORS MECHANISM | New | 200.00 | 60.00 |
| 3 | REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS | New | 1,100.00 | 400.00 |
| 4 | SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS | New | 1,100.00 | 700.00 |
| 5 | RUST PROOFING ON ACCIDENT AFFECTED PORTIONS | New | 140.00 | 0.00 |
| 6 | LOWER FRONT SUSPENSION TO FACILITATE REPAIR | New | 360.00 | 80.00 |
| 7 | COMPUTERIZE WHEEL ALIGNMENT | New | 100.00 | 60.00 |
| Gross Labour Cost (S\$) | | | 3,060.00 | 1,300.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >