

15/5/2010

INS. CASE OWNER:

CC 4 /AIG190

LKK:

IDAC:

Surveyor:

RAM

DOI:

ASSIGNMENT

6/1/19


Date / Time:

Registered in Merimen:

6/1/19

6/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMP 822G

Claim No.:

Name of Insured:

CHAN HON CHOU STANLEY

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

29/1/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

PA 6793X

SMP 822G

SHD 4003A



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS: 01



INSRS:

WSP:

Tel:

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	ASHER 11.12.19
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice	☐ ☐
	LTA / GIA :	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: PSS

Repair Cost:

PP

S\$ 4,210.32

(3 days)

Reduction:

39 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 02.04.20

Confirm with KAZALI

Email ☐ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia : 0%

Repair Cost:

WLS

S\$ 4,505.04

3YEH CC 01 2ND

Loss of Rental (LOR):

S\$ 1,284.00

(10 days) x + 128.40

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ 520.00

(\$ 50 x 10 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

S\$ 1.44

Medical:

S\$ -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

S\$ -

(e.g. Tow/ Independent)

2) Report Format:

TP

Legal Cost

S\$ -

3) Survey fee:

320

Total:

S\$ 6,296.53

Global Sum S\$: 6,290.00

FINAL PAYMENT

Date/Time: 02.04.20

Confirm with: KAZALI

Email ☐ Call ☐

Payee 1:

S\$ 6,290.00

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHD 4003A

MAKE :

MODEL : HYUNDAI IONIQ

Ag Asia - 111
 DATE 6/12/2019 (Fri)

LKK - Ram

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid BUC			\$ 2,480.40
	Boot Lid Lock Upper ? } sm Xnn			\$ 224.00
	Boot Lid Lock Lower ? } sm Xnn			\$ 51.30
	Boot Lid 'H' Emblem rec			\$ 28.00
	Emblem -Hybrid rec			\$ 24.30
	Emblem -Ioniq rec			\$ 31.30
	Boot Lid Glass, Lower rec			\$ 384.90
	Rear Bumper X CE			\$ 459.40
	Rear Bumper Centre Moulding Assy cut			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy cut cra			\$ 155.00
	Rear Bumper Stay Xnn			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) Xnn		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips Xnn			\$ 22.00
	Rear Panel ? Xnn			\$ 532.00
	Rear Panel Garnish ? Xnn			\$ 155.00
	Rear Panel Lower Panel ? Xnn		\$ 39.40	\$ 78.80
	Rear Windscreen Glass Xnn			\$ 607.20
	Rear Windscreen Moulding Xnn			\$ 28.20
SUB TOTAL				\$ 5,917.35
LESS 20% to resurvey before/after spray painting				\$ 1,183.47
DISCOUNTED TOTAL				\$ 4,733.88
	Boot Lid Comfort Logo & Tel No. Sticker rec			\$ 30.00
	Rear No. Plate cra			\$ 25.00
	Rear Bumper Reverse Sensor Xnn			\$ 135.70
	Rear Bumper Rubber Mat rec			\$ 50.00
	Rear Windscreen Sealant Xnn			\$ 46.00
				\$ 286.70
Labour Charge				
	Panel Beating		\$ 750.00	\$ 480
	Spray Painting Charge		\$ 600.00	\$ 400
	Wiring Charge		\$ 50.00	\$ 30
	Tuff Kote		\$ 50.00	\$ 30
	Towing Charge		\$ 60.00	\$ 30
	Remove/Refix Cushion & Upholstery Rear		\$ 150.00	\$ 55
	Remove/Refix Rear Windscreen Glass		\$ 120.00	\$ 50
	Remove/Refix Reverse Sensor		\$ 80.00	Xnn \$1120
TOTAL LABOUR				\$ 1,860.00
ESTIMATE TOTAL				\$ 6,880.58

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Take mileage photo

Ram (LKK)
 6/12/19 1130am
 Ram (LKK)
 88622778
 3 days in day
 8/18 Ref paint photo

\$3400

VEHICLE	:	<u>SHD4003A</u>	TYPE OF CLAIM :	<u>TP</u>
MODEL	:	<u>IONIQ</u>	SURVEY BY :	<u>LKK-RAM</u>
JOB NO	:	<u>305358544</u>	DATE	<u>06/12/19</u>

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]