



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19021576/Upa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-06-2020



ATTN:STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------|----------------|------------|
| Insured Veh. | SKA 9820E | Veh. Inspected | SLG 2328M |
| Policy No. | GA030987 | Coverage (\$) | 0.00 |
| Claim No. | S9M029B4 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 06/12/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|---------------------|--------------|------------|
| Make & Model | HONDA CIVIC IMA (A) | c.c | 1339 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | JHMF36208S213833 | Colour | BROWN |
| Odometer | 272807 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|----------------|------------|--------|---------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | FALKEN | 6 mm |
| L/H Front Tyre | 195/65 R15 | FALKEN | 6 mm |
| R/H Rear Tyre | 195/65 R15 | FALKEN | 6 mm |
| L/H Rear Tyre | 195/65 R15 | FALKEN | 6 mm |

4. Description of Damages

| |
|-----------------------------------------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. |
|-----------------------------------------------------------------------------------------------------------------------------|

5. General Information

| | | | |
|----------------|-------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date | 05/12/2019 | Inspection Date | 06/12/2019 |
| Survey held at | FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | |

5a. Remarks

| |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|----------------|