

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			07312	264400	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

<Automatic Light and Wiper : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			07312	264400	Current		
Past	B2401	Sensor Installation Incorrect					

<Combination Meter : 0 piece>

<Multi-function Display : 0 piece>

<Headlight / Foglight : 2 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			07312	264400	Current		
Past	B2904	LED Headlight Circuit RH	07275	13834700	ommo		**
Past	B2910	Steering Responsive Headlight Communication RH	07275	40049100	ommo		

All diagnosis code

TEL:

FAX:

Employee, in charge:

E-mail:

Date and time: 18/12/2019 10:25:28 AM

Vehicle:

Forester:

VIN: JF1SJ5KC5GG069160

Model:

16MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			07313	8200	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

<Automatic Light and Wiper : 0 piece>

<Combination Meter : 0 piece>

<Multi-function Display : 0 piece>

<Headlight / Foglight : 0 piece>

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R001985
 Name 2: NG GHEE CHUAN
 License: SLB8640Y
 Year: 16
 Technician: KUGAN
 Odometer: 78421
 Date: 19.12.19 11:06

Subaru : Forester : 2016-18 (SJ)
4-Wheel Total Alignment

