

REF: AG / CS / A1919021615 / K1f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: B

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

Part by Part 4128.06 Red. 2635.60 : 38%

Veh No: SLB 8640Y

Yr Regn: 04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester

c.c. 1995

Colour: M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 78.419

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TF1SJ5K C3 G4 009160

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 4/12/19

D.O.I. 9/12/19

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

O/S for body
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 11/5 Typist

Date/Time, File Return to?

2) _____



: Prel. Report



: Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

Survey Fee: 200

Transportation: _____

: S + RS. \$

: Extras

: Others

TOTAL

Report Format: 00

Lump Sum / I.B.I: (\$ 4128.06)

4128.06

200
11
211