

ASS. REC. BY:

REF: CS/C1219021616/uyf307

Special Instruction:

Surveyor: MitchASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

C12

Date/Time:

7.12.19 13.04 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 3227x

Insured:

GZ 4784A

at Workshop m/s

RICO 60 AUTO

Tel:

88112101

of

8 Kaki Bukit Ave 4 #02-24

Policy No:

DMCVS/103029119044

Claim No:

SVM19D705750C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.12.1910.09a.m

Person Contacted:

John Ong

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKL 3227x - xGZ 4784A - x

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 3237X

at Workshop m/s

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 19800

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: _____

Yes or No

Lum Sum: _____

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKL 3237X

Yr Regn: 27/7/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen

Scirocco c.c

Colour: Multicolour

A/C:

Insured / Std / NI / NA

Sp. Reading: 174368

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ13ZAV

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235-402R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 3/12/19

D.O.I. 9/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7th plus LTA @ 13609
agree max 6k.

27/12/19 Confirmed L/S \$6000 with John. (Red \$39,172-32, 86%)

MV = \$19800/-

LTA = \$13609/-

Nett = \$6191/-

RECEIVED 30 DEC 2015

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

27/12/19 Typist

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee: 220

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$ 6000/-)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2019		07 Dec 2019 13:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	THUNG YONG QIANG, JUSTIN, ID: S8838330C		
Vehicle Reg. No.:	SKL3237X	Date of Loss:	03/12/2019 09:00 - :59
Claim Type:	TP / SNM19D205750C02	Policy/Cover Note No.:	DMCVSN30281119044
Vehicle Reg. No. (Insured):	GZ4784A	Policy No. (Claimant):	5102531274-01
		Excess:	S\$0.00
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/12/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Saturday, 7 December, 2019 1:01 PM
To: Rico 60; assignments
Subject: RE: RE: OUR REF: SNM19D205750/GZ4784A/TKL- FW: PRI Arrangement for SKL 3237 X

WITHOUT PREJUDICE

Dear John,

We refer to your email dated 06.12.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Rico 60 [mailto:claims@rico60.com]
Sent: Friday, December 6, 2019 5:49 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: RE: OUR REF: SNM19D205750/GZ4784A/TKL- FW: PRI Arrangement for SKL 3237 X

Dear Sir,

Please have Kelvin Ang survey the said vehicle.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Tan Kah Leong

Sent: Friday, 6 December 2019 1:40 PM

To: claims@rico60.com

Subject: RE: OUR REF: SNM19D205750/GZ4784A/TKL- FW: PRI Arrangement for SKL 3237 X

Without Prejudice

Dear Shanelle,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, December 5, 2019 4:00 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; claims@rico60.com

Subject: OUR REF: SNM19D205750/GZ4784A/TKL- FW: PRI Arrangement for SKL 3237 X

Dear Kah Leong,

Please conduct PRS for SKL3237X.

Note: officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Enquiry [<mailto:claims@rico60.com>]

Sent: Thursday, 5 December, 2019 1:04 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: PRI Arrangement for SKL 3237 X

Dear all,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SKL 3237 X

Your Insured – GZ 4784 A

DOA – 03/12/2019

Thank you.

Best Regards,

Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2019 16:30
Date Of Accident	03/12/2019 09:00
Exact Location Of Accident	CTE(CITY) B4 BRADELL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL3237X
Insured/Policyholder	
Name Of Registered Owner	THUNG YONG QIANG, JUSTIN
NRIC No	S8838330C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82666662
Alternative Phone No	OTHERS-82666662

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SCIROCCO 1.4L AT TSI 1372Q5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102531274-01
Cover Note Number	

Driver

Name of Driver	THUNG YONG QIANG, JUSTIN
NRIC No	S8838330C
Date Of Birth	03/10/1988
Occupation	INDOOR
Date Of Driving Pass	16/07/2010
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82666662
Fax Number	
Contact Number	OTHERS-82666662
EMail Address	NOEMAIL

Address	BLK 465 #11-1060 ANG MO KIO AVENUE 10
Postcode	560465
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE LI HUI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20191203/2058;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ4784A
Vehicle Make/Model/Colour	MITSUBISHI / FB70ABOSRDEB
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD ISKANDAR
NRIC/Passport Number	S9125202C
Contact Number	87523241

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKV4578C

Vehicle Make/Model/Colour

VOLKSWAGEN / JETTA 1.4 TSI AT 1622G5

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KOH REN WEI (XU RENWEI)

NRIC/Passport Number

S8716976F

Contact Number

96683395

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

VEHICLE NO.: SXL 3337X
INSURER : NTUC
DATE & TIME: 03/12/2019 1000hrs

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IPAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492307

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:


Accident Sketch Plan

SKETCH PLAN

Vehicle A: SKL3237X

Vehicle B: GZ 4784A

Vehicle C: SKV4578C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report NO. T/20191203/2098

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
www.idac.com.sg

Reporting Centre Personnel's Signature
Name:
NR/CRN No:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191203/2058

1 of 4

Report No. T/20191203/2058

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/12/2019 12:58	Vide Report No.:	Station Diary No.: 96
--	------------------	--------------------------

Informant's Particulars

Name of Informant: THUNG YONG QIANG, JUSTIN			Address: APT BLK 465 ANG MO KIO AVENUE 10 #11-1060 SINGAPORE 560465		
ID Type / ID No.: NRIC NO / S8838330C			Contact No.: Home/Office: Mobile: 82658662		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 03/10/1988	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: RETAIL SALES			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/12/2019 10:00	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY Along CTE towards City before Braddell. Road towards Upper Serangoon, PIE Changi exit. On the 4th lane from the right.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GZ47B4A	Lorry	MITSUBISHI		White	Slightly Damaged	0
SKL3237X	Car	VOLKSWAGO N	SCIROCCO 1.4L AT TSI 1372Q5	White	Seriously Damaged	1
SKV4578C	Car	VOLKSWAGO N	JETTA	Black	Slightly Damaged	0

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191203/2058

2 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No. 1800-2519999

Report No. T/20191203/2058

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKL3237X	NTUC Income Insurance Co-Operative Limited	5102531274-01	27/07/2019	26/07/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MUHAMMAD ISKANDAR	ID No.	S9125202C
Related Vehicle	GZ4784A (Lorry)	Contact No.	87523241
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	THUNG YONG QIANG, JUSTIN	ID No.	S8838330C
Related Vehicle	SKL3237X (Car)	Contact No.	82666662
Hospital/Clinic	FAMILYCARE CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	LEE LI HUI	ID No.	S8934684C
Related Vehicle	SKL3237X (Car)	Contact No.	98889222
Hospital/Clinic	FAMILYCARE CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191203/2058

3 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20191203/2058

CONTINUATION OF REPORT

Driver Name	KOH REN WEI (XU RENWEI)	ID No.	S8716976F
Related Vehicle	SKV4578C (Car)	Contact No.	96683395
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 03/12/2019 at about 1000hrs, I was with my friend driving my car (purple Volkswagen Scirocco, bearing vehicle registration number SKL3237X) along CTE towards City before Braddell. I was on the 4th lane from the right, travelling on the road towards Upper Serangoon, PIE Changi exit. The traffic was heavy, a car in front of me (black Volkswagen Jetta, bearing vehicle registration number SKV4578C) came to a stop hence I applied brakes to stop.

When my car was stationary, suddenly I felt a collision from the rear. This caused my car to be pushed forward and the front of my car hit onto the rear of another car. I alighted from my car and saw it was a lorry (white Mitsubishi, bearing vehicle registration number GZ4784A) behind my car.

We exchanged particulars and took photographs of the accident. After which we drove off. I then towed my car away when I was at a smaller road.


Due to the accident, the rear door and rear bumper was dented in. The front bumper rear sustained scratches.

No Traffic Police or ambulance attended to the accident scene. I have a front camera installed in my car which recorded the accident. Due to the accident, I felt dizzy neck and shoulder pain. My passenger felt pain in her lower back. We both went to Familycare Clinic and Surgery and was given 3 days Medical Certificate from 03/12/2019 to 05/12/2019.

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T/20191203/2058

4 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999



Report No. T/20191203/2058

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 3 WEE SHUN QIANG, JOSEPH 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 03/12/2019 12:56
Officer In Charge Of Case: TP / AEIT /	Classification Of Case:
Contact No:	

Authentication Stamp
NP158



> Back to OneMotoring



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	330C
Vehicle Details	
Vehicle No.:	SKL3237X
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CAV199315
Chassis No.:	WVWZZZ13ZAV448937
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$23,881.00
Original Registration Date:	27 Jul 2010
First Registration Date:	27 Jul 2010
Transfer Count:	4
Actual ARF Paid:	\$23,881.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2020
PARF Rebate Amount:	\$11,940.00 ✓
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$26,102.00
COE Rebate Amount:	\$1,669.00
Total Rebate Amount:	\$13,609.00

The information contained herein is correct as at 05 Dec 2019

OK

**Toyota Owners please
come in!**

**Disc brakes vs Drum
brakes**

**[Spyshots] 2020 Genesis
GV80 by Hyundai**

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
[Hot Alfa Romeo Hatch!](#)


Direct Owner

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

« Back (1 2) Next »

Sort by Date Posted

20 results/page

30 vehicles

Volkswagen Scirocco

Basic Search



Price Any price **Depre** Any depre **Reg Date** 2010 to 2010 **Eng Cap** Any **Veh Type** All types
Fuel Any fuel **Mileage** Any **OMV** Any **Gear** Any Gear **Past Owners** Any
Category All categories **Scheme** All schemes **Dealer** Any Dealer **Location** Any **Status** Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status



Volkswagen Scirocco 1.4A TSI

\$23,000

\$9,730 /yr

28-Dec-2010

1,390 cc

105,000 km

Sports

Available

Consignment Code: A529. Flexible And Attractive Loan Available. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

CONSIGNMENT

Posted: 05-Dec-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI (New 5-yr COE)

\$39,800

\$7,950 /yr

16-Jul-2010

1,390 cc

80,000 km

Sports

Available

COE Specialist With More Than 200 Positive Reviews And 100% Immediate Loan Approval! Well Known For Its Two Doors Sporty Look That Comes With Luxurious Cinnamon Brown Leather Seats! Priced One Of The Lowest In The Market With The Best Engine And Gearbo...

PREMIUM AD

Posted: 02-Dec-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI

\$23,800

\$11,460 /yr

03-Dec-2010

1,390 cc

149,000 km

Sports

Available

Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appointment To Viewing.

PREMIUM AD

Posted: 02-Dec-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI (New 5-yr COE)

\$38,800

\$7,750 /yr

11-Mar-2010

1,390 cc

-

Sports

Available

The Perfect Ride For COE 5 Or 10 Years! Tip Top Condition Despite Its Age, No Wasted Trips To Our Showroom For Sure! We Provide Loan Packages For Both Bank And In House, We Do Up To 95% Loan Of The Car Price Available! Best Part Is With Competitive Current...

PREMIUM AD

United Motoring Pte Ltd

Posted: 01-Dec-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



BC Racing V1 Coilover

BC (VI) Coilovers for Volkswagen and BMW

More info about this product



Volkswagen Scirocco 2.0A TSI (New 10-yr COE)

\$66,800

\$6,670 /yr

08-Feb-2010

1,984 cc

-

Sports

Available

Looking For A Fun And Easy Drive Coupe? The Only One 2.0A Sunroof Producing 207Bhp Cum Full 'CHARACTERE' Bodykit Unit Look No Further! AA Trust Certified Quality Vehicle! This 207BHP Is The Ideal Car For All The Fun You Seek! Powerful 2.0L Engine That Is Quick...

PREMIUM AD

AA Trust Automotive

Posted: 01-Dec-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI (New 10-yr COE)

\$54,800

\$5,480 /yr

25-May-2010

1,390 cc

-

Sports

Available

1 Owner. Stock Condition. Never Done Modification Before. Sporty White With Luxurious Cinnamon Brown Leather Seats. Excellent Condition. View To Appreciate. Trade In Welcome. Loan Available, Guarantee Superb! See To Believe!

PREMIUM AD

Posted: 30-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen

Compare



Volkswagen Scirocco 1.4A TSI (New 5-yr COE)

\$34,800

\$6,950 /yr

20-Jan-2010

1,390 cc

Sports

Available

New 5 Years COE! Sporty Red, Vehicle In Excellent Condition! Regular Serviced And Maintenance By Owner. 100% In House Loan/ High Trade In. Call For Viewing. Option For 10 Years COE Available.

Posted: 30-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI

\$19,800

\$14,760 /yr

11-Jun-2010

1,390 cc

135,000 km

Sports

Available

Bought A New Car Coming Next Week. Selling Fast.

Posted: 29-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen

DIRECT OWNER



Volkswagen Scirocco 1.4A TSI (New 10-yr COE)

\$53,000

\$5,300 /yr

12-Mar-2010

1,390 cc

Sports

Available

Tastefully Done Up, Fantastic Condition, R Bodykit With CF Bonnet And Rear Spoiler. Staged 2 Tuned. Never Abused By Meticulous Owner. Option To Buy With 5 Years Renewal. Full Loan/Trade In Available. Call/WhatsApp Us For More Information.

Monster Motors Pte Ltd

Posted: 29-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen

PREMIUM AD



Volkswagen Scirocco 1.4A TSI (New 10-yr COE)

\$57,800

\$5,780 /yr

31-Mar-2010

1,390 cc

111,000 km

Sports

Available

Just Arrived! Well Maintained By Previous Owner And New Paintwork! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Posted: 26-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



Volkswagen Scirocco 1.4A TSI (New 10-yr COE)

\$55,900

\$5,590 /yr

09-Nov-2010

1,390 cc

130,145 km

Sports

Available

Smooth Engine, Gearbox And Interior In Showroom Condition! Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Ca...

Posted: 25-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 2.0A TSI (New 10-yr COE)

\$68,800

\$6,870 /yr

10-Aug-2010

1,984 cc

82,503 km

Sports

Available

Super Low Mileage, Only Done 82k Km, Best For COE Renewal. 1 Owner, Well Maintained By Owner. High Bank Loan/In House Loan, High Trade-In.

Posted: 25-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI (OPC) (New 10-yr COE)

\$54,800

\$5,480 /yr

14-Jan-2010

1,390 cc

115,000 km

Sports

Available

OPC Car With Low Mileage. Selling 10 Yrs COE With Normal Plate. Stock Condition. Never Done Modification Before. Sporty White With Luxurious Cinnamon Brown Leather Seats. Excellent Condition. View To Appreciate. Trade-In Welcome. Loan Available, Guarantee Super...

Posted: 24-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen

PREMIUM AD



Volkswagen Scirocco 1.4A TSI (New 10-yr COE)

\$55,500

\$5,550 /yr

17-Sep-2010

1,390 cc

133,000 km

Sports

Available

Some Say It Is An Icon Reborn. Good Looking, Well Built And Well Sorted Coupe With Power And Classless Appeal. Extensive Major Wear And Tear Replacement All Done Over The Past Few Months. Option To Buy With 5/10 Yr COE Available! Impressive Condition, Well Main...

Pang's Motor Trading Pte Ltd

Posted: 24-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen



Volkswagen Scirocco 2.0A TSI (New 10-yr COE)

\$67,000

\$6,690 /yr

10-Feb-2010

1,984 cc

146,000 km

Sports

Available

New Paintwork Done On May! Rare 6 Speed Wet Gearbox W/ Decent Mods. Buy And Drive With A Peace Of Mind. 6.7k Depre! Half Of Parf Unit. Definitely Worth Renewing This 2.0! Flexible Loan Available. Lowest Interest At 3.25% (maybank) Downpay 20k, Monthly Only \$68...

Posted: 23-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen

DIRECT OWNER



Volkswagen Scirocco 1.4A TSI (New 10-yr COE)

\$54,800

\$5,480 /yr

08-Feb-2010

1,390 cc

Sports

Available

Full Loan Available At \$900 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including...

88 Motor Trading

Posted: 20-Nov-2019

Tags: 2010 Volkswagen Scirocco, 2010 volkswagen scirocco, Volkswagen Scirocco, volkswagen scirocco, Volkswagen, Scirocco, scirocco, Used Volkswagen

Compare

Volkswagen Scirocco 1.4A

\$5,780 /yr

10-Aug-2010

1,390 cc

85,000 km

Sports

Available

ATTN:		CHASSIS NUM:			
NO.	DESCRIPTION - PARTS	QTY	PRICE		
1	BONNET	1	\$ 1,499.50		
2	BONNET LOGO (VOLKSWAGEN)	1	\$ 86.70		
3	BONNET INSULATOR	1	\$ 316.80		
4	BONNET HINGE (L+R)	2	\$ 550.80		
5	BONNET STOPPER (L+R)	2	\$ 108.40		
6	BONNET RUBBER STRIP	1	\$ 189.60		
7	HEADLAMP (L+R)	2	\$ 3,114.60		
8	HEADLAMP BRACKET (L+R)	2	\$ 426.40		
9	FRONT GRILLE	1	\$ 975.40		
10	FRONT BUMPER	1	\$ 1,460.80		
11	FRONT BUMPER RETAINER (L+R)	2	\$ 285.60		
12	FRONT BUMPER REINFORCEMENT BAR	1	\$ 950.40		
13	FRONT BUMPER BRACKET (L+R)	2	\$ 224.60		
14	FRONT BUMPER BEAM	1	\$ 436.40		
15	FRONT BUMPER SPONGE	1	\$ 416.70		
16	FRONT BUMPER GRILLE	1	\$ 433.70		
17	FRONT BUMPER TOP LAMP (L+R)	2	\$ 570.80		
18	FRONT BUMPER FOG LAMP (L+R)	2	\$ 775.80		
19	FRONT BUMPER FOG LAMP GARNISH (L+R)	2	\$ 482.20		
20	FRONT BUMPER LOWER (L+R)	2			
21	FRONT BUMPER UNDERCOVER	1	\$ 336.40		
22	FRONT FENDER (L+R)	2			
23	FRONT FENDER COWLING (L+R)	2			
24	FRONT SUPPORT PANEL	1	\$ 1,645.50		
25	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 539.60		
26	AIRCON CONDENSOR	1			
27	HIGH PRESSURE HOSE	1			
28	LOW PRESSURE HOSE	1			
29	RADIATOR	1			
30	SUCTION PIPE	1			
31	DISCHARGE PIPE	1			
32	RADIATOR FAN COWLING	1			
33	RADIATOR FAN BLADE	1			
34	RADIATOR FAN MOTOR	1			
35	WIPER WASHER TANK	1	\$ 404.50		
36	WIPER WASHER MOTOR	1	\$ 493.60		
37	REAR WINDSCREEN MOULDING	1			
38	TAILGATE	1			
39	TAILGATE THIRD BRAKE LAMP	1			
40	TAILGATE WIPER	1			

41	TAILGATE WIPER GARNISH	11 X	1		
42	TAILGATE WIPER MOTOR	11 X	1		
43	TAILGATE LOGO (VOLKSWAGEN)	11 X	1		
44	TAILGATE LOGO HANDLE	11 X	1	105.00	
45	TAILGATE LOCK	11 X	1	199.50	
46	TAILGATE LOCK CATCH	11 X	1		
47	TAILGATE INNER TRIM TOP (CENTER)	11 X	1		
48	TAILGATE INNER TRIM TOP (L+R)	11 X	2		
49	TAILGATE INNER TRIM BOTTOM	11 X	1		
50	TAILGATE HINGE (L+R)	11 X	2		
51	TAILGATE DAMPER (L+R)	11 X	2		
52	TAILGATE STOPPER (L+R)	11 X	2		
53	TAILGATE WEATHERSTRIP	11 X	1		
54	TAIL LAMP (L+R) @ 388.59	015 one lpc	12	777.18	1PC
55	TAIL LAMP PANEL (L+R)	11 X	2		
56	REAR BUMPER	11 X	1	1121.22	
57	REAR BUMPER RETAINER (L+R) @ 65.50	015 one lpc	12	131.00	1PC
58	REAR BUMPER REINFORCEMENT BAR	11 X	1	570.20	
59	REAR BUMPER BRACKET (L+R)	11 X	2		
60	REAR BUMPER BEAM RETAINER	11 X	1	142.65	
61	REAR BUMPER SPONGE	11 X	1		
62	REAR BUMPER CARPLATE LAMP (L+R)	11 X	2		
63	REAR BUMPER LOWER	11 X	1		
64	REAR BUMPER LOWER REFLECTOR (L+R)	11 X	2		
65	REAR BUMPER LOWER GRILLE (CENTER)	11 X	1		
66	REAR BUMPER LOWER GRILLE (L+R)	11 X	2		
67	REAR BUMPER UNDERCOVER	11 X	1		
68	REAR FENDER (L+R)	11 X	2		
69	REAR FENDER WINDOW MOULDING (L+R)	11 X	2		
70	REAR FENDER PETROL CAP (RH)	11 X	1		
71	REAR FENDER SIDE PROTECTOR (L+R)	11 X	2		
72	REAR FENDER INNER TRIM TOP (L+R)	11 X	2		
73	REAR FENDER INNER TRIM TOP SPEAKER (L+R)	11 X	2		
74	REAR FENDER INNER TRIM CENTER (L+R)	11 X	2		
75	REAR FENDER INNER TRIM BOTTOM (L+R)	11 X	2		
76	REAR FENDER COWLING (L+R) @ 184.00	015 one lpc	21	368	1PC
77	ROCKER PANEL (L+R)	11 X	2		
78	ROCKER PANEL GARNISH (L+R)	11 X	1		
79	END PANEL	11 X	1	933.20	
80	END PANEL TOP GARNISH	11 X	1		
81	SPAREWHEEL PANEL	11 X	1		
82	SPAREWHEEL PANEL TOP BOARD	11 X	1		
83	SPAREWHEEL PANEL TOP BOARD TOP MAT	11 X	1		
84	EXHAUST PIPE	11 X	1		
85	EXHAUST GASKET	11 X	1		
86	EXHAUST BRACKET (L+R)	11 X	2		
87	EXHAUST HEAT SHIELD	11 X	1		

		TOTAL		\$ 16,724.80
		LESS 10%		\$ 1,672.48
		PARTS TOTAL		\$ 15,052.32
	SPECIAL NETT	QTY	PRICE	
1	BONNET INSULATOR CLIPS	11 X	10	\$ 100.00
2	FRONT BUMPER CLIPS	per 50	10	\$ 100.00
3	FRONT CARPLATE	one 70	1	\$ 200.00
4	FRONT CARPLATE FRAME		1	\$ 120.00
5	FRONT FENDER COWLING CLIPS	11 X	10	\$ 100.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11 X	10	\$ 100.00
7	RADIATOR COOLANT	11 X	1	\$ 80.00
8	REAR WINDSCREEN SEALANT	per 40	1	\$ 120.00
9	TAILGATE SPOILER CARBON FIBRE	one 1000	1	\$ 6,000.00
10	TAILGATE INNER TRIM TOP CENTER CLIPS	11 X	10	\$ 100.00
11	TAILGATE INNER TRIM TOP CLIPS (L+R)	11 X	10	\$ 100.00
12	TAILGATE INNER TRIM BOTTOM CLIPS	11 X	10	\$ 100.00
13	TAIL LAMP CLIPS	11 X	4	\$ 80.00
14	REAR CARPLATE	one 70	1	\$ 200.00
15	REAR CARPLATE FRAME		1	\$ 120.00
16	REAR BUMPER CLIPS	per 50	10	\$ 100.00
17	REAR BUMPER REVERSE SENSOR SET	shared 200	2	\$ 300.00
18	REAR FENDER SEALANT	11 X	1	\$ 120.00
19	REAR FENDER WINDOW SEALANT	11 X	1	\$ 120.00
20	REAR FENDER INNER TRIM CLIPS TOP (L+R)	11 X	20	\$ 200.00
21	REAR FENDER INNER TRIM CLIPS CENTER (L+R)	11 X	20	\$ 200.00
22	REAR FENDER INNER TRIM CLIPS BOTTOM (L+R)	11 X	20	\$ 200.00
23	REAR FENDER COWLING CLIPS (L+R)	11 X	20	\$ 200.00
24	ROCKER PANEL SEALANT	11 X	1	\$ 120.00
25	ROCKER PANEL GARNISH CLIPS	11 X	20	\$ 200.00
26	END PANEL SEALANT	per 50	1	\$ 120.00
27	END PANEL TOP GARNISH CLIPS	11 X	10	\$ 100.00
28	SPAREWHEEL PANEL SEALANT	11 X	1	\$ 120.00
29	EXHAUST CHROME TIP SET	11 X	2	\$ 3,000.00
30	SPARE TYRE	11 X	1	\$ 800.00
31	SPARE RIM	11 X	1	\$ 1,000.00
		SPECIAL NETT TOTAL		\$ 14,520.00
	LABOUR	QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1500	1	\$ 6,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800	1	\$ 5,100.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	80	1	\$ 250.00
4	TO RNR REAR WINDSCREEN	120	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM	60	1	\$ 400.00
6	TO RNR REAR LUGGAGE COMPARTMENT	80	1	\$ 400.00
7	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS		1	\$ 600.00
8	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	11 X	1	\$ 250.00
9	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	\$ 150.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11 X	1	\$ 250.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2019		07 Dec 2019 13:04 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case






















































Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	THUNG YONG QIANG, JUSTIN, ID: S8838330C								
Vehicle Reg. No.:	SKL3237X	Date of Loss: 03/12/2019 09:00 - :59 [112 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D205750C02	Policy/Cover Note No.: DMCVSN30281119044							
Vehicle Reg. No. (Insured):	GZ4784A	Policy No. (Claimant): 5102531274-01							
	Excess:	S\$0.00							
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















Claim Documents

*SKL3237X (SNM19D205750C02)
[GZ4784A]
TP
THUNG YONG QIANG, JUSTIN
Dec 3 2019 9:00AM
[-]
RICO 60 AUTO SERVICES PTE LTD

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/12/19 17:51	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	09/12/19 17:51	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
23	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
24	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
25	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
26	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
27	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
28	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
29	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
30	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
31	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
32	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
33	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
34	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
35	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
36	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
37	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
38	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
39	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
40	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
41	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
42	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>
43	09/12/19 17:55	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/12/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	27/12/19 08:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	27/12/19 08:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	27/12/19 08:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	27/12/19 08:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	27/12/19 08:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	27/12/19 08:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	27/12/19 08:24	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/12/19 19:45	Accident Statement	 Load HTM	<input type="checkbox"/>
2	06/12/19 19:46	Accident Statement	 Load HTM	<input type="checkbox"/>
3	06/12/19 19:49	Accident Statement	 Load HTM	<input type="checkbox"/>
4	06/12/19 19:51	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	03/12/19 18:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	03/12/19 18:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	03/12/19 18:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	03/12/19 18:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
4	03/12/19 18:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
5	03/12/19 18:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
6	03/12/19 18:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; height: 40px; margin-bottom: 5px;"></div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119021616/UYF3E2

Date: 06/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30281119044
Claimant Vehicle No :	SKL3237X	Insured Vehicle No :	GZ4784A
Date of Loss:	03/12/2019	Nature of Claim: TP	Claim No: SNM19D205750C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL3237X	Engine No:	CAV199315
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WWZZZ13ZAV448937
Reg. Date:	27/07/2010 (Man. Year: 2010)	Odometer:	174368 km
Colour:	Multi-colour		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,854.91	7,477.86	27,377.05	78.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,600.00	3,780.00	11,820.00	75.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,454.91	11,257.86	39,197.05	77.69
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	50,454.91	6,000.00	44,454.91	88.11
+ GST 7.00/7.00% (S\$)	3,531.84	420.00	3,111.84	88.11
Nett Amount (S\$)	53,986.75	6,420.00	47,566.75	88.11

INSPECTION

Date of Assignment: 07/12/2019

Date Inspected: 09/12/2019 Inspected At:

RICO 60 AUTO SERVICES PTE LTD
(HQ)
8, KAKI BUKIT AVENUE 4, #02-24,
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2020)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL3237X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,499.50 FL	*- FL
2	1		*BONNET LOGO (VOLKSWAGEN)	Not Necessary	86.70 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	316.80 FL	*- FL
4	2		*BONNET HINGE (L+R)	Not Necessary	550.80 FL	*- FL
5	2		*BONNET STOPPER (L+R)	Not Necessary	108.40 FL	*- FL
6	1		*BONNET RUBBER STRIP	Not Necessary	189.60 FL	*- FL
7	2		*HEADLAMP (L+R)	Not Necessary	3,114.60 FL	*- FL
8	2		*HEADLAMP BRACKET (L+R)	Not Necessary	426.40 FL	*- FL
9	1		*FRONT GRILLE	Repair	975.40 FL	*- FL
10	1		*FRONT BUMPER	Dented / Deformed	1,460.80 FL	*1,180.65 FL
11	2		*FRONT BUMPER RETAINER (L+R)	Not Necessary	285.60 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT BAR	Repair	950.40 FL	*- FL
13	2		*FRONT BUMPER BRACKET (L+R)	Not Necessary	224.60 FL	*- FL
14	1		*FRONT BUMPER BEAM	Not Necessary	436.40 FL	*- FL
15	1		*FRONT BUMPER SPONGE	Torn	416.70 FL	*196.62 FL
16	1		*FRONT BUMPER GRILLE	Not Necessary	433.70 FL	*- FL
17	2		*FRONT BUMPER TOP LAMP (L+R)	Not Necessary	570.80 FL	*- FL
18	2		*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	775.80 FL	*- FL
19	2		*FRONT BUMPER FOG LAMP GARNISH (L+R)	Not Necessary	482.20 FL	*- FL
20	2		*FRONT BUMPER LOWER (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*FRONT BUMPER UNDERCOVER	Not Necessary	336.40 FL	*- FL
22	2		*FRONT FENDER (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
23	2		*FRONT FENDER COWLING (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL	Not Necessary	1,645.50 FL	*- FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	539.60 FL	*- FL
26	1		*AIRCON CONDENSOR (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*LOW PRESSURE HOSE (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*RADIATOR (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*SUCTION PIPE (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*DISCHARGE PIPE (NPA)	Not Necessary	0.00 FL	*- FL
31	1		*RADIATOR FAN COWLING (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*RADIATOR FAN BLADE (NPA)	Not Necessary	0.00 FL	*- FL
33	1		*RADIATOR FAN MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
34	1		*WIPER WASHER TANK	Not Necessary	404.50 FL	*- FL
35	1		*WIPER WASHER MOTOR	Not Necessary	493.60 FL	*- FL
36	1		*REAR WINDSCREEN MOULDING	Necessary	66.50 FL	*66.50 FL
37	1		*TAILGATE	Badly Dented	1,455.10 FL	*1,455.10 FL
38	1		*TAILGATE THIRD BRAKE LAMP (NPA)	Not Necessary	0.00 FL	*- FL
39	1		*TAILGATE WIPER (NPA)	Not Necessary	0.00 FL	*- FL
40	1		*TAILGATE WIPER GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
41	1		*TAILGATE WIPER MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
42	1		*TAILGATE LOGO (VOLKSWAGEN) (NPA)	Not Necessary	0.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*TAILGATE LOGO HANDLE	Necessary	105.00 FL	*105.00 FL
44	1		*TAILGATE LOCK	Twisted / Jammed	199.50 FL	*199.50 FL
45	1		*TAILGATE LOCK CATCH (NPA)	Not Necessary	0.00 FL	*- FL
46	1		*TAILGATE INNER TRIM TOP (CENTER) (NPA)	Not Necessary	0.00 FL	*- FL
47	2		*TAILGATE INNER TRIM TOP (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
48	1		*TAILGATE INNER TRIM BOTTOM (NPA)	Not Necessary	0.00 FL	*- FL
49	2		*TAILGATE HINGE (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
50	2		*TAILGATE DAMPER (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
51	2		*TAILGATE STOPPER (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
52	1		*TAILGATE WEATHERSTRIP (NPA)	Serviceable	0.00 FL	*- FL
53	1		*TAIL LAMP (L+R)	O/S Cracked	777.18 FL	*388.59 FL
54	2		*TAIL LAMP PANEL (L+R) (NPA)	Repair	0.00 FL	*- FL
55	1		*REAR BUMPER	Distorted	1,121.22 FL	*1,121.22 FL
56	1		*REAR BUMPER RETAINER (L+R)	O/S Bent	131.00 FL	*65.50 FL
57	1		*REAR BUMPER REINFORCEMENT BAR	Bent	570.20 FL	*570.20 FL
58	2		*REAR BUMPER BRACKET (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
59	1		*REAR BUMPER RETAINER	Cracked	142.65 FL	*142.65 FL
60	1		*REAR BUMPER SPONGE (NPA)	Not fitted	0.00 FL	*- FL
61	2		*REAR BUMPER CARPLATE LAMP (NPA)	Not Necessary	0.00 FL	*- FL
62	1		*REAR BUMPER LOWER (NPA)	Not fitted	0.00 FL	*- FL
63	2		*REAR BUMPER LOWER REFLECTOR (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
64	1		*REAR BUMPER LOWER GRILLE (CENTER) (NPA)	Not Necessary	0.00 FL	*- FL
65	2		*REAR BUMPER LOWER GRILLE (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
66	1		*REAR BUMPER UNDERCOVER (NPA)	Not Necessary	0.00 FL	*- FL
67	2		*REAR FENDER (L+R) (NPA)	Repair	0.00 FL	*- FL
68	2		*REAR FENDER WINDOW MOULDING (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
69	1		*REAR FENDER PETROL CAP (RH) (NPA)	Not Necessary	0.00 FL	*- FL
70	2		*REAR FENDER SIDE PROTECTOR (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
71	2		*REAR FENDER INNER TRIM TOP (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
72	2		*REAR FENDER INNER TRIM TOP SPEAKER (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
73	2		*REAR FENDER INNER TRIM CENTER (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
74	2		*REAR FENDER INNER TRIM BOTTOM (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
75	1		*REAR FENDER COWLING (L+R)	O/S Torn	368.00 FL	*184.00 FL
76	2		*ROCKER PANEL (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
77	1		*ROCKER PANEL GARNISH (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
78	1		*END PANEL	Badly Dented	933.20 FL	*933.20 FL
79	1		*END PANEL TOP GARNISH (NPA)	Serviceable	0.00 FL	*- FL
80	1		*SPAREWHEEL PANEL (NPA)	Repair	0.00 FL	*- FL
81	1		*SPAREWHEEL PANEL TOP BOARD (NPA)	Not Necessary	0.00 FL	*- FL
82	1		*SPAREWHEEL PANEL TOP BOARD TOP MAT (NPA)	Not Necessary	0.00 FL	*- FL
83	1		*EXHAUST PIPE (NPA)	Not Necessary	0.00 FL	*- FL
84	1		*EXHAUST GASKET (NPA)	Not Necessary	0.00 FL	*- FL
85	2		*EXHAUST BRACKET (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
86	1		*EXHAUST HEAT SHIELD (NPA)	Not Necessary	0.00 FL	*- FL
87	10		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
88	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
89	1		*FRONT CARPLATE }	Cracked	200.00 FS	*70.00 FS
90	1		*FRONT CARPLATE FRAME }		120.00 FS	*- FS
91	10		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
92	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
93	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
94	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
95	1		*TAILGATE SPOILER CARBON FIBRE	Cracked	6,000.00 FS	*1,000.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	10		*TAILGATE INNER TRIM TOP CENTER CLIPS	Not Necessary	100.00 FS	*- FS
97	10		*TAILGATE INNER TRIM TOP CLIPS (L+R)	Not Necessary	100.00 FS	*- FS
98	10		*TAILGATE INNER TRIM BOTTOM CLIPS	Not Necessary	100.00 FS	*- FS
99	4		*TAIL LAMP CLIPS	Not Necessary	80.00 FS	*- FS
100	1		*REAR CARPLATE }	Cracked	200.00 FS	*70.00 FS
101	1		*REAR CARPLATE FRAME }		120.00 FS	*- FS
102	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
103	2		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
104	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
105	1		*REAR FENDER WINDOW SEALANT	Not Necessary	120.00 FS	*- FS
106	20		*REAR FENDER INNER TRIM CLIPS TOP (L+R)	Not Necessary	200.00 FS	*- FS
107	20		*REAR FENDER INNER TRIM CLIPS CENTER (L+R)	Not Necessary	200.00 FS	*- FS
108	20		*REAR FENDER INNER TRIM CLIPS BOTTOM (L+R)	Not Necessary	200.00 FS	*- FS
109	20		*REAR FENDER COWLING CLIPS (L+R)	Not Necessary	200.00 FS	*- FS
110	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
111	20		*ROCKER PANEL GARNISH CLIPS	Not Necessary	200.00 FS	*- FS
112	1		*END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
113	10		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
114	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
115	2		*SET EXHAUST CHROME TIP	Not Necessary	3,000.00 FS	*- FS
116	1		*SPARE TYRE	Not Necessary	800.00 FS	*- FS
117	1		*SPARE RIM	Not Necessary	1,000.00 FS	*- FS
118	1		*HIGH PRESSURE HOSE (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **37,114.35** **8,138.73**
 - List Item Discount on L Items 10.00/10.00% (S\$) **2,259.44** **660.87**

Total Parts (S\$) **34,854.91** **7,477.86**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK & REALIGN	New	6,000.00	1,500.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	5,100.00	1,800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	80.00
4	TO RNR REAR WINDSCREEN	New	400.00	120.00
5	TO RNR REAR BOOT MECHANISM	New	400.00	60.00
6	TO RNR REAR LUGGAGE COMPARTMENT }	New	400.00	80.00
7	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS }	New	600.00	0.00
8	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	New	250.00	0.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
10	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS }	New	150.00	30.00
11	TO CHECK WIRING LAYOUT AND FRONT BUMPER TOP LAMP FUNCTION }	New	150.00	0.00
12	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	New	150.00	0.00
13	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	0.00
14	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	250.00	60.00
15	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE	New	600.00	0.00
16	TO DO WATER LEAK TEST	New	100.00	0.00
17	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	New	250.00	0.00
18	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	150.00	50.00
Gross Labour Cost (S\$)			15,600.00	3,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >