

22/03/2002

ASS. REC. BY:

REF:

C31A2G19021631/Hqf302

Special Instruction:

Surveyor: Huck Ann

ASSIGNMENT (Office)

From (Person): Winnie Fan

of A14

Date/Time: 9.0.19 2.31p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 5682T

Insured: SML 6370A

at Workshop m/s HL Car Care Service

Tel: 98339415

of Blk 2 Kati Bukit Ave 2 # 02-03 Auto Hub

Policy No: 999994242

Claim No: 9502645937SG

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.12.19 2.35p.m

Person Contacted: HL

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SML 6370A: X

GBF 5682T: X

Disguise survey - 10/12/19

9/12/19 → survey taken

10/12/19 → survey taken

16/12/19 → after put taken.

complete

ASS. REC. BY: H-ANN

REF: AIG

PRS

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: GBF 5682T  
 at Workshop m/s H2 car care service  
 of Blk 2 Kallie Bulent Ave 2  
 Insured: #02-05  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBF 5682T Yr Regn: 13/14/2016  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: T-DYNA c.c. 2982  
 Colour: Silver / orange A/C: . Insured / Std / NI / NA  
 Sp. Reading: 87704 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFAT35Y10K207049  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/R15C  
 R: 155/R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front AS Rear  
 R/Bal. 4 mm R/Bal. 4x2 mm 7/10  
 L/Bal. 4 mm 7/10 L/Bal. 4x2 mm  
 D.O.A. 7/12/19 D.O.I. 8/12/19  
 Survey held at H2 car care service

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>DAR → OK</u>
	<u>Repair days → 4 days</u>
<u>30/12/19</u>	<u>Submit DAR</u>
	<u>MV - 47000</u>
	<u>PV - 34327</u>
	<u>NV - 12600</u>

Date/Time, File Pass to? ☐ : Prell. Report

30/12/19 ☒ : Final Report

Date/Time, File Return to?

3

Report Form: DAR

Long Term / REJ: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Insp (\$)  
☐ : Weekend (\$)

Survey Fee: 180

Transportation: \_\_\_\_\_

S + RS: \_\_\_\_\_

Photos

Other

TOTAL

<u>180</u>
<u>11</u>
<u>191</u>

(10) Burn (11) Burned (12) burned (13) melted (14) cut (15) scratched  
(16) become (17) Shined (18) buried (19) hidden (20) Necessary  
(21) feeling (22) Form (23) he continued (24) the Working

## ACTION PLAN

(1) Place  $\sqrt{1}$  (1) Place  $\sqrt{1}$  (1) Place  $\sqrt{1}$

Aug. 1994

Vehicle No: GBF 5682 T

[illegible]

No of years:

Assessor:

41 - ANN

## Summer Lee (LKK Auto)

---

**From:** Fan, Winnie-LW <Winnie-LW.Fan@aig.com>  
**Sent:** Monday, 9 December, 2019 2:31 PM  
**To:** Admin A; assignments  
**Cc:** Fong, Andy-SY  
**Subject:** Aigencypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SML6370A AND GBF5682T ON 07/12/2019  
**Attachments:** 8632.19-001.pdf; 8632.19.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** ongshanllc@gmail.com <ongshanllc@gmail.com>  
**Sent:** Monday, December 9, 2019 1:58 PM  
**To:** Hor, Yinrul <Yinrul.Hor@aig.com>  
**Cc:** Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>  
**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SML6370A AND GBF5682T ON 07/12/2019

Dear Sirs,

We refer to the above matter and your email on the even date.

Kindly find enclose of our client's reply for your perusal.

Please let us hear from you soonest possible.

Thank you

Yours faithfully,

CM Chen

Ong & Shan LLC

# ONG & SHAN LLC

ADVOCATES & SOLICITORS  
COMMISSIONERS FOR OATHS  
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:  
Lawyer : [ongshanllc@gmail.com](mailto:ongshanllc@gmail.com)  
Secretary :

Please send all correspondences to:

- ☐ 101 Upper Cross Street #06-15B Singapore 058357  
Tel: 6536 7991 | Fax: 6536 7995  
☒ 184 Toa Payoh Central #02-364 Singapore 310184  
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.8632.19(HL)  
Your Ref : Your insured vehicle SML 6370A

9<sup>th</sup> December 2019

Heng Leasing Pte Ltd  
c/o AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Department)  
78, Shenton Way  
#07-16, AIG Building  
Singapore 079120

BY EMAIL

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS  
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)  
ROAD TRAFFIC ACCIDENT INVOLVING GBF 5682T & SML 6370A ON 07.12.2019 ALONG TAMPINES  
AVE 9 @ 1710 HRS**

We refer to the above matter and your fax of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

- |                          |                         |
|--------------------------|-------------------------|
| 1) Patrick Ng Kong Beng  | 6) Matthew Ng Yong Chin |
| 2) Jayson Liaw Leong San | 7) Ong Poh Meng         |
| 3) Loi Boon Juan         | 8) Tan Chin Suan        |
| 4) Lim Say Koon          | 9) Lee                  |
| 5) Ang Guea Kiang        | 10) Dennis Yap Teck Wee |

Name of workshop : M/s. HL Car Care Service Centre  
Address : Blk 2 Kaki Bukit Ave 2 #02-05 Kaki Bukit AutoHub  
Singapore 417921  
Contact person : Regina Tan  
Telephone : 9833-9415  
Fax no : 6746-6798

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single Joint Expert".

We will accordingly inform you who the "Single Joint Expert" is to facilitate your conduct of a pre-repair survey.

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-r

Yours faithfully,

Ong & Shan LLC

A LIMITED LIABILITY

**For Surveyor**

From M/s AIG Asia Pacific Insurance Pte Ltd  
Vehicle GBF 5682T inspected as follows by Name:

Before repair	Parts removed	After repair
Signature: _____	Signature: _____	Signature: _____
Date/ Time: _____	Date/ Time: _____	Date/ Time: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	605R
Vehicle Details	
Vehicle No.:	GBF5682T
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2657696
Chassis No.:	JTFAT35Y10K207049
Maximum Power Output:	-
Open Market Value:	\$24,946.00
Original Registration Date:	13 Dec 2016
First Registration Date:	13 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,002.00
COE Rebate Amount:	\$34,327.00
Total Rebate Amount:	\$34,327.00

The information contained herein is correct as at 10 Dec 2019

OK





Car (S) Pte Ltd

Posted: 29-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$42,500****\$6,990 /yr****08-Jan-2016****2,982 cc****124,248 km****Truck****Av****Fuel Type:** Diesel

1 Owner Only! Well Maintained, Comes With Canopy/ Full Check Plate. Excellent Condition! In House Loan Available. High Trade In Available. Call For More Enquiries!

Fu Yiap Motor Trading

Posted: 25-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$41,800****\$6,420 /yr****13-Jun-2016****2,982 cc****-****Truck****Av****Fuel Type:** Diesel

Good Condition! One Owner, Low Mileage, 10 Feet Lorry, Trade In Well Come, In House Loan Available. Fast Approval And Delivery.

Posted: 22-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$47,800****\$7,110 /yr****30-Aug-2016****2,982 cc****-****Truck****Av****Fuel Type:** Diesel

August 2016 Toyota Dyna 150D 10 Feet With Box Sliding Door, One Owner COE \$42,240/No Repair Needed/Come And Drop A Call Or Whatsapp Us Now!

Think One Automobile &amp; Trading

Posted: 22-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$44,800****\$7,110 /yr****30-Mar-2016****2,982 cc****-****Truck****Av****Fuel Type:** Diesel

View At Our Showroom Now! Cheapest In Market, 1 Owner Full Agent Serviced Unit! Reliable Manual Gear Train, Call Us Now!

Yes Motoring

Posted: 21-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Save up to  
**24%****Save on petrol with UOB One card!**

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!

**Toyota Dyna 150 3.0M****\$45,800****\$7,490 /yr****20-Jan-2016****2,982 cc****-****Truck****Av****Fuel Type:** Diesel

1 Owner Only! Accident Free, Immaculate Condition, No Repairs Needed, New Paintwork, New Servicing Done. Bank And In House Loan With Competitive Rate Available. Trade In Are Welcome. Call Us Now For Appointment.

Skylink Auto Pte Ltd

Posted: 20-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$57,800****\$8,600 /yr****30-Aug-2016****2,982 cc****91,232 km****Truck****Av****Fuel Type:** Diesel

NEW DECK DYNA! SPECIALLY CHANGE IT JUST FOR YOU! BRAND SPEAKS FOR ITSELF! ACCEPTABLE MILEAGE ACCEPTABLE PRICE! ONE OF THE RARE UNIT IN THE MARKET! SERVICING &amp; PAINTWORK DONE JUST FOR YOU! VARIOUS BANK AND IN HOUSE LOAN WITH CO...

Car (S) Pte Ltd

Posted: 16-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$39,800****\$6,250 /yr****21-Apr-2016****2,982 cc****-****Truck****Av****Fuel Type:** Diesel

New Paint, Well Kept. In House Loan Available.

Posted: 16-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$45,800****\$6,850 /yr****15-Aug-2016****2,982 cc****49,085 km****Truck****Av****Fuel Type:** Diesel

New Paint. Low Mileage. 1 Owner Only. In House Loan Available.

Posted: 13-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**Toyota Dyna 150 3.0M****\$39,800****\$6,330 /yr****24-Mar-2016****2,982 cc****70,876 km****Truck****Av****Fuel Type:** Diesel

Compare

ad: 12-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Receive up to \$S6,775 when you join OCBC Premier Banking


Learn

T&Cs apply

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an AdAdvertiser LoginWays of Selling

New 5 Years Renewal COE Toyota Vios 1.5A



2.88% P.A. \$0 Down, \$0 Admin,  
Monthly From \$438, 2 Yrs  
Warranty Engine n Gearbox  
GV Credit StarAd

Think One Automobile

NEW & USED  
COMMERCIAL VEHICLES









Browse by Category

Sort by Date Posted20 results/

16 vehicles

Toyota Dyna

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection	Toyota Dyna		Any	Any	2016	Any	Any	Any	Av
	Toyota Dyna	150 3.0M	\$44,800	\$6,800 /yr	12-Jul-2016	2,982 cc	-	Truck	Av
<b>Fuel Type:</b> Diesel Monthly Installment Only \$699 For This Reliable Toyota Dyna. Good In Condition, Comes With Retractable Canopy, High Trade In Available For Your Current Vehicle, High Loan Available. Call In Now To View On This Vehicle Before Is Gone.									
ABWIN Bus Pte Ltd									
Posted: 09-Dec-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$43,800	\$7,030 /yr	02-Mar-2016	2,982 cc	87,000 km	Truck	Av
<b>Fuel Type:</b> Diesel Engine And Gearbox In Excellent Condition! Low Mileage! High Trade In Value For Your Vehicle! In House Loan Available. Faster Call Our Friendly Sales Person For Viewing And Test Drive!									
KSL Automotive Pte Ltd									
Posted: 07-Dec-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$42,300	\$6,680 /yr	08-Apr-2016	2,982 cc	-	Truck	Av
<b>Fuel Type:</b> Diesel Cheapest In The Market! 1 Owner Only! Borneo Unit! Original Leather Seats! Reverse Sensors! Well Maintained By Previous Owner! The Most Reliable Japanese Workhorse Ever Made! COE Is On The Rise! Wait No Further! Insurance And Loan Available For Your One Stop C...									
Net Link Partners Pte Ltd									
Posted: 02-Dec-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$43,800	\$6,890 /yr	18-Apr-2016	2,982 cc	89,000 km	Truck	Av
<b>Fuel Type:</b> Diesel 1 Owner With Good Condition!Low Mileage, New Paint And New Leather Seats,Trade In More WelCome, In House Loan Available. Call Up Now For Viewing And Test Drive, Dont Miss.									
Posted: 02-Dec-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	<b>Infratint Films For Toyota Cars, from \$288</b> Infratint solar film package available from \$288. More info about this product								
	Toyota Dyna	150 3.0M	\$47,800	\$7,650 /yr	09-Mar-2016	2,982 cc	-	Truck	Av
<b>Fuel Type:</b> Diesel									
Posted: 30-Nov-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$45,800	\$7,450 /yr	01-Feb-2016	2,982 cc	-	Truck	Av
<b>Fuel Type:</b> Diesel Only! Well Maintained, Comes With Canopy/ Full Check Plate. Excellent Condition! In House Loan Available. High Trade In Call For More Enquiries!									

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 09/12/2019 08:42  
Date Of Accident 07/12/2019 17:10  
Exact Location Of Accident TAMPINES AVE 09  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF5682T  
**Insured/Policyholder**  
Name Of Registered Owner ORANGE CLOVE CATERING PTE LTD  
Co Reg No 200809605R  
Email Address NOEMAIL  
Mobile Phone No  
Alternative Phone No OFFICE-88760387

### Vehicle Particulars

Manufacturer TOYOTA  
Model TOYOTA DYNA 150 MANUAL

Actual Purpose for which vehicle was being used at the time of accident

Are you claiming under your own insurance policy for repair to your vehicle? No

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy YES  
Policy Number B 29121335 MKF

Cover Note Number

### Driver

Name of Driver LUMAPAS ORLANDO ANTAWAN  
Passport No/FIN G3348419X  
Date Of Birth 24/07/1989  
Occupation OUTDOOR  
Date Of Driving Pass 03/01/2018  
Driving Experience 1 YEAR AND 11 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-87795318  
Fax Number  
Contact Number  
Email Address NOEMAIL

Address 1 KAKI BUKIT ROAD 1 #05-03/04 ENTERPRISE ONE  
 Postcode 415934  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : VIRAY  
 GENDER: : MALE

#### Details of Police Action

the accident reported to the police? NO  
 Is, Please state which Police Station  
 Was notice of intention of Prosecution given? NO  
 by whom?

#### Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION. STOP WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN. WHILE STOPPING THAT IS WHEN VEHICLE (SML6370A) UNABLE TO STOP ON TIME AND THUS THE COLLISION TOOK PLACE. MY VEHICLE REAR WITH HIS FRONT PORTION WHICH RESULTED TO SUSTAIN DAMAGED.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF VEHICLE PROPERTY 1

Vehicle Registration Number SML6370A  
 Vehicle Make/Model/Colour HONDA / FREED HYBRID 1.5G AUTO  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver AHMAD YAZID BIN ZAINAL ABIDIN  
 NRIC/Passport Number S7513150Z  
 Contact Number 87977149  
 Address BLK 420 WOODLANDS STREET 41 #07-199  
 Postcode 730420  
 Insurance Company Name

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4 #02-02  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@vicom.com.sg](mailto:vackb@vicom.com.sg)

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

9 DEC 2019

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-file

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

-9 DEC 2019



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2019 <a href="#">Edit Reg</a>		09 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	HENG LEASING PTE LTD, Co. Reg. No.: 201840603E		
Main Claimant:	ORANGE CLOVE CATERING PTE LTD, Co. Reg. No.: 200809605R		
Vehicle Reg. No.:	GBF5682T	Date of Loss:	07/12/2019 17:00 - :59 [35 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9502645937SG	Policy/Cover Note No.:	0999994242 (Comprehensive)
Vehicle Reg. No. (Insured):	SML6370A	Policy No. (Claimant):	
		Excess:	
Repairer:	HI Car Care Service Centre (Kaki Bukit) Blk 2 Kaki Bukit Ave 2, #02-05 Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 98339415		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 19/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (12/12/2019): TP GIA report










































ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)
















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

\*GBF5682T (9502645937SG)  
[SML6370A]  
TP  
ORANGE CLOVE CATERING PTE LTD  
Dec 7 2019 5:00PM  
[HENG LEASING PTE LTD]  
HI Car Care Service Centre

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	28/12/19 09:07	Chassis Number														Load JPG	<input checked="" type="checkbox"/>			
2	28/12/19 09:07	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>			
3	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
4	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
5	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
6	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
7	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
8	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
9	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
10	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
11	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
12	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
13	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
14	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
15	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
16	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
17	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
18	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
19	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
20	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
21	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
22	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
23	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
24	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
25	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
26	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
27	28/12/19 09:07	General View														Load JPG	<input checked="" type="checkbox"/>			
28	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
29	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
30	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
31	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
32	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
33	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
34	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
35	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
36	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
37	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
38	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
39	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
40	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
41	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
42	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			
43	28/12/19 09:08	General View														Load JPG	<input checked="" type="checkbox"/>			



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/12/19 09:08	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	28/12/19 09:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	28/12/19 09:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
80	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
81	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
82	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
83	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
84	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
85	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
86	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
87	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
88	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
89	28/12/19 09:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	28/12/19 09:09	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
91	28/12/19 09:09	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
92	28/12/19 09:09	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/12/19 15:41	OI GIA REPORT	 Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19021631/HQF3E2  
Date: 31/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994242  
Claimant Vehicle No : GBF5682T Insured Vehicle No : SML6370A  
Date of Loss: 07/12/2019 Nature of Claim: TP Claim No: 9502645937SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF5682T  
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2657696  
Reg. Date: 13/12/2016 (Man. Year: 2016) Chassis No: JTFAT35Y10K207049  
Colour: Orange/Silver Odometer: 2982 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C (D)  
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4/4 mm  
Front Right Side: Bridgestone 4 mm Rear Right Side: Yokohama 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/12/2019  
Date Inspected: 08/12/2019 Inspected At: HI Car Care Service Centre (Kaki Bukit)  
Blk 2 Kaki Bukit Ave 2, #02-05 Kaki Bukit AutoHub  
Singapore 417921  
Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*REAR NUMBER PLATE BRACKET	Repair	0.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
4	1		*SET REVERSE SENSOR	Shorted	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
7	1		*REAR RH TAILLAMP PANEL	Repair	0.00 F	*- F
8	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
9	1		*TAIL GATE L/H	Bent	0.00 F	*- F
10	1		*TAIL GATE ALUMINIUM PLATE L/H	Necessary	0.00 F	*- F
11	1		*TAIL GATE R/H	Bent	0.00 F	*- F
12	1		*TAIL GATE ALUMINIUM PLATE R/H	Necessary	0.00 F	*- F
				Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >