



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19021643/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 07-08-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 6835Z	Veh. Inspected	SKZ 3039C
Policy No.	GA226064/01	Coverage (\$)	0.00
Claim No.	S9M029DL	Excess (\$)	0.00
Assign From		Assign Date	10/12/2019

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAFZ411MF5534253	Colour	WHITE
Odometer	107593	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/12/2019	Inspection Date	10/12/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------