

2019/12/07

REF: CS/CY 19/12/658/09 B12 Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

Signature: [Signature]
 Date/Time: [Signature]

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMF 3082 H Insured: SKW 51482

at Workshop m/s Zoom Auto works Winefair Tel: 92705882

of BIK 15 kaki Bukit Rd 4 # 01-53

Policy No: DMPCSN 30247119033 Claim No: SNM19D 205842

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 7.12.2019

CA / REV / REP. / REV 24 HRS mp

Date/Time: 9.12.19 357p.m Person Contacted: Jeremy H.O.D. Endorsement: Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMF 3082H - X
	SKW 51482 - CS/CY 19/12/658/09/ KyC 302 DCA 20/07/2019

ASS. REG. BY:

REF: CT1

MARCUS

ASSIGNMENT

From:

Date: 10.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 3082H

at Workshop m/s Zoom Automotiks Ninetree

of BIC 15 Kaki Bukit Rd 4 #01-53

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WOP

7153
Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMF 3082H

Yr Regn:

11.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

or

Make:

Toyota Corolla Altis 1598

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

17256

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MROF3RTH 604592388

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

7/12/19

D.O.I.

10/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/12/19 1/5 \$4500 contact with skin (red \$6369.40, 59%)

RECEIVED 26 DEC 2019

Date/Time, File Pass to?

☐

: Prel. Report

11/12/19

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$1

Phone:

Other:

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format:

mer-Tp

Lump Sum / P.P.T.:

4500

220

Summer Lee (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 9 December, 2019 3:54 PM
To: assignments
Subject: FW: OUR REF: SNM19D205842/SKW5148Z/BEN - Pre-Repair Inspection for SMF 3082 H // Accident on 7/12/2019 @ 22:40HR at along PIE (Tuas) After Eng Neo, involving Vehicle Number SMF 3082 H and SKW 5148 Z

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SMF3082H.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Nineteen Autowerks <nineteenautowerks@gmail.com>
Sent: Monday, December 9, 2019 3:20 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205842/SKW5148Z/BEN - Pre-Repair Inspection for SMF 3082 H // Accident on 7/12/2019 @ 22:40HR at along PIE (Tuas) After Eng Neo, involving Vehicle Number SMF 3082 H and SKW 5148 Z

Hi Ben,

Kindly appoint LKK Marcus for the survey.

Thank you.

On Mon, 9 Dec 2019 at 3:02 PM, Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Google Home.

Hands-free help around the house.

\$169

Buy now

Free delivery.

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Cheapest In The Market! 2017 Toyota Dyna At \$48800



Cheapest In The Market! Tip:
Top Condition! One Owner Only!
Still Under Warranty!
Net Link Partners - StarAd.

Republic Auto

CERTIFIED PRE-OWNED

MERCEDES BENZ



VIEW OUR CARS

Browse by Category

Back (1 2 3) Next >

Sort by Date Posted

20 results/page

42 vehicles

Corolla

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Corolla		Any	Any	2017	Any	Any	Any	Available



Toyota Corolla Fielder Hybrid 1.5A G

\$68,800

\$8,590 /yr

29-Aug-2017

1,496 cc

50,209 km

Stationwagon

Available

Fuel Type: Petrol-Electric

Special Offer Till 31 December Only. Vehicle Viewing At AML Building. G Model With Keyless Entry/Start, Low Fuel Consumption At 27km...

Posted: 10-Dec-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Classic

\$65,000

\$8,000 /yr

04-Jan-2017

1,598 cc

54,500 km

Sedan

Available

Only \$1k Depreciation! Guaranteed Cheapest Toyota Altis In The Market! Agent Maintained Previously, Genuinely Low Mileage Of 54500...

Posted: 09-Dec-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$71,050

\$8,110 /yr

21-Jun-2017

1,598 cc

67,245 km

Sedan

Available

Low Depreciation, High Loan, Bank Loan, In House Loan Are All Available Now! Call Us Now For A Viewing!

Posted: 09-Dec-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$73,800

\$8,230 /yr

28-Dec-2017

1,598 cc

18,000 km

Sedan

Available

Latest Facelift! 1 Careful Owner! Full Agent Maintained With Records! 5 Years Agent Warranty And Servicing! Cheapest Depreciation In...

Golden Charter Pte Ltd

Posted: 08-Dec-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Front Grille (With Chrome)
08 above 2 piece.
More info about this product



Toyota Corolla Altis 1.6A Elegance (OPC)

\$62,800

\$7,000 /yr

27-Jun-2017

1,598 cc

26,694 km

Sedan

Available

1 Owner! High Specs Elegance Model With Push Start And Electric Seat! Warranty Under Borneo Unit, Fully Agent Serviced And Maintain...

Posted: 08-Dec-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance

\$71,800

\$8,230 /yr

12-Jun-2017

1,598 cc

84,609 km

Sedan

Available

Rare, 50th Anniversary Edition! Sporty Black Altis 1.6A, Elegance Model. Serviced At Borneo Motors With Proof/Valid Warranty. Last On...

Lake View Credit Pte Ltd

Posted: 08-Dec-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 715B

Vehicle Details

Vehicle No.: SMF3082H

Vehicle to be Exported: No

Intended Deregistration Date: 10 Dec 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 STANDARD (AUTO)

Primary Colour: Grey

Manufacturing Year: 2018

Engine No.: 1ZR0C55564

Chassis No.: MR053REH604592388

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$19,741.00

Original Registration Date: 01 Nov 2018

First Registration Date: 01 Nov 2018

Transfer Count: 0

Actual ARF Paid: \$19,741.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 31 Oct 2028

PARF Rebate Amount: \$14,805.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$33,798.00

COE Rebate Amount: \$30,045.00

Total Rebate Amount: \$44,850.00

The information contained herein is correct as at 10 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2019 16:19
Date Of Accident	07/12/2019 22:40
Exact Location Of Accident	PIE(TUAS) AFTER ENG NEO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF3082H
Insured/Policyholder	
Name Of Registered Owner	WANG CHUNYAN
NRIC No	S2727715B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90616820
Alternative Phone No	OTHERS-90616820

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.8 STANDARD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA507107/1
Cover Note Number	

Driver

Name of Driver	YU HONGYI
NRIC No	S9473768J
Date Of Birth	16/01/1994
Occupation	INDOOR
Date Of Driving Pass	15/07/2015
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90616820
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	443B FAJAR ROAD #14-78 SPORE 672443
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW5148Z
Vehicle Make/Model/Colour	B.M.W. / 220i COUPE SR HID NAV
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLV2813A
-----------------------------	----------

Vehicle Make/Model/Colour	SUBARU / FORESTER 2.0XT CVT AWD SR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJP4284T
Vehicle Make/Model/Colour	HONDA / FIT 1.3G A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to open up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the issuance of this report to the driver, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurers, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *J. L. N.*
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN

PIE (THAS) AFTER ENG NEO



A → SMF 3082 H

B → SKW 5148 Z

C → SLV 2813 A

D → STP 4284 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time & date, I was travelling in my vehicle,
bearing (SMF 3082 H) on lane 5 of PIE (THAS) after Eng
Neo. As the front vehicle stopped, I managed to stop in time.
Suddenly I felt a huge impact from the rear. I realised that
I got into a chain collision with 3 other vehicles, bearing
(SKW 5148 Z), (SLV 2813 A), (STP 4284 T). We
exchanged particulars and decided to proceed with insurance
claim.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *[Signature]*
SPAC/IRIN No.:



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5883
nineteenautowerks@gmail.com

10 December 2019

REG NO.: SMF 3082 H
MAKE/MODEL: TOYOTA COROLLA ALTIS

Not Authorised
Star
d/s #4500
Salary 10/12/19
the price of this repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ 11 156.80 X
1	Rear boot lid	sent/\$ 566 985.70 ✓
2	Rear boot hinges	\$ 11 171.40 X
2	Rear boot lamps	\$ 11 577.40 X
1	Rear boot lock	\$ 7w1 100.80 ✓
1	Rear boot logo	\$ 2w 89.70 ✓
1	Rear boot "COROLLA" emblem	\$ 2w 80.30 ✓
1	Rear boot "ALTIS" emblem	\$ 2w 75.70 ✓
1	Rear boot outer chrome moulding	\$ 11 288.50 X
2	Rear taillamps	\$ 2w 760.20 ✓
2	Rear taillamp panels	\$ 2w 775.40 X
1	Rear end panel	\$ 5w 6m 777.40 ✓
1	Rear end panel inner garnish	\$ 7w1 200.30 ✓
1	Rear keyless sensor	\$ 11 185.20 X
1	Rear bumper	\$ 2w 488.70 ✓
2	Rear bumper top brackets	\$ 11 181.80 X
2	Rear bumper side brackets	\$ 11 97.00 X
2	Rear bumper reflectors	\$ 11 120.20 X
1	Rear bumper reinforcement	\$ 3w 344.70 ✓
2	Rear bumper reinforcement stays	\$ 11 161.00 X
2	Rear bumper side retainers	\$ 3w 130.00 ✓
2	Rear bumper PDC sensors	\$ 3w 390.00 2005.20
1	Rear spare tyre board	\$ 7w1 363.50 ✓
1	Rear fender	\$ 2w 1,120.70 X
2	Rear fender inner trims	\$ 11 670.80 X
		\$ 9,293.20
	Less 25%	\$ 2,323.30
		\$ 6,969.90
<u>SPECIAL NETT ITEMS</u>		
1	Rear windscreen sealant	\$ 11 80.00 X
1	Rear bumper clip (1 set)	\$ 2w 50.00 40
1	Rear number plate with holder	\$ 11 50.00 X
		\$ 180.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119021658/UQF3N2

Date: 30/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30297119033
Claimant Vehicle No :	SMF3082H	Insured Vehicle No :	SKW5148Z
Date of Loss:	07/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D205842

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3082H	Engine No:	1ZR0C55564
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH604592388
Reg. Date:	01/11/2018 (Man. Year: 2018)	Odometer:	17256 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,149.90	3,488.10	3,661.80	51.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	2,160.00	1,560.00	41.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,869.90	5,648.10	5,221.80	48.04
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	10,869.90	4,500.00	6,369.90	58.60

INSPECTION

Date of Assignment:	26/12/2019	Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE Singapore 417808
Date Inspected:	10/12/2019 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF3082H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	156.80 FL	*- FL
2	1		*REAR BOOT LID	Bent/Buckled	985.70 FL	*985.70 FL
3	2		*REAR BOOT HINGES	Not Necessary	171.40 FL	*- FL
4	2		*REAR BOOT LAMPS	Not Necessary	577.40 FL	*- FL
5	1		*REAR BOOT LOCK	Twisted	100.80 FL	*100.80 FL
6	1		*REAR BOOT LOGO	Necessary	89.70 FL	*60.80 FL
7	1		*REAR BOOT COROLLA EMBLEM	Necessary	80.30 FL	*60.20 FL
8	1		*REAR BOOT ALTIS EMBLEM	Necessary	75.70 FL	*58.50 FL
9	1		*REAR BOOT OUTER CHROME MOULDING	Not Necessary	288.50 FL	*- FL
10	2		*REAR TAILLAMPS	Cracked	760.20 FL	*760.20 FL
11	2		*REAR TAILLAMP PANELS	Repair	775.40 FL	*- FL
12	1		*REAR END PANEL	Badly Dented	777.40 FL	*777.40 FL
13	1		*REAR END PANEL INNER GARNISH	Twisted	200.30 FL	*200.30 FL
14	1		*REAR KEYLESS SENSOR	Not Necessary	185.20 FL	*- FL
15	1		*REAR BUMPER	Dented	488.70 FL	*488.70 FL
16	2		*REAR BUMPER TOP BRACKETS	Not Necessary	181.80 FL	*- FL
17	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	97.00 FL	*- FL
18	2		*REAR BUMPER REFLECTORS	Not Necessary	120.20 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	344.70 FL	*344.70 FL
20	2		*REAR BUMPER REINFORCEMENT STAYS	Not Necessary	161.00 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 FL	*130.00 FL
22	1		*REAR SPARE TYRE BOARD	Torn	363.50 FL	*363.50 FL
23	1		*REAR FENDER	Repair	1,120.70 FL	*- FL
24	2		*REAR FENDER INNER TRIMS	Not Necessary	670.80 FL	*- FL
25	2		*REAR BUMPER PDC SENSORS	Shorted	390.00 FN	*200.00 F
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
28	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (\$\$)	9,473.20	4,570.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,225.80	1,082.70
- Nett Item Discount on N Items 25.00/0.00% (\$\$)	97.50	0.00
Total Parts (\$\$)	7,149.90	3,488.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO TRANSFER REAR BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO APPLY UNDERCOATING	New	150.00	60.00
6	PANEL BEATING	New	1,600.00	700.00
7	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,180.00
Gross Labour Cost (\$\$)			3,720.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >