

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
AXA INSURANCE PTE LTD		Ref: CC4/ASM19011216/Epa3s2-1				
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date: 09-03-2020				
ATTN: XIN YOU		Code: ASM				
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)						
Insured Veh.	SMA 6167D	Veh. Inspected	SKA 7195P			
Policy No.	P2145121	Coverage (\$)	0.00			
Claim No.	S9M01RN1	Excess (\$)	0.00			
Assign From		Assign Date	10/12/2019			
2. Vehicle Particulars & Condition						
Make & Model	TOYOTA WISH	c.c	1798			
Engine No.	HIDDEN	Year of Reg.	2011			
Chassis No.	JTDGG20W405001682	Colour	WHITE			
Odometer	350917	Steering	IN ORDER			
Brakes	IN ORDER	Modification	SPORTS RIM			
General	FAIR					
3. Conditions of Tyres						
	Size	Make	Balance			
R/H Front Tyre	195/65 R15	DUNLOP	5 mm			
L/H Front Tyre	195/65 R15	DUNLOP	5 mm			
R/H Rear Tyre	195/65 R15	DUNLOP	5 mm			
L/H Rear Tyre	195/65 R15	DUNLOP	5 mm			
4. Description of Damages						
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.						
REPAIR CONDITION SEE DETAILS.						
5. General Information						
Accident Date	24/06/2019	Inspection Date	28/02/2020			
Survey held at	TWINCAR AUTOMOTIVE PTE L	TD				
	2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921					
5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair						

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: