

CC3/TM19021685/Fsp302

ASSIGNMENT

Name:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHA 6953K

Yr Regn: 23/04/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i40

C.C 1685

Colour: blue

A/C: Insured / Std / NI / NA

Sp. Reading: 62566.3

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHLB81UMEU053679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 05/12/19

D.O.I. 9/12/19

Survey held at comfort+delgro (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO Policy

SHA 6953K - NA / N (0905312) / V1

12CA - 10/07/2019

SJP 13014 - X

10/12/19 @ 16:11 pm received PA to Fong Gan V's mmm
L/S: \$2800/- with 3 repair days (\$1,659.68 Red - 37%)
confirm on 23/12/19 with Lim Kwok ENG.

RECEIVED 24 DEC 2019

24/12/2019

Date/Time, File Pass to?

24/12/19

Date/Time, File Return to?

Typist



Prel. Report



Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Other (\$

Survey Fee: 290

Transportation:

S + RS: \$

Photos

Other

11

261

Pay on Form 4

Total Cost: \$2,800/- 4/5


Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: JC NO.: 305361886

MEMBER NO. 7010045	REGN NO.: SHA6953K	MILEAGE
SS 383 SIN MING DRIVE	MAKE: HYUNDAI	FUEL
Singapore SINGAPORE 575717	MODEL I-40	E.....1/2.....F
65508755 (O)	YR OF MANU. 23.04.2014	DATE/TIME IN 09.12.2019 09:40
(P)	CHASSIS CODE KMHLB41UMEU053679	TARGET DATE
UNT CARD NO.		COMPLETION DATE/TIME:

To the Marine

Accident Date: 05.12.2019
NATURE: 3P 05.12.2019

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
		

ED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Signature Slip	Exit Pass
SHA6953K LKE	Vehicle No.: SHA6953K
Signature/Date	Name of Service Advisor
Signature/Date	Date
med to Service Reception upon collection	To be kept by Security Guard

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fiona Gan Bee Song

Date: 10 Dec 2019

Preliminary Advice

Insured Vehicle No	: SJP1301Y	Accident Date	: 05/12/2019
TP Vehicle No	: SHA6953K	Assignment Date	: 10/12/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 3 days
Date of Inspection	: 09/12/2019		
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,470.68
Revised Amount	:S\$	3,500.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,500.68

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2019 11:29
Date Of Accident	05/12/2019 19:00
Exact Location Of Accident	KEAT HONG CAMP CARPARK DROP OFF POINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA6953K
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	CHIN KAT HWANG
NRIC No	S1810943C
Date Of Birth	14/11/1952
Occupation	OUTDOOR
Date Of Driving Pass	07/12/1973
Driving Experience	45 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90818478
Fax Number	
Contact Number	
Email Address	CHEN2081103@GMAIL.COM

Address	BLK 208 YISHUN STREET 21 #11-103
Postcode	760208
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : 3P REVERSE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP1301Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	REAR RIGHT
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHIN KAT HWANG
Approximate Age	67
Injuries Sustain	BACK OUT
Injured person in which vehicle?	SHA6953K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821K

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/RC Sketch/PlanForm_V5



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5/12/2014 at about 1900hrs, I vehicle A was driving my taxi along Keat Hong Camp carpark drop-off point when I park my taxi at the pick up point to waiting for my passenger. Vehicle B reverse his vehicle. Collided onto my taxi right near porton. After he hit my taxi I was back out for few second.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO: 199303821K

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.:

COMFORT Insurance Form 1/1



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6953K

DATE 9/12/2019 15:34

MAKE :

MODEL : HYUNDAI i40

Lee

Tolgi Marm

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X (R)			\$ 553.00
	Rear Bumper Clip 10 pcs Xnn			\$ 22.00
	Rear Wheel Hub Cap, RH scr			\$ 107.10
	Rear Door (RH) DD			\$ 2,201.10
	Rocker Panel Outer Garnish (RH) scr			\$ 341.40
	SUB TOTAL			\$ 3,224.60
	LESS 20%			\$ 644.92
	DISCOUNTED TOTAL			\$ 2,579.68 2119.68
	Rear Bumper Advertisement Logo nec			\$ 50.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) nec			\$ 80.00 Nett
	Rear Door Advertisement Logo (RH) nec			\$ 100.00 Nett
				\$ 230.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 600.00 \$560
	Spray Painting Charge			\$ 750.00 \$500
	Wiring Charge			\$ 50.00 Xnn
	Remove/Refix Reverse Sensor			\$ 80.00 Xnn
	Transfer of Door			\$ 120.00 \$80
	Rear Wheel Alignment			\$ 50.00 Xnn
	TOTAL LABOUR			\$ 1,650.00
	ESTIMATE TOTAL			\$ 4,459.68
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No 305361886Date : 21.12.19ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr RAMVehicle Reg No. SHA6953K CTPL05.12.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJP1301Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges


Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%\$2,800.00**Final Lumpsum Repair cost**\$2,800.00*pic
attached*3. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156Signature : Name : RamDate : 23/12/19**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO: SHA 6953K

DATE 9/12/2019 15:34

MAKE :

Lle

Tokio Ma

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X(R)</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>Xnn</i>			\$ 22.00
	Rear Wheel Hub Cap, RH <i>scr</i>			\$ 107.10
	Rear Door (RH) <i>DD</i>			\$ 2,201.10
	Rocker Panel Outer Garnish (RH) <i>scr</i>			\$ 341.40
	SUB TOTAL		<i>2,649.60</i>	\$ 3,224.60
	LESS 20%		<i>-20%</i>	\$ 644.92
	DISCOUNTED TOTAL		<i>2,119.68</i>	\$ 2,579.68
	Rear Bumper Advertisement Logo <i>nee</i>			\$ 50.00
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>nee</i>		<i>230</i>	\$ 80.00
	Rear Door Advertisement Logo (RH) <i>nee</i>			\$ 100.00
				\$ 230.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 600.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	Transfer of Door			\$ 120.00
	Rear Wheel Alignment			\$ 50.00
	<i>Meriman charge</i>			\$ 4.00
	TOTAL LABOUR		<i>1,151</i>	\$ 1,650.00
	ESTIMATE TOTAL		<i>3,500.68</i>	
			<i>-20%</i>	
			<i>2,800.54</i>	\$ 4,459.68

RAM(LKC)
9/12/19 1530hrs

Parasuram@LKKauto.com
88622778 hp

3 repair days

418 #2,800

add repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/12/2019
Vehicle Reg. No.:	SHA6953K	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	23/04/2014
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDDU395893	Chassis No:	KMHLB41UMEU053679
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/12/2019
Vehicle Reg. No.:	SHA6953K	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	23/04/2014
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDDU395893	Chassis No:	KMHLB41UMEU053679
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	2,809.68
Miscellaneous Items	11.00
Labour	1,650.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,470.68
+ GST 7.00% (S\$)	312.95
Nett Amount (S\$)	4,783.63

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 09 Dec 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA6953K/09/12/2019 17:57**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*553.00 FL XR
2	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL XNN
3	1		*REAR WHEEL HUB CAP RH	20.00	0.00	*107.10 FL /SLR
4	1		*REAR DOOR RH	20.00	0.00	*2,201.10 FL /DD
5	1		*ROCKER PANEL OUTER GARNISH RH	20.00	0.00	*341.40 FL /SLR
6	1		*REAR BUMPER ADVERTISEMENT LOGO	0.00	0.00	*50.00 F /NEL
7	1		*REAR DOOR ADVERTISEMENT LOGO RH	0.00	0.00	*100.00 F /NEL
8	1		*REAR DOOR COMFORTDELGRO & APPS STICKER RH	0.00	0.00	*80.00 F /NEL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,454.60
- List Item Discount on L Items (S\$)	644.92

Total Parts (S\$)	2,809.68
--------------------------	-----------------

ComfortDelGro Engineering Pte Ltd/SHA6953K/09/12/2019 17:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00 ✓
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING - REPAIR FENDER RH	New	600.00 560
2	SPRAY PAINTING CHARGE	New	750.00 500
3	WIRING CHARGE	New	50.00 X 111
4	REMOVE/REFIX REVERSE SENSOR	New	80.00 X 111
5	TRANSFER OF DOOR	New	120.00 80
6	REAR WHEEL ALIGNMENT	New	50.00 X 111
Gross Labour Cost (S\$)			1,650.00

ComfortDelGro Engineering Pte Ltd/SHA6953K/09/12/2019 17:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Dec 2019 17:47 Sendback Est	09 Dec 2019 17:57 S\$4,470.68	10 Dec 2019 10:13 Edit Adj Rpt	S\$2,800.00 Edit Estimates	S\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA6953K	Date of Loss:	05/12/2019 18:00 - :59 [67 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1909547	Policy/Cover Note No.:	MS010158 (Comprehensive) Coverage: 02/09/2019 - 11/09/2020
Vehicle Reg. No. (Insured):	SJP1301Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 19/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA6953K (M1909547)
[SJP1301Y]
TP
CTPL
Dec 5 2019 6:00PM
[CTPL]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)							Thumbnail	Print	
1	09/12/19 17:57	Repairer Estimates							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	10/12/19 16:11	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
2	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
3	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
4	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
5	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
6	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
7	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
8	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
9	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
10	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
11	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
12	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
13	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
14	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
15	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
16	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
17	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
18	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
19	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
20	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
21	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
22	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
23	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
24	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
25	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
26	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
27	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
28	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
29	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
30	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
31	11/12/19 09:07	General View							Load JPG	<input checked="" type="checkbox"/>	
32	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
33	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
34	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
35	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
36	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
37	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
38	24/12/19 10:11	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
39	24/12/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	24/12/19 10:11	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	09/12/19 17:59	E-filed GIA report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19021685/FSF3E2

Date: 27/12/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS010158

Claimant Vehicle No : SHA6953K

Insured Vehicle No : SJP1301Y

Date of Loss: 05/12/2019

Nature of Claim: TP

Claim No: M1909547

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA6953K

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDDU395893

Reg. Date: 23/04/2014 (Man. Year: 2014)

Chassis No: KMHLB41UMEU053679

Colour: Blue

Odometer: 625663 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable): Yes

Engine Modification: No

Pre-accident Condition: Good

Good

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,809.68	2,349.68	460.00	16.37
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,650.00	1,140.00	510.00	30.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,470.68	3,500.68	970.00	21.70
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,470.68	2,800.00	1,670.68	37.37
+ GST 7.00/7.00% (S\$)	312.95	196.00	116.95	37.37
Nett Amount (S\$)	4,783.63	2,996.00	1,787.63	37.37

INSPECTION

Date of Assignment: 10/12/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 09/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA6953K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	553.00 FL	-	*- FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
3	1		*REAR WHEEL HUB CAP RH	Scratched	107.10 FL	-	*107.10 FL
4	1		*REAR DOOR RH	Dented	2,201.10 FL	-	*2,201.10 FL
5	1		*ROCKER PANEL OUTER GARNISH RH	Scratched	341.40 FL	-	*341.40 FL
6	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	-	*50.00 FS
7	1		*REAR DOOR ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 FS
8	1		*REAR DOOR COMFORTDELGRO & APPS STICKER RH	Necessary	80.00 F	-	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,454.60	2,879.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	644.92	529.92

Total Parts (\$\$)	2,809.68	2,349.68
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING - REPAIR FENDER RH	New	600.00	560.00
2	SPRAY PAINTING CHARGE	New	750.00	500.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
5	TRANSFER OF DOOR	New	120.00	80.00
6	REAR WHEEL ALIGNMENT	New	50.00	0.00
Gross Labour Cost (S\$)			1,650.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >