ASS. REC, BY:		REF: 08 INC 190	21746/QV	3 Special	instruction:	
Surveyor :	Sunpin	ASSIGNA	MENT (Office)			
From (Person)	Cyathia Ang	of	IMC	Date	Time 9-55 amout	1/2/19
Estimated Cos			Bill to:			
OD TP WS	STTP RESTOD RI	ES/EVA/INV/MV				,
To Inspect Ve	hicle No:	×D 20	A STATE OF THE PARTY OF THE PAR	_ Insured;		
at Workshop i		Shingob Co	and the state of t	Tel:	96797561	2
of	10	Krunji Cres	ecent .			
Policy No:			Claim No: _	M7/10	74827-801	
Sum Insured:			Excess:			
Make of Veh: (Client's Record	Brown Co. Co.		1	D.0	.A. 3/12/2019	
CA / REV	REP. / REV 24 I	IRS to No	+ Finalized	Н	O.D. Endorsement:	
		12/14 erson Contacted			A (IN)OUT	
Date/Time	Action/Instruction	() Estima	te	***	1	
	XD 2918J-	CS3/EGT 180	11289/1Vb	e 2-1	DOA: 19/6/	218
	XD7874					
				74		
6/1/2020	@ 9339m W	Villiam said	rehicle la	rai-runa d	for spale parts	
23/20	Hand to	informed the	ebr first	Lection 1	malice	
10/6/20		0 confirmed by ema			Malina	
	* Do not indicate con	firmed in survey report				

ASSIGNMENT

From. Dale: 10/12/19	Veh No: XD 2918J Yr Regn: 01/Sep /2008
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Corry Taxi / Prime Mover /
OD (TP I) VS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: ×02918 J	Make: ISUZY CYZ52L 0.0 15681
at Workshop m/s Shingda Construction	Colour White A/C: Insured / Std / NI / NA
at Workshop m/s Shingda Construction of 10 Krunji Crescent	Sp.Reading 424891 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JALC7252L87090079
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Informer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: In order / Jammed / Leaked / Burnt or
Make of Veh: William @ 9679 7561	Modi: Nil / S/Rim / STO A)Rim or
Make of Veh: William @ 9679 7561 As call william after	Tyre Size: F: 295/60 R 22-5
(Policy Condition) Realth.	R: 245/60 R22-5
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Autine
Bal. or Market Value: XXXX	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.; Yes or No	D.O.A. 03/12/2019 D.O.I. 10/12/2019
Lum Sum: % 3 Val.: Yes or No	Survey held at Shingda
CA / REV / REP. / 24 HRS (WP)	Des. of Damages : Frt / (Rear / O/S / N/S / U/C / Rooftop or
venice, in 7 out	
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Mr. 38k. Sun Pin	
Chec	-k parts prices-
	Month
	1/12/1
	10/12
granumag	
Dale/Time, File Pass to? : Preli. Report	Days Of Repair: 12
i) : Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to? 3.1/12/20-Typist Actor Fee	Transportation:
2) 31/12/20-Typist Add Fee	Leading 1
TO TO	: Interview (\$) Photos
Peport Format : TP	: Tech Invs (\$) Other
Lung Sing / LEA: /3 \$47,310	. Weekend 48

Veron Chen (LKKAuto)		DOA: 3/12/19	DOJ = 10/12/19
From: Sent: To: Subject:	Veron Chen (LKKAuto) Wednesday, 11 November 20 Chester Chong; Admin-D (LKI RE: Survey involving XD2918J MT/1074827-001	020 8:18 AM KAuto); SUR at SHINGDA CONSTRUC	fix hove to a near of the trion pre LTD; REFide the hide who send number of Send number of Send number
	Sun Pin ask we	exception only and	jet new Semal number
Dear Chester,			
We will check and revert.	10/6/20 Sun Pin	\$ H7,310 infor	hed reporter.
	10/6/20 William	TMA VI A	(A)
	A Library	de no	+
Best Regards,		TMA in a	A C
Veron Chen Case Handler		Croff V	
Phone: 6256-3561 email :sur@lkka	outo gom four 6256 1215	machine	where
Blk 51, Paya Ubi Industrial Park, Ub		TV KILVO.	100
Dix 31, raya Oor muusutai raik, Oo	11 Avenue 1, #02-23 3(408933)	subject t	o wear
From: Chester Chong < Chester Sent: Tuesday, 10 November 2 To: Veron Chen (LKKAuto) < SUR < sur@lkkauto.com > Subject: RE: Survey involving 001	2020 5:38 PM <pre><veronchen@lkkauto.com>;</veronchen@lkkauto.com></pre>	Admin-D (LKKAuto)	
Dear Veron,		We wil	1 get back.
Please kindly let us have your	recommendation for this cas	se. Please apply depreci	ation for TMA.
Please DO NOT finalise COR	with Third Party yet.		
Please also let us have the follo 1. Damage photos showin 2. After repair photos sho	owing: ng serial number of damaged wing serial number of replac	TMA - attendy dem	ble to take IND
Thank you			ta
Kind regards,			located at
Chester Chong	Vegr to		Wumpled avec of demograd THI
Claims Executive Operations, Motor and Personal Line		z .	ornipled aver
T+65 6430 7919			of dome nd To
UINCOME U	under the GA	24	
requirent, on	u damaged t is vagni d Safety	ne to	
	0 1		

Nivitha (LKK Auto)

From:

Sent: ö

Subject:

ü

Nivitha (LKK Auto); assignments@lkkauto.com

Cynthia Ang <Cynthia.Ang@income.com.sg>

Tuesday, 10 December 2019 11:31 AM

RE: TP CASES FARMED OUT TO LKK ON 10/12/2019

Dear LKK,

Resend to furnish following details.

With Regards

Admin Assistant Cynthia Ang

Operations, Motor & Personal Lines (PL)

r +65 6430 7900

www.income.com.sg











PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

At income, we are 'In with You' on Performance, Growth.

innovation and impact. These attributes reflect what we promise

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com] Sent: Tuesday, 10 December 2019 10:30 AM

To: Cynthia Ang <Cynthia. Ang@income.com.sg>; assignments@lkkauto.com

Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; 'SUR' <sur@lkkauto.com> Subject: RE: TP CASES FARMED OUT TO LKK ON 10/12/2019

Dear Sir/Mdm,

Thank you for the assignments.



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cynthia Ang [mailto:Cynthia.Ang@income.com.sg]

Sent: Tuesday, 10 December 2019 9:55 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com> Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 10/12/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction:-

)IC		Claim No	Vehicle	WorkShop	WorkShop Address	WorkShop Survey Contact Time	Survey	OI VEH	DOA	Additional Remarks
2										
7		18					ā.			3157 2624
Charlo 1 Chew	Charlotte Chew	MT/1074829- 002	SLE6740P	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		SJY7068J	08/12/2019	/ 315 / 2628
		MT/1074833-		AUTO INSURE		Sam Goh /				3157 2624 /3157
Alice	2 Alice Low	002	SMC8704E	PTE LTD	6 MARSILING LANE	9743 6363		SJS2126P	08/12/2019	2628
A du y	Muhammad	Muhammad MT/1074779-	CB7054C	CONNECT3	566 WOODLANDS ROAD (MANDAI ESTATE)	Ms Lau / 9850-9666	14:00-	GR5300Z	07/12/2019	2

SGS3718K 24/11/2019	SKV2307G 03/11/2019	03/12/2019	05/12/2019
SGS3718K	SKV2307G	XD7874T	SJL5207G
09:30- 13:00	14:00-		
Coco Lu Ting / 6568 4501 / 91865200	Hui Wen / 6362 3393	William GO / 9679 7561	Melvin Wee / 67737377 / 87783338
209 PANDAN GARDENS SINGAPORE 609339	74 SUNGEI KADUT STREET 1 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729374	10 KRANJI CRESCENT	38 TOH GUAN ROAD EAST #01- 57 ENTERPRISE HUB SINGAPORE 608581
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	LEXBUILD AUTO & TRADING PTE. LTD.	SHINGDA CONSTRUCTION PTE LTD	WAH HONG MOTORS & CREDIT PTE LTD
SLL8649X	PC90998	XD2918J	SLN6154J
MT/1072811- 002	MT/1069713- 002	MT/1074827- 001	MT/1074804- 001
Chester 4 Chong	Eric Tang	Chester	Muhammad MT/1074804- 7 Airwan 001
4	S	9	7

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Admin Assistant Cynthia Ang

Operations, Motor & Personal Lines (PL)

T+65 6430 7900

made different www.income.com.sg





Ö

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...



Innovation and impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

At Income, we are 'In with You' on Performance, Growth,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	619M
Vehicle No.:	XD2918J
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2019
Vehicle Make:	ISUZU
Vehicle Model:	CYZ52L
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	6WG1408720
Chassis No.:	IAI CV7521 97000070
Maximum Power Output:	JALC1232L07000079
Open Market Value:	\$81,959.00
Original Registration Date:	01 Sep 2008
First Registration Date:	01 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$4,098.00
Intended PARF Rebate Details	Ψ-1,070.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,582.00
COE Rebate Amount:	\$11,585.00
Total Rebate Amount: Message	\$11,585.00
Please note that all future COE renewals for this vehicle co	an only be for a 5-year period, subject to the statutory lifespan (if applicable) of the

The information contained herein is correct as at 12 Dec 2019

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Black Rhino Abram 18° Off-Road Jehicle Rims



New 5 Years Renewal COE Toyota Wish 1.8A.

Mercedes E



Stylish Red Brake Kit



Ultra-flexible Speaker Ca.

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!



2.88% P.A. SO Admin, Monthly From \$688, 2 Years Warranty GV Credit StarAd

VALUE FOR MONEY VALUE FOR TIME A PEACE OF MIND OTLINE: 6741 9997 view our cars

Browse by Category

Post an Ad

Advertiser Login

Sort by Date Posted

Any

▼ 20 results/page

3 vehicles

Isuzu CYZ52L

Isuzu CYZ52L Tipper (COE till

Model

Ways of Selling

Advanced Search

Depreciation

Reg Date Eng Cap

Mileage

Veh Type

Search Selection

Isuzu CYZ52L

Price

old

> 10 year(s)

Available

06/2022)

\$48,000

\$19,320 /yr

07-Jun-2007

15,681 cc

Truck

Available

Fuel Type: Diesel

10 Wheeler Tipper Truck, Well Maintain, New Paintwork, In-House Loan Is Available, Call Now For Viewing!

Convince Auto

Posted: 09-Nov-2019 Tags: 2007 Isuzu CYZ52L, 2007 isuzu cyz52l, Isuzu CYZ52L, isuzu cyz52l, Isuzu, CYZ52L, cyz52l, Used Isuzu

Isuzu CYZ52L Tipper (COE till 06/2027)

\$68,000

\$9,070 /vr

11-Jun-2007

15.681 cc

Truck

Available

Fuel Type: Diesel

Posted: 16-Nov-2019 Tags: 2007 Isuzu CYZ52L, 2007 isuzu cyz52l, Isuzu CYZ52L, isuzu cyz52l, Isuzu CYZ52L, cyz52l, Used Isuzu



Isuzu CYZ52L (COE till 09/2023)

\$40,000

\$10,700 /yr

08-Sep-2008

15,681 cc

Truck

Available

DISEAST CONNER

Fuel Type: Diesel

Posted: 29-Nov-2019 Tags: 2008 Isuzu CYZ52L, 2008 isuzu cyz52l, Isuzu CYZ52L, isuzu cyz52l, Isuzu, CYZ52L, cyz52l, Used Isuzu

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Red Date

Eng Cap

Mileage

20 ▼ results/page

For old advertisements, view Expired ads

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars, & OPC cars, You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu CYZ52L, Isuzu CYZ52L Singapore, used Isuzu CYZ52L singapore, used Isuzu CYZ52L, used vehicles Singapore or even buy used Isuzu CYZ52L Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	04/12/2019 10:28
Date Of Accident	03/12/2019 12:30
Exact Location Of Accident	AT PIE EXIT 38
Country/State of Loss	SINGAPORE
C. C	DETAILS OF OWN VEHICLE
Vehicle Registration Number	XD2918J
Insured/Policyholder	
Name Of Registered Owner	SHINGDA EQUIPMENT LEASING PTE. LTD
Co Reg No	201723619M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63688936
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYZ52L
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2019-V0105500-VCV-R001
Cover Note Number	
Driver	
Name of Driver	NAGU MURUGESAN
Passport No/FIN	F8277399K
Date Of Birth	16/02/1977
	CLITROOP

(LOCAL) +65-97163552

6 YEARS AND 11 MONTHS

OUTDOOR 27/12/2012

MALE

Mobile Number Fax Number

Occupation

Gender

Date Of Driving Pass

Driving Experience

Contact Number

EMail Address NOEMAIL

Address

NA

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

.....

ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance

NO

soliciting/offering accident claims assistance.

...

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

WOODLANDS WEST N.P.C

Police Station Address

ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

XD7874T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 12

DETAILS OF INJURED PERSON 1

Name

UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

XD7874T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted (b) to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No .:

KETCH PLAN				
A = XD 2918 J				
		i I A		
B= XD 7874T		7/8/		
DESCRIBE CIRCUMSTANCES OF T	HE ACCIDENT			
Accident Date & Time : 03/1	2/2019. 12:30	HRS.	10 To	
Accident Location : AT PIE				
	E 18			K :
	s per police re	port)		
	2 2 23			-
- 1	- American	-	a N	
	3 (9)			
	*			
				· .
* * * * * * * * * * * * * * * * * * * *		-	***************************************	
	F			•
	The second second			
Th.				
· ·	All		•	
(*)	20	(in)		-
				1
☐ Reporting	Only Own Dama	ge 🏻 Third Party (Claim at other w	vorkshop (OD/TI
DECLARATION /We declare the foregoing particulars	are true in every respect.	* IMPORTANT NOTE: You had been advised by the workshop that there is a FOURTEEN (14) days clause w occurrence	in the event that you wish to claim agains hereby the claim must be made within the	at your own policy (Own Damage C e stipulated limeframe from the de
186				

STARBARC ScenchPlanForm_VB

Page 5 of 12

Police Report Pg. 1





Police Station Of Origin: Woodlands West N.P.C.

1 Woodlands Street 12 SINGAPORE 738622 Tel No: 1800-363 9999

1 of 3

Report No. T/20191203/2145

REPORT	OF A TRAFFI	C ACCIDENT			
Date/Time Report Made: 03/12/2019 18:50			Vide Report No.: Station Diary No.: J/20191203/0059 641		
Informa	nt's Partic	ulars			
	f Informant: //URUGES/		Address: 10 KRANJI CRESCENT SH 728660	INGDA BUILDING SINGAPORE	
ID Type / ID No.: FIN NO / F8277399K		oK .	Contact No.: Home/Office: 97163552	Mobile:	
National INDIAN	ity:		Email:		
Sex: Male	Age:	Date of Birth: 16/02/1977	Type of Informant: Driver		
Race:		ts.	Language:	Institution / School Name:	
Occupat Trailer-ti	tion: ruck driver	(4)	Driving Licence Information: Class:	Date of Expiry:	

General Inform	nation of the Accident	600.00000000000000000000000000000000000	the state of the s	Distriction of the second
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/12/2019 12:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND PIE EXIT 38 Lamp Post Nu	EXPRESSWAY			,
Weather: Clear	111001. 1000	Road Surface: Dry	F	Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collisi Between Movi	en: ng Vehicles - Head To R	ear	8	Anyone conveyed by ambulance: Yes

Vehicle No	Type	Make	Model	Color - Pres	Condition	No of Passenge
XD2918J	Lorry				Slightly Damaged	0
XD7874T	Lorry	a. 69	2E.	1 2 1	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg. 1





Police Station Of Origin: Woodlands West N.P.C. 1 Woodlands Street 12 St

Report No. T/20191203/2145

2 of 3

1 Woodlands Street 12 SINGAPORE 738622

Tel No: 1800-363 9999

CONTINUATION OF REPORT

Name	NAGU MURUGESA	N.		ID No		F8277399K
Related Vehicle	NIL			Conta	ct No.	97163552
Hospital/Clinic	NIL		=	Class Drivin Licen Expin	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL .		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of		NIL	

Brief Details.

On the 03/12/2019 at about 1230hrs, I was travelling along PIE exit 38 and had parked on the right side 3rd lane near the lamp post 1906 for road works to be done. I had turned on the left right arrow for both lanes beside me as there were work to be done infront. I then suddenly felt a loud bang at the rear in which my vehicle moved forward and came to a stop after. I then came out to make a check and saw the other driver was unconscious and I could not get to him as he was stuck inside and other people had called for ambulance and civil defense. I then took pictures of the scene first and SCDF had came to scene shortly after to rescue the other driver out before they convey him to hospital. I had talked with the traffic police and was informed by the police to make a police report in regards to it. This is the first time such incident has happened to me. I do not know how the other driver had collided into my rear.

Police Report Pg. 1





Police Station Of Origin: Woodlands West N.P.C.

3 of 3 Report No. T/20191203/2145

1 Woodlands Street 12 SINGAPORE 738622

Tel No: 1800-363 9999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 2 CHOONG JIA LE, DION	N' mael
Signature Of Interpreter:	Date/Time:
Not applicable	03/12/2019 18:50
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
TP/GIT/	
Contact No.:	
Authentication Stamp	



ESTIMATE

VEHICLE NO.: XD2918J

DATE: 09/12/2019

MODEL NO.: NISSAN CYZ52L

CHASSIS NO.: JALCYZ52L87000079

TO: NTUC INCOME INSURANCE CO-OPERATIVE

ENGINE NO.: 6WG1-408720

ATTN: MOTOR CLAIMS DEPARTMENT

REG. DATE:

OFFICE / MOBILE : -**EMAIL ADDRESS: -**

FROM: SHINGDA TRADING PTE LTD

D.O.A.: 03/12/2019

ATTN: MR WILLIAM GO

POLICY NO. : -

CLAIM TYPE: TP CLAIM - NTUC

OFFICE / MOBILE: 9679-7561

EMAIL ADDRESS: WILLIAM GO@SHINGDA COM

WORKSHOP: 10 KRANJI CRESCENT (S) 728660

S/N	PART NO.	DESCRIPTION	QUANTITY		PRICE
5	SPECIAL-NET	TITEMS			
1		SAFESTOP 180 TMA ASSY / CRY.	1	\$	52,000.00)
2		TMA ALUMINIUM PANEL (BIG) CRY	1	\$	550.00 117 60
3		TMA ALUMINIUM PANEL (SMALL) / CRU	1	\$	400.00
4		REFLECTIVE STICKER / Ne C	1	\$	600.00
5		REAR NUMBER PLATE / CKU.	2	\$	40.00 /
6		"60 KM/H" STICKER / SCH.	2	\$	40.00
7		REAR LAMP LED LH / CRA	1	\$	60.00/
8		REVERSE LAMP LED LH CRY	1	\$	100.00
9		SIDE LAMP ? / CRU	4	* * * * * * * * * * * *	120.00
10		BEACON LIGHT / CRU	13	\$	600.00 150
11		REAR NUMBER PLATE LAMP / CRU.	2	\$	100.00 50
12		REAR BUCKET ALUMINIUM PANEL / CRY	1 1	\$	650.00
13		REAR BUCKET ALUMINIUM PANEL FRAME / 13T.	1	\$	300.00 /
14		REAR METAL MUDGUARD LH / BT	1	\$	300.00 /
15		MUDFLAP LH XCVC.	1	\$	30.00X
16		MUDFLAP STRIP LH BT	1	\$	100.00
17		TMA BRACKET LH/RH / BT. 7 × SVC	2	\$	600.00
18		ARROW LED SIGN BOARD	1	\$	2,500.00
19		ARROW LED SIGN BOARD FRAME ? X SVC	1	\$	700.00
		PARTS TOTAL :		\$	59,790.00



& SERVICES LABOUR CHARGES / Nec. 1 TO TOW VEHICLE FROM ACCIDENT SCENE. 2 TO INSTALL WIRING ON TMA. TO REMOVE & INSTALL LIGHTING ON TMA. 680.00 /500 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. / Nec 3 TO PANEL BEAT/REPAIR/REALIGN/WELDING MAIN CHASSIS FRAME. 1 day -350-3,000.00 2000 4 TO REMOVE & INSTALL ALUMINIUM PANELS & MUDGUARD. 3 pcs. 1,000.00 700 5 TO REMOVE & REFIX ARROW LED SIGN BOARD. CHECK FUNCTION. 9 \$ 350 700.00 500 6 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC. 1 pgral - 250 2,000.00 1750 3-Alyning 7 SUNDRIES 150.00 100 X 1-chasa/mudyuaul.
Peffector
I-tram/budget tulque LABOUR TOTAL: 7,730.00 **GRAND TOTAL:** 67,520.00 Repairday - 12 days PREPARED BY: WILLIAM GO DATE / TIME :

SURVEYOR: MOBILE NO. : OFFICE FAX NO. : EMAIL ADDRESS: PART-BY-PART / LUMPSUM REPAIR TYPE :

RE-SURVEY:

BEFORE PAINT / AFTER PAINT

NO. OF DAYS:

REMARKS:

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sun Pin (Uck)

10/12/2019.

TP nother prejudice

Sunpin @ Ikkautu-com

8661 2627.

A member of SHINGDA Group of Companies

Veron Chen (LKKAuto)

From:

William GO Shaw Chan <william.go@shingda.com>

Sent:

Friday, 27 March 2020 3:53 PM

To:

Veron Chen (LKKAuto); Oi Sun Pin (LKK Auto); SUR

Cc:

Derek CHOW Zhi Da; Cynthia SING; Edward CHU Chiun Kwong; TIA Ming Ee

Subject:

RE: XD 2918J-DOA: 31/12/2019

Dear Veron.

I am getting the documents from my finance department. I will forward to you once I get it.

Thank you.

Yours sincerely,
William GO Shaw Chan
Motor Claims Executive
SHINGDA Group of Companies

M +65 9679 7561 | T +65 6368 8936 (Ext.262) | F +65 6366 1470 | E william.go@shingda.com | W shingdagroup.com SHINGDA Building, 10 Kranji Crescent, Singapore 728660



SHINGDAGONSTRUCTION

SHINGDA

SHINGDA ACADEMY SHINGDA

DA SHINGDA S INVESTMENTS SINGAPORE PIPING ENGINEERING

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 27 March, 2020 3:24 PM

To: William GO Shaw Chan <william.go@shingda.com>; Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>; SUR

<sur@lkkauto.com>

Cc: Derek CHOW Zhi Da <derek.chow@shingda.com>; Cynthia SING <cynthia.sing@shingda.com>; Edward CHU

Chiun Kwong <edward.chu@shingda.com>; TIA Ming Ee <mingee.tia@shingda.com>

Subject: RE: XD 2918J-DOA: 31/12/2019

Dear William,

Any update for the purchase invoice.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: William GO Shaw Chan <william.go@shingda.com>

Sent: Monday, 2 March 2020 11:21 AM

To: Oi Sun Pin (LKK Auto) < sunpin@lkkauto.com>

Cc: Derek CHOW Zhi Da derek.chow@shingda.com/; Cynthia SING <cynthia.sing@shingda.com/; Edward CHU Chiun Kwong <edward.chu@shingda.com>; TIA Ming Ee <mingee.tia@shingda.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: XD 2918J-DOA: 31/12/2019

Dear Sun Pin,

Please see the attached marked estimate. Can we confirm the repair cost @ \$62,030.00?

Thank you.

Yours sincerely, William GO Shaw Chan Workshop Executive SHINGDA Group of Companies

M +65 9679 7561 | T +65 6368 8936 (Ext.262) | F +65 6366 1470 | E william.go@shingda.com | W shingdagroup.com SHINGDA Building, 10 Kranji Crescent, Singapore 728660



SHINGDA NSTRUCTION SHINGDA

SHINGDA **ACADEMY**

SHINGDA & SERVICES

SHINGDA

SINGAPORE PIPING **ENGINEERING**

From: William GO Shaw Chan

Sent: Monday, 6 January, 2020 9:59 AM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Cc: Derek CHOW Zhi Da <derek.chow@shingda.com>; Cynthia SING <cynthia.sing@shingda.com>; Edward CHU

Chiun Kwong < edward.chu@shingda.com >; TIA Ming Ee < mingee.tia@shingda.com >

Subject: RE: XD 2918J-DOA: 31/12/2019

Dear Veron.

As spoken, the parts will only arrive estimated by end of FEB 2020. I will update you once repair completed.

The DOA should be 03/12/2019.

Thank you.

Yours sincerely, William GO Shaw Chan Workshop Executive SHINGDA Group of Companies

M +65 9679 7561 | T +65 6368 8936 (Ext.262) | F +65 6366 1470 | E william.go@shingda.com | W shingdagroup.com SHINGDA Building, 10 Kranji Crescent, Singapore 728660



SHINGDA CONSTRUCTION SHINGDA

SHINGDA

SHINGDA

& SERVICES

SHINGDA

SINGAPORE PIPING ENGINEERING From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 3 January, 2020 2:34 PM

To: William GO Shaw Chan < william.go@shingda.com>

Subject: XD 2918J-DOA: 31/12/2019

Dear William,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 2 March 2020 4:28 PM

To:

Chester Chong; Admin-D (LKKAuto); SUR

Subject:

RE: Survey involving XD2918J at SHINGDA CONSTRUCTION PTE LTD; REF:

MT/1074827-001

Dear Chester,

We just received finalise from repairer.

Our surveyor is still checking on the parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chester Chong < Chester. Chong@income.com.sg>

Sent: Monday, 2 March 2020 2:32 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: Survey involving XD2918J at SHINGDA CONSTRUCTION PTE LTD; REF: MT/1074827-001

Dear Sir/Mdm,

We refer to the above vehicle. Please do not confirm the finalised cost of repair for this vehicle. Please inform us should the workshop is asking you to finalise cost of repair.

Thank you.

Kind regards,
Chester Chong
Claims Executive
Operations, Motor and Personal Lines
T+65 6430 7919
www.income.com.sg











At Income, we are 'in with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplely. . Find out more at income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s)

Veron Chen (LKKAuto)

From:

William GO Shaw Chan <william.go@shingda.com>

Sent:

Monday, 6 January 2020 9:59 AM

To:

Veron Chen (LKKAuto)

Cc:

Derek CHOW Zhi Da; Cynthia SING; Edward CHU Chiun Kwong; TIA Ming Ee

Subject:

RE: XD 2918J-DOA: 31/12/2019

Dear Veron,

As spoken, the parts will only arrive estimated by end of FEB 2020. I will update you once repair completed.

The DOA should be 03/12/2019.

Thank you.

Yours sincerely. William GO Shaw Chan Workshop Executive SHINGDA Group of Companies

M +65 9679 7561 | T +65 6368 8936 (Ext.262) | F +65 6366 1470 | E william.go@shingda.com | W shingdagroup.com SHINGDA Building 10 Kranji Crescent, Singapore 728660



SHINGDA

SHINGDA

SHINGDA

SHINGDA PRODUCTS

SHINGDA & SERVICES

SINGAPORE PIPING ENGINEERING

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 3 January, 2020 2:34 PM

To: William GO Shaw Chan <william.go@shingda.com>

Subject: XD 2918J-DOA: 31/12/2019

Dear William,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ESTIMATE

DATE: 09/12/2019

VEHICLE NO. : XD2918J

MODEL NO. : NISSAN CYZ52L CHASSIS NO.: JALCYZ52L87000079

TO: NTUC INCOME INSURANCE CO-OPERATIVE

ENGINE NO.: 6WG1-408720

ATTN: MOTOR CLAIMS DEPARTMENT

REG. DATE :

OFFICE / MOBILE : -**EMAIL ADDRESS: -**

D.O.A.: 03/12/2019

FROM: SHINGDA TRADING PTE LTD ATTN: MR WILLIAM GO

POLICY NO. : -

CLAIM TYPE: TP CLAIM - NTUC

OFFICE / MOBILE: 9679-7561

EMAIL ADDRESS: WILLIAM GOOSHINGDA COM

WORKSHOP: 10 KRANJI CRESCENT (S) 728660

S/N	PART NO.	DESCRIPTION	QUANTITY		PRICE
	SPECIAL-NETT	ITEMS			
1		SAFESTOP 180 TMA ASSY / CRY.	1	\$	52,000.00 🕇
2		TMA ALUMINIUM PANEL (BIG) / CRY	1	\$	
3		TMA ALUMINIUM PANEL (SMALL) / CRU	1	\$	400.00
4		REFLECTIVE STICKER / Nec	1	φ	600.00
5		REAR NUMBER PLATE / CRU.	2	8	40.00
6		"60 KM/H" STICKER / 5 CH.	2	0	40.00
7		REAR LAMP LED LH / CRA	2	9	
8		REVERSE LAMP LED LH / CRY	1	Ð	60.00
8		SIDE LAMP TO A	1	5	100.00
10		BEACON LIGHT / CRU	4	\$	120.00
11			1-8	\$	600.00 Job 150
12		REAR NUMBER PLATE LAMP / CRU.	1 2	\$	100.00 56
13		REAR BUCKET ALUMINIUM PANEL / CRY	· 1	\$	650.00
		REAR BUCKET ALUMINIUM PANEL FRAME / 13T.	1	\$	300.00
14		REAR METAL MUDGUARD LH / BT	1	\$	300.00
15		MUDFLAP LH XCVC.		-\$-	30.00
16		MUDFLAP STRIP LH > B T	1	\$	100.00
17		TMA BRACKET LH/RH BT.	2	\$	600.00
18		ARROW LED SIGN BOARD		-\$-	2,500,00
19_		ARROW LED SIGN BOARD FRAME ?	1	-\$-	700.00

PARTS TOTAL :

56/00.00\$ 59,790.00

SHINGDA

PRODUCTS & SERVICES

200.00 / X 680.00 / 500 3,000.00 2000
3,000.00 2000
1,000.00 700
700.00 500
2,000.00 1750
150.00 100×
7,730:00
67,520.00
z days
•
uto.
to
de
dice
-com

SHINGDA

PRODUCTS & SERVICES

ESTIMATE

VEHICLE NO. : XD2918J

DATE: 09/12/2019

MODEL NO.: NISSAN CYZ52L

CHASSIS NO.: .IALCY752L87000079 ENGINE NO.: 5WG1-408720

TO : NTUC INCOME INSURANCE CO-OPERATIVE

ATTN: MOTOR CLAIMS DEPARTMENT

REG. DATE :

OFFICE / MOBILE : -EMAIL ADDRESS : -

D.O.A.: 03/12/2019

FROM: SHINGDA TRADING PTE LTD

POLICY NO. :

ATTN: MR WILLIAM GO

CLAIM TYPE : TP CLAIM - NTUC

OFFICE / MOBILE: 9679-7561

EMAIL ADDRESS : WELLIAM TENE

WORKSHOP : 10 KRANJI CRESCENT (S) 728860

S/N P	ART NO.	DESCRIPTION	QUANTITY		PRICE
SPE	CIAL-NETT IT	EMS			
1	S	AFESTOP 180 TMA ASSY	1	S	52,000,00 ₀
2	7.9	MA ALUMINIUM PANEL (BIG) - CTG	3	5	550 00438,90
3		MA ALUMINIUM PANEL (SMALL) - (F)	1	S	400.007 20/90
4		EFLECTIVE STICKER > NAC	4	S	600 00 /
5	85	EAR NUMBER PLATE _ CAU	2	\$	40.00
5 5 7	" 6	O KM/H" STICKER / ICH	2	\$	40.00
1.00	R	EAR LAMP LED LH CERS	1	5.	50.00/
8	R	EVERSE LAMP LED LH / CP 4	1	\$	100.00
	S	DE LAMP ? PERS	4	\$	120.00
10	8	EACON LIGHT Z FRU	1 3	5	600.00 150
11	R	EAR NUMBER PLATE LAMP / CRU	. 2"	15	100,00 50
12	R	EAR BUCKET ALUMINIUM PANEL / (1)-1	1	\$	850.00
13	R	EAR BUCKET ALUMINIUM PANEL FRAME / 15T	1	\$	300.00
14	R	EAR METAL MUDGUARD LH / BT	1	\$	300.00
14 15 16	M	UDFLAPIH XCVC	1	\$	30.00X
16	1.4	UDFLAP STRIP LH / PT	7	5	100.00
17	1	MA BRACKET LHIRH / B T - V SV	2	S	600.00
18	A	RROW LED SIGN BOARD	1	S	2,500.00X
19	A	RROW LED SIGN BOARD FRAME 7 X 3VC	1	\$	700 00 X
		PARTS TOTAL :		5	59,790.00
					42,010

и извиди и замеже Сподред Опиразия

SHINGDA

PRODUCTS & SERVICES

TO TO TOW VEHICLE FROM ACCIDENT SCENE 2 TO INSTALL WIRING ON TMA. TO REMOVE & INSTALL LIGHTING ON TMA. TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. 3 TO PANEL BEATTREPAIRREALIGNWELDING MAIN CHASSIS FRAME 1 69 - 350 \$ 3,000.00 7 CCC 4 TO PEMOVE & INSTALL ALUMINIUM PANELS & MUDGUARD. 775- 5 TO REMOVE & REFIX ARROW LED SIGN BOARD. CHECK FUNCTION 7 \$ 700.00 350 6 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC. 1 1 1 1 1 2 5 0 \$ 2,000.00 175.00 7 SUNDRIES 7 My From 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	LABOUR CHARG	ES			
TO CHECK FOR 8 RECTIFY WIRING FAULTS, ETC. 3 TO PANEL BEAT/REPAIR/REALIGN/WELDING MAIN CHASSIS FRAME 1 dg - 150 s 3,000,00 7,000 s 3,000,00 7,000 s 1,000,00 s 1,000,0			X	\$	200 00 X
S TO PANEL BEATREPAIR/REALIGN/WELDING MAIN CHASSIS FRAME 1 dg - 150 S 3,000 00 7 C/DO 4 TO REMOVE & INSTALL ALUMINIUM PANELS & MUDGUARD. 7/15 S 1,000,00 7 C/DO 5 TO REMOVE & REFIX ARROW LED SIGN BOARD. CHECK FUNCTION 7 S 700 00 350 S 2,000 00 1750 S 2,000 S 2,000 00 1750 S 2,000 S 2,000 00 1750 S 2,000 S 2,00			: 18 1 - 17 - 17 1 - 17 1 - 18 1 1 1 - 18 - 18	5	· 680 00 - 4 t-1)
S TO REMOVE & REFIX ARROW LED SIGN BOARD CHECK FUNCTION S 700 60 350 6 TO PUTTY, CLEAN, SPRAY PAINT & POLISH ETC. 1900 250 5 2,000.00 175.00 7 SUNDRIES 2 TM4 brocky 7 pc. 5 150.00 400.00 1 - chols in moderal LABOUR TOTAL: 5 7,730.00 5,300 1 - chols in moderal LABOUR TOTAL: 5 67,520.00 PREPARED BY WILLIAM GO RAND TOTAL: 5 67,520.00 DATE / TIME: SURVEYOR MOBILE NO. OFFICE FAX NO. EMAIL ADDRESS: REPAIR TYPE PART-BY-PART / LUMPSUM RE-SURVEY BEFORE PAINT / AFTER PAINT NO. OF DAYS. REMARKS: REMARKS: 10 / 12/2019 REMARKS: 10 / 12/2019 REMARKS: 10 / 12/2019 REMARKS: 10 / 12/2019 N=42,010 L=5,300 N=42,010 L=5,300 SE61 2627. ADDRESS OF RECEIPER N=47,310 SE61 2627. ADDRESS OF RECEIPER ADDRESS OF RECEIPER ADDRESS OF RECEIPER S TOO 000 350 S 2000.00 175.00 S 2000.00 S 2000.00 175.00 S 2000.00 S 2000.00 S 2000.00 S 2000.00 S	3 TO PANEL BEA	AT/REPAIR/REALIGN/WELDING MA		3	3,000 00 7 (100)
S TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC. Pany -250. S 2,000.00 7550 7 SUNDRIES 2 - TM4 blocky 700 S 150.00 +000 X - chaja	4 TO REMOVE 8	INSTALL ALUMINIUM PANELS & M	UDGUARD 1/15-	3	1.000.00 700
S TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC. Pany -250. S 2,000.00 7550 7 SUNDRIES 2 - TM4 blocky 700 S 150.00 +000 X - chaja	S TO REMOVE &	REFIX ARROW LED SIGN BOARD	CHECK FUNCTION 7	S	780.00 350
TO SUNDRIES 2 - T M4 blocky - chara resugrand LABOUR TOTAL S 7,730.00 5,300 - chara resugrand S 7,730.00 5,300 - chara resugrand S 67,520.00 5,300 - chara resugrand S 67,520.00 5,300 - chara resugrand S 67,520.00 5,300 - chara S 67,520.00 5,300		EAN, SPRAY PAINT & POLISH, ETC		S	2.000.00 /750
PREPARED BY WILLIAM GO DATE / TIME: SURVEYOR MOBILE NO. OFFICE FAX NO. EMAIL ADDRESS: REPAIR TYPE RESURVEY BEFORE PAINT / AFTER PAINT NO OF DAYS. REMARKS LEKK Auto Consultation librating control from the control of the latter spins and a select to the latter spins and a select to the latter spins and a select to the latter spin of the control of the latter spin of the	7 SUNDRIES				- 63
PREPARED BY WILLIAM GO DATE / TIME: SURVEYOR MOBILE NO. OFFICE FAX NO. EMAIL ADDRESS: REPAIR TYPE RESURVEY BEFORE PAINT / AFTER PAINT NO OF DAYS. REMARKS LEKK Auto Consultation librating control from the control of the latter spins and a select to the latter spins and a select to the latter spins and a select to the latter spin of the control of the latter spin of the		1 - those mulpant	LABOUR TOTAL :	5	7,730 00 5,300
DATE / TIME: SURVEYOR MOBILE NO OFFICE FAX NO. EMAIL ADDRESS: REPAIR TYPE RESURVEY RESURVEY RESURVEY RESURVEY REMARKS LEK A site Connecting to the inflowing: No of class REMARKS No decide connecting to the inflowing: Parts or connecting to the inflowing: Parts or connecting to the confirmation Parts or connecting to the c		1- Fram / Hydles tolance	GRAND TOTAL:	\$	67,520,00
SURVEYOR MOBILE NO. OFFICE FAX NO. EMAIL ADDRESS: REPAIR TYPE PART-BY-PART/LUMPSUM RE-SURVEY BEFORE PAINT / AFTER PAINT NO. OF DAYS: REMARKS: LEK Auto Commutating thenous motify this Repaired of the Inflowing: To depute before the open country To depute before the open country The reports during a result during inclusives Perts onced are expect to continuous To depute before the open country The ports during a result during inclusives Perts onced are expect to continuous To depute before the continuous of changes The ports during a result during inclusives Perts onced are expect to continuous To depute the inclusive of continuous of continuous The ports during a result during inclusives The ports during a resul	PREPARED BY	WILLIAM GO	Repurdey.	-12	days
MOBILE NO. OFFICE FAX NO. EMAIL ADDRESS: REPAIR TYPE PART BY PART / LUMPSUM RE-SURVEY BEFORE PAINT / AFTER PAINT NO OF DAYS REMARKS LEK Auto Commutations helicolomothy the Repairt of the following: To be accurate below with a province continue To diplus conveys a continue continue To diplus continue T					
REPAIR TYPE PART-BY-PART/LUMPSUM RE-SURVEY BEFORE PAINT / AFTER PAINT NO OF DAYS REMARKS LEK Auto Comparture is hence motify the Repair of the Inflowing: N = 42,010 L = 5,300 N = 42,010 L = 5,300 N = 47,310 Supplied of Substitution of Substitut		THE THE STATE OF T	- Xp hotor spra	\$0 Paul	te.
REPAIR TYPE PART BY PART / LUMPSUM RE-SURVEY BEFORE PAINT / AFTER PAINT NO OF DAYS: REMARKS LEK Auto Commutating history motify the Reputation of the following: A to require definition motify The reputation of the following: A to require definition of the following: Perts process are expect to confirmation The reputation of the following: The reputation of the following: Perts process are expect to confirmation The reputation of the following: Perts process are expect to confirmation The reputation of the following: Perts process are expect to confirmation The reputation of the following: Perts process are expect to confirmation The reputation of the following: Perts process are expect to confirmation The reputation of the following: Perts process are expected to confirmation The reputation of the following: Perts process are expected to confirmation The reputation of the following: Perts process are expected to confirmation The reputation of the following: Perts process are expected to confirmation The reputation of the following: Perts process are expected to confirmation The reputation of the following: Perts process are expected to confirmation The reputation of the following: Perts process are expected to confirmation to confirm the following: Perts process are expected to confirm th					
RESURVEY DEFORE PAINT AFTER PAINT NO OF DAYS REMARKS LEK Auto Commutate to the following: A To sequence before with spread assume To display demonstrate to restrict the control of the following: To display demonstrate to restrict the control of the following: The parts describe the following: The parts describe the control of the following: The parts described the control of the following: The parts described the par			12/19	p to th	ē.
RESURVEY DEFORE PAINT AFTER PAINT NO OF DAYS REMARKS LEK Auto Commutate to the following: A To sequence before with spread assume To display demonstrate to restrict the control of the following: To display demonstrate to restrict the control of the following: The parts describe the following: The parts describe the control of the following: The parts described the control of the following: The parts described the par	REPAIR TYPE	PART-BY-PART / LUMPSUM	1 (3) Jun Par CE	Ick)	
REMARKS LEK Auto Computation in the committy The Repair by of the inflowing: * To explain by of the inflowing: * To e			10/12/201	C-f	
IN Auto Compater is thenes matrix The Repair of the Inflowing: A To explain an inflowing province before with approx name in the province before with approx name in the province before with a confirmation in the province before the confirmation in the province before the confirmation in the province and a province beautiful to the sequence before the confirmation in the sequence of the			- 1 - 1 - 1 - 2 - 2 - 1	100	
The Republic of the Inflowing: * To display this specification of the Inflowing: * To display this specification of the Confidence of the Inflowing terrations are already to confidence of the Inflowing terrations of the Infl			- Tip wethout 1	orts if	41
# Treat parts discrete a first force of the sendous based on the sendous	the Repairer of the inflowing: • To require below the grow service	N=42,0		(zud), -	ram
Asknowledged for Face of the State of the St	 Parti oncea are subject to confirmation I need pure survey. I need pure survey. I need pure survey. 			Ç27.	
Askonarcount or Repeice		sep Commune	10		
		4-1731			
The state 12 days		129	ays		

A member of Shift SQL Croup of Dompasies

SHINGDA TRADING PTE LTD 救速复聚私人有限公司

SHINGDA Building: 10 Kranji Cruscent, Singepore 728660 (1 +65 6368 8936) F +65 6560 1470 (Wishingdaprovolution Co. / 667 Reg. No.: 201312342C

TN SAFETY PTE LTD

1090 LOWER DELTA ROAD #01-03

SINGAPORE 169201 TEL: 62767997 FAX: 62727261 E-MAIL: tnsafetypl@gmail.com GST REG NO.: 201806429M

CC FEG NC.: 201806429M

TO: SHINGDA TRADING PTE LTD

10 KRANJI CRESCENT SINGAPORE 728660

TAX INVOICE : INV 00210400

DATE

: 26/02/2020

P/0

: 00290490

TERMS

SALESMAN CODE :

PAGE NO.

: 001

ATTN : ACCOUNTS DEPARTMENT TEL/FAX: 6368 8936/6366 1470

NO.

_______ DESCRIPTION QTY UOM UNIT-PRICE AMOUNT

SGD

ORDERED BY: MR WILLIAM GO SHAW CHAN

- 96797561

TRUCK NO : XD 2918 J

SGD

TO SUPPLY & INSTALL

001 SAFE-STOP (TMA'S) 180 TRUCK MOUNTED ATTENUATOR

C/W HYDRAULIC LIFT UP (PASSED 6 TESTS BASED ON

NCHRP 350 TEST LEVEL 2 & 3) CART S/N: 5659A [23/08/19] ;

: 5662B [12/12/19]

FRAME S/N: 1894 [12/12/19]

UNIT PRICE - \$52,900.00 LESS: TRADE DISCOUNT - \$ 9,000.00 : SPECIAL DISCOUNT - \$ 3,000.00

: ADDITIONAL SPECIAL - \$ 1,500.00

DISCOUNT

: FURTHER ADDITIONAL - \$ 500.00

SPECIAL DISCOUNT

1.00 UNIT 38900.00 38,900.00

Continue ...

ALL CHEQUES SHOULD BE CROSSED 'A/C PAYEE ONLY' & MADE PAYABLE TO TN SAFETY PTE LTD

TN SAFETY PTE LTD

E. & O.E

TN SAFETY PTE LTD

1090 LOWER DELTA ROAD #01-03 SINGAPORE 169201 TEL: 62767997 FAX: 62727261 E-MAIL: tnsafetypl@gmail.com GST REG NO.: 201806429M CO REG NO.: 201806429M

TO: SHINGDA TRADING PTE LTD

ATTN : ACCOUNTS DEPARTMENT

TEL/FAX: 6368 8936/6366 1470

10 KRANJI CRESCENT SINGAPORE 728660

TAX INVOICE : INV 00210400

:

DATE P/0

: 26/02/2020

D/0

: 00290490

TERMS

SALESMAN CODE :

PAGE NO. : 002

_____ NO.

QTY UOM UNIT-PRICE AMOUNT -----

SGD SGD

TERMS: 1ST PAYMENT - 50% DEPOSIT

: BAL PAYMENT - 50% UPON

INSTALLATION OF TMA ONTO YOUR VEHICLE & COLLECTION OF YOUR

VEHICLE

SUB-TOTAL 38,900.00

ADD 7.00% GST

2,723.00

TOTAL

41,623.00

SINGAPORE DOLLARS FORTY ONE THOUSAND SIX HUNDRED TWENTY THREE ONLY.

ALL CHEQUES SHOULD BE CROSSED 'A/C PAYEE ONLY' & MADE PAYABLE TO TN SAFETY PTE LTD

TN SAFETY PTE LTD

E. & O.E

TN SAFETY PTE LTD

1090 LOWER DELTA ROAD #01-03
SINGAFORE 169201
TEL: 62767997 FAX: 62727261
E-MAIL: thsafetypl@gmail.com
GST REG NO.: 201806429M
CO REG EO.: 201806429M

BILL TO : SHINGDA TRADING PTE LTD 10 KRANJI CRESCENT SINGAPORE 728660

DELIVER TO : SELF COLLECTION DELIVERY ORDER: 00290490

DATE

: 20/02/2020

P/O

TERMS

007

SALESMAN CODE : PAGE NO.

OOT

NO. STOCK-CODE

DESCRIPTION

CALA DOW

ORDERED BY: NR WILLIAM GO SHAW CHAN -96737561

TO SUPPLY & INSTALL

001 TMA-SS180

SAFE-STOP (TMA'S: 180
TRUCK MOUNTED ATTENUATORS
(PASSED NCHRP 353 TEST LEVEL 2 & 3 - 6 TESTS)
C/W HYDRAULICS LIFT UP

1.00 UNIT

- * TRUCK NO: XD2918J
- * TMA S/N : 5659 A[=3/08/19]; 5662 B[12/12/19]
- * FRAME NO: 1894 [12/12/19]

RECEIVED IN GOOD ORDER AND CONDITION

HIP. -84381020

1 8 W. TASE7

TN SAFETY PTE LTD

E. & O.E

DOA: 3/12/19

TN SAFETY PTE LTD

1090 LOWER DELTA ROAD #01-03 SINGAPORE 169201

FAX: 62727261 TEL: 62767997 E-MAIL: tnsafetypl@gmail.com

GST REG NO.: 201806429M CO REG NO.: 201806429M

BY:----

TO: SHINGDA EQUIPMENT LEASING FTE LID

10 KRANJI CRESCENT SINGAPORE 728660

TAX INVOICE : INV 00210031

DATE P/0

: 12/07/2018

D/0 TERMS : 00290026

SALESMAN CODE : PAGE NO.

ATTN : ACCOUNTS DEPARTMENT TEL/FAX : 6368 8936/6966 1470

DESCRIPTION NO.

QTY UOM UNIT-PRICE

AMOUNT

SGD

SGD

ORDERED BY: MR MOK LOO SENG -56211398 TRUCK NO : XD 2918 J X7 19

TO SUPPLY & INSTALL

WO

(()

001 SAFE-STOP (TMA'S) 180 PA (SF-777)

TRUCK MOUNTED ATTENUATOR C/W HYDRAULIC LIFT UP (PASSED 6 TESTS BASED ON NCHRP 350 TEST LEVEL 2 & 3) S/N: 5368A [19/04/18] ; 5313B [17/04/18]

- \$ 4E,00C.00 UNIT PRICE 5,000.00 LESS: TRADE DISCOUNT 3,000.00 : GOODWILL DISCOUNT

> \$ 3€,000.00 - \$ 1,500.00 : ADDITIONAL SPECIAL


DISCOUNT

: FURTHER ADDITIONAL 500.00 - \$ SPECIAL DISCOUNT

1.00 UNIT

34000.00

34,000.00



1000 0001

\$ 34000.00

3050 0001

\$-2380.02

Continue ...

ALL CHEQUES SHOULD BE CROSSED 'A/C PAYEE ONLY' & MADE PAYABLE TO TN SAFETY PTE LTD

BY:

E. & O.E

TN SAFETY PTE LTD