

22/03/2002

ASS. REC. BY:

REF:

CS / FWD 19021757 / ALF3

Special Instruction:

Survevor: Adrian**ASSIGNMENT (Office)**From (Person): Venus Chan

of

FWDDate/Time: 10.12.19 3.03pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLN 3740LInsured: SLA 7601Yat Workshop m/s Flying High SprayTel: 67492997of 1 Kaki Bukit Dr 6 #01-29 AutobayPolicy No: PNDV2018-00003363-01Claim No: 1201900039010

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 8-Dec-19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.12.19 3.27pmPerson Contacted: Phuron

H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 3740L: X
	SLA 7601Y: X
	Finalize lump Sum \$4200+ (Cred: 6758, 61%)

ASSIGNMENT

Form

Estimated Cost

GD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS.

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLN3740L. 2017 April.

Type: ☒ Cab / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Megane 1461

Colour: Grey. A/C: Insured / Std / Nil / NA

Sp Reading: 53439. T/Ratio: Insured / Std / Nil / NA

Eng/No:

C/No: VFIRFB00056852479

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R17.

R: 205/50R17.

BS / DUN / EXNOVA / GY / FS / LIZ / ☒ MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm

R/Bal: 06 mm

L/Bal: 06 mm

L/Bal: 06 mm

D.O.A.

D.O.I. 11/12/19.

Survey held at

Flying High.

Des. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP FWD.

MV:

PV:

Nett:

RECEIVED 12 MAR 2020

Date/Time: File Poss 10/

12/3 Typist

Date/Time: File Return 10/



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trips: 1

Add Fee:



Site Insp 15



Interview 15



Technical 15



Photography 15

Survey Fee

Transportation

Other

Subtotal

Total

250

50

50

11

Report to be sent

Lump 0

TP

42001

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Tuesday, 10 December 2019 3:03 PM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com
Subject: PRE-REPAIR SURVEY --- YOUR REF: SLA 7601 Y --- ACCIDENT INVOLVING SLN 3740 L AND SLA 7601 Y ON 8 DECEMBER 2019 OUR CLAIM REF: 1201900039010

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Tuesday, December 10, 2019 2:54 PM
To: Elaine Toh
Cc: Motor Claims SG - SG Common
Subject: PRE-REPAIR SURVEY --- YOUR REF: SLA 7601 Y --- ACCIDENT INVOLVING SLN 3740 L AND SLA 7601 Y ON 8 DECEMBER 2019 ALONG TUAS MALAYSIA CHECKPOINT AT ABOUT 1710 HOURS

Hi Elaine,

Thank you for your selection of LKK Auto Consultants.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Tuesday, December 10, 2019 2:36 PM

To: Venessa Chan - SGUser

Cc: Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SLA 7601 Y --- ACCIDENT INVOLVING SLN 3740 L AND SLA 7601 Y ON 8 DECEMBER 2019 ALONG TUAS MALAYSIA CHECKPOINT AT ABOUT 1710 HOURS

Importance: High

Our Ref: SLN 3740 L (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: M/s Flying High Spray Painting
1 Kaki Bukit Ave 6
#01-29 Autobay @ Kaki Bukit
Singapore 417883
Contact: Mr. Zack @ 6749 2997 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Regards,
Elaine Toh (Secretary)
VISION LAW LLC



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 65342811 (Ext. 122) / Fax: 65356802

cc: SLN 3740 L – By email only

From: venessa.chan@fwd.com [mailto:venessa.chan@fwd.com]

Sent: Tuesday, 10 December, 2019 11:20 AM

To: Elainetoh@visionlawllc.com

Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com

Subject: PRE-REPAIR SURVEY --- YOUR REF: SLA 7601 Y --- ACCIDENT INVOLVING SLN 3740 L AND SLA 7601 Y ON 8 DECEMBER 2019 ALONG TUAS MALAYSIA CHECKPOINT AT ABOUT 1710 HOURS

WITHOUT PREJUDICE

Dear Elaine,

Refer to your email dated on 10.12.2019 of the PRI Notice of your client's vehicle SLN3740L;

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Tuesday, December 10, 2019 11:04 AM

To: Motor Claims SG - SG Common

Subject: PRE-REPAIR SURVEY --- YOUR REF: SLA 7601 Y --- ACCIDENT INVOLVING SLN 3740 L AND SLA 7601 Y ON 8 DECEMBER 2019 ALONG TUAS MALAYSIA CHECKPOINT AT ABOUT 1710 HOURS

Importance: High

**Our Ref: SLN 3740 L (et)
WITHOUT PREJUDICE**

Dear Sir/Madam,

We are instructed by **CHIA WAI MUN** to notify you of a road traffic accident on 8 December 2019 at about 1710 hours along Tuas Malaysia Checkpoint involving our client's motor vehicle registration number SLN 3740 L and motor vehicle registration number SLA 7601 Y driven by you/your insured at the material time.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh (Secretary)
VISION LAW LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 65342811 (Ext. 122) / Fax: 65356802

cc: SLN 3740 L – By email only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2019 12:38
Date Of Accident	08/12/2019 17:10
Exact Location Of Accident	TUAS MALAYSIA CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN3740L
Insured/Policyholder	
Name Of Registered Owner	CHIA WAI MUN
NRIC No	S8025432F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92212069
Alternative Phone No	OFFICE-92212069

Vehicle Particulars

Manufacturer	RENAULT
Model	MEGANE SEDAN

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10160444R00
Cover Note Number	

Driver

Name of Driver	CHIA WAI MUN
NRIC No	S8025432F
Date Of Birth	26/08/1980
Occupation	INDOOR
Date Of Driving Pass	21/06/2004
Driving Experience	15 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92212069
Fax Number	
Contact Number	OFFICE-92212069

Address	BLK 558 PASIR RIS ST 51 #05-297
Postcode	510558
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Passenger 1	NAME: : SUSAN LOH
	GENDER: : FEMALE

Passenger 2	NAME: : JOYCE CHIA
	GENDER: : FEMALE

Passenger 3	NAME: : JODY CHIA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON SUNDAY 08/12/2019, WHEN I WAS DRIVING STRAIGHT ON MALAYSIA SECOND LINK CHECKPOINT, THERE WAS A JAM, I CAME TO A STOP. WHEN THE CAR IN FRONT OF MY VEHICLE MOVE FORWARD, I MOVED MY CAR STRAIGHT FORWARD AS WELL. OUT OF A SUDDEN, I HEARD A SOUND AND FELT AN IMPACT COMING FROM THE LEFT HAND SIDE OF MY CAR (SLN3740L). I STEP OUT OF MY CAR AND TAKE A LOOK AND REALISED THAT VEHICLE B (SLA7601Y) COLLIDED ONTO THE LEFT HAND SIDE OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA7601Y
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B



Name of Driver	ANDREW
NRIC/Passport Number	
Contact Number	97992051
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the Sunday 8 of December 2019,
when I was driving straight on Malaysia Second link
Checkpoint, there was a Jam so I come to a stop.
When the car in front of my vehicle move forward,
I move my car straight forward as well, all of a
sudden I heard a sound and feel the impact
coming from the left hand side of my car. (SLN3740L)
I step out of my car and take a look and
realise that Vehicle B (SLA7601Y) collided into
the left hand side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Identification Card Pg. 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8025432F




Name
CHIA WAI MUN
(XIE WEIWEN)
谢委纹

Race
CHINESE

Date of Birth
26-08-1980

Sex
M

Country of Birth
SINGAPORE



A0111648



NRIC No. S8025432F



Group A

Date of issue
11-03-2002


APT BLK 558 PASIR RIS STREET 51 #05-297
SINGAPORE 510558

NRIC No: S8025432F


Date: 04/05/2011

No: 6782183

Driving License Pg. 1



Driving License Pg. 1



Budget Direct insurance

Certificate of Insurance

Comprehensive Car Policy
Policy Number: P10160444R00

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) (Republic of Singapore), Motor Vehicles (Third-Party Risks And Compensation) Rules, 1996 Edition (Republic of Singapore), Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Certificate Number P10160444R00 (Comprehensive / Named Driver Plan / Any Workshop)

1) Vehicle Registration Number	:	SLN3740L
Chassis Number	:	-
2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	:	28/04/2019 (00:00)
3) Date / Time of Expiry of Insurance	:	27/04/2020 (23:59)
4) Excess (i) Policy	:	S\$ 600.00
(ii) Windscreen	:	S\$ 100.00
5) Policyholder	:	Chia Wai Mun
6) Persons or Classes of Persons Entitled to Drive*	<p>Drivers named as a Main / Named Driver in this Certificate of Insurance only.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.</p> <p>Main Driver / Date of Birth : Chia Wai Mun (26/08/1980)</p> <p>Named Driver(s) / Date of Birth : SUSAN LOH AI PING (11/05/1978)</p>	
7) Limitation as to use*	<p>Use only for social, domestic and pleasure purposes. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p><i>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</i></p>	
8) Finance Company	:	NA

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Issued in Singapore on
30/03/2019

Auto & General Insurance (Singapore) Pte. Limited
Trading as Budget Direct Insurance



Simon Birch

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



TP FWD
Denise

SLN3740L

Renault Megane

VFIRFB800056852479

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Rear Bumper Rehd 1455 ✓

Rear Bumper Clips M 30 -

Rear Bumper Side Holder LH. Nec 75 ✓

Rear LH Fender. Reps 1675 +

Rear Windscreen Moulding. 2 185 +

Rear Windscreen Sealant. 1 60(SW) -

3115 Rear Wheel Rim HL. Lit 950(SW) 750(SW)

280350 Rear LH Door Dented 1390 ✓

SN 750 Rear LH Door Weatherstripe. Nec 165 ✓

Front LH Door Reps 1297 +

Front LH Door Weatherstripe. Nec 156 +

Whl 526350

L/S 4.2K

050up.

Panel Beating. 1710 ~~1500~~ 600 To remove rear 60 sensor 100.

Spry Painting. ~~1200~~ 30 To remove fuel tank. 150.

Wiring. ~~1200~~ 1500 X.

To undersoil ~~1500~~ 180 +

To remove rear windscreen. 300 80

To transfer door fittings. ~~150~~ 80

To remove upholstery

10953 11218

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2019 Edit Reg		10 Dec 2019 00:00 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Tay Wee Sin Andrew, ID: S7244399C		
Main Claimant:	CHIA WAI MUN, ID: S8025432F		
Vehicle Reg. No.:	SLN3740L	Date of Loss:	08/12/2019 16:00 - :59 [31 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900039010	Policy/Cover Note No.:	PNPV2018-00003363-01 (Comprehensive) Coverage: 16/03/2019 - 15/03/2020
Vehicle Reg. No. (Insured):	SLA7601Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Flying High Spray Painting (HQ) BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay, 417883 Kaki Bukit - Tel: 67492997		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

































***SLN3740L (1201900039010)**
[SLA7601Y]

TP
CHIA WAI MUN
Dec 8 2019 4:00PM
[Tay Wee Sin Andrew]
Flying High Spray Painting

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/19 09:56	Video - Accident	 Load AVI	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	11/03/20 18:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
33	11/03/20 18:15	General View	Load JPG	<input checked="" type="checkbox"/>
34	11/03/20 18:15	General View	Load JPG	<input checked="" type="checkbox"/>
35	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	11/03/20 18:15	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	11/12/19 09:56	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	Load PDF	
2	11/12/19 09:56	SLA7601Y OI GIA	Load PDF	
3	11/12/19 09:56	SLN3740L TP GIA.	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19021757/ATF3S2
Date: 16/03/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00003363-01
Claimant Vehicle No: SLN3740L Insured Vehicle No: SLA7601Y
Date of Loss: 08/12/2019 Nature of Claim: TP Claim No: 1201900039010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN3740L
Make & Model: RENAULT MEGANE, 1.5 SEDAN (A) Engine No: K9KG657R005419
Reg. Date: 28/04/2017 (Man. Year: 2016) Chassis No: VF1RFB00056852479
Colour: Grey Odometer: 53439 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,388.00	3,553.50	3,834.50	51.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,710.00	2,120.00	55.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,218.00	5,263.50	5,954.50	53.08
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	11,218.00	4,200.00	7,018.00	62.56

INSPECTION

Date of Assignment: 10/12/2019
Date Inspected: 11/12/2019 Inspected At: Flying High Spray Painting (HQ)
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
Parts:	143	RENAULT MEGANE 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3740L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,455.00 F	*1,455.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER LH	Necessary	75.00 F	*75.00 FL
4	1		*REAR LH FENDER	Repair	1,625.00 F	*- FL
5	1		*REAR WINDSCREEN MOULDING	Not Necessary	185.00 F	*- FL
6	1		*REAR LH DOOR	Dented	1,390.00 F	*1,390.00 FL
7	1		*REAR LH DOOR WEATHERSTRIP	Necessary	165.00 F	*165.00 FL
8	1		*FRONT LH DOOR	Repair	1,297.00 F	*- FL
9	1		*FRONT LH DOOR WEATHERSTRIP	Not Necessary	156.00 F	*- FL
10	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
11	1		*REAR WHEEL RIM LH	Cut	950.00 FS	*750.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,388.00	3,865.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	311.50
Total Parts (\$\$)	7,388.00	3,553.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,500.00	600.00
2	SPRAY PAINTING.	New	1,200.00	800.00
3	WIRING.	New	100.00	30.00
4	TO UNDERSEAL.	New	150.00	60.00
5	TO REMOVE REAR WINDSCREEN.	New	180.00	0.00
6	TO TRANSFER DOOR FITTINGS.	New	300.00	80.00
7	TO REMOVE UPHOLSTERY.	New	150.00	80.00
8	TO REMOVE REVERSE SENSOR.	New	100.00	60.00
9	TO REMOVE FUEL TANK.	New	150.00	0.00
Gross Labour Cost (\$\$)			3,830.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >