



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19021765/Upa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 08-05-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 1908L	Veh. Inspected	SJK 3326P
Policy No.	VPA/P2067734	Coverage (\$)	0.00
Claim No.	S9M029HB	Excess (\$)	0.00
Assign From		Assign Date	10/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ZNE100410762	Colour	GREY
Odometer	141324	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R17	MICHELIN	6 mm
L/H Front Tyre	215/50 R17	MICHELIN	6 mm
R/H Rear Tyre	215/50 R17	MICHELIN	6 mm
L/H Rear Tyre	215/50 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S & FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/12/2019	Inspection Date	10/12/2019
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	------------------------