

INS. CASE OWNER:

CC 3 / QBE1902 1775, Fearg

LKK:
IDAC:

Surveyor:

Ram

DOI:

ASSIGNMENT

a/w/19

Date / Time:

a/w/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

GDA 71514

Claim No. :

Name of Insured :

Lift Hub Engineering Pte Ltd

Policy No. :

Insured Tel No. :

HP:

Make / Model : Toyota Hilux 2.8 DG Double Cab (H)

Excess Sec II :S\$

D.O.A :

5/11/19

Place of Accident : Bukit Batok East Ave 3

Is driver the owner?

(YES / (NO))

Nature of Accident :

If NO, Driver Name / Age : Wang Liang Liang


Driver Tel No. : 9643 4906

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SH 90454



INSRS:

WSP:

Tel :

Liability :

RMKS:

L045
m

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time	STAGE	DATE / PIC
19-03-20	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	EMAIL 19/3/20
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice	☐ ☐
	LTA / GIA :	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by: RAM		
Repair Cost: 45 S\$600.00	(2 days) Reduction: 53 %	Email ☒ Call ☐
FINAL SETTLEMENT Date/Time: 01-04-20 Confirm with CAT		
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No. : 27	Email ☒ Call ☐
Repair Cost: 45 S\$642.00	OLD REAR ENDED TP:	If NO or B 28, Ass. Lia :
Loss of Rental (LOR): S\$ 166.01	(1.5 days) x 110.67	
Loss of Use (LOU): S\$ -	(\$ x days)	
Loss of Income (LOI): S\$ 75.00	(\$ 50 x 1.5 days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☒	[Tick only one]	
GIA/LTA Search	S\$ 7.49	
Medical:	S\$ -	
Disbursement:	S\$ -	(e.g. Tow/ Independent)
Legal Cost	S\$ -	
Total:	S\$ 890.50	Global Sum S\$: 890.00
FINAL PAYMENT Date/Time: 01-04-20 Confirm with: CAT		
Payee 1:	S\$ 890.00	Name 1: COMFORT DELGRO ENGINEERING PTE LTD
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9045U

DATE: 9. Dec. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 5. Dec. 2019

QBE

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>X(R)</i>			\$553.00
10	Rear Bumper Clips <i>X 1mm</i>		\$2.20	\$22.00
1	Rear Bumper Sponge <i>Xmm</i>			\$103.50
1	Rear Bumper Reinforcement <i>Xng</i>			\$428.40
1	Rear Bumper Undercover <i>Xmm</i>			\$228.00
SUB TOTAL				\$1,334.90
LESS 25%				\$333.73
DISCOUNTED TOTAL				\$1,001.17
1	Advertisement – Rear Bumper <i>rec</i>			\$50.00
2	Advertisement – Rear Fenders RH/LH <i>rec</i>		\$100.00	\$200.00
				\$250.00
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$250.00
1	Wiring Charge			\$50.00
1	Remove/refix Reverse Sensor			\$80.00
TOTAL LABOUR				\$680.00
ESTIMATE TOTAL				\$1,931.17
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DISCOUNTED TOTAL

Ram (LKK)

9/12/19 1330hrs

Parasuram LKK Auto.com

88622778 hp

45 aft repair photo

Larry Ng

Nett
Nett\$28
\$20
Xmm
Kma