

NS/INC 1902792 / FSL302

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLR 73284

Policy No. 5093574429-02 (27/08/2019-24/03/20)

Claims No. MT/1075061-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH 6545M

Yr Regn: 17/03/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai i40

C.C. 1685

Colour:

blue

A/C: Insured / Std / NI / NA

Sp. Reading

633773

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM HLB410M51035566

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

10/12/2019 11:10

D.O.I.

10/12/19

Survey held at

comfortdohmo (Layang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SH 6545M - NBA / INC 1902792/10/14

Rpt - 10/12/19

SLR 73284 - NBA / INC 1902792/10/14

PSA - 10/14/2019 INC

LIS: \$900/-

(2 repair days)

Confirm on 16/12/19 with LARRY.

(\$ 5,118.08

Red - 85%)

RECEIVED 18 DEC 2019

Date/Time: File Pass to?

17/12/19

1) Typist

Date/Time: File Return to?

2)

Pop out from 3

Find out from 10/12/19



Preli. Report



Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Meal and (\$

Survey Fee:

Transportation:

3 + PS. \$

Phone:

Other:

Total:

160

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5093574429-02		LOO EI-LEEN	58004947A	GPC	drive PREMIUM	SLR7328Y	SLR7328Y	25/08/2019	24/08/2020

TP Claims against NTUC Income: Follow-Through Survey

Date : 17/12/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	Not our insured	COMFORT TRANSPORTATION PTE LTD	SHA 1123Y	SIU 5226D	05/12/2019	07:45	\$ 3,275.68	\$ 1,395.81
2	MT/1075061-002	COMFORT TRANSPORTATION PTE LTD	SH 6545M	SLR 7328Y	10/12/2019	11:10	\$ 6,018.08	\$ 900.00
3	MT/1075118-002	COMFORT TRANSPORTATION PTE LTD	SHC 3383P	SFH 1618Z	08/12/2019	22:10	\$ 3,599.28	\$ 2,500.00
4	MT/1074824-002	COMFORT TRANSPORTATION PTE LTD	SHD 7183T	SKG 5243R	05/12/2019	19:20	\$ 4,846.88	\$ 2,500.00

Claim received from LKK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 13:46
Date Of Accident	10/12/2019 11:10
Exact Location Of Accident	BLK 28A HAVELOCK ROAD MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6545M
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAY TSENG AIK @ TAY CHEN AIK
NRIC No	S2552914F
Date Of Birth	26/07/1952
Occupation	OUTDOOR
Date Of Driving Pass	01/08/1975
Driving Experience	44 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96313678
Fax Number	
Contact Number	
Email Address	FRANCISTAY678@HOTMAIL.COM

Address	BLK 22 HAVELOCK ROAD #03-683
Postcode	160022
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR7328Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	FRT RIGHT
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Loke Wei Yeng
NRIC/FIN No.:

GIANIC Sketch Plan Form_V3



Sketch Plan Pg. 2

SKETCH PLAN



A: SH 6545 M

B: SLR 7328 Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/12/19 at about 11:10 hrs, I Veh A was driving out from above said location without pax. Suddenly Veh B coming from opposite side turning right and it front right portion collided onto the front right portion of my taxi.

No injury reported in this accident. Scene photo taken to support my claims.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199203931A

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wei Yieng
NRIC/FIN No.:

QARAD SWSCHENForm 95

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609280

320 Ubi Road Singapore 408099

24 Serangoon Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

801 Yishun Industrial Park A Singapore 768731

Date/Time: 10.12.2019 14:54

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305365749

CUSTOMER

VMS

CUSTOMER NO.

ADDRESS

L (R)

(P)

ACCOUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO.:

SH 6545M

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

10.12.2019 11:55

YR OF MANU.

17.03.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU085566

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 10.12.2019


NATURE: 3P 10.12.2019

S/NO

LABOR CODE

DESCRIPTION

NTUC - Right Front
Lkl/Ram.



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SH 6545M

LARRY

Vehicle No.:

SH 6545M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6545M

DATE: 10. Dec. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 10. Dec. 2019

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover Xnn			\$1,052.20
1	Front Bumper Side Bracket – RH xnn			\$24.60
1	Front Bumper Top Bracket – RH xnn			\$22.40
10	Front Bumper Clips xnn		\$2.20	\$22.00
1	Front Bumper Grille – RH xnn			\$41.60
1	Headlamp – RH xnn			\$1,388.00
1	Front Fender – RH BUC			\$566.30
1	Front Wheel Cover – RH sch			\$107.10
1	Front Rim – RH xnn			\$325.30
1	Front Lower Arm – RH xnn			\$529.30
1	Knuckle Arm – RH xnn			\$552.00
1	Wheel Bearing – RH ? xnn			\$150.90
1	Front Shock Absorber – RH xnn			\$342.20
1	Front Absorber Mounting – RH xnn			\$108.80
1	Steering Tie Rod End – RH xnn			\$62.60
1	Sabliazer Bar - RH xnn			\$252.30
SUB TOTAL				\$5,547.60
LESS 20%				\$1,109.52
DISCOUNTED TOTAL				\$4,438.08
1 Advertisement – RHF Fender				\$100.00
Labour Charge				\$100.00
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$50.00
1	Wiring Charge			\$50.00
1	Front Wheel Alignment			\$100.00
1	Remov/refix Front Undercarriage			\$180.00
TOTAL LABOUR				\$1,480.00
ESTIMATE TOTAL				\$6,018.08
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

\$538.72

Nett

\$280
\$200
\$50
xnn
xnn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to the surveyor's confirmation

Acknowledged by Repairer

Signature:

Date:

Larry Ng

Ram (LKK)

10/12/19 1340 hrs

Parasuram@lkkauto.com

88622778 hp

aft repair photo

45 \$900 =
2 repair days

Our Job Ref No : 305365749

Date : 14. Dec. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SH 6545M

Date of Accident: 10. Dec. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SLR7328Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \$900.00

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature :

Name : Ram

Date : 16/12/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19021792/Fsf3n2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-12-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 7328Y	Veh. Inspected	SH 6545M
Policy No.	5093574429-02	Coverage (\$)	0.00
Claim No.	MT/1075061-002	Excess (\$)	0.00
Assign From		Assign Date	10/12/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU085566	Colour	BLUE
Odometer	633773	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/12/2019	Inspection Date	10/12/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6545M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	NOT NECESSARY	1,052.20	-
1	FRONT BUMPER SIDE BRACKET-RH	NOT NECESSARY	24.60	-
1	FRONT BUMPER TOP BRACKET-RH	NOT NECESSARY	22.40	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT BUMPER GRILLE-RH	NOT NECESSARY	41.60	-
1	HEADLAMP-RH	NOT NECESSARY	1,388.00	-
1	FRONT FENDER-RH	BUCKLED	566.30	566.30
1	FRONT WHEEL COVER-RH	SCRATCHED	107.10	107.10
1	FRONT RIM-RH	NOT NECESSARY	325.30	-
1	FRONT LOWER ARM-RH	NOT NECESSARY	529.30	-
1	KNUCKLE ARM-RH	NOT NECESSARY	552.00	-
1	WHEEL BEARING-RH	NOT NECESSARY	150.90	-
1	FRONT SHOCK ABSORBER-RH	NOT NECESSARY	342.20	-
1	FRONT ABSORBER MOUNTING-RH	NOT NECESSARY	108.80	-
1	STEERING TIE ROD END-RH	NOT NECESSARY	62.60	-
1	STABILIZER BAR-RH	NOT NECESSARY	252.30	-
	LESS 20% DISCOUNT		-1,109.52	-134.68
			4,438.08	538.72
<u>SPECIAL NETT ITEMS</u>				
1	ADVERTISEMENT-RHF FENDER (SN)	NECESSARY	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING.		600.00	280.00
	SPRAY PAINTING CHARGE.		500.00	200.00
	TUFF KOTE.		50.00	30.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	FRONT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	REMOVE/REFIX FROTN UNDERCARRIAGE.	NOT NECESSARY	180.00	-
			1,480.00	510.00

Report Ref No. NS/INC19021792/Fsf3n2



Page No.:2 of 2

GRAND TOTAL		6,018.08	1,148.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			900.00

Report Ref No. NS/INC19021792/Fsf3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.