

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping
LKF - Ram. CLS

(Fri)

Date: 06.12.2019

Time: 17:45:33

Page: 1/2

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305359825
REGN NO : SHD3114U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 16.06.2016
DATE/TIME IN : 06.12.2019 13:40
ACCIDENT DATE : 06.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	X(R)
0002	04-01-0103-0782-A	HEADLAMP RH	1	1,388.00	20.00	1,110.40	Xnn
0003	04-01-0103-0573-A	FRT FENDER RH	1	663.00	20.00	530.40	X(R)
0004	04-01-0103-4991-G	FRT BUMPER GRILLE RH	1	51.70	20.00	41.36	Xnn
0005	04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	Xnn
0006	04-01-0103-0640-G	FRT FENDER RETAINER RH	1	24.60	20.00	19.68	Xnn
0007	04-01-0103-0658-G	FRT WHEEL CAP RH	1	107.10	20.00	85.68	scr
0008	04-01-0103-0594-G	WING MIRROR RH	1	670.00	20.00	536.00	X(R)

\$85.68

SUB-TOTAL : 3,183.20

JOB NATURE

0000	PB	PANEL BEATING	600.00	\$560
0001	SP	SPRAYPAINT CHARGE	500.00	\$450
0002	17-01	CHECK ALL LIGHTING	40.00	\$20

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE *China Taiping CLJ*
LKK - Ram.

(Fri)
Date: 06.12.2019
Time: 17:45:33
Page: 2/2 *TS*

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305359825
REGN NO : SHD3114U
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 16.06.2016
DATE/TIME IN : 06.12.2019 13:40
ACCIDENT DATE : 06.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 20-00 TUFF COAT ON AFFECTED PARTS.

40.00 *Xmn*

0004 L WHEEL ALIGNMENT

120.00 ~~Xmn~~ \$60

SUB-TOTAL : 1,300.00

Lmk

TOTAL : 4,483.20

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Ram (LKK)
10/12/19 1200hrs
Parasuram@lkkqato.com
88622778 *(L/S)*
add repair photo
(3 repair days)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: