

22/03/2012

ASS. REC. BY:

REF:

CS3/CTI/9021844/Cyd3en

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Ben tung

of

CTI

Date/Time: 11/12/19 @ 2:16pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJN 9817J

Insured:

GBJ 903SP

at Workshop m/s

Gold Autoworks

Tel:

8199 9149

of

18 Jln Guan Road East # 01-119

Policy No:

Claim No:

SNM190205862

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:23pm @ 11/12/19

Person Contacted:

Simon

Vehicle IN/OUT

Date/Time	Action/Instruction
	Polymold (X)
	SJN 9817J - CS3/7MT12004827/Rlyh
	GBJ 903SP - X

DA: 4/3/2012

Burrup

Steve

REF: CT1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJN 9877J

Yr Regn: 9/3/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish

c.c 1794

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading 345968

T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo: JTOER12W 903002153

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rm / STD A/Rlm or

Tyre Size: F: 215/59R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 9/12/19

D.O.I. 11/12/19

Survey held at

Gold Auto

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-33K

Repair large

Repair days

5K-6K

8 days

9/11/2020

RECEIVED 13 JAN 2020

Date/Time, File Pass to?

☐ : Proll. Report

Days Of Repair: 8

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

2)

9/1/20 Typist

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Insp (\$☐ : Weekend (\$

Transportation:

) S + RS, SI

) Pkgs

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

150

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 11 December 2019 2:16 PM
To: claims@goldautoworks.com.sg
Cc: Claims Dept of CTI; assignments
Subject: RE: OUR REF: SNM19D205862/GBJ9035P/BEN - Requesting for PRE-Repair survey for our vehicle number SJN9817J

Dear Sirs

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: claims@goldautoworks.com.sg <claims@goldautoworks.com.sg>
Sent: Tuesday, December 10, 2019 3:39 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205862/GBJ9035P/BEN - Requesting for PRE-Repair survey for our vehicle number SJN9817J

Without Prejudice

Dear Sir/Madam,

We have instructions to reject your surveyors and propose to engage a surveyor from the list below:-

- 1) Appraisal VP Pte Ltd - Victor Png
- 2) Appraisal VP Pte Ltd - Jaclyn Loh
- 3) Prominent Appraisal - Hon Andrew
- 4) Absolute Appraisal Services Pte Ltd - Nicky Seah

Kindly see our attached letter and the workshop details as below:-

Workshop Name: Gold Autoworks Pte Ltd
Address: 48 Toh Guan Rd East, Enterprise Hub #01-119 Singapore 608586 Contact Person: Simon Contact Number: 8199-9149

THANKS & REGARDS,
SIMON TAN
GOLD AUTOWORKS PTE LTD
8199-9149

On 2019-12-10 15:22, Ben Tang wrote:

> WITHOUT PREJUDICE

>

> Dear Sir,

>

> We intend to conduct a pre-repair survey of the damage to your
> client's vehicle jointly with your client/your motor workshop. We
> propose to use one of the following motor surveyors to conduct the
> joint pre-repair survey as a single joint expert.

>

> LKK / LBS / STA

>

> ADRIAN LING

>

> Kelvin Ang

>

> SEE CHEW SENG

>

> MOHD FADHILAH BIN OSMAN

>

> XING QUO QIANG

>

> KENNETH KONG

>

> SIMON HO

>

> CHUA WEIJIE

>

> MARCUS CHUA

>

> HENRY NG

>

> Please let us know within two(2) working days whether you agree to the
> appointment of any of these motor surveyors as a single joint expert.

>

> You may select one of the listed motor surveyors and we will bear the

> cost of the pre-repair survey carried out by the single joint expert.
>
> Thank you.
>
> Best Regards
>
> Ben Tang
>
> Executive
>
> Claims Department
>
> CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
>
> 3 Anson Road #XX-00 Springleaf Tower Singapore 079909
>
> DID: (65) 6389 6175 | F: (65) 6222 1033
>
> W: www.sg.cntaiping.com [1] | FB:
> www.facebook.com/chinataipingsg/ [2] | WECHAT: 太平狮城
> Taiping SG
>
> _Disclaimer: This e-mail and any files transmitted with it is intended
> only for the named recipients and may contain confidential
> information. Any unauthorized disclosure, use or dissemination of this
> message, either in whole or partial, is prohibited. If you are not the
> intended recipient, please notify the sender immediately. Please
> delete the e-mail and any copies of it thereafter._
>
> -----Original Message-----
> From: Lim Shu Min
> Sent: Tuesday, December 10, 2019 3:16 PM
> To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow
> <sochow.chee@sg.cntaiping.com>; claims@goldautoworks.com.sg
> Subject: OUR REF: SNM19D205862/GBJ9035P/BEN - Requesting for
> PRE-Repair survey for our vehicle number SJN9817J
>
> Dear Ben,
>
> Please conduct PRS for SJN9817J.
>
> Note : officer in charge – Ben Tang 63896175.
>
> *** Kindly quote our reference number when replying.
>
> Thank you
>
> Lim Shu Min
>
> Executive
>
> Claims Department
>
> China Taiping Insurance (Singapore) Pte. Ltd.
>

> 3 Anson Road #15-00 Springleaf Tower Singapore 079909
 >
 > DID: (65) 63896156 | F: (65) 62247175
 >
 > W: www.sg.cntaiping.com [3] | FB:
 > www.facebook.com/chinataipingsg/ [2] | WeChat: 太平狮城
 > Taiping SG
 >
 > Disclaimer: This e-mail and any files transmitted with it is intended
 > only for the named recipients and may contain confidential
 > information. Any unauthorized disclosure, use or dissemination of this
 > message, either in whole or partial, is prohibited. If you are not the
 > intended recipient, please notify the sender immediately. Please
 > delete the e-mail and any copies of it thereafter.
 >
 > -----Original Message-----
 >
 > From: claims@goldautoworks.com.sg [mailto:claims@goldautoworks.com.sg]
 >
 >
 > Sent: Monday, 9 December, 2019 6:50 PM
 >
 > To: DL-CLAIMS <claims@sg.cntaiping.com>
 >
 > Subject: Requesting for PRE-Repair survey for our vehicle number
 > SJN9817J
 >
 > ATTENTION MOTOR CLAIM DEPARTMENT
 >
 > Dear Sir/Mdm,
 >
 > Accident involving SJN9817J & GBJ9035P AT PIE > TUAS (NEAR ADAM ROAD
 > EXIT 20A)
 >
 > 1. We are here to notify you of a road traffic accident on 09/12/19
 > 07:30HRS at PIE > TUAS (NEAR ADAM ROAD EXIT 20A) involving our client
 > vehicle registration
 >
 > number SJN9871J and vehicle registration number GBJ9035P driven by
 > your insured at the material time.
 >
 > 2. As a result of the accident, our client vehicle SJN9817J has been
 > damaged. Please arrange and conduct a PRE- REPAIR SURVEY of the say
 > vehicle. If
 >
 > we do not receive any reply from you within the stipulated timeline,
 > our client shall proceed to repair the vehicle without further
 > reference to you.
 >
 > 3. Please arrange a PRE-REPAIR SURVEY at 48, TOH GUAN RD EAST,
 > ENTERPRISE HUB #01-119 S(608586)
 >
 > THANKS & REGARDS,
 >
 > SIMON TAN

>
> GOLD AUTOWORKS PTE LTD

>
> 8199-9149

>
>
> _____
>

> This email has been scanned by the Symantec Email Security.cloud
> service.

>
> For more information please visit <http://www.symanteccloud.com> [4]

> _____
>

> Links:

> -----

- > [1] <http://www.sg.cntaiping.com/>
- > [2] <http://www.facebook.com/chinataipingsg/>
- > [3] <http://www.sg.cntaiping.com>
- > [4] <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2019 18:01
Date Of Accident	09/12/2019 07:30
Exact Location Of Accident	PIE > TUAS (NEAR ADAM RD EXIT 20A)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN9817J
Insured/Policyholder	
Name Of Registered Owner	ALTITUDE CAR LEASING PTE LTD
Co Reg No	201703858E
Email Address	ENQUIRY@ALTITUDELEASING.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-81812300

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	999994236
Cover Note Number	02/05/2019-01/05/2020

Driver

Name of Driver	MUHAMAD HAFIDZ BIN YUB
NRIC No	S7811943H
Date Of Birth	28/04/1978
Occupation	OUTDOOR
Date Of Driving Pass	12/09/2006
Driving Experience	13 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92375597
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 359 YUNG AN ROAD #11-71
Postcode	610359
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : JESSICA WATSON GENDER: : FEMALE
Passenger 2	NAME: : LAVRYN MARY GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKECTH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ9035P
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE GUAN HOCK
NRIC/Passport Number	S0233686C
Contact Number	85184055
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 9/12/19

Reporting Centre Personnel's Signature
Name: Rakeshwaran, Arund
NRIC/FIN NO:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 4/12/19 at around 2.30 am I was driving Veh A: SJN 9817J travelling on PIE towards Tuas with 2 passenger inside my car. Suddenly a red vehicle bearing carplate no: SLF 1145K (Ever Chieh Zhuo Kai) cut into my lane without signal, I then apply brake unfortunately behind Veh B: GBJ 9035P can't brake in time and collided to my car.

I confirm that I didn't bang the red car: SLF 1145K; that's no damaged on the front end of my car.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- ☒ Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time 4/12/19

Reporting Centre Personnel's Signature
Name: Rakeswaran, Arun d
Nric/Fin No.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	858E
Vehicle Details	
Vehicle No.:	SJN9817J
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1ZZ3232746
Chassis No.:	JTDER12W903002153
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	09 Mar 2009
First Registration Date:	09 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$18,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$16,509.00
COE Rebate Amount:	\$13,999.00
Total Rebate Amount:	\$13,999.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Dec 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal COE Toyota Wish 2.0A.



2.0 litre P.A. 15 Valve, Horizontally
Front Drive, 2 Years Warranty,
Engine And Gearbox,
GV Credit. [View](#)


[Browse by Category](#)
[Back \(1 2 3 4 5 6 7 8 \)](#) [Next](#)
[Sort by Date Posted](#)
[20 results/page](#)

149 vehicles

Toyota Wish

Advanced Search

Price	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Notes
Search Selection	Toyota Wish	Any	Any	> 10 year(s) old	Any	Any	Any	Available



Toyota Wish 1.8A (COE till 10/2028)

\$49,800

\$5,600 /yr

30-Oct-2008

1,794 cc

-

MPV

Available

2 Owners! Low Mileage! Most Popular 7 Seater Japanese MPV Well Known For It's Reliability And Space. Perfect Ride For More Than 10 Years, Great Condition Despite Its Age. A Good Car For Family Usage. Hurry Contact Our Sales Person Before It's Taken, Flexible Loan S...

Posted: 15-Nov-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (COE till 11/2028)

\$54,000

\$6,010 /yr

01-Dec-2008

1,794 cc

138,000 km

MPV

Available

Decent Mileage, No Repairs Needed To Be Done. All Fluids Had Been Flushed By Me Recently. Beautiful Paintwork With Clean Interior! Selling Due To Upgrade. Price Slightly Negotiable For Fast And Sincere Buyers. No Dealers Or Consignments Please. Car Has Never Been...

Posted: 20-Nov-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (COE till 12/2028)

\$47,900

\$5,310 /yr

17-Dec-2008

1,794 cc

-

MPV

Available

A Popular Family MPV. New Paintwork, Super Condition, Very Well Maintained, Flexible Financing, Bank/In House Finance Available. Call Us For A Discussion.

Posted: 08-Dec-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (COE till 01/2029)

\$51,500

\$5,660 /yr

16-Jan-2009

1,794 cc

-

MPV

Available

1 Owner Only! Intend To Drive Longer For This Beloved Family Car, Therefore Rewrapped The Leather Seats, Changed The Tyres And Renew The COE For Another 10 Years. But Wife Wants To Change To Another Bigger MPV As Family Is Growing! Therefore Have To Sell...

Posted: 25-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Wish 1.8A Aero Tourer (COE till 02/2024)

\$25,800

\$6,170 /yr

16-Feb-2009

1,794 cc

200,000 km

MPV

Available

Very Nice Paint Work.

Posted: 06-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 02/2029)

\$51,800

\$5,620 /yr

02-Mar-2009

1,794 cc

100,000 km

MPV

Available

Consignment Code: A399. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Posted: 29-Nov-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 03/2024)

\$33,800

\$7,950 /yr

11-Mar-2009

1,794 cc

-

MPV

Available

Full Loan Monthly \$800! Grab, Go-Jek Are Welcome! Many Other Loan Scheme At Your Comfort. Cheap And Practical 7 Seaters Up For Sale. Reliable Engine And Gearbox, Low Maintenance Cost. Call Us View And Test Drive! Don't Miss It Hurry!

88 Motor Trading

Posted: 09-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 02/2029)

\$52,000

\$5,640 /yr

20-Mar-2009

1,794 cc

107,000 km

MPV

Available

Low Mileage Done. 100% Loan Available! No Repairs Needed To Be Done, Very Well Maintained By Previous Owner! Beautiful Paintwork With Clean Interior! High Demand MPV In The Market Now! Excellent Condition, View To Believe. Hurry, Call To View! Viewing By Appt...

Posted: 26-Nov-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A (COE till 03/2024)

\$36,800

\$8,610 /yr

20-Mar-2009

1,794 cc

150,000 km

MPV

Available

Well Maintained. Loans Available, With Lowest Interest Rates. High Trade-In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.

Car Search

Posted: 15-Nov-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A X (COE till 03/2024)

\$35,800

\$8,320 /yr

30-Mar-2009

1,794 cc

-

MPV

Available

Loan Available! Optional For 5 Or 10 Years COE Renewal, 1 Years Extended Engine And Gearbox Warranty! Engine And Gearbox (Great). Exterior (Free Respray). Interior (Great). Undercarriage (Great). Trade In Welcome. Call Our Friendly Sales Consultant Today To View A...

Posted: 08-Dec-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Don't get caught without proper car insurance!

Does your car insurance have the features that you really need? Check against this guide and find out if you're getting the right car insurance benefits.

Find out more!

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Dec 2019		13 Dec 2019 13:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	ALTITUDE CAR LEASING PTE LTD	
Vehicle Reg. No.:	SJN9817J	Date of Loss: 09/12/2019 07:00 - :59 [129 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205862/GBJ9035P/BEN	Policy/Cover Note No.: DMCVSN3073291900 (Comprehensive)
Vehicle Reg. No. (Insured):	GBJ9035P	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	Gold Autoworks Pte Ltd (HQ) 48 TOH GUAN ROAD EAST, #01-119 ENTERPRISE HUB, 608586 Jurong East - Tel:	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 24/12/2019]	












































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

































ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SJN9817J (SNM19D205862/GBJ9035P/BEN)
[GBJ9035P]**

**TP
ALTITUDE CAR LEASING PTE LTD
Dec 9 2019 7:00AM
[-]
Gold Autoworks Pte Ltd**

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
2	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/01/20 10:01	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
5	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/01/20 10:01	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
30	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/01/20 10:01	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/01/20 10:02	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/01/20 10:02	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/01/20 10:02	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/01/20 10:02	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
39	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
40	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
41	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
42	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
43	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
45	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
46	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
47	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
48	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
49	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
50	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
51	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
52	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
53	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
54	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
55	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
56	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
57	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
58	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
59	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
60	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
61	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
62	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
63	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
64	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
65	09/01/20 10:03	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
66	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	09/01/20 10:03	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19021844/EYD3E2

Date: 15/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3073291900

Claimant Vehicle No: SJN9817J Insured Vehicle No: GBJ9035P

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: SNM19D205862/GBJ9035P/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN9817J**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3232746

Reg. Date: 09/03/2009 (Man. Year: 2009) Chassis No: JTDER12W903002153

Colour: White Odometer: 345968 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 11/12/2019 Inspected At: Gold Autoworks Pte Ltd (HQ)
48 TOH GUAN ROAD EAST, #01-119
ENTERPRISE HUB
Singapore 608586

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN9817J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >