

INAC

INS. CASE OWNER:

CC 6 / AIG18015775, AIG

LKC

IDAC

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$5

Is driver the owner?

SKU 1117A

SOH N UERN (SH UERN)

HP: 87777777

D.O.A: 2/8/18

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: UM SWE KANT TIAOCH

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

2018/18

2018/18

KIA

LA TMS WOODLANDS HOSPITAL

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

SKO WRAP



INSRS:

WSP:

Tel:

Liability:

RMKS:

madison



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

20/8/18
vivan

31/18

SKO WRAP - 4

SKU 1117A - 4

confirm accident inform if claim
later and out
email workshop liability under

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call OI	
After call 1st to OI	2/9/18 JIBUN
Documentation Check List:	Handler Typist
Notification 1st (if non-pickup)	
After call 1st to OI	
Authorisation To Act	
Release Voucher	
Final Repair Bill	
Car Rental Invoice	
Towing Invoice	
LTA / GIA	
Medical Bill	
PIR	
Mandate/Reject Instruction	
LOD	
Payment Breakdown Form	
Post-Repair Photos	
Others	

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	%	SD (Agreed / Assessed) BOLA S/N No.:	NIL
Repair Cost:	\$5		
Loss of Rental (LOR):	\$5	(days)	
Loss of Use (LOU):	\$5	(\$ x days)	
Loss of Income (LOI):	\$5	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		[Tick only one]	
GIA/LTA Search	\$5		
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow/ Independent)	
Legal Cost	\$5		
Total:	\$5	Global Sum \$5:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5	Name 1:	
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

COPY SENT
24/2/2021

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: 0/0
- 3) Survey fee: 4330

ASS. RES. BY Adrian Ling

REF:

W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: ∞ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD2239DYr Regn: 2011 / NovType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Scirocco cc 1390Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 104513 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 222 132 CV 910411Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/40 R18R: 235/40 R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 30/08/18Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

45: \$1,000 (CED: \$2,616.90 72%)

Date/Time, File Pass to?

☐

: Prefl. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + P.S. \$

Photos: _____

Others: _____

TOTAL

Report Format _____

Lump Sum / L.B.E (\$) _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18015775/wb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-08-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 1117A	Veh. Inspected	SKD 2239P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/08/2018	Inspection Date		
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SKD2239P

Volkswagen Scirocco.

WVW222132CV010011

Rear Bumper. 14yr 1121 +

Rear Bumper Clips Not ~ 30 /

Rear Bumper Reinforcement. ~ 570 +

Rear Bumper Lower Spoiler ~ 820 ✓

Reverse Sensor ~ 280 (SN) /

LKK Auto Consultants hence notify the Reparer of the following:

- To Re-survey before after spray painting
- To discuss "unpainted parts" during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

~~Labour~~

Panel Beating

Spray Painting

Wiring

To remove reverse sensor

~~400~~ 200

~~500~~ 300

~~50~~ 30

~~120~~ 60

List: 820

Gen 10%: 738

Labour 590

Total: 1328

V/S: 1K

03 Days



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18015775/wb3

04 September 2018

Soh Li Chern

Blk 788 Choa Chu Kang North 6

#14-214

Singapore 680788

Dear Sir/Madam,

ACCIDENT INVOLVING SKU 1117A & SKD 2239P ON 27/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 17/09/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 21 February 2020 10:20 AM
To: Foo, Chityan
Subject: Your Ref: 9333312597SG // ACCIDENT INVOLVING SKD 2239P AND SKU 1117A ON 27/08/2018

Your Ref: 9333312597SG

Hi Jimmy,

We refer to the above matter.

ACCIDENT INVOLVING SKD 2239P AND SKU 1117A ON 27/08/2018

We were informed by TP workshop that claimant do not come back to their workshop for repair up to date.

In view of the above, We will proceed to submit our w/p report and close file.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Aug 2018 Edit Reg		30 Aug 2018 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Soh Li Chern (Su Lizhen) , ID: 57521025F									
Main Claimant: CHONG BOON KYAN , ID: S8970267D									
Vehicle Reg. No.: SKD2239P		Date of Loss: 27/08/2018 13:00 - :59 [81 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9333312597SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SKU1117A		Policy No. (Claimant): 5098761468							
Excess:									
Repairer: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKD2239P (9333312597SG)
[SKU1117A]

TP
CHONG BOON KYAN
Aug 27 2018 1:00PM
[Soh Li Chern (Su LiZhen)]
Modern Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Photos/Images										1 per page 1 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	20/02/20 17:52	General View		Load JPG	☒						
2	20/02/20 17:52	General View		Load JPG	☒						
3	20/02/20 17:52	General View		Load JPG	☒						
4	20/02/20 17:52	General View		Load JPG	☒						
5	20/02/20 17:52	General View		Load JPG	☒						
6	20/02/20 17:52	General View		Load JPG	☒						
7	20/02/20 17:52	General View		Load JPG	☒						
8	20/02/20 17:52	General View		Load JPG	☒						
9	20/02/20 17:52	General View		Load JPG	☒						
10	20/02/20 17:52	General View		Load JPG	☒						
11	20/02/20 17:52	General View		Load JPG	☒						
12	20/02/20 17:52	General View		Load JPG	☒						
13	20/02/20 17:52	General View		Load JPG	☒						
14	20/02/20 17:52	General View		Load JPG	☒						
Documentation										1 per page 1 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	29/08/18 17:06	TP GIA REPORT		Load PDF							
2	21/02/20 10:21	EMAIL TO AIG DD 210220		Load PDF							
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print						
1	30/08/18 09:24	OI GIA REPORT		Load PDF							

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)						
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.						

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18015775/AES3Q2

Date: 26/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SKD2239P

Insured Vehicle No : SKU1117A

Date of Loss: 27/08/2018

Nature of Claim: TP

Claim No: 9333312597SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD2239P

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 (A)

Engine No: HIDDEN

Reg. Date: 01/11/2011 (Man. Year: 2011)

Chassis No: VWWZZZ13ZCV010411

Colour: Blue

Odometer: 104513 km

Engine Capacity: 1390 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18

Rear Tyre Size: 235/40 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,821.00	738.00	2,083.00	73.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	590.00	460.00	43.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,871.00	1,328.00	2,543.00	65.69
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	3,871.00	1,000.00	2,871.00	74.17
+ GST 7.00/7.00% (S\$)	270.97	70.00	200.97	74.17
Nett Amount (S\$)	4,141.97	1,070.00	3,071.97	74.17
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 30/08/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,121.00 F	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	30.00 F	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	570.00 F	*- FL
4	1		*REAR BUMPER LOWER SPOILER	Deformed	820.00 F	*820.00 FL
5	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
Sub Total (\$\$)					2,821.00	820.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	82.00
Total Parts (\$\$)					2,821.00	738.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	500.00	300.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
Gross Labour Cost (S\$)			1,050.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >