

ASS. REC. BY:

REF: CS3/ASM19021879/RH f30 Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Oh Vale of ASM (AXA) Date/Time: 12/12/19 10:06am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 2910B Insured: PBL 5156P

at Workshop m/s my car consultant Tel: 88668832

of 53 Ubi Ave 1, Pagar Ubi Industrial

Policy No: Claim No: S9M029T5

Sum Insured: Excess:

Make of Veh: D.O.A. 9.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 12-12-19 10:09am Person Contacted: Hui Qin Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SMA 2910B - NA / AIG 19021645124 Rat - 09/12/2019
	PBL 5156P - X
	* Rasu mentioned TP owner should be report for 2 accident reporting due to involved 2 vehicle.
13/12/19 @ 11:02am	have clarified with Hui Qin (wks), she said one report can claim two different insurance as accident happened on same time. Anything else can call later.

ASS. REC. BY:

REF:

ASM (AXA)

5976

ASSIGNMENT

From: _____ Date: 12.12.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 2910Bat Workshop m/s my car consultantof 53 ubi Ave 1 #01-33

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 886 L8832

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 190K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS np.7

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMA 2910B Yr Regn: 2018 mayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: JAGUAR F-PACE 2.0P C.C. 1997Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 0/8001 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SADCB2AX4JA 265 809Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R19R: 2"BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 09/12/19D.O.I. 12/12/19 1118AMSurvey held at MY CAR CONSULTANT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear & Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range & Days — <u>5-6</u> / 4 days <u>19/12/2019</u>
<u>19/12@2:07pm</u>	<u>check with him in confirm not no estimate</u>
<u>20/12-</u>	<u>upload IA in SMART CLAIM. & photo</u>
	Dismantle part: <u>13/12/2019</u> RECEIVED 10 JAN 2020
	After repair: <u>16/12/2019</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 41) 101 Typist☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 100

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

100Rep. Format: PRS

Lump Sum / F.B. / C




Service Request Details

Claim

S9M029T5

Reference

None 

Loss Date

December 9, 2019

Report Date

Dec 11, 2019 1:24:19 PM

Request Date

December 11, 2019

Due Date

December 18, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SMA2910B

Model

F-PACE 2.0P RWD

Service Address

...

Primary Contact/Insured

ABDUL SALAM MUHAMMAD FAIZAL BIN

BLK 218 YISHUN STREET 21, #02-363, 760218, Singapore

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

4

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Summer Lee (LKK Auto)

From: My Car Consultant <admin@mycar.sg>
Sent: Wednesday, 11 December, 2019 11:46 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] OUR REF: SMA2910B YOUR REF: FBL5156P PRE-REPAIR INSPECTION FOR SMA2910B
Attachments: SMA2910B_09122019 (1).pdf
Categories: Namrata

WITHOUT PREJUDICE

OUR REF: SMA2910B
YOUR REF: FBL5156P

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SMA2910B
ACCIDENT INVOLVING SMA2910B AND FBL5156P

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd



[+65 88668832](tel:+6588668832)

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

DHIWAR Namrata

From: My Car Consultant <admin@mycar.sg>
Sent: Wednesday, December 11, 2019 11:46 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] OUR REF: SMA2910B YOUR REF: FBL5156P PRE-REPAIR INSPECTION FOR SMA2910B
Attachments: SMA2910B_09122019 (1).pdf
Categories: Namrata

WITHOUT PREJUDICE

OUR REF: SMA2910B
YOUR REF: FBL5156P

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SMA2910B
ACCIDENT INVOLVING SMA2910B AND FBL5156P

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd



[+65 88668832](tel:+6588668832)

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

Summer Lee (LKK Auto)

From: Weng Kit <wengkit@chiaarul.com>
Sent: Tuesday, 10 December, 2019 9:49 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'Jerone'
Subject: [EXTERNAL] Our Ref: FBE 6447E (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING FBE 6447E & YK 7644S ALONG TUAS SOUTH BOULEVARD ON 23 OCTOBER 2019
Attachments: 20191210094746391.pdf
Categories: Namrata

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 10 December 2019 for your attention.

Best Regards,

Weng Kit (Mr.)

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	597G
Vehicle Details	
Vehicle No.:	SMA2910B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2019
Vehicle Make:	JAGUAR
Vehicle Model:	F-PACE 2.0P RWD
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	170727Y0137PT204
Chassis No.:	SADCB2AX4JA265809
Maximum Power Output:	184.0 kW (246 bhp)
Open Market Value:	\$54,866.00
Original Registration Date:	31 May 2018
First Registration Date:	31 May 2018
Transfer Count:	0
Actual ARF Paid:	\$70,759.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2028
PARF Rebate Amount:	\$53,069.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,700.00
COE Rebate Amount:	\$32,076.00
Total Rebate Amount:	\$85,145.00

The information contained herein is correct as at 20 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 11:12
Date Of Accident	09/12/2019 13:15
Exact Location Of Accident	PIE (TUAS) BEFORE LOR 6 TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA2910B
Insured/Policyholder	
Name Of Registered Owner	KINOSHITA CHIKAKO
NRIC No	S7087597G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96740144
Alternative Phone No	OFFICE-96740144

Vehicle Particulars

Manufacturer	JAGUAR
Model	F-PACE 2.0P RWD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800063470
Cover Note Number	

Driver

Name of Driver	KINOSHITA CHIKAKO
NRIC No	S7087597G
Date Of Birth	05/09/1970
Occupation	INDOOR
Date Of Driving Pass	07/12/2012
Driving Experience	7 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96740144
Fax Number	
Contact Number	OFFICE-96740144
EEmail Address	NOEMAIL

Address	65 CAIRNHILL ROAD #23-02
Postcode	229721
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ6064G
Vehicle Make/Model/Colour	BMW 5 SERIES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	FBL5156P
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(*) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Reporting Centre Personnel's Signature
Name: _____
NTSC/FIN No.: _____

Accident Sketch Plan

SKETCH PLAN PSE towards turn before Lor 6 Tanjong

Veh: A
SMA 2410 B
Veh: B
SLJ 6064 G
Veh: C
FBL 5156 P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


ON the stated time and date.

I was travelling my vehicle bearing car plate SMA 2410 B along PSE towards turn before Lor 6 Tanjong. The traffic was stationary. I was moving slowly. Suddenly I felt a great impact from my rear. I alighted and realise a vehicle bearing car plate SLJ 6064 G was collided on my rear. There was another motorbike bearing license number FBL 5156 P which collided onto the left side of my vehicle just right after I was rear ended by SLJ 6064 G.

DECLARATION

(We declare the foregoing particulars are true in every respect.)


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/TIN No.:

10/10/2017 10:00 AM



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19021879/R1tf3e2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date: 16-01-2020		
ATTN : OH VALE		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBL 5156P	Veh. Inspected	SMA 2910B	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M029T5	Excess (\$)	0.00	
Assign From	OH VALE	Assign Date	12/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR F-PACE 2.0P	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SADCB2AX4JA265809	Colour	BLACK	
Odometer	18001 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/55 R19	PIRELLI	6 mm	
L/H Front Tyre	255/55 R19	PIRELLI	6 mm	
R/H Rear Tyre	255/55 R19	PIRELLI	6 mm	
L/H Rear Tyre	255/55 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR AND REAR N/S PORTION.				
5. General Information				
Accident Date	09/12/2019	Inspect Date / Time	12/12/2019 (11:18 AM)	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/ASM19021879/R1tf3e2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.