

ASS. REC. BY:

REF: CS/CTI 19021887/Ha f3ek Special Instruction:

Surveyor: Hock AnnASSIGNMENT (Office)

From (Person):

Ben King

of

CTI

Date/Time:

12.12.19 9.16.47

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 9246 L

Insured:

4P 96696

at Workshop in/s

I - One Automotive

Tel:

66342112

of

1 Kaki Bukit Ave 6 # 01-85 / 87 Autobay

Policy No:

DMCUSN19002419000

Claim No:

SNM1117205891

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9.12.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

12.12.19 10.49.47

Person Contacted:

Syafirah

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKF 9246 L - X4P 96696 - NA / MSG 19/12/2019P.OD - 23/08/2019survey photo → 18/12/19Recovery photo → 19/12/19after photo → 23/12/19

ASS. REC. BY: H-AUN

REF: CT1

ASSIGNMENT

From: _____ Date: 18.12.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKF 9246L

at Workshop m/s: Z-ONE Automotive

of 1 Kari Bukit Ave 6 Blk C #01-52 Aukbay

Insured: 01-87

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 66342112 Shah After 1100a.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF 9246L Yr Regn: 18/06/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FORD Focus cc 1596

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 23867km T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WFOMXX GCBMCC 26715

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50/R17

R: 215/50/R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 57 mm

L/Bal: 5 mm

D.O.A: 9/12/19

Survey held at: Z-one

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* SKF 9246L Finalised Amt 2/sup * SKF 9246L
 \$2800 DOR 3 days, Agree by workshop 110 Limit
 (Nun sy FINISH) (Red 6 4986.40, 64%)

RECEIVED 30 JAN 2020

MV - 29000

PV - 25715

NV - 7272

Ah xing. → 90292102

Date/Time, File Pass to?

☐ : Preli. Report

1) 30/1 FINISH

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: 220

Transportation

S + RS: \$

Photos

Others

Total

220

Rep. Form:

MER-TP

Lump Sum / UIC:

2800

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Monday, 13 January, 2020 6:07 PM
To: Nur Syafirah
Cc: Shiau Chan (LKKAuto)
Subject: FW: SKF 9246L FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 2.1.2020

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear nur syafirah ,

Good day, o.k will be process base on finalized total amount COR \$ 2800 Lump/sump REPAIR and DOR 3 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct (china taiping ins)claim dept .

Thanks.

Best Regards,
Hock Ann| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Nur Syafirah [mailto:service@z-one.com.sg]
Sent: Monday, 13 January, 2020 4:39 PM
To: Hock Ann (LKK Auto)
Cc: Shiau Chan (LKKAuto); Sya Z1
Subject: Re: SKF 9246L FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 2.1.2020

RESEND

Hi Hock Ann,

We confirm to agree on Lump Sum \$2800.00.

Thank you!

Best Regards,

Nur Syafirah
Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883
Tel: 66342112 Fax: 6634 2122

From: Nur Syafirah
Sent: Friday, January 3, 2020 10:44 AM
To: Hock Ann (LKK Auto) ; ENQUIRY@Z-ONE.COM.SG
Cc: Shiau Chan (LKKAuto)
Subject: Re: SKF 9246L FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 2.1.2020

Hi Hock Ann,

We confirm to agree on Lump Sum \$2800.00.

Thank you.

Best Regards,

Nur Syafirah
Z-One Automotive Pte Ltd
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883
Tel: 66342112 Fax: 6634 2122

From: Hock Ann (LKK Auto)
Sent: Thursday, January 2, 2020 10:37 AM
To: SERVICE@Z-ONE.COM.SG ; ENQUIRY@Z-ONE.COM.SG
Cc: Shiau Chan (LKKAuto)
Subject: RE: SKF 9246L FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 2.1.2020

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear ah xiong ,

Good day , Kindly attached refer SKF 9246L FORD FOCUS finalized updated calculate adjustment on 2.1.2020 .

COR - \$ 2800

DOR – 3 DAYS

Please refer adjustment updated total LUMP/SUMP amount \$ 2800 if agree total LUMP/SUMP amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

ESTIMATE

LOH ING YING
43 SIMS DRIVE #09-201 Singapore 380043
Contact : 97657570

Code : C101947
Date in : 18/12/2019
Vehicle Num. : SKF9246L
Model : FORD FOCUS 1.6 TITANIUM
Chassis/Eng# : WF0MXXGCBMCC26715/CC26715

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Rear bumper ✓ DO	1	1525.00	1,625.00 1300.50 ✓
Rear bumper inner garnish ✓ BT	1	125.00	125.00 100.50 ✓
Rear bumper lower ✓ SCR	1	340.00	340.00 300.80 ✓
Rear bumper reflectors 2 LH ✓ X RH (SVC) 1/2	2	65.00	130.00 55 ✓
Rear bumper reinforcement ✓ BT	1	626.00	626.00 497.70 ✓
Rear bumper retainers 2 LH only ✓ X RH X (SVC) 1/2	2	37.50	75.00 ✓
Rear end panel X (R)	1	160.00	160.00
Rear end panel inner garnish X (SVC)	1	201.00	201.00
Rear tailgate X (R)	1	1900.00	1,900.00
Rear tailgate 'FOCUS' emblem ✓ (new)	1	110.00	110.00 75.80 ✓
Rear tailgate 'TITANIUM' emblem ✓ (new)	1	125.00	125.00 75.80 ✓
Rear tailgate lock ✓ JM	1	210.00	210.00 ✓
Rear tailgate rubber ✓ CRA	1	346.00	346.00 189.20 ✓
Rear taillamp RH LH ✓ CRA	1	960.00	960.00 442.80 ✓
Subtotal before discount			6,833.00
Percentage discount 20%			1,366.60
Sub-total 1			5,466.40
Parts-total			5,466.40



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning. ✓	50.00 20 ✓
To remove, refix / renew reverse sensor assy and rectify for proper functioning. ✓	120.00 30 ✓
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) X	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. ✓	900.00 400 ✓
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident. X	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900.00 400 ✓
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel. ✓	150.00 30 ✓
Labour Total	2,320.00
Parts & Labour Total	7,786.40

Signature
19/12/19
L/s report
without prejudice
Recovery other part
3 day
Hock Ann
LKK
85311873
Hock Ann @ LKK Auto.com

page 2

*Revised labour
12/12/19 2:30pm*

Parts	3248.12
Parts less	20%
	2598.48
labour	880
	3478.48
L/s less	20%
	2782.78
Total	↓
L/s AT	\$ 2800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Thursday, 12 December 2019 9:16 AM
To: assignments
Subject: FW: OUR REF: SNM19D205891/YP9669G/BEN - PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING SKF9246L & YP9669G ON 09/12/2019 AT 1345HRS

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SKF9246L.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Yvonne Yong <service@z-one.com.sg>
Sent: Wednesday, December 11, 2019 6:58 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205891/YP9669G/BEN - PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING SKF9246L & YP9669G ON 09/12/2019 AT 1345HRS

Dear Ben Tang,

Kindly appoint Marcus Chua for the PRS.

Thank you!

Best Regards,
Nur Syafirah
Z-One Automotive Pte Ltd
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883
Tel: 66342112 Fax: 6634 2122

From: Ben Tang
Sent: Wednesday, December 11, 2019 5:28 PM
To: service@z-one.com.sg
Cc: Claims Dept of CTI
Subject: RE: OUR REF: SNM19D205891/YP9669G/BEN - PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING SKF9246L & YP9669G ON 09/12/2019 AT 1345HRS

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, December 11, 2019 4:03 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; service@z-one.com.sg

Subject: OUR REF: SNM19D205891/YP9669G/BEN - PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING SKF9246L & YP9669G ON 09/12/2019 AT 1345HRS

Dear Ben,

Please conduct PRS for SKF9246L.

Note : officer in charge – Ben Tang 63896175.

***** Kindly quote our reference number when replying.**

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Yvonne Yong [<mailto:service@z-one.com.sg>]

Sent: Wednesday, 11 December, 2019 10:51 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Sya Z1 <enquiry@z-one.com.sg>

Subject: (DS) PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING SKF9246L & YP9669G ON 09/12/2019 AT 1345HRS

Dear Sir /Mdm,

Kindly find the attached PRS Request & GIA Report for your kind attention.

Please do send us the list of your 10 surveyor for us to choose.

Our customer's vehicle is already in our workshop.

Do revert back to us at the soonest.

For any further clarifications, kindly contact Sya @ 66342112.

Thank you!

Best Regards,

Nur Syafirah

Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883

Tel: 66342112 Fax: 6634 2122

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	933E
Vehicle Details	
Vehicle No.:	SKF9246L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Dec 2019
Vehicle Make:	FORD
Vehicle Model:	FOCUS 1.6 TITANIUM 4-DR C346
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	CC26715
Chassis No.:	WF0MXXGCBMCC26715
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$15,981.00
Original Registration Date:	18 Jul 2012
First Registration Date:	18 Jul 2012
Transfer Count:	0
Actual ARF Paid:	\$15,981.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2022
PARF Rebate Amount:	\$9,588.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$62,600.00
COE Rebate Amount:	\$16,127.00
Total Rebate Amount:	\$25,715.00

The information contained herein is correct as at 19 Dec 2019

OK



Ford Focus 1.6A

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » Cosmo Automobiles » Ford Focus Wagon 1.6A Trend

Ford Focus Wagon 1.6A Trend

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$57,800

Depreciation ☒ \$8,530 /yr
View models with similar depreReg Date 20-Oct-2015
(5yrs 10mths COE left)

Mileage 36,339 km (8.7k /yr)

Manufactured 2015

Road Tax ☒ \$742 /yr

Transmission Auto

Dereg Value ☒ \$44,671 as of today (change)OMV ☒ \$15,968COE ☒ \$56,001ARF ☒ \$15,968

Engine Cap 1,596 cc

Power 92.0 kW (123 bhp)

Curb Weight ☒ 1,433 kgNo. of Owners ☒ 1

Type of Vehicle Stationwagon

Features

Powerful And Responsive DOHC Engine, Smooth 6 Speed Auto Transmission, Multi Function Steering, 6 Airbags, ESP. View specs of the Ford Focus Wagon (2012-2015)

Accessories

16" Alloy Rims, Powershift, Audio System, Tanned Leather Seats, Premium 3M Solar Film, Reverse Sensors.

Description

Offer 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident Free Quality Pre-Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing. View Today!

Category

PARF Car, STA Evaluated Car, Low Mileage Car

Status

Available

Resources



State of the Art

Compare

Request to have this car evaluated professionally. Find out more

STA Evaluation

This vehicle has undergone a 120-point check by and has received a Graded B ☒ for its overall condition.

View more STA vehicles | Learn More on STA



Location Map

Shortlist

Compare

Add to

Report Error

More Actions

Seller Information

Cosmo Automobiles

37 vehicles for sale. 76 sold in past 3 mths

210 Turf Club Road Lot A16/A23

Car Mall @ The Grandstand

Tel: 64651090

Search cars nearby

Kevin

97976757

DOA = 7/12/11

Before 2 yr bank

MV - 27000

Depn - 8500 yr

PV - 25715

8500/12 = 708

NV - 3200

16800 + 4248 + 7790

= 29038

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 09:50
Date Of Accident	09/12/2019 13:45
Exact Location Of Accident	CTE TWDS AYE BEFORE PIE (CHANGI) EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF9246L
Insured/Policyholder	
Name Of Registered Owner	LOH ING YIING
NRIC No	S7681933E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97657570
Alternative Phone No	OFFICE-97657570

Vehicle Particulars

Manufacturer	FORD
Model	FOCUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800082869-01
Cover Note Number	

Driver

Name of Driver	LOH ING YIING
NRIC No	S7681933E
Date Of Birth	07/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	04/07/2008
Driving Experience	11 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97657570
Fax Number	
Contact Number	OFFICE-97657570
Email Address	NOEMAIL

Address	BLK 43 SIMS DRIVE #09-201
Postcode	380043
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, AT THE STATED VENUE, MY VEHICLE A (SKF9246L) WAS TRAVELLING STRAIGHT ON MY RIGHTFUL LANE. VEHICLE IN FRONT OF ME STOPPED SO I FOLLOWED SUIT. MOMENTS LATER, I FELT AN IMPACT ON THE REAR PORTION OF MY STATIONARY VEHICLE. VEHICLE B (YP9669G) FAILED TO STOP. HENCE, COLLIDED ONTO THE REAR PORTION OF MY STATIONARY VEHICLE. DUE TO THE IMPACT, I FELT PAIN ON THE BACK OF MY HEAD AND DIZZINESS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP9669G	<i>Color / make</i>
Vehicle Make/Model/Colour		
Details Of Properties	VEHICLE B	
Vehicle Category	COMMERCIAL VEHICLE	
Name of Driver		
NRIC/Passport Number		
Contact Number		
Address		
Postcode		
Insurance Company Name		
Nature Of Damage		
No. Of Passenger (Including Driver)		

DETAILS OF INJURED PERSON 1

Name LOH ING YIING

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKF9246L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



SKETCH PLAN

CTE towards AYE before PIE Changi Exit

Vehicle A: SKF9246L
Vehicle B: YP9669G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, at the stated venue,
my vehicle 'A' SKF9246L was travelling straight on
my rightful lane. Vehicle in front of me stopped so I
followed suit. Moments later I felt an impact on the
rear portion of my stationary vehicle. Vehicle 'B' YP9669G
failed to stop, hence collided onto the rear portion of
my stationary vehicle.

Due to the impact, I felt pain on the back of my
head and dizziness.

DECLARATION

(We declare the foregoing particulars are true in every respect.)


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:






































...CLAIM SUBFOLDER...(Pending for Survey Report)




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Dec 2019		28 Jan 2020 16:11 Edit Adj Rpt	S\$2,800.00 Edit Estimates	S\$2,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Co. Reg. No.: -								
Main Claimant:	LOH IING YING								
Vehicle Reg. No.:	SKF9246L	Date of Loss:	09/12/2019 13:00 - :59 [88 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205891	Policy/Cover Note No.:	DMCVSN19002419000						
Vehicle Reg. No. (Insured):	YP9669G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Z One Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, Bldg D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 06/02/2020]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKF9246L (SNM19D205891)
[YP9669G]
TP
LOH IING YING
Dec 9 2019 1:00PM
[-]
Z One Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/01/20 11:11	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	30/01/20 11:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
13	30/01/20 11:14	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
14	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/01/20 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
46	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
47	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
48	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
49	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
50	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
51	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
52	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
53	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
54	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
55	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
56	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
57	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
58	30/01/20 11:15	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
59	30/01/20 11:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	30/01/20 11:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	30/01/20 11:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	30/01/20 11:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	30/01/20 11:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	30/01/20 11:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19021887/HQF3E2

Date: 05/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19002419000
Claimant Vehicle No :	SKF9246L	Insured Vehicle No :	YP9669G
Date of Loss:	09/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D205891

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF9246L	Engine No:	CC26715
Make & Model:	FORD FOCUS,	Chassis No:	WF0MXXGCBMCC26715
Reg. Date:	18/07/2012 (Man. Year: 2012)	Odometer:	238674 km
Colour:	White		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,466.40	2,628.48	2,837.92	51.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	880.00	1,440.00	62.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,786.40	3,508.48	4,277.92	54.94
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	7,786.40	2,800.00	4,986.40	64.04
+ GST 7.00/7.00% (\$\$)	545.05	196.00	349.05	64.04
Nett Amount (\$\$)	8,331.45	2,996.00	5,335.45	64.04

INSPECTION

Date of Assignment: 28/01/2020
Date Inspected: 18/12/2019 Inspected At:

Z-One Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6,, Blk D #01-87,
Autobay @ Kaki Bukit,
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2020)
Parts: 143	FORD FOCUS (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKF9246L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,525.00 FL	*1,300.50 FL
2	1		*REAR BUMPER INNER GARNISH	Bent	125.00 FL	*100.50 FL
3	1		*REAR BUMPER LOWER	Scratched	340.00 FL	*300.80 FL
4	1		*REAR BUMPER REFLECTORS	N/S Crumpled / O/S Serviceable	130.00 FL	*55.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	626.00 FL	*497.70 FL
6	1		*REAR BUMPER RETAINERS	N/S Crumpled / O/S Serviceable	75.00 FL	*37.50 FL
7	1		*REAR END PANEL	Repair	160.00 FL	*- FL
8	1		*REAR END PANEL INNER GARNISH	Serviceable	201.00 FL	*- FL
9	1		*REAR TAILGATE	Repair	1,900.00 FL	*- FL
10	1		*REAR TAILGATE FOCUS EMBLEM	Necessary	110.00 FL	*75.80 FL
11	1		*REAR TAILGATE TITANIUM EMBLEM	Necessary	125.00 FL	*75.80 FL
12	1		*REAR TAILGATE LOCK	Jammed	210.00 FL	*210.00 FL
13	1		*REAR TAILGATE RUBBER	Crumpled	346.00 FL	*189.20 FL
14	1		*REAR TAILLAMP LH	Cracked	960.00 FL	*442.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,833.00	3,285.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,366.60	657.12
Total Parts (\$\$)	5,466.40	2,628.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	50.00	20.00
2	TO REMOVE, REFIX / RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	120.00	30.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	100.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	400.00
5	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	0.00
6	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	900.00	400.00
7	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL	New	150.00	30.00
Gross Labour Cost (S\$)			2,320.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >