

2/13/2011

ASS. REC. BY:

REF: 081AIG19021896/Ktd3er Special Instruction:

Signature: Kenneth

ASSIGNMENT (Office)

From (Person): Horyinnul

of

AIG

Date/Time: 12/12/19 @ 8:58am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EJ1311J

Insured:

SMP 2813U

at Workshop in/s

Yee Auto

Tel:

6457 5768

of

160 Sin Ming Drive #02-17

Policy No:

Claim No:

608 5235 928 SG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:01am @ 12/12/19

Person Contacted:

Mr Chen

Vehicle IN OUT

Date/Time

Action/Instruction

Johnyob

EJ1311J- NA/INC14002242/13

D.O.A: 5/12/2014

SMP 2813U- X

16/12 11 Lms @ 310d e mail (Red: 7193.40, 69%)

ASS. REC. BY: Kenneth

REF: A16

## ASSIGNMENT

From

Date: 12/12/19

Estimated Cost:

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

EJ 1311J

at Workshop m/s

Yee Auto

of

160 Sin Ming Drive # 02-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

147

Date:

3/27

Person Contacted:

Vehicle: IN / OUT

Veh No:

EJ 1311J

Yr Regn:

03 07

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Lexus

GS300 C.C.

2995

Colour:

M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading

222962

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT14B14965 50505117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/30ZR20

R:

285/25ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/12/19

D.O.I.

12/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 JAN 2020

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

250

Transportation:

S + RS. \$

Photos

Others

11

TOTAL

261

Report Format:

TP

Lump Sum / L.B.J. (\$)

3100

**PRE-REPAIR INSPECTION REQUEST – EJ1311J vs SMP2813U (OI) on D.O.A.: 08/12/2019**

From: Hor, Yinrul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni  
Sent: 12/12/2019 8:58:26 AM  
Attachments:  YeeAuto-EJ1311J.LTA.pdf  YeeAuto-EJ1311J.LTA.PDF

Hi,

Please refer to the enclosed request from **BONNIE KWOK LLC**.

Claim no : 6085235928SG003  
Case Owner : Lee Ming Yao

If you have any queries/concerns, please let us know.  
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002208  
[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** bonnie kwok <litigation@bonniekwok.com>  
**Sent:** Wednesday, December 11, 2019 4:34 PM  
**To:** Hor, Yinrul <Yinrul.Hor@aig.com>  
**Cc:** Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>  
**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMP2813U AND EJ1311J ON 08/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Our client agrees to Kenneth Kong of LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have his report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,  
ST

**BONNIE KWOK LLC**

Advocates & Solicitors  
101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358  
TEL: 6536 6026  
FAX: 6536 2279  
email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Wed, 11 Dec 2019 at 14:38, Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)> wrote:



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-12-18 00:38 CST to read your message. After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**From:** Yinrul.Hor@aig.com  
**To:** litigation@bonniekwok.com  
**Cc:** Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com  
**Subject:** aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMP2813U AND EJ1311J ON 08/12/2019  
**Date:** Wed, 11 Dec 2019 06:37:58 +0000  
**Without Prejudice**

Your Reference : YeeAuto-EJ 1311 J  
Our Reference : 6085235928SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002208  
[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

From: bonnie kwok <[litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)>

Sent: Wednesday, December 11, 2019 2:14 PM

To: AIG SGP, Claims-Survey <[AIGSGP\\_ClaimsSurvey@aig.com](mailto:AIGSGP_ClaimsSurvey@aig.com)>

Subject: [EXTERNAL] Urgent: Pre-Repair Inspection: Your Vehicle: SMP 2813 U; Our Ref: YeeAuto-EJ 1311 J; Accident Involving EJ 1311 J & SMP 2813 U on 8 December 2019

This message is from an external sender; be cautious with links and attachments.

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. EJ 1311 J at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,

ST

--

**BONNIE KWOK LLC**

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

## Denise Tay (LKKAuto)

---

**From:** yeeauto pteltd <yeeautopteltd@gmail.com>  
**Sent:** Thursday, 16 January 2020 12:28 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** Re: EJ 1311J / TP / AIG / DOA: 8/12/2019

Hi Sir,

We accept amount S\$3100/- (bf GST) and 04 working days.

Thanks & Regards

Ms Phang

**Yee Auto Pte Ltd**

160 Sin Ming Drive

#02-17 Sin Ming AutoCity

Singapore 575722

ROC & GST No.: 201719251W

email: [yeeautopteltd@gmail.com](mailto:yeeautopteltd@gmail.com)

Contact No: 6457 2625 Fax: 6252 8459

On Thu, 9 Jan 2020 at 14:39, Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)> wrote:

Dear Sir/Madam,

Please confirm on finalized lump sum \$3100, 4days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/12/2019 17:14
Date Of Accident	08/12/2019 18:00
Exact Location Of Accident	JUNCTION OF BUANGKOK EAST DRIVE & UPP SERANGOON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EJ1311J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FONG CHEE CHIM
NRIC No	S1513471B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91288293
Alternative Phone No	OFFICE-91288293

### Vehicle Particulars

Manufacturer	LEXUS
Model	GS300-3.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5081786697-03
Cover Note Number	

### Driver

Name of Driver	FONG JIA JIN
NRIC No	S9239041A
Date Of Birth	16/10/1992
Occupation	INDOOR
Date Of Driving Pass	04/08/2018
Driving Experience	1 YEAR AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93221311
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 429 BUKIT PANJANG RING ROAD #16-713
Postcode	670429
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FRIEND GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMP2813U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Records Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

(A) EJ1311J

(B) SMP2813 U

Upp Serangoon Rd



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/12/2019 at 6:00 pm. I was travelling my vehicle (A) EJ1311J along Buangkok East Drive before Upp Serangoon Rd. The traffic light turn amber. I move slowly and stop. Suddenly, the vehicle (B) SMP2813 U cannot stop in time and hit my vehicle rear portion.

\* owner came with complete & signed report as he say his son (driver) busy @ work.

TP claim to do at Yee Auto. Pls email report to them.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 08/12/2019

TP Veh Reg No: SMP2813U

Estimate No: ES1900145

Date: 11 Dec 2019

Policy No:

Veh Reg No: EJ1311J

Make/Model: TOYOTA LEXUS GS300  
AUTO

Chassis No: JTHBH96S505050117

Engine No: 3GR0198614

Reg. Date: 08/03/2007

## Estimate Repair Cost to Vehicle No :EJ1311J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>Net Price</b>				
1 REVERSE SENSORS	350.00	1 PC	350.00	200.50
			350.00	350.00
<b>Spare Parts</b>				
2 REAR BUMPER 864	950.90	1 PC	950.90	✓
3 REAR BUMPER CLIPS	60.00	1 SET	60.00	✓
4 REAR BUMPER LOWER GARNISH	565.20	1 PC	565.20	X
5 REAR BUMPER REINFORCEMENT	525.30	1 PC	525.30	2
6 REAR BUMPER SIDE RETAINER - LH	98.00	1 PC	98.00	X
7 REAR BUMPER SIDE RETAINER - RH	98.00	1 PC	98.00	✓
8 REAR BUMPER SPONGE 146.70	281.00	1 PC	281.00	2
9 REAR BUMPER BUZZER SENSOR	198.00	1 PC	198.00	2
10 REAR END PANEL	698.50	1 PC	698.50	X
11 REAR END PANEL TOP GARNISH	392.80	1 PC	392.80	X
12 REAR END PANEL TOP GARNISH CLIPS	60.00	1 SET	60.00	X
13 REAR TAILGATE	1,221.00	1 PC	1,221.00	X
14 REAR TAILGATE EMBLEM 'LOGO'	81.00	1 PC	81.00	✓
15 REAR TAILGATE EMBLEM 'GS300'	75.00	1 PC	75.00	✓
16 REAR TAILGATE LOCK	280.00	1 PC	280.00	X
17 REAR TAILGATE WEATHERSTRIP	221.20	1 PC	221.20	X
18 REAR TAILLAMP - RH	635.00	1 PC	635.00	✓
19 REAR FENDER INNER GARNISH - RH	568.50	1 PC	568.50	X
20 REAR BUMPER TOWING COVER	65.50	1 PC	65.50	✓
21 REAR BOOT LID 'LEXUS' EMBLEM	98.50	1 PC	98.50	✓
			7,173.40	7,173.40
<b>Labour</b>				
22 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY:	1,200.00	1 JOB	1,200.00	500
23 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	600
24 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	X
25 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	120.00	1 JOB	120.00	X
26 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	200
			2,770.00	2,770.00



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
Email: yeeautopteltd@gmail.com  
Registration No: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 08/12/2019  
TP Veh Reg No: SMP2813U

Estimate No: ES1900145  
Date: 11 Dec 2019  
Policy No:  
Veh Reg No: EJ1311J  
Make/Model: TOYOTA LEXUS GS300  
AUTO  
Chassis No: JTHBH96S505050117  
Engine No: 3GR0198614  
Reg. Date: 08/03/2007

## Estimate Repair Cost to Vehicle No :EJ1311J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 10,293.40
			Add GST @ 7%	526.64
			Total Amount Payable	SS 10,820.04

TOTAL: SINGAPORE DOLLAR TEN THOUSAND EIGHT HUNDRED TWENTY AND CENTS FOUR ONLY

For Yee Auto Pte Ltd

  
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Dec 2019 <a href="#">Edit Reg</a>		12 Dec 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,100.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,100.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>AW GUAN LEE</b> , ID: S7001370C									
Main Claimant: -									
Vehicle Reg. No.: <b>EJ1311J</b>		Date of Loss: 08/12/2019 00:00 - :59 [153 Months From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 6085235928SG</b>		Policy/Cover Note No.: (Comprehensive) Coverage: 19/09/2019 - 18/09/2020							
Vehicle Reg. No. (Insured): <b>SMP2813U</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Yee Auto Pte Ltd (HQ)</b> 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6457 2625									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 23/12/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (13/12/2019): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*EJ1311J (6085235928SG)  
[SMP2813U]  
TP

-  
Dec 8 2019 12:00AM  
[AW GUAN LEE]  
Yee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
2	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
3	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
4	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
5	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
6	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
7	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
8	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
9	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
10	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
11	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
12	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
13	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
14	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
15	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
16	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
17	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
18	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
19	17/01/20 16:20	General View													Load JPG	<input checked="" type="checkbox"/>		
20	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
21	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
22	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
23	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
24	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
25	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
26	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
27	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
28	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
29	17/01/20 16:21	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	09/01/20 14:25	TP Singapore Accident Statement													Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	13/12/19 13:20	OI GIA REPORT													Load PDF			

Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19021896/KTD3E2

Date: 23/01/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : EJ1311J

Insured Vehicle No : SMP2813U

Date of Loss: 08/12/2019

Nature of Claim: TP

Claim No: 6085235928SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EJ1311J

Make &amp; Model: TOYOTA LEXUS GS300 AUTO, 3.0 (A)

Engine No: 3GR0198614

Reg. Date: 08/03/2007 (Man. Year: 2007)

Chassis No: JTHBH96S505050117

Colour: Metallic Pearl White

Odometer: 222962 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/30Z R20

Rear Tyre Size: 285/25Z R20

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,523.40	2,762.30	4,761.10	63.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,120.00	1,650.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,293.40</b>	<b>3,882.30</b>	<b>6,411.10</b>	<b>62.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	10,293.40	3,100.00	7,193.40	69.88
<b>+ GST 7.00/7.00% (S\$)</b>	720.54	217.00	503.54	69.88
<b>Nett Amount (S\$)</b>	<b>11,013.94</b>	<b>3,317.00</b>	<b>7,696.94</b>	<b>69.88</b>

### INSPECTION

Date of Assignment: 12/12/2019

Date Inspected: 12/12/2019 Inspected At:

Yee Auto Pte Ltd (HQ)  
160 SIN MING DRIVE, #02-17 SIN MING  
AUTOCITY  
Singapore 575722

Estimated Period of Repair: 4.0 days



---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSORS	Dented	350.00 FS	*200.00 FS
2	1		*REAR BUMPER	Buckled / Cracked	950.90 F	*864.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Serviceable	565.20 F	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	525.30 F	*525.30 FL
6	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	98.00 F	*- FL
7	1		*REAR BUMPER SIDE RETAINER -RH	Distorted	98.00 F	*98.00 FL
8	1		*REAR BUMPER SPONGE	Cracked	281.00 F	*146.70 FL
9	1		*REAR BUMPER BUZZER SENSOR	Cracked	198.00 F	*198.00 FL
10	1		*REAR END PANEL	Repair	698.50 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Serviceable	392.80 F	*- FL
12	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 F	*- FL
13	1		*REAR TAILGATE	Repair	1,221.00 F	*- FL
14	1		*REAR TAILGATE EMBLEM LOGO	Necessary	81.00 F	*81.00 FL
15	1		*REAR TAILGATE EMBLEM GS300	Necessary	75.00 F	*75.00 FL
16	1		*REAR TAILGATE LOCK	Repair	280.00 F	*- FL
17	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	221.20 F	*- FL
18	1		*REAR TAILLAMP -RH	Cut	635.00 F	*635.00 FL
19	1		*REAR FENDER INNER GARNISH -RH	Serviceable	568.50 F	*- FL
20	1		*REAR BUMPER TOWING COVER	Dented	65.50 F	*65.50 FL
21	1		*REAR BOOT LID LEXUS EMBLEM	Necessary	98.50 F	*98.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,523.40</b>	<b>3,047.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00</b>	<b>284.70</b>
<b>Total Parts (S\$)</b>	<b>7,523.40</b>	<b>2,762.30</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,200.00	500.00
2	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,200.00	600.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	150.00	0.00
4	TO REMOVE/TRANSFER TAILGATE COMPONENTS	New	120.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
Gross Labour Cost (S\$)			2,770.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >