

REF: CS/MSG 18001617 / kgf307
 ASSIGNMENT (Office)
 Kenneth
 Catherine Thia
 MSIG
 Date Time 25/1/18 @ 1:30pm
 OD: TP/WS/TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SLE 8392 Y Insured: FBJ 9946 K
 at Workshop no: Accord Auto Insured: 9740 0999
 10, AMK Ind. Prk 2A # 03-11 Autopoint
 Policy No: MSD/VMFT/16-978980 Claim No: MSC/V/18-000143
 Date Insured: 22/01/2018
 CA: REV: REF: REV 24 HRS: up
 Date Time: 8:43am @ 26/1/18 Insured: jessy Insured IN: OUT

Date Time: 01/10/18 - vehicle not in yet.
 SLE 8392 Y - X 2/11/18 - VNI yet
 FBJ 9946 K - X 19/12/18 - Temporary close case.
 13/8/18 - called jessy vehicle still not in yet. - Reverted through merimen
 24/8/18 - VNI
 5/9/18 - vehicle still not in
 19/11/18 - vehicle not in (pending liability)

12/12/19 @ 2:31pm confirmed with Cerin final fig @ 200, 1 day.
 (Red @ 1090.96, 85%)

12/12/19 @ 2:35pm revised to Catherine Thia via merimen.

12/12/2019

150
 + 11
 161

ASS. REC. BY:

REF:

MSG

ASSIGNMENT

From

Date:

11/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLE 8392Y

at Workshop m/s

ACCORD AUTO

of

10 AMK Ind. park 2A Autopoint

Insured:

#03-11

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

1-2m

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01

days

Res.: Yes or No

Lump Sum:

1-131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 8392Y

Tr Regn:

08/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

A)

Polo C.C

1197

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

50585

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVW 888 6R8 GU 045173

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

22/1/18

D.O.I.

11/12/19

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8204

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / L&S: (\$

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 12 Dec 2019

Preliminary Advice

Insured Vehicle No	: FBJ9946K		
TP Vehicle No	: SLE8392Y	Accident Date	: 22/01/2018
Make	: VOLKSWAGEN POLO	Assignment Date	: 25/01/2018
Date of Inspection	: 11/12/2019	Est. Duration of Repair	: 1.00
Inspection At	: ACCORD AUTO SERVICES PTE LTD (HQ) 10 ANG MO KIO IND PARK 2A #03-11, AMK AUTO POINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,290.96
Revised Amount	:S\$	200.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	200.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

*SLE8392Y (MSC/V/18-000143)
[FB39946K]

TP

TEO SIEW SUAN

Jan 22 2018 12:00AM

[LIM WYE WAH]

Accord Auto Services Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 19/12/2018 15:01 PM.
To catherine.thia@sg.entalping.com
Subject SLE 8392Y

Dear Sir/Mdm,

Please be informed that we are unable to conduct the inspection after some attempts to inform the workshop to present the vehicle.
This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.
Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Actioned	Status
Main	24 Jan 2018		25 Jan 2018 13:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		LIM WYE WAH, ID: S9207498F [Created by insurer]							
Main Claimant:		TEO SIEW SUAN, ID: S1474175E							
Vehicle Reg. No.:		SLE8392Y	Date of Loss:	22/01/2018 00:00 - :59					
Claim Type:		TP / MSC/V/18-000143	Policy/Cover Note No.:	MSD/VMFT/16-978980 (TP, Fire & Theft) Coverage: 30/01/2017 - 29/01/2018					
Vehicle Reg. No. (Insured):		FBJ9946K	Policy No. (Claimant):						
			Excess:						
Repairer:		Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/01/2018]							
Adj Asp. Remarks:		pls assign Kenneth. PRI							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/01/2018 17:29
Date Of Accident	22/01/2018 18:10
Exact Location Of Accident	PIE(CHANGI) EXIT OF LORNIE ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLE8392Y
Insured/Policyholder	
Name Of Registered Owner	TEO SIEW SUAN
NRIC No	S1474175E
Email Address	CHARMAINEHAILEY078@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96559009
Alternative Phone No	OFFICE-96559009
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	POLO GP 1.2 TSI A/T 6C13EZ SR LED
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0008344
Cover Note Number	
Driver	
Name of Driver	CHARMAINE KWOK SHU HUI
NRIC No	S9127854E
Date Of Birth	07/08/1991
Occupation	INDOOR
Date Of Driving Pass	22/05/2010
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96512292
Fax Number	
Contact Number	
Email Address	CKWOK.SERENA@GMAIL.COM

Address	138 SERANGOON GARDEN WAY
Postcode	556040
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON PIE(CHANGI AIRPORT) EXITING TO LORNIE ROAD, TRAFFIC WAS HEAVY AND MOVING SLOW. AS 2 LANES WERE MERGING INTO ONE, A BIKE ON THE LEFT (WITH A MAN IN ARMY UNIFORM) BUMPED ONTO THE LEFT BACK-SIDE OF MY CAR RESULTING IN A MINOR SCRATCH. HE STOOPED FOR A BRIEF MOMENT AND LOOKED AT ME, THEN TURNED AND RODE OFF.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ9946K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN Vehicle A: SLE 8392Y Vehicle B: FBJ 9946K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Accident: 22/01/2018 Time of Accident: 6:12pm

On PIE (Changi Airport) exiting to Lornie Road, traffic was heavy and moving slow. As ~~two~~ ² lanes were merging into one, a bike on the left (with a man in army uniform) bumped onto the ^{left} back-side of my car resulting in a minor scratch. He stopped for a brief moment and looked at me, then turned and rode off.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 23/1/18 5:10pm

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/11/18, 5:10pm

ACCORD AUTO SERVICES PTE. LTD.
 10 Ang Mo Kio Industrial Park 2A
 #03-11 A&A Autopoint
 Singapore 568047

Reporting Centre Personnel's Signature
Name: Jessy Soe
NRIC/FIN No: G203107ZW

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Accident Claims Department

1 day

Date : 24/01/2018
 Vehicle No : SLE8392Y
 Veh Make/Model : Volk. Polo GP 1.2 TSI A/T
 YOM : 2016
 Chassis No : WVVZZZ6RZGU045173
 Date of Accident : 22/01/2018

X

204

x

X

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2018		25 Jan 2018 13:30 Edit Adj Rpt	S\$200.00 Edit Estimates	S\$200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LIM WYE WAH , ID: S9207498F									
Main Claimant: TEO SIEW SUAN , ID: S1474175E									
Vehicle Reg. No.: SLE8392Y		Date of Loss: 22/01/2018 00:00 - :59 [17 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000143		Policy/Cover Note No.: MSD/VMFT/16-978980 (TP, Fire & Theft) Coverage: 30/01/2017 - 29/01/2018							
Vehicle Reg. No. (Insured): FBJ9946K		Policy No. (Claimant):							
		Excess:							
Repairer: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/02/2018]									
Adj Asg. Remarks: pls assign Kenneth. PRI									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE8392Y (MSC/V/18-000143)
[FBJ9946K]
TP
TEO SIEW SUAN
Jan 22 2018 12:00AM
[LIM WYE WAH]
Accord Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser ▼	
Assessment Reports			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼ <input checked="" type="checkbox"/>
1	12/12/19 14:35	Adjuster Immediate Advice	<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> Load HTM </div>
Photos/Images			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼ <input checked="" type="checkbox"/>
1	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
2	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
3	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
4	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
5	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
6	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
7	23/12/19 13:51	General View	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
8	23/12/19 13:51	Odometer Reading	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
9	23/12/19 13:51	Chassis Number	<div style="display: flex; justify-content: space-between;"> Load JPG <input checked="" type="checkbox"/> </div>
Documentation			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼ <input checked="" type="checkbox"/>
1	25/01/18 13:32	TP GIA REPORT	<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> Load PDF </div>
2	25/01/18 13:32	TP WORKSOP NOMINATE KENNETH FROM LKK TO BE THE SJE	<div style="display: flex; justify-content: space-between;"> Load PDF </div>

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
<div style="display: flex; justify-content: flex-end; align-items: center;"> ^ v </div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001617/KQF3E2-1

Date: 23/12/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMFT/16-978980
Claimant Vehicle No :	SLE8392Y	Insured Vehicle No :	FBJ9946K
Date of Loss:	22/01/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000143

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE8392Y	Engine No:	CJZA21216
Make & Model:	VOLKSWAGEN POLO, 1.2 TSI (A)	Chassis No:	WWWZZZ6RZGU045173
Reg. Date:	02/08/2016 (Man. Year: 2016)	Odometer:	50585 km
Colour:	White		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R16	Rear Tyre Size:	215/45 R16
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	660.96	0.00	660.96	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	200.00	430.00	68.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,290.96	200.00	1,090.96	84.51
+ GST 7.00/7.00% (S\$)	90.37	14.00	76.37	84.51
Nett Amount (S\$)	1,381.33	214.00	1,167.33	84.51

INSPECTION

Date of Assignment: 25/01/2018

Date Inspected: 11/12/2019 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11,
AMK Auto Point
Singapore 568047

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2019)
Parts:	144	VOLKSWAGEN POLO 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE8392Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	734.40 FL	*- FL
					Sub Total (\$\$)	0.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	250.00	200.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT, WELD AND REALIGN ACCIDENT AFFECTED AREA	New	300.00	0.00
3	TO APPLY ANTI RUST TREATMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			630.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >