CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

 VEHICLE NO: SH 8121P
 DATE: 10.12.2019

 MAKE:
 TEL: 6542 5119

MODEL : HYUNDAI IONIQ FAX : 6542 6039 AIG

MODEL	: HYUNDAI IONIQ FAX : 6542 6039 AIG					
Qty	Parts Description/ Labour	Type	Unit Price		Amount	╛
	Radiator Grille			\$	1,409.10	
	Front Bumper Cover			\$	418.30	1
	Front Bumper Sponge			\$	86.90	1
	Front Bumper Reinforcement			\$	1,075.10	1
	Front Bumper Absorber			\$	86.90	
	Front Bumper Grille (LH)			\$	186.90	
	Front Bumper Centre Moulding			\$	188.00	
	Front Bumper Moulding (LH)			\$	93.60	
	Front Bumper Lower Stiffner			\$	85.10	
	Front Bumper Lip			\$	35.10	
	Front Bumper Bracket Top (LH)			\$	35.00	
	Front Bumper Bracket (LH)			\$	28.00	
	Front Bumper Clips 10 pcs			\$	22.00	
	Front Bumper Centre Grille			\$	318.80	
	Headlamp Support Top Cover			\$	398.00	
	Headlamp Support Panel Assy			\$	949.30	
	Headlamp (LH)			\$	1,198.80	
	Day Light, LH			\$	642.50	
	Day Light Wire, LH			\$	585.50	
	Emblem-Blue Drive (LH)			\$	26.60	
	Radiator			\$	510.50	
	Radiator Shroud			\$	275.50	
	Front Fender (LH)			\$	490.70	
	Aircon Condenser			\$	663.60	
	Front Wheel Rim (LH)			\$	1,124.20	
	Front Wheel Hub Cap (LH)			\$	346.40	
	Front Wheel Bearing			\$	454.00	
	Front Shock Absorber (Assy) (LH)			\$	372.50	
	Front Shock Absorber Mounting (LH)			\$	206.90	
	Front Shock Absorber Fork (LH)			\$	206.90	
	Front Suspension Upper Arm (LH)			\$	244.30	
	Front Drive Shaft (LH)			\$	936.70	
	Rack & Pinion Assy			\$	887.40	
	STG Tie End			\$	91.50	
	Front Suspension Lower Arm (LH)			\$	296.80	
	Knuckle Arm (LH)			\$	363.60	
	Engine Crossmember			\$	1,803.90	
	SUB TOTAL			\$	17,144.90	-
	LESS 20%			\$	3,428.98	
	DISCOUNTED TOTAL			\$	13,715.92	
	Front Fender Advertisement Logo (LH)			\$	100.00	Net
	Front Tyre (LH)			\$	216.00	1
				\$	316.00	
L	Page 1 of 2			<u> </u>	310.00	J

SH 8121P

				SH 8121P
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,000.0
	Spray Painting Charge			\$ 500.0
			!	\$ 50.0
	Wiring Charge			
	Towing Charge			\$ 90.0
	Remove/Refix Undercarriage (FRT)			\$ 400.0
	Front Wheel Alignment			\$ 120.0
	Remove/Refix Aircon & Refill Gas			\$ 150.0
	Re-set Frt ABS System		'	\$ 200.0
	Diagnostic & Resetting To Erase Fault Code			\$ 480.
	TOTAL LABOUR			\$ 2,990.
	ESTIMATE TOTAL	:		\$ 17,021.
	ESTIMATE TOTAL			\$ 17,021.
		ı		
		:		
		:		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

	ACCIDENT STATEMENT
Date Of Report	10/12/2019 15:01
Date Of Accident	09/12/2019 18:30
Exact Location Of Accident	MOULMEIN ROAD T-JUNCTION SINARAN DRIVE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SH8121P
	the control of the first of the control of the cont

Insured/Policyholder

Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD

Co Reg No 199303821R

Email Address FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI Model IONIQ HYBRID

Exact Purpose for which vehicle was being used at time of accident

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver

LIM SIAH HWA

NRIC No

S1107747A

Date Of Birth

25/04/1955

Occupation

OUTDOOR

Date Of Driving Pass

09/06/1976

Driving Experience 43 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-92359531

Fax Number

Contact Number

EMail Address LIMSIAHHWA@YAHOO.COM

BLK 534 SERANGOON NORTH AVENUE 4 Address

#07-217

550534 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE CLEAR

Weather Conditions Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

YES

NO

3

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME:

GENDER:

: FEMALE

Passenger 2

NAME:

YES

NO

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] HOUGANG NPC

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20191210/2032

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMN8352D

Vehicle Make/Model/Colour **VOLVO**

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver LIEW SHU LING

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage FRONT RH

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM SIAH HWA

Approximate Age

Injuries Sustain NECK AND CHEST

Injured person in which vehicle? SH8121P
Were seat belts worn? YES

Was this injured conveyed to hospital by

ambulance?

YES

Address Postcode

DETAILS OF INJURED PERSON 2

Name UNKNOWN(PAX)

Approximate Age

Injuries Sustain REDNESS ON LEFT CHEEK

Injured person in which vehicle? SH8121P

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

YES

Address Postcode

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

OMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time: 10.12.2019@14:00hrs

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the Police Report No:T/20191210/2032					
I had 3 days MC given by doctor.					

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 10.12.2019@14:00hrs

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





1 of 4

Report No. T/20191210/2032

Police Station Of Origin: Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775 Tel No: 1800-4890999

REPORT (OF A	TRAFFIC	ACCIDENT
----------	------	----------------	-----------------

Date/Time Report Made: 10/12/2019 11:02			Vide Report No.:		Station Diary No.: 44		
informant:	s Particul	ars					
Name of Informant:			Address:				
LIM SIAH F	I WA		APT BLK 534 SERANGOON NORTH AVENUE 4 #07-217				
		·	SINGAPORE 550534				
ID Type / it	No.:		Contact No.:				
NRIC NO / S1107747A			Home/Office: Mobile: 92359531		359531		
Nationality:			Email:				
SINGAPOF	RE CITIZE	N					
Sex:	Age:	Date of Birth:	Type of Informant:				
Male	64	25/04/1955	Driver				
Race:			Language:	Institution	/ School Name:		
Chinese							
Occupation:			Driving Licence Information:				
Taxi driver			Class: 2B,2A,2,3	Date of Ex	piry:		

				10.000 mg (10.000 mg (
Generakinkonnati	on of the Accident			Car with the street of the str		
Type of Accident:	Injury Conveyed By Ambuland	Drink ce Drive: No	Date/Time of Accident: 09/12/2019 18:30	Type of Location: T-Junction		
Location: Junction of Road 1 and Road 2 MOULMEIN ROAD SINARAN DRIVE						
**Cation		Road Surface:		Road Speed Limit:		
Clear	Di	ry				
Traffic Flow:	Tr	raffic Control:	٦	Traffic Volume:		
	N	ot Controlled	N	Moderate		
Type of Collision: Between Moving	Vehicles - Side Swipe - S	Same Direction	. a	anyone conveyed by ambulance: No		

Vasiala No	Ti	Maya	Model	Color	Condition	No of Passenge
SH8121P	Car	HYUNDAI		Blue	Seriously Damaged	2
SMN8352D	Car	VOLVO		Black		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 4

Report No. T/20191210/2032

Police Station Of Origin: Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775 Tel No: 1800-4890999

CONTINUATION OF REPORT

Passenger						
Name	BETHANY TAN			ID No.		NIL
Related Vehicle	SH8121P (Car)			Contac	ct No.	NIL
Hospital/Clinic	NIL			Class	of	Class: NIL
1 103pital/Oll/110	1412			Driving		Date of Expiry: NIL
				Licenc		
				Expiry	Date	
Date Treatment	NIL		Date Disch		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	
Driver						And the second of the second
Name	LIM SIAH HWA			ID No.		S1107747A
Related Vehicle	SH8121P (Car)			Conta	ct No.	92359531
Hospital/Clinic	TAN TOCK SENG HO	SPITAL		Class	of	Class: 2B,2A,2,3
				Driving	_	Date of Expiry: NIL
				Licend		
					Date	
Date Treatment			Date Disc			2/2019
No. of Days gran	ted Medical Leave	03	Degree of	Injury	NIL	
Passenger 🔭 🖰						**************************************
Name	KATHY NG			ID No		NIL
Related Vehicle	SH8121P (Car)			Conta	ct No.	98430426
	1					
Hospital/Clinic	NIL			Class	of	Class: NIL
Hospital/Clinic	NIL			Class Drivin		Class: NIL Date of Expiry: NIL
Hospital/Clinic	NIL			Drivin Licen	g ce &	
Hospital/Clinic	NIL			Drivin Licen	g	
			Date Disc	Drivin Licend Expiry harge	g ce & / Date NIL	
Date Treatment		NIL	Date Disc	Drivin Licend Expiry harge	g ce & / Date	
Date Treatment	NIL ted Medical Leave	NIL		Drivin Licend Expiry harge Injury	g ce & / Date NIL NIL	Date of Expiry: NIL.
Date Treatment No. of Days gran	NIL	NIL		Drivin Licend Expiry harge	g ce & / Date NIL NIL	
Date Treatment No. of Days gran	NIL ted Medical Leave	NIL		Drivin Licend Expiry harge Injury	g ce & / Date NIL NIL	Date of Expiry: NIL.
Date Treatment No. of Days gran Driver Name Related Vehicle	NIL ted Medical Leave LIEW SHU LING SMN8352D (Car)	NIL		Drivin Licence Expiry harge Injury ID No	g ce & / Date NIL NIL	Date of Expiry: NIL.
Date Treatment No. of Days gran Driver Name	NIL ted Medical Leave	NIL		Drivin Licence Expiry harge Injury ID No	g ce & / Date NIL NIL act No.	Date of Expiry: NIL S7144816I NIL Class: NIL
Date Treatment No. of Days gran Driver Name Related Vehicle	NIL ted Medical Leave LIEW SHU LING SMN8352D (Car)	NIL		Drivin Licence Expiry harge Injury ID No	g ce & / Date NIL NIL act No.	Date of Expiry: NIL. S7144816I NIL
Date Treatment No. of Days gran Driver Name Related Vehicle	NIL ted Medical Leave LIEW SHU LING SMN8352D (Car)	NIL		Drivin Licence Expiry harge Injury ID No Conta Class Drivin Licen	g ce & / Date NIL NIL act No.	Date of Expiry: NIL S7144816I NIL Class: NIL
Date Treatment No. of Days gran Driver Name Related Vehicle	NIL ted Medical Leave LIEW SHU LING SMN8352D (Car)	NIL		Drivin Licence Expiry harge Injury ID No Conta Class Drivir Licen Expir	g ce & / Date NIL NIL act No. of eg ce &	Date of Expiry: NIL S7144816I NIL Class: NIL





Police Station Of Origin: Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999 **CONTINUATION OF REPORT** 3 of 4

Report No. T/20191210/2032

Brief Details.

On 09/12/2019 at about 1830hrs, I was driving along Moulmein Road and was headed towards Balestier, when a black Volvo car suddenly turned out from Sinaran Drive and knocked its side onto the left side of my taxi. I checked on my passengers and noticed that the 7-year-old had some redness on her left cheek. The collision caused some serious damages on the front left portion of my taxi. Shortly after, traffic police and ambulance arrived. My 7-year-old passenger was subsequently conveyed to KK Hospital with the company of her mother, who was my other passenger, while I was conveyed to TTSH for aches on the left side of my neck and chest. I wish to state that my taxi had a dash camera which recorded the accident.





4 of 4

Report No. T/20191210/2032

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999 CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 3 ANNA ANTHONY	j
Signature Of Interpreter:	Date/Time:
Not applicable	10/12/2019 11:02
140t apphoable	
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
Staff Sgt QHAIRIL BIN ZULKEFLEE / /	
Contact No.: 65476187	
Authentication Stamp	·
NP168	
A STATE OF THE PARTY OF THE PAR	