

15/5/2010

INS. CASE OWNER:

~~CC 4, FCI 190 21926, Hka3q2~~

LKK:

IDAC:

**ASSIGNMENT**

Surveyor: H.A.W.W. DOI: 11/12/10 Date / Time : 10/12/10  
Registered in Merimen: \_\_\_\_\_

**Pre-assign / CCU / FTE**



Insured Vehicle No. : SHD 4207D Claim No. : \_\_\_\_\_  
Name of Insured : \_\_\_\_\_ Policy No. : \_\_\_\_\_  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_ Make / Model : \_\_\_\_\_  
Excess Sec II : \$\$ \_\_\_\_\_ D.O.A : 5/12/10 Place of Accident : \_\_\_\_\_  
Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SGU 8385T → \_\_\_\_\_ → \_\_\_\_\_ → \_\_\_\_\_



INSRS: Bifrost  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_ Confirm by: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_  
Repair Cost: L/S \$2,250.00 ( 4 days) Reduction: 5,194.90/70% % Email  Call

**FINAL SETTLEMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Final Liability: % (Agreed / Assessed) BOB S/N No. : \_\_\_\_\_ If NO or B 28, Ass. Lia : \_\_\_\_\_  
Repair Cost: \$\$ \_\_\_\_\_  
Loss of Rental (LOR): \$\$ \_\_\_\_\_ days \_\_\_\_\_  
Loss of Use (LOU): \$\$ (\$ \_\_\_\_\_ days) \_\_\_\_\_  
Loss of Income (LOI): \$\$ (\$ \_\_\_\_\_ days) \_\_\_\_\_  
LOR only  LOU only  LOR + LOU  LO  [Tick only one]  
GIA/LTA Search: \$\$ \_\_\_\_\_  
Medical: \$\$ \_\_\_\_\_  
Disbursement: \$\$ \_\_\_\_\_ (e.g. Tow/ Independent )  
Legal Cost: \$\$ \_\_\_\_\_

1) Claim status: Normal/Reject/Private Settle  
2) Report Format: WP  
3) Survey fee: \$359

**Total:** \$\$ \_\_\_\_\_ **Global Sum \$:** \_\_\_\_\_

**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$\$ \_\_\_\_\_ Name 1: \_\_\_\_\_  
Payee 2: (Strike if N.A.) \$\$ \_\_\_\_\_ Name 2: \_\_\_\_\_  
Payee 3: (Strike if N.A.) \$\$ \_\_\_\_\_ Name 3: \_\_\_\_\_

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SGU 8385 T  
 at Workshop m/s Resublon Arbonne  
 of P. Kato Insult for 4 01-49  
 Insured: (Premier)  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SGU 8385 T Yr Regn: 28/105/2007  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
 Make: T. Vios E c.c. 1492  
 Colour: silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 224897km T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MR053HY7305000539  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/60/R15  
 R: 185/60/R15

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm *NEW TON*  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 5/12/19 D.O.I. 11/12/19  
 Survey held at Resublon Arbonne  
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>* SGU 8385 T</u>
	<u>NO amount by estimate.</u>
	<u>(L/S \$2,250/ RED \$5,194.90/70%)</u>
	<u>assessment_val@bifrostauto.com</u>
	<u>Lucas → 8/3/65/8</u>
	<u>MV - 18000</u>
	<u>PV - 12448</u>
	<u>NV - 5506</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Wash and ...

Survey Fee:	\$150
Transportation:	\$50 X3 = \$150
Photos:	\$ 59
Others:	
TOTAL:	\$359