

ASS. REC. BY:

REF: CS1A1619021929/Ut f3/12
Special Instruction:SURVEYOR Marcus ASSIGNMENT (Office)From (Person): Hor Yinnul of A1G Date/Time: 12.12.19 3.41 p.m.

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE1670Z Insured: SMK 88965at Workshop m/s Mah Lian motor Tel: 62823336of NO 38 Dahu Laru 9Policy No: _____ Claim No: 003074492656003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5.12.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 12.12.19 3.54 p.m. Person Contacted: Si Hui H.O.D. Endorsement: _____Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>XE 1670Z - X</u>
	<u>SMK 88965 - X</u>

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE16702

at Workshop m/s

of

Insured:

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

BAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 27232

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: XE16702

Yr Regn: 4, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU CYH52T

c.c.

15681

Colour: black

A/C:

Insured / Std / NI / NA

Sp. Reading: 160392

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JALCYH52TG7000151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

295/60R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Double star

Front

Rear

R/Bal. 6/6

6/6

R/Bal. 6/6

6/6

L/Bal. 6/6

6/6

L/Bal. 6/6

6/6

D.O.A. 5/12/19

D.O.I. 13/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/1/20 4/5 \$5350 confirmed with S. Kim. (Red: 4820; 490)

RECEIVED 17 JAN 2020

Date/Time. File Pass to?

1) 16/1 Typst

Date/Time. File Return to?

2) _____



Prel. Report



Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Add Fee: _____

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

) \$ + RS \$ _____

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$ 5350)

250

11

261

PRE-REPAIR INSPECTION REQUEST – XE1670Z vs SML8896S (OI) on D.O.A.: 05/12/2019

From: Hor, Yinnul
 To: 'assignments@ikauto.com', Admin A (admin-a@ikauto.com)
 Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Div
 Sent: Thursday, 12 December, 2019 3:41:07 PM
 Attachments: 0587-051.pdf 0588-051.pdf

Hi,

Please refer to the enclosed request from **Vision Law LLC**:

Claim no : 0030744926SG003
 Case Owner : Norsiah Bte Md Noor

If you have any queries/concerns, please let us know.
 Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 PNO, Adjuster 1
 Singapore AUTO Claims

Tel: 8001205558 | Ext: 1002208
 Email: HorYinRul@aig.com | www.aig.sg

From: Hor, Yinnul
 Sent: Thursday, December 12, 2019 9:03 AM
 To: 'jactan@visionlawllc.com' <jactan@visionlawllc.com>
 Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
 Subject: signcrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SML8896S AND XE1670Z ON 05/12/2019

Without Prejudice

Your Reference : AM.jt.las.M46 XE1670Z.19 (s)
 Our Reference : 0030744926SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Raul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 PNO, Adjuster 1
 Singapore AUTO Claims

Tel: 8001205558 | Ext: 1002208
 Email: HorYinRul@aig.com | www.aig.sg

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI DIO MUNIANDY
ANG KIM NOI DIANE
RAVENORA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.Jt.Ins.M46.XE1670Z.19 (sj)
Your Ref: **SMK 8896 S**

11 December 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

Email: claimsdocmanagement@aig.com
Email: noormariesa.abukassim@aig.com
Email: shengyang.lm@aig.com
Email: Syazairdina.Azlan@aig.com
Email: yinhui.hor@aig.com
Email: Lee-ying.chin@aig.com

Dear Sirs,

ACCIDENT INVOLVING XE 1670 Z & SMK 8896 S ON 05 DECEMBER 2019 ALONG SENOKO DRIVE AT ABOUT 1705 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We are instructed by K.U.S Pre-Cast (S) Pte Ltd to notify you of a road traffic accident on **05 DECEMBER 2019** at about **1705 HOURS** at/along **SENOKO DRIVE** involving our client's vehicle registration number **XE 1670 Z** and vehicle registration number **SMK 8896 S** driven by you/your insured at the material time

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: **XE 1670 Z** – By fax: 6289-3336 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
AND KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSE
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.112378.19 (sj)
Your Ref: 0030744926SG-003

11 December 2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

Email: claimsdcmangement@aig.com
Email: noormariesa.abukassim@aig.com
Email: shengyang.lim@aig.com
Email: Syazairdina.Azlan@aig.com
Email: yinhui.hor@aig.com
Email: Lee-ying.chin@aig.com

Dear Sirs,

ACCIDENT INVOLVING XE 1670 Z & SMK 8896 S ON 05 DECEMBER 2019 ALONG SENOKO DRIVE AT ABOUT 1705 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 12 December 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua From LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor :
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

cc: XE 1670 Z – by fax: 6289-3336 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	590N
Vehicle Details	
Vehicle No.:	XE1670Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2019
Vehicle Make:	ISUZU
Vehicle Model:	CYH52T
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	6WG1427079
Chassis No.:	JALCYH52TG7000151
Maximum Power Output:	-
Open Market Value:	\$94,150.00
Original Registration Date:	26 Apr 2016
First Registration Date:	26 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$4,708.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$27,232.00
Total Rebate Amount:	\$27,232.00

The information contained herein is correct as at 26 Dec 2019

OK

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlun@singnet.com.sg
 GST:M90362564P RCB NO.201327339E

M/S: AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way #07-16
 AIG Building, Singapore 079120

FAX: 6415 3727

ATTN: Motor Claim Department
 Your Ref No: K.U.S PRE-CAST (S)PL
 Claim Type: Third Party
 Accident Date: 05/12/2019
 TP Veh Reg No: SMK8896S

Estimate No: ES1700614
 Date: 05 Dec 2019
 Policy No: DMCG19003884
 Veh Reg No: XE1670Z
 Make/Model: ISUZU CYH52T
 Chassis No: JALCYH52TG7000151
 Engine No: 6WG1427079
 Reg. Date: 26/04/2016

Estimate Repair Cost to Vehicle No :XE1670Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Set Price				
1 Sideguard Assy	1,800.00	1 SET	1,800.00	1,200.00
2 Sideguard Bracket - LH/RH	850.00	2 PC	1,700.00	1,000.00
3 Aluminium Diesel Tank	3,200.00	1 PC	3,200.00	
4 Rear Mudguard Mudflap	580.00	1 PC	580.00	
5 Mudguard Rubber	80.00	1 PC	80.00	
6 ISUZU Aluminium Plate	280.00	1 PC	280.00	
			7,640.00	7,640.00
Labour				
7 Labour to renew all above parts & weld & refix .	1,500.00	1 JOB	1,500.00	800
8 To spray & painting on affected area .	850.00	1 JOB	850.00	250
9 To rust proofing .	180.00	1 JOB	180.00	
			2,530.00	2,530.00
			Total	SS 10,170.00
			Add GST @ 7%	711.90
			Total Amount Payable	SS 10,881.90

TOTAL: SINGAPORE DOLLAR TEN THOUSAND EIGHT HUNDRED EIGHTY ONE AND CENTS NINETY ONLY

For MAH LIAN MOTOR VEHICLE
 REPAIRER

Signature: _____
 AUTHORIZED SIGNATURE

Not Allowed
 Here
 13/12/19
 1/5 @ 5350
 400

P-4060
 152
 9-3457
 S.N.2200
 L-1050
 6701
 5360

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park.

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19021929/UTF3N2
Date: 21/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900092335
 Claimant Vehicle No: XE1670Z Insured Vehicle No: SMK8896S
 Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: 0030744926SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE1670Z
 Make & Model: ISUZU CYH52T, 15.7 D (M) Engine No: 6WG1427079
 Reg. Date: 26/04/2016 (Man. Year: 2015) Chassis No: JALCYH52TG7000151
 Colour: Black Odometer: 160392 km
 Engine Capacity: 15681 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 (D/D) Rear Tyre Size: 295/80R22.5 (D/D)
 Front Left Side: Double Star 6/66/6 mm Rear Left Side: Double Star 6/66/6 mm
 Front Right Side: Double Star 6/66/6 mm Rear Right Side: Double Star 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,640.00	5,651.00	1,989.00	26.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,050.00	1,480.00	58.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,170.00	6,701.00	3,469.00	34.11
Approved Total (Overridden) (S\$)		5,350.00		
(S\$)	10,170.00	5,350.00	4,820.00	47.39
+ GST 7.00/7.00% (S\$)	711.90	374.50	337.40	47.39
Nett Amount (S\$)	10,881.90	5,724.50	5,157.40	47.39

INSPECTION

Date of Assignment: 12/12/2019
 Date Inspected: 13/12/2019 Inspected At: Mah Lian Motor Vehicle Repairer (HQ)
 Estimated Period of Repair: 4.0 days NO. 38 DEFU LANE 9
 Singapore 539278

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALUMINIUM DIESEL TANK	Badly Dented	3,200.00 F	*3,200.00 FL
2	1		*REAR MUDGUARD MUDFLAP	Distorted	580.00 F	*580.00 FL
3	1		*MUDGUARD RUBBER	Not Necessary	80.00 F	*- FL
4	1		*ISUZU ALUMINIUM PLATE	Bent	280.00 F	*280.00 FL
5	1		*SET SIDEGUARD ASSY	Distorted	1,800.00 FS	*1,200.00 FS
6	2		*SIDEGUARD BRACKET-LH/RH	Bent/Twisted	1,700.00 FS	*1,000.00 FS
					Sub Total (S\$)	7,640.00 6,260.00
					- List Item Discount on L Items 0.00/15.00% (S\$)	0.00 609.00
					Total Parts (S\$)	7,640.00 5,651.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RENEW ALL ABOVE PARTS & WELD & REFIX	New	1,500.00	800.00
2	TO SPRAY & PAINTING ON AFFECTED AREA	New	850.00	250.00
3	TO RUST PROOFING	New	180.00	0.00
Gross Labour Cost (S\$)			2,530.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >