

NATIONAL Assessment Centre Services

[ver 1 Jan'05]

MMA 119163736

Date In: 12/12/19 15:55	Job description	Date & Time Completed	Done by
Ref No: MA1 IMC190219301h4	SAS e-filing		
Veh No: SJM 3921K	E-mail (within 2hrs, AIC 2hrs)		
D.O.A: 11/12/19 16:30	I-Motor Claim Form	MT/1075566 ⁰⁰¹	13/12/19 11:17
☒ TP / Reporting Only	I-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
	Assessment/Survey Report		
TP Insurer:	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No:	INC () / Non-INC ()
Owner / Driver: (	Tel:	()
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: (	Date:	Time: ()
Insured/Driver Liability: (%)	[Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repaler.
() Total Loss Case : to e-mail Insurer URGENTLY.
Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC 10 times 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury:	
Date/Time	Actions

MA1909363	Invoice/Repairation Checklist	Am (\$)	Am (\$)
Claimant's Particulars:	1) AL: Accident Reporting (\$30)	30.00	
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$50)	80.00	
Contact No:	3) TP: Towing Fee \$40/\$45		
Damaged Portion:	4) PT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) PT: Follow-Through Survey (Resurvey) \$30		
Auditors' Comments:	For claiming against INC Only (ver 10 Jan 2005)		
	6) TR: Re-Inspection \$75		
	7) NI: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	ON:		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10	10.00	
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (N-in INC) against INC \$20		
	9) N12: Idao Mobile 30		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2019 15:55
Date Of Accident	11/12/2019 16:30
Exact Location Of Accident	ECP SLIP RD EXIT TO SIGLAP RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM3921K
Insured/Policyholder	
Name Of Registered Owner	NURUL AQILAH BINTE AZMI
NRIC No	S9720890E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98252043
Alternative Phone No	OFFICE-98252043

Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106086690
Cover Note Number	

Driver

Name of Driver	NURUL AQILAH BINTE AZMI
NRIC No	S9720890E
Date Of Birth	28/06/1997
Occupation	OUTDOOR
Date Of Driving Pass	24/03/2016
Driving Experience	3 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98252043
Fax Number	
Contact Number	OFFICE-98252043
Email Address	NOEMAIL

Address	3 TOSCA TERRACE
Postcode	455397
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191212/2113

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Signal Rod

Grass patch

A

A

Skidled

ECP

A = SJM 3921K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION





SINGAPORE POLICE FORCE



T/20191212/2113

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20191212/2113

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/12/2019 15:12		Vide Report No.: G/20191211/0128		Station Diary No.:	
Informant's Particulars					
Name of Informant: NURUL AQILAH BINTE AZMI			Address: APT BLK 3 TOSCA TERRACE OPERA ESTATE SINGAPORE 455397		
ID Type / ID No.: NRIC NO / S9720890E			Contact No.: Home/Office: Mobile: 98252043		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 22	Date of Birth: 28/06/1997	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 2B,2A,2,3,3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 11/12/2019 16:30	Type of Location:
Location: Along Road 1 EAST COAST EXPRESSWAY SIGLAP ROAD ECP (AP) SLIP RD SIGLAP RD				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: SELF SKIDDED				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM3921K	Car	HONDA	FIT 1.3G SKYROOF A	Yellow	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJM3921K	NTUC Income Insurance Co-Operative Limited	5106086690	08/12/2018	29/12/2019



**SINGAPORE
POLICE FORCE**



T/20191212/2113

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 o.
Report No. T/20191212/21

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NURUL AQILAH BINTE AZMI	ID No.	S9720890E
Related Vehicle	SJM3921K (Car)	Contact No.	98252043
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON 11/12/2019 @ 1630 HRS AT ECP(AP) SLIP RD SIGLAP RD, I WAS NEGOTIATING A BEND WHEN I SUDDENLY SKIDDED AND LANDED IN THE GRASS PATCH. THE WEATHER WAS DRIZZLING AND ROAD WAS WET. I DID NOT SUSTAIN ANY INJURIES.

THAT IS ALL

IO AFIQ

65476171



**SINGAPORE
POLICE FORCE**



T/20191212/2113

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20191212/2113

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
LEE CHEN EN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
12/12/2019 15:12

Classification Of Case:



SINGAPORE
POLICE FORCE

Signature:

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	11/12/2019 15:44							
Vehicle No.(For Motor)	SJM3921K	Certificate Number								
Search										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5106086690		NURUL AQILAH BINTE AZMI	S9720890E	GPC	drivo CLASSIC	SJM3921K	SJM3921K	08/12/2018	29/12/2019
Continue										

Claim Handling

Accident MT/1075566

Policy No.	5106086690	Vehicle No.	SJM3921K	GST Registration No.	
Certificate No.					
Policyholder Name	NURUL AQILAH BINTE AZMI	Cover Type	drive CLASSIC	Policyholder NRIC	S9720890E
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)		Loading	0
Contact No.(Mobile)	98252043	Special Remark		Contact No.(Home)	
Email Address		TCA	= No Yes	eCode	No
KFK	= No Yes	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	No
Accident Details					
Report Date	13/12/2019 11:13	Accident Report Within 24 hrs	Yes	Accident Type	Others
Date of Accident	11/12/2019	Time of Accident hh:mm	16:30	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	BCP SLIP RD EXIT TO SIGLAP RD				
Excess					
Own damage Excess	600.00	Additional Excess	1500	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	800.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
Benefits					
GST Registered Information					
GST Registered	No	GST Registration Date		GST Status Verified	Yes
GST Registration No.					
Modification History					
Policyholder Mailing Address					
Address 1	3 TOSCA TERRACE	Address 2	#3 OPERA ESTATE	Address 3	SINGAPORE 455397
Address 4		Address Type	Singapore address	Post Code	455397
Unit No.	3	Related Policy Number	S112317697		
OI Driver Info					
Driver Name	NURUL AQILAH BINTE AZMI	Driver Type	Main Driver	Driver DOB	28/06/1997
Unnamed driver Name		Driver NRIC	S9720890E	Driving Experience	3
Register Date of Driver License	24/03/2016	Driver Age	22	Contact No.(Home)	
Contact No.(Mobile)	98252043	Contact No.(Office)		Address 3	SINGAPORE 455397
Address 1	3 TOSCA TERRACE	Address 2	#3 OPERA ESTATE	Post Code	455397
Address 4		Address Type	Singapore address		
Unit No.	3				
Does he own a Singapore Registered car?	Yes = No	Driver Vehicle No.		Driver Insurer Company	
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes = No		

Modification History

Claim 001 New

Claim Type *	OD-MD	Insured Name	NURUL AQILAH BINTE AZMI	Insured NRIC	S9720890E
Contact No.(Mobile)	98252043	Contact No.(Home)	84400220	Contact No.(Office)	
Email Address	ILAHAZMI@HOTMAIL.COM	DI	SJM3921K	TP	
Claim Description	SJM3921K ON 11 Dec 2019			Vehicle Number	
Preferred Workshop	0	Insured Liability	Partially at Fault	Name of Preferred Workshop	0
Submit No.	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered				Claim Close Date	13/12/2019 11:15
Report Taken By	LIEW SHAN HUI			Date Received	13/12/
Print AK letter					
OD Excess Collected by Workshop					
Save Submit					

Attachment

Accident No.	MT/1075566	Claim No.	001		
Last Doc. Received	* Yes No	Upload Date	13/12/2019 11:17		
Path *					
Choose File	No file chosen	Clear	Please Select		
Choose File	No file chosen	Clear	Please Select		
Choose File	No file chosen	Clear	Please Select		
Choose File	No file chosen	Clear	Please Select		
Choose File	No file chosen	Clear	Please Select		
Choose File	No file chosen	Clear	Please Select		
Choose File	No file chosen	Clear	Please Select		
Message Read		Clear	Please Select		
Attachment List					
Attachment	Uploaded By/Date	Category	Urgency	Description	M
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o	13 Dec 2019 11:17	NRIC/ Driving License	Y	Normal	NRIC/ Driving License 2019-12-13



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:17	SAS	Normal	SAS 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:17	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:16	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:16	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:16	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:16	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:16	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:16	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13
NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 Dec 2019 11:15	Photos	Normal	Photos 2019-12-13

Video List

Uploaded By/Date:	Folder Date:	File Name	Source
-------------------	--------------	-----------	--------

Display in New Window

Scan and uploading

ASSIGNMENT (UDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motor Car ()
 - b) Motorcycle ()
 - c) Bicycle ()
- 2) Vehicle hit:
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govt Property ()
(E.g. signboard, banner, tree etc)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other ()
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case:
 - a) Stolen ()
 - b) Damage found when recovered ()
- 8) Fire:
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information:

Veh No: **SM 3921 K** Date: **30 Dec 2008**
 Type: ☒ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Trailer / Truck / Trailer or
 Make & Model: **Honda Fit 1.3 G Skyroof**
 Colour: **Yellow** Transmission Type: ☒ Auto / Manual
 Eng No: **GE61134113** Sp Reading: **109394**
 Gen Cond: Good / ☒ Poor / Burnt or
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: Nil / ☒ STD A/Rim or
 Tyre Size: F: **195/55 R15 - MIC**
 R: **L**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: **4** mm R/Bal: **6-LION SPORT** mm
 L/Bal: **4** mm L/Bal: **6-BS** mm

Parallel Import: ☒ Yes / No Towed-In: ☒ Yes / No
 Repair Type: ☒ L.S. / I.B.I Towing Required: ☒ Yes / No
 No of Repair Days: **6** Vehicle in Idac: ☒ Yes / No
 D.O.I: **13/12/2019** Time: **10.10 am**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govt Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass/Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started

Time completed

1) CSO

2) ASS

3) Entire Operation Completed Time:

MOTOR CAR (LH)

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror	DIS		
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper	ART		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer LH			
1008	991433	Frt Bumper Reinforcement Clips	NEC		6
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spotter Cover	DD		
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	BVC		
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector ^{inner shield}	ORA		
		Frt LH Wheel Rim	ORA		
		" " Tyre			50%
		Frt LH Wheel housing garnish	DD		

Vehicle No: SJM 3921K

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1167	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			
		Rear LH Wheel Rim	DD		
		" " Tyre			70%
		Petrol Tank			

No of Items: _____ Assessor: _____

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (UC)

ALUMINUM

(1) *Benisek v. U.S.* (2) *Bennis v. U.S.*

(4) Not Consistent (NC)

Vehicle No: SJM 392TK

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber		?	
1373	991944	Frt LH Shock Absorber Mounting		?	
1374	990632	Frt LH Coil Spring		?	
1375	995198	Frt LH Knuckle Arm		?	
1376	995199	Frt LH Knuckle Arm Bearing		?	
1377	995178	Frt LH Lower Arm		?	
1378	995169	Frt LH Upper Arm		?	
1379	995183	Frt LH Tie Rod		?	
1380	995143	Frt LH Drive Shaft		?	
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion		?	
1391	994435	Steering Cross Member		?	
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage LH		?	
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber	BT		
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing	NEC		
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor Drum		?	
1417	992937	Rear LH Brake Caliper Assy		?	
1418	990434	Rear LH Brake Pipe		?	
1419	992946	Rear LH Brake Hose		?	
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam	BT		
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

No of Items: _____ Assessor: _____

Original copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	890E
Vehicle Details	
Vehicle No.:	SJM3921K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G SKYROOF A
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	L13A4148198
Chassis No.:	GE61134113
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,544.00
Original Registration Date:	30 Dec 2008
First Registration Date:	30 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$15,544.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$11,147.00
Total Rebate Amount:	\$11,147.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Dec 2019

OK

Claim Handling

Task Transfer Exit

Accident MT/1075566

LOS SAL SUB

Policy No.	5106086690	Vehicle No.	SJM3921K	GST Registration No.	
Certificate No.					
Policyholder Name	NURUL AQILAH BINTE AZMI			Policyholder NRIC	S9720890E
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	98252043	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	13/12/2019 11:13	Accident Report Within 24 hrs	Yes	Accident Type	Others
Date of Accident	11/12/2019	Time of Accident hh:mm	16:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	ECF SLIP RD EXIT TO SIGLAP RD				

Excess

Own damage Excess	600.00	Additional Excess	1500	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	3 TOSCA TERRACE	Address 2	#3 OPERA ESTATE	Address 3	SINGAPORE 455397
Address 4		Address Type	Singapore address	Post Code	455397
Unit No.	3	Related Policy Number	S112317697		

OI Driver Info

Driver Name	NURUL AQILAH BINTE AZMI	Driver Type	Main Driver	Driver DOB	28/06/1997
Unnamed driver Name		Driver NRIC	S9720890E	Driving Experience	3
Register Date of Driver License	24/03/2016	Driver Age	22	Contact No.(Home)	
Contact No.(Mobile)	98252043	Contact No.(Office)		Address 3	SINGAPORE 455397
Address 1	3 TOSCA TERRACE	Address 2	#3 OPERA ESTATE	Post Code	455397
Address 4		Address Type	Singapore address		
Unit No.	3				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

LOS SAL SUB

Claim Case Officer Ng Hak Joo

Claim Type	OD-MD	Insured Name	NURUL AQILAH BINTE AZMI	Insured NRIC	S9720890E
Contact No.(Mobile)	98252043	Contact No. (Home)	64400220	Contact No. (Office)	
Email Address	LAHAZMI@HOTMAIL.COM	OI Vehicle Number	SJM3921K	TP Vehicle Number	
Claim Description	SJM3921K ON 11 Dec 2019			Name of Preferred Workshop	0
Preferred Workshop Repair Option	☐ Yes ☒ No	Preferred income to assign workshop		Insured Liability report	
Date Registered	13/12/2019 11:17	Claim Close Date		Date Received	13/12/2019 00:00
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	FIT	Engine Capacity	
Date of Registration	30/12/2008	Classis No.	GE61134113		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☒ Yes ☐ No

Type of Tender * **Own Damage**Assessor Name * **SIMON**

Survey Current Status

IDAC/Workshop Name **NATIONAL ASSESSMENT CENTR**IDAC/Workshop Location **51 UBI AVENUE 1 #01-25 PAYA**Windscreen:
Parts & Labour
CostTotal Loss * ☐ Yes ☒ No

Market Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

Remark

REMARK:NO OF REPAIR DAYS:6 DAYS.1X FRT BUMPER LOWER COVER - REPLACE.1X FRT LH WHEEL RIM - REPLACE.1X FRT LH WHEEL HOUSING GARNISH - REPLACE.1X REAR LH WHEEL RIM - REPLACE.1X PETROL TANK - UNCONFIRM.1X FRT LH TIE ROD - UNCONFIRM.1X FRT LH ANTI ROLL BAR LINKAGE - UNCONFIRM.1X REAR LH BRAKE DRUM BASE - UNCONFIRM.1X REAR LH BRAKE PIPE - UNCONFIRM.

Remark for
Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	23306701	DOOR VIEW MIRROR (FRONT LEFT)	1	Replace	X
ABS	2	16000101	BUMPER (FRONT)	1	Replace	X
ABSORBER	3	16005101	BUMPER RETAINER (FRONT LEFT)	1	Unconfirm	X
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
ACTUATOR	5	25400102	FENDER (FRONT LEFT)	1	Replace	X
ADVERTISEMENT STICKER	6	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
AIR BAG	7	43600101	TYRE (FRONT LEFT)	1	Unconfirm	X
AIR BLOWER	8	43600103	TYRE (REAR LEFT)	1	Unconfirm	X
AIR BOX	9	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Unconfirm	X
AIR CHAMBER BOX	10	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm	X
AIR CLEANER	11	30000101	KNUCKLE ARM (FRONT LEFT)	1	Unconfirm	X
AIR COMPRESSOR	12	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Unconfirm	X
AIR CDN	13	30500101	LOWER ARM (FRONT LEFT)	1	Unconfirm	X
AIR CDN (VAN)	14	23600101	DRIVE SHAFT (FRONT LEFT)	1	Unconfirm	X
AIR COOLER	15	401028	STEERING RACK & PINION	1	Unconfirm	X
AIR DISTRIBUTOR	16	401021	STEERING CROSS MEMBER	1	Unconfirm	X
AIR FILTER	17	36600103	SHOCK ABSORBER (REAR LEFT)	1	Replace	X
AIR FLOW	18	44800503	WHEEL BEARING (REAR LEFT)	1	Replace	X
AIR GRILLE	19	15701203	BRAKE DRUM (REAR LEFT)	1	Unconfirm	X
AIR HORN	20	15701501	BRAKE HOSE (REAR LEFT)	1	Unconfirm	X
AIR INTAKE	21	13700102	AXLE BEAM (REAR)	1	Replace	X
AIR RESONATOR BOX						
AIR THROTTLE BODY AND SENSOR						
ALARM						
ALTERNATOR						
ALUMINIUM PANEL - SIDE						
AMPLIFIER						
ANTENNA						
ANTI ROLL						

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SJM 3921 K Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: MODERN

Collection Date: 16/12/19 Time: 1405 with Keys: Yes / No

Tow Truck No: YMT654C Tow Man: FAM KONG WEI NRIC: G696354TX

Signature: [Signature] 98990083

For office use

Attended by: Shan Hui

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Monday, 16 December 2019 11:03 AM
To: Chin
Cc: LKK Paya Ubi
Subject: MT/1075566, SJM3921K

Dear Modern

Please tow this vehicle from Idac and contact owner Ms Nurul at 98252043 when the reoair is done as we have informed her the excess of \$2100/-.

Our Ref: MT/CA/OD/051/1075566-001/NHJ

16 Dec 2019

MODERN AUTOMOTIVE PTE LTD

BLK 3023A #01-61 UBI ROAD 1

SINGAPORE 408717

Dear Sir

CLAIM NUMBER: MT/1075566-001

REPAIR OF VEHICLE NUMBER: SJM3921K

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 16 Dec 2019

Make: HONDA

Model: FIT

Estimated Repair Days: 5

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 2100.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank You

Ng Hak Joo

Executive

Operations, Motor and Personal Lines (PL)

T +65 64307890

www.income.com.sg

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.