

01/12/2019

ASS. REC. BY:

REF: CS3/III19014881/R19d31⁰²

Special Instruction:

Survey: RCSI

ASSIGNMENT (Office)

meimen

From (Person): Gabriel Wee

of III

Date/Time: 11/12/2019

Estimated Cost:

Bill to:

OD ☒ TR / WS / TR RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: FBK 24664

Insured: SHA 7895M

at Workshop in/ MCS Auto

Tel: 6296 9939

at 1100 Serangoon Road

Policy No: MCDMODIS

Claim No: MC719080461

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 19/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:41 AM @ 23/8/19

Person Contacted:

Stephenie

Vehicle ☒ IN ☐ OUT

Date/Time:

Action/Instruction

11/12/19 ☒ X

FBK 24664 - NS/INC/19014638/K/sf3

D.O.A. 19/12/2019


SHA 7895M - NS/INC/19014642/K/sf3

D.O.A. 19/12/2019

Dismantle: 28/8/2019 @ 4pm

US \$480, 4 days.

(Ref \$1100, 19%)



17/12/2019

260-131 = 119

119+11 = 130

RECEIVED 18 DEC 2019

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBK 24664

at Workshop mis MCS AUTO

of 1100, STRANGLING RD

Insured: 111

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

FBK 24664

Yr Regn:

2015 / MAY

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KANASAKI ER 300B

cc

296

Colour:

MULTI

A/C:

Insured / Std / NI / NA

Sp Reading

50822

T/Radio:

Insured / Std / NI / NA

EngNo:

CINr:

JKAE R300ABDA 03550

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/60ZR17

R:

160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

3

mm

R/Bal:

3

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

19/08/19

D.O.I.

23/08/19

0236pm

Survey held at

MCS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear & o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RAHE / day - (2K-3K) - 4 days

Date/Time: File Pass in?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return in?

3)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee

Transportation

F + PS \$

Phone

Other

TOTAL

Add Fee:

☐

Site Insp \$5

☐

Interview \$5

☐

Tech. Insp \$5

☐

Wash \$5

Report Format:

PRS

Long Form / LE: 10

120

11

131

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	654D
Vehicle Details	
Vehicle No.:	FBK2466U
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	KAWASAKI
Vehicle Model:	ER300B
Primary Colour:	Green
Manufacturing Year:	2015
Engine No.:	EX300AEA51990
Chassis No.:	JKAER300ABDA03550
Maximum Power Output:	-
Open Market Value:	\$5,119.00
Original Registration Date:	25 May 2015
First Registration Date:	25 May 2015
Transfer Count:	1
Actual ARF Paid:	\$768.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,501.00
COE Rebate Amount:	\$3,540.00
Total Rebate Amount:	\$3,540.00

The information contained herein is correct as at 13 Dec 2019

OK

Date of accident: 19/08/19

6000

3540

2460

Repair limit 2k

Nivitha (LKK Auto)

From: Gabriel Wee <Gabriel@iii.com.sg>
Sent: Wednesday, 11 December 2019 11:42 AM
To: 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: Stanley Lai; Manivel Priyadarshini
Subject: III REF: MCT19080461| REQUEST PAPER SURVEY TP VEH FBK2466U

Dear Sir/Mdm,

Please conduct paper survey for the below TP vehicle and let us have your report urgently. LOD uploaded and rights granted to you in Merimen.

TP Veh No. : FBK2466U

Thank you.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BSW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Chevrolet Cruze, Chevrolet Cruze Singapore, used Chevrolet Cruze Singapore, used Chevrolet Cruze, used vehicles Singapore or even buy used Chevrolet Cruze Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

119080461 / 01 / MP

RESERVES

TPPD

PRESERVE

TPPI

PRESERVE

UNINSURED LOSS

PRESERVE

SUBRO

PRESERVE

LPPN

INVESTIGATION FEE

SURVEY FEES

P.S

LEGAL FEES

OTHERS

FRAUD CHECK

UPLOAD TO MERIMEN

GRANT RIGHTS

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO 2392
 RECIPIENT ADDRESS 65356802
 DESTINATION ID
 ST. TIME 26/11 17:59
 TIME USE 00'29
 PAGES SENT 2
 RESULT OK

FAXED
 26 NOV 2019
 MOTCLM DEPT.

VISION LAW LLC


Advocates & Solicitors - Notary Public - Commissioner for Oaths
 (Incorporated with limited liability)

ERIC NG CHING BOON
 WONG KENG LEONG RAYNEY
 AUDREY WONG SU-HSIEN
 PAUL YAP TAI SAN
 ANJALI D/O MUNIANDY
 ANG KIM NOI DIANE
 RAVENDRA KRISHNASAMY
 CHEONG YUNHUI, CLARISSA
 SONIA LIM WEI LEI

Unique Entity Number :200721148

Head Office: 133 New Bridge Road
 #18-01/02 Chinatown Point
 Singapore 059413

Branch: 490 Toa Payoh
 #03-11 HDB Hub
 Singapore 310490



TEL: 65342811 (Hunting)
 FAX: 65356802
 E-MAIL: sallychong@visionlawllc.com
 TEL: 65380703

WHEN REPLYING PLEASE QUOTE OUR REFERENCE

Our Ref : AW1-scv-Ins-M78-111355-19(js) (sallychong@visionlawllc.com)

Your Ref : SHA 7895 M

WITHOUT PREJUDICE

20 November 2019

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 Cecil Street
 #04-00/#05-00 IOB Building
 Singapore 049711
Attention: Motor Claims Department

BY HAND

COMFORT TRANSPORTATION PTE LTD
 383 Sin Ming Drive
 GAS Building
 Singapore 575717

CERTIFICATE OF POSTING
 (For your information only)

mc7/19080461.

Png 23/11/2019

Dear Sirs

CLAIMANT: YUNOS BIN HARUN
ACCIDENT INVOLVING FBK 2466 U & SHA 7895 M ON 19-Aug-2019 ALONG BEDOK NORTH AVENUE 1 (ROUNDAABOUT) AT ABOUT 22:30 HRS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **19-Aug-2019 ALONG BEDOK NORTH AVENUE 1 (ROUNDAABOUT) AT ABOUT 22:30 HRS** involving our client's motorcycle registration number **FBK 2466 U** and vehicle registration number **SHA 7895 M** driven by you/your insured at the material time.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEI

Unique Entity Number :200721148F1

Head Office: 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490



TEL: 65342811 (Hunting)
FAX: 65356802
E-MAIL: sallychong@visionlawllc.com
TEL: 63580703

WHEN REPLYING PLEASE QUOTE OUR REFERENCE

Our Ref : AW1-scv-Ins-M78-111355-19(js) (sallychong@visionlawllc.com)

Your Ref : SHA 7895 M

WITHOUT PREJUDICE

20 November 2019

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04-00/#05-00 IOB Building
Singapore 049711
Attention: Motor Claims Department

BY HAND

COMFORT TRANSPORTATION PTE LTD
383 Sin Ming Drive
GAS Building
Singapore 575717

CERTIFICATE OF POSTING
(For your information only)

mc1/19080461.

Prg = 23/11/2019

Dear Sirs

CLAIMANT: YUNOS BIN HARUN
ACCIDENT INVOLVING FBK 2466 U & SHA 7895 M ON 19-Aug-2019 ALONG BEDOK NORTH AVENUE 1 (ROUNDAABOUT) AT ABOUT 22:30 HRS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **19-Aug-2019 ALONG BEDOK NORTH AVENUE 1 (ROUNDAABOUT) AT ABOUT 22:30 HRS** involving our client's motorcycle registration number **FBK 2466 U** and vehicle registration number **SHA 7895 M** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and/or management of your/your insured vehicle. As a result of the accident, our client's motorcycle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1.	Cost of Repair	\$ 5,900.00
2.	Loss of use (7 days x \$120 per day) (in view of PRI)	\$ 840.00
3.	Survey report fees	\$ 381.00
4.	Towing fee	\$ 50.00
5.	GIA & LTA search / report fees	\$ 39.00
6.	Costs Contribution (\$1,500 + 7% GST)	\$ 1,605.00
7.	Photocopy, facsimile and other incidentals (\$100 + 7% GST)	\$ 107.00
		\$ 8,922.00

.../2 to be continued next page

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AW1-scv-Ins-M78-111355-19(js)
Your Ref : SHA 7895 M
Date : 20 November 2019

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA reports made by the rider of FBK 2466U and driver of SHA 7895M;
- (b) LTANet Search;
- (c) Traffic investigation result from the Traffic Police dated 27 August 2019;
- (d) Final Repair Bill from MCS Auto;
- (e) Towing receipt from Orange Plus Towing;
- (f) Surveyor's report & invoice from Keno Assessors and Services ; and
- (g) **21 original photographs** depicting the damages to motor-cycle FBK 2466 U.
 - (P.S:- Original photographs will be sent to insurance co. only)
 - (P.S:- Kindly return us all original photographs within 7 days hereof)

We hereby give you notice of our client's claim, please revert if you request re-inspection within 14 days of this letter. We have notified you on 22 August 2019 and given you the pre-repair inspection notice.

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries. As our client's injury has not stabilised, we are now filing our client's damages pertaining to his motor vehicle only and shall forward his claim for damages and consequential loss in relation to his personal injuries later.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

AUDREY WONG
(HEAD OFFICE)
encls.

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Our Ref : TP/IP/51547/2019
Date : 27 August, 2019

YUNOS BIN HARUN
BLK 851 TAMPINES STREET 83
#06-198
SINGAPORE 520851

Dear Sir/Madam

**ACCIDENT INVOLVING FBK2466U & SHA7895M ALONG ROUNDABOUT OF
BEDOK NORTH AVENUE 1 AND BEDOK NORTH STREET 3 ON 19 AUGUST
2019 AT 2224 HRS**

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver of SHA7895M had committed an offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act, Chapter 276. Action has been initiated against the said driver for the said offence.

3. If you have any queries, please contact the Investigation Officer, Jerry Yeo Chun Jian at 65476213 or via email at YEO_Chun_Jian@spf.gov.sg

Yours faithfully

Perlin Chong
for Head Traffic Investigation
Traffic Police

M/S: Yunos Bin Harun
Blk 851 Tampines Street 83
#06-198
Singapore 520851

Invoice No : INV19/10-02
Our Ref. : KN/FBK2466/19034
Date : 21 October 2019

DESCRIPTION	AMOUNT
Inspection report fees inclusive of transport and photographs Twenty-One (21) copies	\$ 381.00
Singapore Dollars : Three Hundred and Eighty-One Only	\$ 381.00

Yours faithfully
Keno Assessors and Services



Phee Wee Keong
Senior Appraiser

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S: Yunos Bin Harun
Blk 851 Tampines Street 83
#06-198
Singapore 520851

Date : 21 October 2019
Our Ref. : KN/GBK2466/19034

REFERENCE PARTICULARS

Date of Accident : 19 August 2019
Date of Inspection : 27 August 2019

Your Ref. No. : -
Type of Inspection : Third Party Claim

VEHICLE PARTICULARS

Reg. No. : FBK 2466 U
Make : Kawasaki
Model : ER300B
Year : 2015

Chassis No. : JKAER300ABDA03550
Engine No. : EX300AEA51990
Odometer : -
Colour : Green

PRE-ACCIDENT CONDITION (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Front brake : Affected
Rear brake : Serviceable

General Body Work : Body frame affected
Steering : Affected
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

Location	Make	Size	Thread Balance
Front	Pirelli	120/60ZR17	5 mm
Rear	Pirelli	160/60ZR17	5 mm

GENERAL DESCRIPTION OF DAMAGES

The motorcycle sustained damage at the left and right side portion.

Front cowl, brake lever, clutch lever, handle bar, fork inner tubes, front fender, front rim, radiator assy, fuel tank, brake pedal, gear pedal, front footrest, front footrest bracket, exhaust protector, exhaust muffler, etc damaged.

For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as \$ 5,900.00 (Lump Sum)

Inspection conducted at : MCS Auto

Enclosed Twenty-One (21) photographs depicting damage to the vehicle.

Estimated time required for repairs : Seven (07) days.

In accordance to your instruction, we have **not authorised** repair.

The inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

KEN-0

Vehicle No. FBK 2466 U
Model: Kawasaki ER300B

Qty	Description	Condition	Repairer's Estimate	Our Assessment
2 pcs	View mirror L/R @ \$120.00	Grazed	240.00	250.00
1 pc	Brake lever	Grazed	95.00	95.00
1 pc	Clutch lever	Grazed	95.00	95.00
1 pc	Handle bar	Bent	360.00	360.00
1 pc	Handle bar balancer RH	Grazed	105.00	105.00
1 set	Handle grip X	Necessary	50.00	50.00 X SVC
2 pcs	Fork inner tubes L/R @ \$220.00 X	Repair	440.00	- X
2 pcs	Front signal lamp L/R @ \$120.00 X	Grazed	240.00	240.00 X SVC
1 pc	Front fender repair	Grazed	210.00	210.00 R
1 pc	Radiator assy	Dent	490.00	490.00
1 pc	Radiator cover	Bent	85.00	85.00
1 pc	Front brake disc X	Serviceable	440.00	- X
1 pc	Front sports rim X	Repair	750.00	- X
2 pcs	Front fairing L/R @ \$355.00	Grazed	710.00	710.00
1 pc	Fuel tank	Dent	820.00	820.00
1 pc	Brake pedal	Grazed	108.00	108.00
1 pc	Gear pedal	Bent	98.00	98.00
2 pcs	Front footrest L/R @ \$85.00	Missing/ Broken	170.00	170.00
2 pcs	Front footrest bracket L/R	Broken/ Bent	320.00	320.00
2 pcs	Side lower cowling L/R @ \$225.00	Cracked/ Grazed	450.00	450.00
1 pc	Rear footrest LH	Grazed	85.00	85.00
1 pc	Front exhaust protector	Grazed	215.00	215.00
1 pc	Rear exhaust protector	Grazed	160.00	160.00
1 pc	Exhaust muffler	Grazed	950.00	950.00
			7686.00	6066.00 5566
		Less 10%	768.60	606.60 10%
			6917.40	5459.40 5009.40
Special Nett Item				
1 pc	Steering cone	Necessary	125.00	125.00 X SVC
1 set	Body sticker set	Necessary	90.00	90.00 60
2 bots	Fork oil @ \$15.00	Necessary	40.00	40.00 X SVC
2 pcs	Fork oil seal @ \$25.00	Necessary	50.00	50.00 X SVC
	Parts Total :		7222.40	5764.40 60

Vehicle No. FBK 2466 U
Model: Kawasaki ER300B

Labour charges

1)	Towing service charge	60.00	60.00 40
2)	Front rim balancing (Above part repair)	~ 40	50.00 30
3)	Front fork alignment (Above part repair)	~ 100	100.00 X
4)	Body frame alignment	300.00	250.00 150
5)	Spray-painting	1000.00	900.00 500
6)	Remove, replace, repair & realign all affected parts & lighting check.	350.00	300.00 250
Labour Total :		1710.00	1660.00 970
Total Parts & Labour :		8932.40	7424.40

FINAL LUMP SUM ADJUSTMENT

\$ 5,900.00

9091.40

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair at our recommended amount of \$ 5,900.00 Lump Sum, corresponding to supply of parts, spraypainting & labour charges. We now revert for your decision on the above claim.

Yours faithfully
Keno Assessors



Phee Wee Keong
Licensed Appraiser

5009.40
60.00
970.00
6039.40
20%
4831.52
45-4,800

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2019 14:19
Date Of Accident	19/08/2019 22:30
Exact Location Of Accident	BEDOK NORTH AVENUE 1 (ROUND-ABOUT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK2466U
Insured/Policyholder	
Name Of Registered Owner	YUNOS BIN HARUN
NRIC No	S7443654D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93384100
Alternative Phone No	OFFICE-93384100

Vehicle Particulars

Manufacturer	KAWASAKI
Model	ER300B
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5108903989 TPFT
Cover Note Number	

Driver

Name of Driver	YUNOS BIN HARUN
NRIC No	S7443654D
Date Of Birth	14/09/1974
Occupation	OUTDOOR
Date Of Driving Pass	17/03/2011
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93384100
Fax Number	
Contact Number	OFFICE-93384100
Email Address	NOEMAIL



4
Address BLK 851 #06-196 TAMPINES STREET 83
Postcode 520851
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED (REMARKS: TAXI PLATE NUMBER SHOULD BE SHA7895M AND NOT SHA7895N)

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA7895M
Vehicle Make/Model/Colour HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name YUNOS BIN HARUN

Approximate Age 44

Injuries Sustain

Injured person in which vehicle? FBK2466U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of **policy liability** on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be **forwarded** by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you **herby consent** to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, notices, reports or notices to me, which could involve disclosure of certain personal data about me to being about delivery of the same as well as on the external cover of envelopes/mail package(s) and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to third party service providers or agents/providing their lawyers/law firms, which may be situated outside of Singapore for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud applications, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time


21 AUG 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416497 Fax: 67492305
Email: info@idac-singapore.com.sg
Note:
HRT/71's Ltd.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to
Police Report

DECLARATION

We declare the foregoing particulars are true and correct.

[Signature]
Name & Title

21 April 2019

Witness - (Optional)
If driver is not the policyholder
Name & Title

IDAC KAKI-BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vacbb@singnet.com.sg

Witnessing Cases & Representations
Name
Mobile: 9771 7111

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20190820/2123

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

1 of 3

Report No: T/20190820/2123

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 20/08/2019 16:20	Vide Report No: G/20190819/0208	Station Diary No.: 93
---	------------------------------------	--------------------------

Informant's Particulars

Name of Informant YUNOS BIN HARUN			Address: APT BLK 851 TAMPINES STREET 83 #06-198 SINGAPORE 520851	
ID Type / ID No.: NRIC NO / S7443654D			Contact No.:	Mobile: 93384100
Nationality SINGAPORE CITIZEN			Home/Office:	
			Email	
Sex: Male	Age: 44	Date of Birth: 14/09/1974	Type of Informant: Rider	
Race: Malay			Language:	Institution / School Name:
Occupation: DELIVERY			Driving Licence Information: Class:	
			Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/08/2019 22:30	Type of Location: Roundabout
Location: Along Road 1 BEDOK NORTH AVENUE 1				
ROUNDAABOUT				
Weather: Clear		Road Surface Dry		Road Speed Limit.
Traffic Flow:		Traffic Control		Traffic Volume:
Type of Collision Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK2466U	Motorcycle	KAWASAKI	ER300B	Green		0
SHA7895N	Taxi	HYUNDAI		Blue		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBK2466U	NTUC Income Insurance Co-Operative Limited	5108903989	25/05/2019	24/05/2020

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20190820/2123

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3
Report No. T/20190820/2123

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	YUNOS BIN HARUN	ID No.	S7443654D
Related Vehicle	FBK2466U (Motorcycle)	Contact No.	93384100
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/08/2019	Date Discharge	19/08/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL

Brief Details.

On the date, time and location mentioned above, I V1 (FBK2466U) was riding towards the roundabout, upon making a right turn on the roundabout, V2 (SHA7895N) was travelling from my right towards me and collided onto the left rear portion of my vehicle.

As V2 was driving fast, after collision, I had flown towards front and landed onto the road itself. However, landed safely although impact was hard. However, as I felt pain, I was conveyed to hospital.

No mechanical fault. No CCTV.

Individual Statement



SINGAPORE
POLICE FORCE



T/20190820/2123

Police Station Of Origin
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No. 1800-5871999

3 of 3

Report No. T/20190820/2123

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan



IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 GOH JUN KIAT JASON

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
20/08/2019 16:20

Officer In Charge Of Case:
TP / GIT /
SI YEO CHUN JIAN
Contact No. 65476213

Classification Of Case:

Authentication Stamp
NP158

Individual Statement



Changi
General Hospital
SingHealth



ORIGINAL

MEDICAL CERTIFICATE


EMD2019163318

Name YUNUS BIN HARUN		NRIC No. S7443654D	
This is to certify that the above named is unfit for duty for a period of <u>5</u> days from <u>19-Aug-2018</u> to <u>23-Aug-2018</u>			
Type of medical leave granted:			
<input type="checkbox"/> Hospitalisation Leave	<input checked="" type="checkbox"/> Outpatient Sick Leave		
Admitted on: _____	<input type="checkbox"/> Maternity Leave	Commenced on: _____	
Discharged on: _____	<input type="checkbox"/> Menopausal leave	Commenced on: _____	
This certificate is not valid for absence from court attendance			
Diagnosis		Surgical Operation (if applicable)	
Fit for night duty from <u>NA</u> to <u>NA</u>			
Comments			
Has above named patient provided any consent for medical advice or treatment? <u>NA</u> and self as <u>NA</u>			
Wing/Staff Clinic Emergency Medicine Changi General Hospital	Ward No. CGH Accident & Emergency Date 20-Aug-2018	Signature, Name (in BLOCK LETTERS) and Designation MCR No.  NARAIN PURUSHOTTARAM E1952C	

Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2019 13:25
Date Of Accident	19/08/2019 22:20
Exact Location Of Accident	ROUNABOUT OF BEDOK NORTH AVE 1/BEDOK NORTH ST 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7895M
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	JAMALUDDIN BIN ABU BAKAR
NRIC No	S1534213G
Date Of Birth	22/07/1962
Occupation	OUTDOOR
Date Of Driving Pass	14/06/1984
Driving Experience	35 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96844577
Fax Number	
Contact Number	
Email Address	PUMPKINFAIRY@GMAIL.COM

Address	62 05-101 LORONG 4 TOA PAYOH
Postcode	310062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TOA PAYOH NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK2466U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	93384100
Address	
Postcode	
Insurance Company Name	

Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name RIDER

Approximate Age

Injuries Sustain NOT SURE

Injured person in which vehicle? FBK2466U

Were seat belts worn?


Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attached police report

T/20190820/2007

DECLARATION

I/We declare the foregoing particulars are true in every respect.

FOR OFFICE USE ONLY
POLICE OFFICER'S SIGNATURE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

20/8/19

Sketch Plan Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190820/2007

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 4

Report No. T/20190820/2007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/08/2019 01:22		Vide Report No.: G/20190819/0208		Station Diary No.: 22	
Informant's Particulars					
Name of Informant: JAMALUDDIN BIN ABU BAKAR			Address: APT BLK 62 LORONG 4 TOA PAYOH #05-101 SINGAPORE 310062		
ID Type / ID No.: NRIC NO / S1534213G			Contact No.: Home/Office: Mobile: 96844577		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 22/07/1962	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/08/2019 22:20	Type of Location: Roundabout
Location: Junction of Road 1 and Road 2 BEDOK NORTH AVENUE 1 BEDOK NORTH STREET 3 At the roundabout junction of Bedok North Avenue 1 and Bedok North Street 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK2486U	Motorcycle	KAWASAKI		Green	Seriously Damaged	0
SHA7895M	Car	HYUNDAI		Blue	Seriously Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan Pg. 3



SINGAPORE
POLICE FORCE



T/20190820/2007

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

2 of 4

Report No T/20190820/2007

CONTINUATION OF REPORT

Rider			
Name	Unknown Rider	ID No.	NIL
Related Vehicle	FBK2466U (Motorcycle)	Contact No.	93384100
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	JAMALUDDIN BIN ABU BAKAR	ID No.	S1534213G
Related Vehicle	SHA7895M (Car)	Contact No.	96844577
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/08/2019 at about 2220hrs, I was driving my taxi (Comfort Del Gro, blue Hyundai, bearing vehicle registration number SHA7895M) with one female passenger seated at the rear left seat. I was driving along Bedok North Avenue 1 and approached the roundabout junction of Bedok North Street 3. I stopped at the stop line of the roundabout. I saw there were no incoming traffic hence entered the roundabout.

When I was at the roundabout, I suddenly felt a side swipe collision from the right side of my taxi. I then saw that it was a motorcycle (black and green Kawasaki, bearing vehicle registration number FBK2466U) collided into my taxi and the rider fell. I then stopped my vehicle and alighted to assist the rider. I only managed to get the contact number of the rider.

Shortly after, Traffic Police and ambulance arrived at scene. The rider was then conveyed by the ambulance. The Traffic Police gave me the report number G/20190819/0208, IO Jerry Yeo. My taxi's front camera SD card was handed over to the TP officer and a NP323 was issued to me. I was advised to lodge a Traffic Accident report.

Due to the accident, my taxi's right front tyre was punctured, the front right portion of my taxi was dented and alignment was out. The front right bumper also slightly came out. My taxi and the motorcycle was towed away. Due to the accident, I did not sustain any injuries. My passenger did not complain of any injury.



**SINGAPORE
POLICE FORCE**



T/20190820/2007

Police Station Of Origin:
Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

3 of 4

Report No. T/20190820/2007

CONTINUATION OF REPORT



SINGAPORE
POLICE FORCE



T/20190820/2007

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999




CONTINUATION OF REPORT

4 of 4
Report No. T/20190820/2007

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 3 WEE SHUN QIANG, JOSEPH 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 20/08/2019 01:22
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case: SN 168
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: **Loke Wei Yieng**
NRIC/FIN No:

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. SHA7895M As At 19 Aug 2019 / 22:30:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: M78.MISC.19.FBK2466U

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHA7895M
Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Insurance Company Name: INDIA INT'L INS PTE LTD

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19014881/R1qd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 19-12-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7895M	Veh. Inspected	FBK 2466U
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19080461	Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	11/12/2019

2. Vehicle Particulars & Condition

Make & Model	KAWASAKI ER300B	c.c	296
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JKAER300ABDA03550	Colour	MULTI COLOUR
Odometer	50822	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/60Z R17	PIRELLI	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60Z R17	PIRELLI	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2019	Inspection Date	23/08/2019
Survey held at	MCS AUTO NO. 1100 SERANGOON ROAD SINGAPORE 328195		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 2466U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	VIEW MIRROR L/R @\$120.00	GRAZED	250.00	250.00
1	BRAKE LEVER	GRAZED	95.00	95.00
1	CLUTCH LEVER	GRAZED	95.00	95.00
1	HANDLE BAR	BENT	360.00	360.00
1	HANDLE BAR BALANCER RH	GRAZED	105.00	105.00
1	SET HANDLE GRIP	SERVICEABLE	50.00	-
2	FORK INNER TUBES L/R @\$220.00	TO REPAIR SEE LABOUR	440.00	-
2	FRONT SIGNAL LAMP L/R @\$120.00	SERVICEABLE	240.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	210.00	-
1	RADIATOR ASSY	DENTED	490.00	490.00
1	RADIATOR COVER	BENT	85.00	85.00
1	FRONT BRAKE DISC	SERVICEABLE	440.00	-
1	FRONT SPORTS RIM	TO REPAIR SEE LABOUR	750.00	-
2	FRONT FAIRING L/R @\$355.00	GRAZED	710.00	710.00
1	FUEL TANK	DENTED	820.00	820.00
1	BRAKE PEDAL	GRAZED	108.00	108.00
1	GEAR PEDAL	BENT	98.00	98.00
2	FRONT FOOTREST L/R @\$85.00	MISSING / BROKEN	170.00	170.00
2	FRONT FOOTREST BRACKET L/R	BROKEN / BENT	320.00	320.00
2	SIDE LOWER COWLING L/R @\$225.00	CRACKED / GRAZED	450.00	450.00
1	REAR FOOTREST LH	GRAZED	85.00	85.00
1	FRONT EXHAUST PROTECTOR	GRAZED	215.00	215.00
1	REAR EXHAUST PROTECTOR	GRAZED	160.00	160.00
1	EXHAUST MUFFLER	GRAZED	950.00	950.00
	LESS 10% DISCOUNT		-769.60	-556.60
			6,926.40	5,009.40
SPECIAL NETT ITEMS				
1	STEERING CONE (SN)	SERVICEABLE	125.00	-

Report Ref No. CS3/III19014881/R1qd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BODY STICKER (SN)	NECESSARY	90.00	60.00
2	BOTS FORK OIL @\$15.00 (SN)	SERVICEABLE	40.00	-
2	FORK OIL SEAL @\$25.00 (SN)	SERVICEABLE	50.00	-
			305.00	60.00
	LABOUR			
	TOWING SERVICE CHARGE		60.00	40.00
	FRONT RIM BALANCING		50.00	30.00
	FRONT FORK ALIGNMENT	NOT NECESSARY	100.00	-
	BODY FRAME ALIGNMENT		300.00	150.00
	SPRAY-PAINTING		1,000.00	500.00
	REMOVE, REPLACE, REPAIR & REALIGN ALL AFFECTED PARTS & LIGHTING CHECK. INCLUSIVE OF THE REPAIR OF FORK INNER TUBES L/R, FRONT FENDER AND FRONT SPORTS RIM		350.00	250.00
			1,860.00	970.00
	GRAND TOTAL		9,091.40	6,039.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CS3/III19014881/R1qd3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng.AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.