

ASS. REC. BY:

REF:

CS/ABE19021960/4yd30

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Jenny Toh

of

QBEDate/Time: 12/12/19 @ 3:47pm

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: \_\_\_\_\_

GBG 2244P

Insured: \_\_\_\_\_

YM 9959K

at Workshop in/s \_\_\_\_\_

Huat Automobile

Tel: \_\_\_\_\_

9137 8893

of \_\_\_\_\_

Blk 3007 Ubi Road 1 # 01-404

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

VC013265

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

D.O.A. \_\_\_\_\_

4/12/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10:23am @ 13/12/19

Person Contacted: \_\_\_\_\_

TommyVehicle: INT/OUT

Date/Time	Action/Instruction
	<u>Johnnie</u> ✓
	<u>GBG 2244P - X</u>
	<u>YM 9959K - X</u>

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

QBE/

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7006

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBG 22442 617

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make:

maxus 610 c.c 1850

Colour:

grey

A/C: Insured / Std / NI / NA

Sp. Reading

53054

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LSK646L1XHA04488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/70 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/12/19

D.O.I.

13/12/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Analysis Estimate. LHA 27689  
 headed by 1655

9/1/20 confirmed L/S @ 3200 with Tamy (Red \$2789-00, 46%)

RECEIVED 13 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

9/1/20

Days Of Repair:

3

Resurvey No. of Trip:

3

Survey Fee:

300

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

300

Report Format :

Lump Sum / I.B.I. (\$) \$3200/=

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

## Nivitha (LKK Auto)

---

**From:** Jenny Toh <jenny.toh@qbe.com>  
**Sent:** Thursday, 12 December 2019 3:47 PM  
**To:** assignments  
**Cc:** claims-singapore  
**Subject:** [VC013265] PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: YM 9959K // Our ref: L.19.1494.lt.cj

10:23am @ 13/12/19  
P: Tomy

Our ref: VC013265

Hi all

Kindly survey the third party claim.

regards

---

**Jenny Toh**

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#)

[LinkedIn](#)

[Twitter](#)



---

**From:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Sent:** Thursday, 12 December 2019 3:41 PM  
**To:** Jenny Toh <jenny.toh@qbe.com>  
**Cc:** claims-singapore <claims-singapore@qbe.com>  
**Subject:** Re: [VC013265] PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: YM 9959K // Our ref: L.19.1494.lt.cj

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

**HUAT AUTOMOBILE AIR CON SERVICE**

**Blk 3007 Ubi Road 1**

**#01-404**

**Singapore 417921**

**Tel: Tomy Tan 9137 8893**

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

On Thursday, 12 December 2019, 2:59:15 pm SGT, Jenny Toh <[jenny.toh@qbe.com](mailto:jenny.toh@qbe.com)> wrote:

Our ref : VC013265

Dear Lena

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Priority Services
Infiniti Appraisal Service
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

regards

---

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583



---

**From:** Kuru & Co <[kurulegal@yahoo.com.sg](mailto:kurulegal@yahoo.com.sg)>  
**Sent:** Thursday, 12 December 2019 10:36 AM  
**To:** claims-singapore <[claims-singapore@qbe.com](mailto:claims-singapore@qbe.com)>; Jenny Toh <[jenny.toh@qbe.com](mailto:jenny.toh@qbe.com)>  
**Subject:** Re: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: YM 9959K // Our ref: L.19.1494.It

Dear Sirs,

**ACCIDENT INVOLVING GBG 2244P AND YM 9959K ON 04.12.19  
AT/ALONG CARPARK ENTRANCE OF 1 YISHUN STREET 23  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Chuan Heng Lee Electrial Company**, whose vehicle registration number **GBG 2244P** was damaged in the above accident.

A copy of the Singapore Accident Statement filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,

Lena

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

----- IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

----- IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/12/2019 20:30
Date Of Accident	04/12/2019 20:15
Exact Location Of Accident	1YISHUN STREET 23 SINGAPORE 768441
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG2244P
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	CHUAN HENG LEE ELECTRICAL COMPANY
Co Reg No	26824700E
Email Address	C.H.L.ELECTRICAL.CO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98191314
Alternative Phone No	OFFICE-98191314

#### Vehicle Particulars

Manufacturer	MAXUS
Model	G10-1.9 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900101388
Cover Note Number	

#### Driver

Name of Driver	GOH MOH KHOON
NRIC No	S0103052C
Date Of Birth	17/11/1953
Occupation	INDOOR
Date Of Driving Pass	29/06/1993
Driving Experience	26 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98191314
Fax Number	
Contact Number	

Address	BLK 274 YISHUN STREET 22 #05-156 SINGAPORE
Postcode	760274
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9959K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passengers (Including Driver)	



# Sketch Plan #2

## SKETCH PLAN

Vehicle  
A - G8G2244 P  
B - YM9959 K

Legend

vehicle

Motorcycle

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

04 December 2019 8.36am I Was Waiting in queue to go into the Building carpark when the dummy in front YM19959K Suddenly reverse into my parked vehicle

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

**CHUAN HENG LEE ELECTRICAL CO.**

Block 274 Yishun Street 22 #05-158

Date & Time: Singapore 760274 (if driver is not the policyholder)

Telephone: 6755 8838 Mobile: 9819 1314

Email: ch.leeelectrical@gmail.com

**CHUAN HENG LEE ELECTRICAL CO.**

Block 274 Yishun Street 22 #05-158

Singapore 760274

Telephone: 6755 8838 Mobile: 9819 1314

Email: ch.leeelectrical@gmail.com

CHUAN HENG LEE ELECTRICAL CO.

Block 274 Yishun Street 22 #05-158

Singapore 760274

Telephone: 6755 8838 Mobile: 9819 1314

Email: ch.leeelectrical@gmail.com

Signature

Signature

Signature

Signature

Signature

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**CHUAN HENG LEE ELECTRICAL CO.**

Block 274 Yishun Street 22 #05-156

Singapore 760274

Telephone: 6755 5636 Mobile: 9819 4314

Policyholder's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Reporting Centre Personnel's Signature: \_\_\_\_\_

CHUAN HENG LEE ELECTRICAL CO.

Block 274 Yishun Street 22

Singapore 760274

Telephone: 6755 5636 Mobile: 9819 4314

email: chuanheng@chuanheng.co

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	700E
<b>Vehicle Details</b>	
Vehicle No.:	GBG2244P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2019
Vehicle Make:	MAXUS
Vehicle Model:	G10 VAN 6AT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	19D4N1RYH124K087
Chassis No.:	LSKG4GL1XHA044488
Maximum Power Output:	-
Open Market Value:	\$20,744.00
Original Registration Date:	30 Jun 2017
First Registration Date:	30 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$1,038.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$27,689.00
<b>Total Rebate Amount:</b>	<b>\$27,689.00</b>

The information contained herein is correct as at 26 Dec 2019

OK

HUAT AUTOMOBILE AIR CON SERVICE  
BLK 3007 Ubi Road 1 #01-404 (408701)  
TEL : 67461868 FAX : 67462065

Not Authorized  
2/s \$3200  
3dy.

GBG 2244P

S. NETT ITEM

1PC FRONT BUMPER  
1PC FRONT BUMPER CENTRE GARNISH  
1PC FRONT BUMPER SIDE GARNISH LH  
1PC FRONT BUMPER LOWER CENTRE GRILLE  
1PC FRONT BUMPER SPONGE  
1PC FRONT BUMPER REINFORCEMENT  
1SET FRONT BUMPER CLIPS  
1PC FRONT HEADLAMP LH  
1PC FRONT GRILLE

102

n/re \$909.00 ✓  
2/s \$235.00 ✓  
re \$68.00 ✓  
11 \$165.00 x  
11 \$98.00 x  
n \$617.00 x  
re \$60.00 ✓  
cm \$1,652.00 ✓  
cm \$685.00 ✓  
\$4,489.00

TO CHECK WIRING  
TO REFILL AIR CON GAS  
TO SPRAY RUST PROOFING  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

\$50.00 20  
11 \$120.00 x  
11 \$50.00 x  
\$600.00 380  
\$680.00 380

TOTAL \$5,989.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

p-3609  
102  
p-3248.10  
1-780.00  
4028.10  
202  
3222.




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE19021960/Uyd3e2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 23-01-2020		
		Code : QBE		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YM 9959K	Veh. Inspected	GBG 2244P	
Policy No.		Coverage (\$)	0.00	
Claim No.	VC013265	Excess (\$)	0.00	
Assign From	JENNY TOH	Assign Date	12/12/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAXUS G10 (A)	c.c	1850	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	LSKG4GL1XHA044488	Colour	GREY	
Odometer	53054	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/70 R16	HANKOOK	6 mm	
L/H Front Tyre	215/70 R16	HANKOOK	6 mm	
R/H Rear Tyre	215/70 R16	HANKOOK	6 mm	
L/H Rear Tyre	215/70 R16	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/12/2019	Inspection Date	13/12/2019	
Survey held at	HUAT AUTO-BLK 3007 UBI ROAD 1# 01-404			
Repairer	-			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2244P**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (N)	DENTED / DEFORMED	909.00	909.00
1	FRONT BUMPER CENTRE GARNISH (N)	DISTORTED	235.00	235.00
1	FRONT BUMPER SIDE GARNISH LH (N)	DEFORMED	68.00	68.00
1	FRONT BUMPER LOWER CENTRE GRILLE (N)	NOT NECESSARY	165.00	-
1	FRONT BUMPER SPONGE (N)	NOT NECESSARY	98.00	-
1	FRONT BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	617.00	-
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	60.00	60.00
1	FRONT HEADLAMP LH (N)	CRACKED	1,652.00	1,652.00
1	FRONT GRILLE (N)	CRACKED	685.00	685.00
	LESS 10% DISCOUNT		-	-360.90
			4,489.00	3,248.10
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		600.00	380.00
	TO PUTTY & SPRAY PAINTING.		680.00	380.00
			1,500.00	780.00
<b>GRAND TOTAL</b>			<b>5,989.00</b>	<b>4,028.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/QBE19021960/Uyd3e2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.