		MENT (Office	)
iinul	From (Person): Chang Burn Sen of	CIL	Date/Time: 13.n.n 10.51a.m
	Estimated Cost:	Bill to:	
(	OD TP+WS/TP RES/OD RES/EVA/INV/M To Inspect Vehicle No: GBH 17129	V i CS	Insured:
	at Workshop m/s Sng Ah Tel		Tel: 62 6 8 6 183
	of BIK 3 Pioneer Rd North		
	Policy No: DMC USN 3014311900	Claim No	SNM 14 D 2058 6 )
	Sum Insured:	Excess:	\$ 450.00
	Make of Veh:		D.O.A. 8.12.2019
	(Client's Record)		
	CA REV REP. / REV 24 HRS	Stage	H.O.D. Endorsement:
	Date/Time: 13.12.19 11.00a.10 Person Contac	ited.	Vehicle IN LOUT
	Date/Time Action/Instruction ( ) Estimate GBH 17126- (53/671		463 NOA - 03/12/2019
	18/12/19@9.45 an 13064 Sen info		
	18/12/1909.45an Boon Sen info	vared C/A	un menaren.
	18/14/19 Olp. 1200 informed ing	Ah Tee C,	A & Ex: # 450 by ener 1
	(b) ( ( 1 - cb) ( ) )	1	

Date/Time File Pass to? Prell. Report Days Of Repair: 5

Days Of Repair: Date/Time, File Pass to? Preli. Report Resurvey No. of Trip: 30/04 Typist Final Report Date/Time, File Return to? Add Fee: Site Insp (\$ Interview (\$ Tech. Inve G MER-OD Peron Format : 2174 Mederid (4 11.E.E.E.E.

Transportation:
) \_\_S + RS\_\_St
) Photos
) cellust

Survey Fee:

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj	Rpt	Adj Submitte	ed In	s Auth'ed	Status		
Main	12 Dec 2019 Sendback Est	13 Dec 2019 09:20 <b>\$\$3,178.20</b>	13 Dec 2019 10:51 Assign						New Assignment Cancel Case		
	Main	Refere	nce		Claim De	tails	t	Oocuments		Show All	
CLAIM S	UBFOLDER DETAIL	s									
Insured:		GREENLIT	E ELECTRIC PTE.	LTD.,	Co. Reg	. No.: 2004040	54W				
Vehicle Re	g. No.:	GBH171	2G		Date of	Loss:		[21 Mon	019 15:00 - oths and <b>2</b> Da e (Man Yr)]	:59 sys From LTA	
Claim Type	e:	OD / SNM19D2 CBS	SNM19D205861/GBH1712G/			Policy/Cover Note No.:			DMCVSN3014311900 (Comprehensive)		
					Excess:			S\$450.0	10		
Repairer:			e Motor & Panel el: 6268 6183	Servic	e Pte Lto	i (Pioneer) Blk	3 Pioneer	Road North	n, #01-18, 6	28457	
Handling I	nsurer:	China Taip Sen]	ing Insurance (S	Singap	ore) Pte	. Ltd. (HQ) - To	el: 6389 6	111 [Har	ndled by <b>Cho</b>	ng Boon	
Adjuster:		LKK Auto	Consultants Pte I	Ltd (H	Q) - Tel:	6256-3561 [	Final Rp	t due 24/	/12/2019]		
Driver/Cus	itodian:	PARAMASIN	AM RADHAKRISHI	NAN (3	2 / Male)	, NRIC: G824	0586R,	Tel: +6591	320613 Ema	II: NOEMAIL	
ASSOCIA	TED MAIL RECEIV	ED						View All	Compos	e Case Mail	
There are	no mail for this case.										
E ALL ASS	OCIATED TASKS					. 1				1 -	
		1777 122 1779 174 177 177 177 177 177 177 177 177 177	ATT THE WILLIAM TO		-		h Tasks		New Task	Complete	
Due Da	te Priority Ty	pe Task Grou	p Subject	Handl	er A	ssigned By	Comple	ted On	Created (	On Done	

# Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 18 December 2019 10:12 AM

To:

admin@sngahtee.com; janice@sngahtee.com; SAMANTHA TAN;

sharon@sngahtee.com

Cc:

SUR

Subject:

OD VEHICLE GBH 1712G (DOA: 08/12/2019)

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle GBH 1712G (Excess \$450/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# Claim Audit

A	UDIT	RAIL		Ву
0.	On	Audit	Remarks	[R] JOYCE
	12 Dec	Clm Veh	10 miles (10 mil	TAN LAI
	2019	Model	(204479) TOYOTA DYNA 150 3.0 D (M).	CHIN
	13:31	Changed	and (12/00 Claim Types OD Jacurer: Chi	5 T V
	12 Dec		Reg No: GBH1712G, Policy No: DMCVSN3014311900, Acct Date: 2019/12/09, Claim Type: OD, Insurer: Chi	TANIAL
	2019	Clm Created	na Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Sng An Tee Motor & Pariet Service Pte Ltd. (HQ).	CHIN
	13:31		eer), Created from SAS:MSAT19162945	[R] JOYC
	12 Dec	Clm		TAN LAI
3	2019	Submitted	3178.20.	CHIN
	16:54		59PTM03423750C	Serior III.
	12 Dec	Ins Sent	PLEASE TAKE NOTE ACCIDENT INCURRED ON 08.12.2019-REFER TO POLICE REPORT. AND DO AMENDMEN	[I] Angie
į.	2019	Back Est	T IN SAS REPORT	Foo
	17:16	Dack Lat		[R] JOYC
	13 Dec	Clm	2010/12/09	TAN LAI
7). 1	2019		Acct Date:2019/12/09->2019/12/08.	CHIN
	09:18	Modified		[R] JOYC
	13 Dec	Clm	2470.20	TAN LAI
5	2019	Submitted	3178.20.	CHIN
	09:20			[I] Chon
	13 Dec		5.450.00	Boon Se
7	2019		Excess: -> 450.00.	50011 00
	10:51	Modified		[I] Chon
_	13 Dec	Adj Co	LKK Auto Consultants Pte Ltd (HQ):	Boon Se
В	2019	Assigned	LKK Auto Consultation File Life (1147).	500,100
	10:51	Add Nove		[I] Chon
		Adj Next	Next Rpt:Final Rpt.Due Date:2019/12/24	Boon Se
9	2019 10:51	Rpt Changed	HEAL ROLL HILL ROLL OF COLUMN AND ADDRESS OF THE PARTY OF	
		103372310 <b>7</b> 70		[I] Chon
	13 Dec 2019	Mandate	Approved:0.00.	Boon Se
U	10:51		Approved.sion.	
		Assignment		[A] LEE
11	2019	1st		SU THIN
•	10:54	3.075.75.75		
	13 Dec			[A] LEE
12	2019	Adjuster	[None] -> MOHD RASUL	SU THIN
	11:07			
	16 Dec			[A] SHIA
13	2019	Adj Rpt Initiated		CHAN
	14:46	Initiated		
	16 Dec	Adj Im.		[A] SHIA
14	2019	Advice	Next Rpt:Final Rpt.Due Date:2019/12/24	CHAN
	14:51	Submitted		
	16 Dec	Adj	THE PROPERTY OF PARTY COST ECONOMICAL WE HAVE NOT AUTHORISE REPAIR	[A] SHIA
15	2019	Mandate	Cur.Req:3058.20:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR	CHAN
		Request		F11 01
		Adj Next	No. 5 - 1 8-1 8-1 Pure Ports 2010/12/24	[I] Chor
16	2019	Rpt	Next Rpt:Final Rpt.Due Date:2019/12/24	Boon Se
		Changed		(11) Ch
	18 Dec		4	[I] Chor Boon Se
17	2019	Mandate	Approved:3058.20.	Boon Se
	09:45	set		

	_	-	
	PEND	TV	
ACT	IIV.		

No record

erimen Bill	ing for this cas	e - Transactio	n History		T Swarpenson		UKSHINI.	0.000.000.000
Bill Ref No	Bill Date	BIII Туре	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2374934	12 Dec 2019 13:31:51	OD/TP Case (Repairer)	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	GBH1712G		xx.xx
2377950	16 Dec 2019 14:46:34	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBH1712G		11.77

# Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Chong Boon Sen

Date: 16 Dec 2019

# Preliminary Advice

Vehicle No.

: GBH1712G

Accident Date

: 08/12/2019

Make

Attn:

: TOYOTA DYNA 150

Policy No.

: DMCVSN3014311900

Assignment Date

: 13/12/2019

Excess

: S\$450.00

Date of Inspection

: 13/12/2019

Est. Duration of Repair

: 5.00

Inspection At

: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

BLK 3 PIONEER ROAD NORTH, #01-18

SINGAPORE 628457

# Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,178.20
Revised Amount	:S\$	2,783.20
Check Items (Estimated)	:S\$	275.00
Total	:S\$	3,058.20

:S\$ Lump Sum Repair

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	27,373.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,627.00

## Remarks

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy collet us have your authorisation.	
---	--

v	The vehicle is	uneconomical	to be	repaired.	vou are	advised	to	invite	tender	for	the	wreck	Κ.
- 20	The vehicle is	uneconomical	IO DO	Topalicu,	you are	dationa	***						

Other comments:

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	064W
Vehicle No.:	GBH1712G
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2774594
Chassis No.:	JTFAT35Y80K209803
Maximum Power Output:	( <del>-</del> )
Open Market Value:	\$27,084.00
Original Registration Date:	06 Mar 2018
First Registration Date:	06 Mar 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$1,355.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	·
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	05 Mar 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$33,277.00
COE Rebate Amount:	\$27,373.00
Total Rebate Amount:	\$27,373.00

The information contained herein is correct as at 13 Dec 2019

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	064W
Vehicle No.:	GBH1712G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2774594
Chassis No.:	JTFAT35Y80K209803
Maximum Power Output:	*
Open Market Value:	\$27,084.00
Original Registration Date:	06 Mar 2018
First Registration Date:	06 Mar 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$1,355.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	E. Carrier
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	05 Mar 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$33,277.00
COE Rebate Amount:	\$27,115.00
Total Rebate Amount:	\$27,115.00

The information contained herein is correct as at 11 Dec 2019

ОК

58,000 27115 30,885

## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIE	<b>YEN</b>	тет	ATE	MEN	т
ACCIL	/EN			111-11	

Date Of Report 11/12/2019 12:35
Date Of Accident 08/12/2019 15:30

Exact Location Of Accident ALONG AYE TOWARDS LOWER DELTA RD

Country/State of Loss SINGAPORE

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number GBH1712G

Insured/Policyholder

Name Of Registered Owner GREENLITE ELECTRIC PTE. LTD.

Co Reg No 200404064W

Email Address SYWONG@GREENLITE.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-68772911

Vehicle Particulars

Manufacturer TOYOTA

Model DYNA 150-3.0 D (M)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number DMCVSN3014311900

Cover Note Number

Driver

Name of Driver PARAMASIVAM RADHAKRISHNAN

 Passport No/FIN
 G8240586R

 Date Of Birth
 15/06/1987

 Occupation
 OUTDOOR

 Date Of Driving Pass
 07/07/2009

Driving Experience 10 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91320613

Fax Number Contact Number

EMail Address NOEMAIL

Page 1 of 20

N/A Address Postcode Was driver an employee of the Insured's Company YES If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident COLLISION - CHANGE/CROSS LANE Weather Conditions CLEAR Road Surface DRY Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles (including own vehicle) 2 involved in the accident Was any body injured in the Accident? NO Was any injured conveyed to hospital by NO ambulance? Was any other material or property damaged? NO I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. 1 Number of Passengers (Including Driver) Details of Police Action Was the accident reported to the police? YES If Yes, Please state which Police Station Police Station Name CHOA CHU KANG NPC ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 . Police Station Address COUNTRY: SINGAPORE Police Station Contact TEL NO: - FAX NO: Was notice of intended Prosecution given? NO If Yes, against whom? Circumstances of Accident REFER TO POLICE REPORT T/20191209/2042 Attachment(s) Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO NO Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SLC7644M Vehicle Make/Model/Colour **Details Of Properties** PRIVATE CAR Vehicle Category Name of Driver NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes,
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law anforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

GEORGE SERVICES

Policyholder's Signature Date & Time: C

Drivers signature Representative

(If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature

NRIC/FIN No.:

I AM AWARED THAT MY IN SURER MAY HAVE A 14 DAYS TWEFRAM E FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

# Sketch Plan Pg. 2

ESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	100 11 11 100 11 101 101
	525 DE CHIERAS SERVICES DE LA CONTRACTOR D	1209/2042
Reser to Po	ice Report T/20191	120412042
Camark: Drive	= I or of our o	UnPamo?
Comark: Drive	r is longer at our c	conth-md
	310	
	7.5000	
		2 Claim own policy
		Claim third party
		Claim OD / TP at other works hop
COLADATION COLUMN		Policy No. DMCU SN30/431/900 Insurer CRN9 Veh No. GBATTIZ
ECLARATION	nulner are true in avery respect	Insuer China Veh No. GBH 7712
Ask deciate the totellough backs	culars are true in every respect.	
(ST122)	H	14
SOUTH AND SOUTH		
olicyholder's Signature	Driver's Signature Represtative	Reporting Centre Personnel's Signature
ate & Time:	(If driver is not the policyholder)	Name: NRIC/FIN No.:
	Date & Time:	MINUTERS INVO

## police report Pg. 1





Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286

1 of 3 Report No. T/20191209/2042

Tel No: 1800-7659999

DRIVER

REPORT C	OF A TRAFFIC	CACCIDENT		
Date/Time Report Made: 09/12/2019 12:01			Vide Report No.:	Station Diary No.: 45
Informa	nt's Partici	ulars	<b>发展的特殊的</b>	Special and the control of the control of
Name of	f Informant:		Address:	
ID Type / ID No.: FIN NO / G8240586R			Contact No.: Home/Office: Mobile: 91320613	
National			Email:	
Sex: Age: Date of Birth:		Date of Birth: 15/06/1987	Type of Informant: Driver	
Race: Indian			Language:	Institution / School Name:
Occupation:			Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 08/12/2019 15:30	Type of Location Straight Road	
		Road Surface:		Road Speed Limit:	
Weather:		Dry			
Clear	Traffic Flow: Traffic Control:			Traffic Volume: Light	
Clear Traffic Flow: One Way				3.5. (T. 10.5.5)	

Details of Ve	PRODUCED CONTRACTOR OF	Make	Model	Color	Condition	No of Passenger
Vehicle No.	A STATE OF THE PARTY OF THE PAR	Wake	Service Chr. Service Control		Slightly	0
GBH1712G	Lorry				Damaged	_
	0				Slightly	1
SLC7644M	Car				Damaged	

## police report Pg. 2





Police Station Of Origin: Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999 2 of 3 Report No. T/20191209/2042

CONTINUATION OF REPORT

#### Brief Details.

On the above mentioned date, time and location, I was turning into 2nd lane towards Lower Delta Road. Before turning I made a check and saw a car traveling straight into Lower Delta Road however it was far. I proceeded to make a turn. Suddenly, the car was on the extreme right lane and had already knocked my vehicle at the right side. No one was injured. We then exchanged particulars and left the scene. I have a camera in my lorry however there was no footage captured as informed by my company.

The driver of the car is : Kang Swee Kok, S7426027F

## police report Pg. 3





Police Station Of Origin; Choa Chu Kang N.P.C 20 Choa Chu Kang Street 52 #01-02 SINGAPORE 689286 Tel No: 1800-7659999

3 of 3 Report No. T/20191209/2042

CONTINUATION OF REPORT

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report J / Sgt 2 ABAYA PRITHA D/O SELVAM ARUMUGAM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/12/2019 12:01
SNIGATORE POLICE POLICE	
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151 SIGNATURE	Classification Of Case:
Authentication Stamp	

Authentication Stamp NP168

# Sng Ah Tee Motor Pte Ltd Blk 3 Pioneer Road North, #01-18, 628457

**Insurer Reference:** 

Repairer Reference: GBH1712G-OD CHINA Date calculated: 12/12/2019 4:35 PM

Full Report Registration: GBH1712G Printed: 12/12/2019 4:40 PM

## **Summary Information**

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

SNG AH TEE

Currency:

SGD

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Date of Incident: Hire Car Start:

09/12/19

Hire Car End:

## Vehicle Details

Vehicle

Manufacturer:

TOYOTA DYNA

Model:

Sub Model:

BASE MODEL

Model Sheet Number:

70 1C 01

Registration:

GBH1712G

VIN number: Odometer:

**Model Specs** AIR CONDITIONING

**PLATFORM** 

WHEELBASE 2525MM

STANDARD CAB

TWO COAT METALLIC

PREPARE OFF VEHICLE

## **Vehicle Condition**


### Vehicle Status

Pre-Accident Damage: Date of Inspection:

### **Damage Areas**

All

Underbody



### Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Audatex System Using Manufacturer Times

Page 1 of 4

PRINT DATE 12/12/2019

Code	Description		wu	Price SGD
520011	RENEW FRONT BUMPER		10.0	42.00
	INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS			
751011	R + R RADIATOR GRILLE		3.0	12.60
810051)	R + R R/HEADLAMP		1.0	4.20
810031)	(RADIATOR GRILLE REMOVED)		1.0	4.20
	DOES NOT INCLUDE: ADJUST HEADLAMP			
810151A	ADJUST HEADLAMPS		3.0	12.60
670051	RENEW R/F DOOR		14.0	58.80
	INCLUDES: R + R DOOR,			
	CONVERT ALL ATTACHED PARTS,			
	ADJUST DOOR			
752051	R + R R/DOOR MIRROR CPL		5.0	21.00
	INCLUDES: R/END MOULDING			
	REMOVE AND REFIT.			
670201)	R + R R/F DOOR HINGE/S		1.0	4.20
NN	R/F STEP R&R / NEW PARTS		90.0*	378.00
0413	ENGINE FIREWALL REPAIR		15.0*	63.00
0912	R/OUTER A-PILLAR REPAIR		20.0*	84.00
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	16.20	162.0	680.40
	Total of Labour			680.40

a		

Paint Work		Time Basis	10 WU/h
Code	Description - TWO COAT METALLIC	wu	Price SGD
LE 0281	FRONT BUMPER NEW PART PAINT ST 1	12.0	50.40
LE 0888	R/END MOULDING NEW PART PAINT ST 1	6.0	25.20
LE 1482	RIGHT FRONT DOOR NEW PART PAINT ST 1	16.0	67.20
LE 2206	R/F STEP NEW PART PAINT ST 1	6.0	25.20
LS 0413	ENGINE FIREWALL REPAIR PAINT ST IV	23.0	96.60
LS 0912	R/OUTER A-PILLAR REPAIR PAINT ST IV	15.0	63.00
L 0418	OUTER ENG FIREWALL SURFACE PAINT ST 2	5.0	21.00
NO NUMBER	PREPARE FOR PAINTING	21.0	88.20
NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	5.0	21.00

# **Spare Parts**

opare i ai				
Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
	82		5,(3)	
0281	FRONT BUMPER	52111 37301 🚜		230.00
0410	GRILLE	53111 37891 <b>S</b> (		200.00
0562	RIGHT HEADLAMP ASSY	81110 37120	0	320.00
0608	R/HEADLAMP TRIM	81193 37050 ?	- 4	30.00
0678	R/F INDICATOR CPL	81610 37200 6	0/	120.00
0888	R/END MOULDING	53813 37100A0	3 %	85.00

Code	Description	Part Number , Supplier	Price SGD
1482	RIGHT FRONT DOOR	67001 37292 H	560.00
1488 "	R/F UPPER DOOR HING		35.00
1496	R/F LOWER DOOR	69730 37010	35.00
1450	HINGE	68/30 3/010 7	33.00
1510	R/DOOR SEAL	67861 37021 Nu	25.00
1578	R/INN DOOR LOCK	69310 37070 💢	120.00
2206	R/F STEP	51771 37211	90.00
2200	NISIEF	517/1 3/211	90.00
f: OEM Parts	Savings		0.00
n: Non-OEM Parts			1,850.00
u: Used parts	Fixed Sundry Parts	s Price	100.00
	Total		
	Total		1,950.00
Extras			
Code	Description		Price SGD
1000	IO CHECK WILLING		30.00*
1001	FRT DOOR ROC STICKER	ne /	20.00*
1002	FRT CORNER PANEL BRAC	KET RH 1	40.00*
	Total Extras		90.00
	1	1 Carlo	
E!! G ! !		Imis. /	
Final Calcula	ation	1 V1 Q	
		SGD SGD	SGD
Parts	*	#p 900 (00 68 1,850.00 100.00 5 days	
Fixed Sundry	Parts Price	100.00	
Total Parts	90093235 N. STRT	- O	1,950.00
		5 days	-,-30.30
abour Time	Base 10 WU/h	, ,	
	WU X 42.00 SGD/h	P P 680.40	
Total of Labour		11/	680.40
		Excess: 450	
Total Of Extras	i	A., O.,	90.00
		0	
Paint Work Ti	me Base 10 WU/h	Revert	
	109.0 WU X 42.00 SGD/h	457.80	2001.024/96/2010/04/96
Total Paint Inc	luding Material	a later wint	457.80
	-11 CCT	hosway school	1200-20-20-2
Repair Cost Ex		11 0:-	3,178.20
GST (+7.0%)		13/12/19 (0) 1520	222.47
cepuii cost Illi	ciadea do i	Ti Comment	3,400.67
Repair Cost Ind		Resurvey Seture paint 13/12/19@1520	
Comments	VED DATA	1900	
- USER SUPPLI		LKK Auto Consultants hence notify	1
	ACTURERS CODE EXISTS	the Repairer of the following:	
- WU PARTIAL	INCL IN OTHER POSITIONS		
		To display damaged part(s) during resurvey     Parts prices are subject.	
Assessment	Note	Parts prices are subject to confirmation     Third process.	
		No illegal modification(s) is allowed     Suppose that the state of the state	
		is subject to final approval from Insurance Company	
udatex System	Using Manufacturer Times	Page 3 of 4 by Repairer PRINT DATE	E 12/12/2019
50		Signature Signature	,,,,
		Signature:	

Signature:

