

22/03/2002

ASS. REC. BY:

REF: CS/C7119021988/Ey13

Special Instruction:

Surveyor: STRVL

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of C11 Date/Time: 13.12.19 14.11p.m

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 9777R Insured: GBD 2608P

at Workshop m/s Car City Auto Tel: 67810300 / 96214666

of BIK 9006 #01-198 Tampine Street 93

Policy No: DMKVS1 305929 17022 Claim No: SVM19 17 20592102

Sum Insured: Excess:

Make of Veh: D.O.A. 10.12.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 13.12.19 2.11pm

Person Contacted: Mr HO

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 2608P: X
	SJN 9777R: X

Survivor

Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured.

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh. had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJN 9777 R

Yr Regn:

29/12/05

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

Toyota Camry

c.c.

1998

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

134480

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRO53 BK 4107038092

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size:

F:

215/60R 16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

10/12/19

D.O.I.

13/12/19

Survey held at

Car City Auto

Dos. of Damages (Fr) / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 25,000

PV- 12,748

NV- 12,252

18/12 Pending Price -

29/5 Submit \$2354-47 (Red \$2277-40, 49%)

Date/Time, File Pass to?



: Procl. Report

1)



: Final Report

Date/Time, File Return to?

2)

5/6/20 Typist

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ + RS. SI

) P/B

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Insp (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2019		13 Dec 2019 14:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:			[Created by insurer]						
Main Claimant:		SHERRIE SUN YANGGENG, ID: S7983558G							
Vehicle Reg. No.:		SJN9777R	Date of Loss:	10/12/2019 23:00 - :59					
Claim Type:		TP / SNM19D205921C02	Policy/Cover Note No.:	DMCVSN30597919022					
Vehicle Reg. No. (Insured):		GBD2608P	Policy No. (Claimant):	GA431587					
		Excess:	S\$500.00						
Repairer:		Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/12/2019]							
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.			View All	Compose Case Mail					
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
						Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 13 December 2019 2:08 PM
To: ccacpl@singnet.com.sg; assignments
Subject: RE: OUR REF: SNM19D205921/GBD2608P/TKL - NOTICE OF ACCIDENT: 3RD PARTY CLAIM SJN9777R AGAINST YOUR INSURED GBD2608P's policy.

WITHOUT PREJUDICE

Dear Mr Ho,

We refer to your email dated 13.12.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: ccacpl@singnet.com.sg [mailto:ccacpl@singnet.com.sg]
Sent: Friday, December 13, 2019 1:29 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205921/GBD2608P/TKL - NOTICE OF ACCIDENT: 3RD PARTY CLAIM SJN9777R AGAINST YOUR INSURED GBD2608P's policy.

Dear Mr Tan,

We select No 9 Mr Marcus Chua.

Please help to check is this a Direct Settlement with liability in favour of our customer.

Regards,

Ho Too Boon
CAR CITY AUTO CENTRE PTE LTD
TEL: 67810300 FAX: 67820300

EMAIL:: ccacpl@singnet.com.sg

On Fri Dec 13 2019 11:58:08 GMT+0800 (Singapore Standard Time) Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

----- Original Message -----

Without Prejudice

Dear Mr Ho,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From:

Claims Dept of CTI

Sent: Friday, December 13, 2019 11:28 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow

<sochow.chee@sg.cntaiping.com>; ccacpl@singnet.com.sg

Subject: OUR REF: SNM19D205921/GBD2608P/TKL - NOTICE OF ACCIDENT: 3RD PARTY CLAIM SJN9777R AGAINST YOUR INSURED GBD2608P's policy.

Dear Kah Leong,

Please conduct PRS for SJN9777R.

Note: officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From:

ccacpl@singnet.com.sg [mailto:ccacpl@singnet.com.sg]

Sent: Thursday, 12 December, 2019 5:29 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: NOTICE OF ACCIDENT: 3RD PARTY CLAIM SJN9777R AGAINST YOUR INSURED GBD2608P's policy.

Dear Sir,

Attached is our customer, SJN9777R 's SAS report doing a 3rd party claim against your insured GBD2608P's policy.

We are in the midst of preparing the repair estimate.

For your info.

Regards,

Ho Too Boon

CAR CITY AUTO CENTRE PTE LTD

TEL: 67810300 FAX: 67820300

EMAIL: ccacpl@singnet.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2019 14:48
Date Of Accident	10/12/2019 23:40
Exact Location Of Accident	ANG MO KIO CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN9777R
Insured/Policyholder	
Name Of Registered Owner	SHERRIE SUN YANGGENG
NRIC No	S7983558G
Email Address	JHINGSUN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90888191
Alternative Phone No	OFFICE-90888191

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA431587
Cover Note Number	21/12/2019-30/12/2020

Driver

Name of Driver	ANG JHING SUN
Passport No/FIN	G2915154M
Date Of Birth	09/01/1987
Occupation	INDOOR
Date Of Driving Pass	22/08/2017
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	+65-82182772
Fax Number	
Contact Number	
EMail Address	JHINGSUN@GMAIL.COM

Address	88 BEDOK TERRACE
Postcode	469247
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD2608P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	MS EVE 66591600
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is ~~not~~ the policyholder)
Date & Time:


17/10/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LA 00000000000000000000

Sketch Plan Pg. 2

SKETCH PLAN



(A) - SJN 9777R
(B) - GBD2608P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was park stationary in the parking lot and after work I noticed was damaged and found a note on my windscreen and I called the owner of GBD2608P and admitted that his vehicle did hit my car.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
Claim OD
Claim TP
<input checked="" type="checkbox"/> Claim OD (TP) at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/10/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 558G

Vehicle Details

Vehicle No.: SJN9777R
Vehicle to be Exported: Yes
Intended Deregistration Date: 14 Dec 2019
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour: Silver
Manufacturing Year: 2008
Engine No.: 1AZE121988
Chassis No.: MR053BK4107038092
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$25,403.00
Original Registration Date: 29 Dec 2008
First Registration Date: 29 Dec 2008
Transfer Count: 3
Actual ARF Paid: \$25,403.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2023
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$15,777.00
COE Rebate Amount: \$12,740.00
Total Rebate Amount: \$12,740.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Dec 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	558G
Vehicle Details	
Vehicle No.:	SJN9777R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1AZE121988
Chassis No.:	MR053BK4107038092
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$25,403.00
Original Registration Date:	29 Dec 2008
First Registration Date:	29 Dec 2008
Transfer Count:	3
Actual ARF Paid:	\$25,403.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$15,777.00
COE Rebate Amount:	\$12,748.00
Total Rebate Amount:	\$12,748.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Dec 2019

OK

Car City Auto Centre Pte Ltd
#01-198, Blk 9006 Tampines Street
93, *Has*
528840

Insurer Reference:
Repairer Reference: TP/19051
Date calculated: 13/12/2019 3:04 PM

Full Report
Registration: SJN9777R
Printed: 13/12/2019 3:05 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	HO TOO BOON	Currency:	SGD
Claim Reference:		Date of Incident:	10/12/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	CAMRY/AURION
Sub Model:	BASE MODEL
Model Sheet Number:	70 CA 01
Registration:	SJN9777R
VIN number:	MR053BK4107038092
Odometer:	134480
Model Specs	
2.0 LTR 108 KW	4-SPEED AUTOMATIC MALAYSIA VERSION

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Steve (LKK)
8322 8813

WHL M/L
6 days
L/S

Ry AL Sy

13/12/19, 3:30pm

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B100	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0		16.80
B140	RENEW FRONT PANEL	22.0		92.40
NO NUMBER	RENEW RIGHT FRONT SIDE MEMBER CLOSING	15.0		63.00
B110	RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)	5.0		21.00
B100	R + R LEFT SILL RAIL	3.0		12.60
B100	R + R RIGHT SILL RAIL	3.0		12.60
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	15.0		63.00
B040)	RENEW R/HEADLAMP (REMOVED)	2.0		8.40
B040	R + R HEADLAMPS (BUMPER REMOVED)	4.0		16.80
B070	RENEW BONNET	6.0		25.20
B080	R + R BONNET HINGES	1.0		4.20
530121)	R + R BONNET OPENER CABLE	2.0		8.40
851091)	R + R WASHER RESERVOIR	4.0		16.80
851061	R + R WASHER NOZZLES	2.0		8.40
M010)	RENEW CONDENSER (REMOVED)	1.0		4.20
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED) INCLUDES: BLEED COOLING SYSTEM	16.0		67.20
M010)	RENEW RADIATOR	3.0		12.60
NO NUMBER	R + R ENGINE COVER	1.0		4.20
1437	WASHER PUMP CHECK			
1006	alignment ALIGNMENT			60.00* X
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		10.90	109.0	457.80
Alignment				
Fixed Rate				60.00
Total of Labour				517.80

Paint

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description			WU	Price SGD
	BONNET NEW PART PAINTING			24.0	
	R/F WING NEW PART PAINTING			10.0	
	LOCK CARRIER STRUT SURFACE PAINT			4.0	
	FRONT PANEL SURFACE PAINT			6.0	
	R/SIDE MEMBER EXT SURFACE PAINT			4.0	
	FRONT BUMPER NEW PART PAINT K1R			11.0	
	L/F WING REPAIR PAINTING >50%			16.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	68.51

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	16.12
0988	LOCK CARRIER STRUT SURFACE PAINT	0.88
1009	FRONT PANEL SURFACE PAINT	11.97
1206	R/SIDE MEMBER EXT SURFACE PAINT	0.53
0283	FRONT BUMPER NEW PART PAINT K1R	47.12
0741	L/F WING REPAIR PAINTING >50%	12.84

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		75.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	95.0	399.00

Material Cost - Paint

	Price SGD
New Part Painting	84.63
New Part Painting - Plastic K1R	47.12
Repair Painting	12.84
Surface-/Blend Paint	13.38
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	185.07

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	52119 06922	BR	230.00
0318	R/F UPP BUMPER BRKT	52535 06080	BR	30.00
0340	BUMPER SUPPORT	52021 06060	NH	120.00
0344	FRT BUMPER ABSORBER	52611 06110	NH	40.00
0412	CTR BUMPER GRILLE	53112 06070	NH	55.00
0471	BONNET	53301 06110	DD	320.00
0475	L/BONNET HINGE	53420 06130	NH	30.00
0476	R/BONNET HINGE	53410 06130	NH	30.00
0493	LOWER BONNET LOCK	53510 06101	NH	40.00
0497	L/BONNET DAMPER	53450 0W090	NH	65.00
0498	R/BONNET DAMPER	53440 0W110	NH	65.00
0562	RIGHT HEADLAMP ASSY	81110 06271	BR	250.00
0639	L/F BUMPER MOULDING	52713 06010	MC	35.00
0640	R/F BUMPER MOULDING	52712 06010	CUT	35.00
0742	R/F WING	53801 06130	DD	175.00
0768	R/WING MOULDING	53825 06040	TH NH	45.00
0842	R/WHEELHOUSE SHELL	53875 06080	TH TN	65.00
0988	LOCK CARRIER STRUT	53208 06040	NH	35.00
1009	FRONT PANEL	53201 06171	R	350.00
1170	R/RADIATOR AIR GUIDE	53293 06060	NH	40.00
1206	R/SIDE MEMBER EXT	57107 06061	NH	65.00
1436	WASHER CONTAINER	85315 06160	NH	60.00
3012	BADGE "VVT-I" R	75443 06540	MC	15.00

Code	Description	Part Number	Supplier	Price SGD
4465	CONDENSER	88460 06170 X	NN/	400.00
7761	RADIATOR	16400 0H250 X	NN/	480.00
1007	RH FOG LAMP	FOG LAM X	NN/	80.00
1008	RH FOG LAMP COVER	FOG LAMP COVER X	NN/	55.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	3,210.00
u: Used parts	Total	3,210.00

Extras

Code	Description	Price SGD
1000	SUNDRY PARTS SUNDRY PARTS <i>11c</i>	<i>30 /</i> 100.00*
1001	CHECK WIRING CHECKING WIRING <i>11c</i>	25.00*
1002	ANTI-FREEZE ANTI-FREEZE	20.00* X
1003	AIR-CON GAS AIR-CON GAS	50.00* X
1004	SUNDRY PARTS SUNDRY PARTS	100.00* X
1005	CHECK WIRING CHECKING WIRING	25.00* X
Total Extras		320.00

Final Calculation

	SGD	SGD
Parts	3,210.00	
Total Parts		3,210.00
Labour Time Base 10 WU/h		
Total 109.0 WU X 42.00 SGD/h	457.80	
Alignment		
Fixed Rate	60.00	
Total of Labour		517.80
Total Of Extras		320.00
Paint Work Time Base 10 WU/h		
Labour Cost 95.0 WU X 42.00 SGD/h	399.00	
Material Cost	185.07	
Total Paint Including Material		584.07
Repair Cost Excludes GST		4,631.87
GST (+7.0%)		324.23
Repair Cost Included GST		4,956.10

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.