

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.12.2019

Time: 12:37:45

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305366323
 REGN NO : SHA1161L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 26.05.2016
 DATE/TIME IN : 11.12.2019 11:30
 ACCIDENT DATE : 07.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40	? - def.	
0002	04-01-0103-0740-G	I40VC BEAM-RR BUMPER#	1	428.40	20.00	342.72	? x svc	
0003	04-01-0103-0743-G	I40VC STAY-RR BUMPER RH	1	80.30	20.00	64.24	? x svc	
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	? x svc	\$ 553.00
0005	04-01-0103-0575-G	I40V2 PANEL ASSY-QUARTER	1	2,171.40	20.00	1,737.12	X R	20%
0006	04-01-0103-0745-G	I40VC MOULDING-RR WDO GLA	1	28.30	20.00	22.64	X NN	\$ 442.40
0007	05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2 N	46.00	2.00-	46.00	X NN	
0008	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	? x svc	
0009	04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1	30.60	20.00	24.48	? x svc	

SUB-TOTAL : 2,879.60

JOB NATURE

0000	PB	PANEL BEATING	800.00	560
0001	SP	SPRAYPAINT CHARGE	500.00	400

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305366323
 REGN NO : SHA1161L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 26.05.2016
 DATE/TIME IN : 11.12.2019 11:30
 ACCIDENT DATE : 07.12.2019

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01 CHECK ALL LIGHTING	50.00	XNN			
0003 20-00 TUFF COAT ON AFFECTED PARTS.	50.00	40			
0004 20-204 REMOVE/REFIX UPHOLSTERY ASST REPAIR	120.00	XNN			
0005 L REMOVE/REFIX RR WINDSCREEN GLASS	120.00	XNN			1,200.00
0006 20-05 RENEW ADVERTISEMENT STICKER-	200.00	NEL			
					SUB-TOTAL : 1,840.00
					1200
					TOTAL : 4,719.60

MVA NAME & SIGNATURE

DATE :

[Signature]
 19/12/19
 NAZ LKK

13/12/19 1545

LIS

3 days

CHECK ITEMS PHOTOS

AFTER REPAIR PHOTOS

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE

DATE :

\$1,642.40
 less 20%

\$1,313.92

Hq \$1,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305366323

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO.: SHA1161L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 11.12.2019 11:30
YR OF MANU. 26.05.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU089934	COMPLETION DATE/TIME:

DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 07.12.2019
NATURE: 3P 07.12.19

S/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vo.: SHA1161L JU AIG

Vehicle No.: SHA1161L

Service Advisor Signature/Date Name of Service Advisor Date

turned to Service Reception upon collection To be kept by Security Guard