

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.12.2019

REPAIR ESTIMATE

Time: 12:37:45

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305366323
 REGN NO : SHA1161L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 26.05.2016
 DATE/TIME IN : 11.12.2019 11:30
 ACCIDENT DATE : 07.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40	?	- dif.
0002	04-01-0103-0740-G	I40VC BEAM-RR BUMPER#	1	428.40	20.00	342.72	?	sub
0003	04-01-0103-0743-G	I40VC STAY-RR BUMPER RH	1	80.30	20.00	64.24	?	sub
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	?	x sub
0005	04-01-0103-0575-G	I40V2 PANEL ASSY-QUARTER	1	2,171.40	20.00	1,737.12	X	R
0006	04-01-0103-0745-G	I40VC MOULDING-RR WDO GLA	1	28.30	20.00	22.64	X	NN
0007	05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2 N	46.00	2.00-	46.00	X	NN
0008	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	?	x sub
0009	04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1	30.60	20.00	24.48	?	x sub

SUB-TOTAL : 2,879.60

JOB NATURE

0000	PB	PANEL BEATING	800.00	560
0001	SP	SPRAYPAINT CHARGE	500.00	400

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.12.2019

REPAIR ESTIMATE

Time: 12:37:45

Page: 2


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305366323
REGN NO : SHA1161L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 26.05.2016
DATE/TIME IN : 11.12.2019 11:30
ACCIDENT DATE : 07.12.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01	CHECK ALL LIGHTING	50.00	XNN			
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	40			
0004 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	120.00	XNN			
0005 L	REMOVE/REFIX RR WINDSCREEN GLASS	120.00	XNN			
0006 20-05	RENEW ADVERTISMENT STICKER-	200.00	NEL			
SUB-TOTAL						: 1,840.00
TOTAL						: 4,719.60

MVA NAME & SIGNATURE

DATE :


19/12/19
NAZUKK

13/12/19 1545

LIS

3 days

CHECK ITEMS PHOTOS

AFTER REPAIR PHOTOS

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :