WITHOUT PREJUDICE

Our Re	f:	T 1219/ SHA1161L /KS(st)
Your R	ef:	
Date	:	15-Jan-2020



AIG ASIA PACIFIC	INSURANCE PTE LTD
AIG Building	

CDGE Taxi Claims Dept ComfortDelGro Engineering Pte Ltd 59 Loyang Drive 4th Floor 205 Braddell Road Singapore 579701

Singapore 508969

Mainline +65 6383 6280 Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Singapore 079120

78 Shenton Way

#07-16

Workshops

Attn: Motor Claims Department

Braddell 205 Braddell Road Singapore 579701

Dear Sir

Loyang

ACCIDENT INVOLVING OUR TAXI SHA1161L YOUR INSURED SMQ7159L ON 07.12.19 AND OTHER

59 Loyang Drive Singapore 508969 Sin Ming 383 Sin Ming Drive

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No SHA1161L which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

Pandan 45 Pandan Road Singapore 609286

Singapore 575717

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

As the accident was caused by the negligent act of your insured driving **SMQ7159L** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

IAA	OWNERS CERTIFI	•	4 444 50
1	Cost of Repair	\$	1,444.50
2	7 days Loss of Rental @ \$ 116.95 per day	\$	818.65
3	Survey Report Fees (Surveyed by M/s LKK)	\$	
4	GIA / LTA Search Fees	\$	7.49
5	GIA / Police Report Fees	\$	-
6	Towing Fee	\$	-
		\$	2,270.64
HIRE	CR'S CLAIM	100	
7	7 days Loss of Income @ \$ 80.00 per days	\$	560.00
	Total Claims :	\$	2,830.64

We enclose herewith the following documents to support the claims: -

Original repair bill: a)

LTA search slip/s of: b)

SMQ7159L

GIA / Police report/s of : c)

SHA1161L

Letter of authority from owner / hirer / operator d)

) Photograph/s of Accident Scene

() Certificate of Insurance

) Witness statement/s

(x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel: 6214 8736 Fax: 6214 1843 Email: kazali@cdge.com.sg

This is a computer generated letter. No signature is required.



LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

Hyundai Ioniq SHD4463E , FBH3671C

ON 10-Dec-19 14:15

ALONG

OUTSIDE BLK 771 PASIR RIS ST 71

I / We

MAH KOK TONG

(Hirer) NRIC No.:

SXXXX043H

and/or

(Relief) NRIC No.: SXXXX043H

Taxi Number

SHD4463E

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

10-Dec-2019

Name of Hirer

MAH KOK TONG

Hirer NRIC

SXXXX043H

Signature:

Address

425 PASIR RIS DRIVE 6 #10-89

510425

Contact No.

93831489



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

801.0004

SINGAPORE

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

(COMPANY RKG, NO.: 199506048W

Page: 1

VEHCLE NO SHA11611.

NO/DATK 91488525 09.01.2020

MAKE HYUNDAL JOB NO. 305366323

MODEL.

OIXMETER READING

DATE OF REG 26.05.2016

JOB TYPE CHASSIS CODE KMHT.B41UMGU089934

Description: 3P 07.12.19

CONTACT NO: 64193000

Invoice for Lump Sum Repair

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY.AIG BUILDING #07-16 SINGAPORE 079120

Total Lump Sum Repair Amt.
Add GST 0 7.000 % 1,350.00

Total Invoice amount

1,444.50

KATHERINETAN 09.01.2020 08:09:21

3225094

Repair Type : CLSO/57/57 Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT**

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT19120217

Date: 08 January 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

07/12/2019 @ 23:50 hrs

ALONG

SENGKANG EAST AVE

INVOLVING SMQ7159L

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA1161L (the "Taxi"). The Taxi was hired to SEE EE KOK IC NO SXXXX180A a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$116.95 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	ALC:	W IIKI						
DATE	NAME OF DRIVER	MI FACE BEADING	MILEAGE	HOURS OPERATED (TIM	SATED (TIM	F + 4 C		Y
7180		מוורבאמב אבאסוואמ	(KM)	FROM	TO	DAIE	NAME OF DRIVER	MILEA
9/11/19	See Ex KSh	382001	77	0290	0000			
6) /(1) 01	- // -	382324	343	orar	mn			
11 112/19	- 11 · ·	9 th W XZ	12.5	01/40	1118			
11-17-19	Account	ma	3	128	(,			
19-0-1	Depar	2		(360				
	-						4	

Enquire Vehicle Insurance Details

Vehicle No. Incident Date/Time

Search Status Insurance Company Code

Insurance Company Name

SMQ7159L 07 Dec 2019 / 23:50:00

Successful

A04

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

5401161L

OK