

ASS. REC. BY:

REF: CS/CTI 19022022/ Fvd3

72

Special Instruction:

Assigner: Steve

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 13/12/19 @ 2:47pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT9909G

Insured:

GU36214

at Workshop m/s

Performance Motor

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

SNM19D205822

Sum Insured:

Excess:

Make of Veh:

D.O.A. 5/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:30pm 13/12/19

Person Contacted:

Carline

Vehicle IN (OUT)

Date/Time

Action/Instruction

Estimated

SGT9909G - X

GU 36214 - X

ASS. REC. BY:

Steve

REF:

C91

ASSIGNMENT

From:

Date:

12/12/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGT 9909G

at Workshop m/s

of

Performance.
303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

low - 12pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGT 9909G

Yr Regn:

31/5/18

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 318i

c.c

1499

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

37911

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WB A 8E36070 NU 82124

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/40R18

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

5/12/19

D.O.I.

17/12/19

Survey held at

Performance

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/1/20

MV- 124K

Finalize \$4751.15, 3 days (Sharon) (Red 742.35, 14/1)

7/1/2020

RECEIVED 08 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

ij

Final Report

Date/Time, File Return to?

2/8/11 -typist

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Inv. (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS: SI

Plains

Others

TOTAL

220

Report Format:

merimen

Lump Sum / L.B. (\$

4751.15

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 13 December 2019 2:47 PM
To: PBSP
Cc: 'assignments'
Subject: RE: OUR REF: SNM19D205822/GU3621U/CBS - REQ FOR DIRECT SETTLEMENT - SGT9909G & GU3621U ON 05.12.2019

Dear LKK,

Fyi.

Kindly assist to advise on claimant details for me to merimen.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Friday, December 13, 2019 2:46 PM

To: 'PBSP' <pml-pbsp@simedarby.com.sg>

Subject: RE: OUR REF: SNM19D205822/GU3621U/CBS - REQ FOR DIRECT SETTLEMENT - SGT9909G & GU3621U ON 05.12.2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Meanwhile, we direct settle subject to surveyor consistencies

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Friday, December 13, 2019 11:56 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205822/GU3621U/CBS - REQ FOR DIRECT SETTLEMENT - SGT9909G & GU3621U ON 05.12.2019

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Wednesday, 11 December 2019 4:52 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205822/GU3621U/CBS - REQ FOR DIRECT SETTLEMENT - SGT9909G & GU3621U ON 05.12.2019

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Monday, 9 December 2019 11:44 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; PBSP <pml-pbsp@simedarby.com.sg>

Subject: OUR REF: SNM19D205822/GU3621U/CBS - REQ FOR DIRECT SETTLEMENT - SGT9909G & GU3621U ON 05.12.2019

[External Mail] This email originated from outside of the organisation; be careful with requests, attachments and links.

Dear Boon Sen,

Please conduct PRS for SGT9909G.

Note: officer in charge – Boon Sen 63896171.

***** Kindly quote our reference number when replying.**

Regards,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Saturday, 7 December, 2019 10:52 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: REQ FOR DIRECT SETTLEMENT - SGT9909G & GU3621U ON 05.12.2019

Dear Sirs,

We refer to the above matter. Please copy the dropbox link below and paste it onto a new browser to view the video evidence.

https://www.dropbox.com/s/26243cohgpxsxd4/EVT_20191205_114816_2.avi?dl=0



EVT_20191205_114816_2.avi

Shared with Dropbox

www.dropbox.com

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or

proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: Steve Chen (LKK Auto)
Sent: Monday, 6 January 2020 7:42 PM
To: Sharon Heng L K
Cc: Veron Chen (LKKAUTO)
Subject: DIRECT SETTLEMENT FINAL REPORT - SGT9909G - YOUR REF : SNM19D205822

Dear Sharon,

We confirm the finalize \$4,751.15 (P/P, before GST). 3 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K [mailto:sharon.heng.leekun@simedarby.com.sg]
Sent: Friday, January 03, 2020 6:53 PM
To: Steve Chen (LKK Auto)
Cc: Veron Chen (LKKAUTO)
Subject: DIRECT SETTLEMENT FINAL REPORT - SGT9909G - YOUR REF : SNM19D205822

Dear Steve

For your perusal :

Labor	\$2164.00
Parts	\$2587.15
Total	\$4751.15

Owner is claiming CAR RENTAL - \$300.00(3 DAYS).
 GIA SEARCH FEE - \$2.00.

Note : Please seek MANDATE from your Principle ASAP.

Note : 3 working days.

• Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123
Fax : 64743229

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]
Sent: Friday, 3 January, 2020 4:50 PM
To: Sharon Heng L K
Subject: Message from KM_C458

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	334E
Vehicle Details	
Vehicle No.:	SGT9909G
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	318I LED NAV SHAD. LIGHT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	F2611835B38B15A
Chassis No.:	WBA8E36070NU82124
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,502.00
Original Registration Date:	31 May 2018
First Registration Date:	31 May 2018
Transfer Count:	0
Actual ARF Paid:	\$40,303.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2028
PARF Rebate Amount:	\$30,227.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,989.00
COE Rebate Amount:	\$32,106.00
Total Rebate Amount:	\$62,333.00

The information contained herein is correct as at 17 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2019 11:35
Date Of Accident	05/12/2019 17:50
Exact Location Of Accident	ALG GAMBAS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT9909G
Insured/Policyholder	
Name Of Registered Owner	XU WEI
NRIC No	S2661334E
Email Address	XU.WEI@SEAGATE.COM
Mobile Phone No	(LOCAL) +65-96610788
Alternative Phone No	OFFICE-96610788

Vehicle Particulars

Manufacturer	BMW
Model	318I LED NAV SHAD. LIGHT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10919333
Cover Note Number	

Driver

Name of Driver	XU WEI
NRIC No	S2661334E
Date Of Birth	21/03/1965
Occupation	INDOOR
Date Of Driving Pass	03/03/2005
Driving Experience	14 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96610788
Fax Number	
Contact Number	OFFICE-96610788
Email Address	XU.WEI@SEAGATE.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My vehicle was already stopped due to red light (pedestrian crossing). While waiting, suddenly I felt an impact from behind and saw a vehicle had already hit onto my rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UPLOADED INTO AVIVA FILE ZILLA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU3621U
Vehicle Make/Model/Colour	DAIHATSU / S221RV-ZMLF
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	EE YONG YEOW
NRIC/Passport Number	
Contact Number	S71016911
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A: SGT 9909G

B: GU 3621U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Sketch Plan #3

ACCIDENT STATEMENT (2000 characters)

My vehicle was already stopped due to red light (pedestrian crossing). While waiting, suddenly I felt an impact from behind and saw a vehicle had already hit onto my rear portion.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

6 December 2019 at 10:00 AM

Date/Time:

6 December 2019 at 10:00 AM

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



Survey & repair
17/12 210am
* survey before 12pm

GST REG. NO : M2 - 0020081 - X

07 DEC 2019

ESTIMATE

Estimate No. : b1 53703
Date Estimated : 07/12/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Xu Wei
Blk 50 Bayshore Road
#17-07

Singapore 469977

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT9909G	WBA8E36070NU82124	31/05/2018	318i	0

DESCRIPTION

To replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

Sundries.

VALUE

1,275.00

1,038.00

177.00

177.00

80.00

Total Labour 1: 2,747.00

DESCRIPTION

TAILPIPE TIP BLACK CHROME x NAI
RR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CARRIER (ECE)
INSERT FOR BUMPER REAR (M)
REAR BUMPER PANEL PRIMED (M)
SET MOUNTS PDC SENSOR RR (M)
REAR LH REFLECTOR (M)
REAR RH REFLECTOR (M)
DECOUPLING RING PDC TORQUE CONVERTE
ULTRASONIC SENSOR WC10 MEDITERRANEA
(DG/SL) ADHESIVE SET K6

QTY	PRIC	VALUE
1	121.60	121.60
1	72.65	72.65
1	470.25	470.25
1	147.40	147.40
1	1,326.20	1,326.20
1	67.30	67.30
1	37.75	37.75
1	37.75	37.75
4	5.10	20.40
1	370.00	370.00
1	53.05	53.05

Total Parts : 2,724.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53703
Date Estimated : 07/12/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT9909G	WBA8E36070NU82124	31/05/2018	318i	0

[Signature]
19/12/19

Steve (LKK) W/L Ajul 17/12/19, 10:15am
3 days
P/P
By B&L SJ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5493.50

Labour 1	:	2,747.00
Parts	:	2,724.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	382.99
Grand Total	:	5,854.34

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sino Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53703**
Date Estimated : **07/12/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Xu Wei
Blk 50 Bayshore Road
#17-07

Singapore 469977

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT9909G	WBA8E36070NU8212	31/05/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER (ECE)	470.25	1.00	0	470.25
INSERT FOR BUMPER REAR (M)	147.40	1.00	0	147.40
RR BUMPER BOTTOM REINFORCEMENT (M)	88.15	1.00	0	88.15
REAR BUMPER PANEL PRIMED (M)	1,326.20	1.00	0	1,326.20
SET MOUNTS PDC SENSOR RR (M)	67.30	1.00	0	67.30
# PLUG BLACK D=5MM <i>nrc</i>	0.95	7.00	0	6.65
REAR LH REFLECTOR (M)	37.75	1.00	0	37.75
DECOUPLING RING PDC TORQUE CONVERTE	5.10	1.00	0	5.10
DECOUPLING RING PDC TORQUE CONVERTE	5.10	3.00	0	15.30
ULTRASONIC SENSOR WC10 MEDITERRANEA	370.00	1.00	0	370.00
(DG/SL) ADHESIVE SET K6	53.05	1.00	0	53.05

SUPPLEMENTARY ITEMS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Total Labour :	2,164.00 /
Total Parts :	2,587.15 /
Total Labour & Parts :	4,751.15 /
GST @7%:	332.58
Grand Total :	<u>5,083.73</u>

DATE	NAME	AMOUNT	REMARKS
31/1/20	steve LKH	3	

CAR RENTAL = \$300.00 (3 DAYS)
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559N, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53703**
Date Estimated : **07/12/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Xu Wei
Blk 50 Bayshore Road
#17-07

Singapore 469977

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT9909G	WBA8E36070NU8212	31/05/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLUG BLACK D=5MM / APC	0.95	7.00	0	6.65

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	6.65
Total Labour & Parts :	6.65

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022022/EVD3N2
Date: 10/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30580518000
Claimant Vehicle No: SGT9909G Insured Vehicle No: GU3621U
Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: SNM19D205822C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT9909G Engine No: F2611835B38B15A
Make & Model: BMW 318I, 1.5 (A) Chassis No: WBA8E36070NU82124
Reg. Date: 31/05/2018 (Man. Year: 2017) Odometer: 37911 km
Colour: Blue
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40R18 Rear Tyre Size: 255/40R18
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,826.50	2,667.15	159.35	5.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,493.50	4,751.15	742.35	13.51
+ GST 7.00/7.00% (S\$)	384.55	332.58	51.97	13.51
Nett Amount (S\$)	5,878.05	5,083.73	794.32	13.51

INSPECTION

Date of Assignment: 08/01/2020
Date Inspected: 17/12/2019 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2020)
Parts:	143	BMW 318i 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT9909G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILPIPE TIP BLACK CHROME	Not Necessary	121.60 FS	*- FS
2	1		*RR BUMPER BOTTOM REINFORCEMENT	Broken	88.15 FS	*88.15 FS
3	1		*REAR BUMPER CARRIER (ECE)	Dented	470.25 FS	*470.25 FS
4	1		*INSERT FOR BUMPER REAR (M)	Cut	147.40 FS	*147.40 FS
5	1		*REAR BUMPER PANEL PRIMED (M)	Dented	1,326.20 FS	*1,326.20 FS
6	1		*SET MOUNTS PDC SENSOR RR (M)	Necessary	67.30 FS	*67.30 FS
7	1		*REAR LH REFLECTOR (M)	Cracked	37.75 FS	*37.75 FS
8	1		*REAR RH REFLECTOR (M)	Not Necessary	37.75 FS	*- FS
9	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.40 FS	*20.40 FS
10	1		*ULTRASONIC SENSOR WC10 MEDITERRANEA	Shorted	370.00 FS	*370.00 FS
11	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
12	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
13	7		*PLUG BLACK D=5MM	Necessary	6.65 FS	*6.65 FS
Total Parts (S\$)					2,826.50	2,667.15

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,667.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >