

### MOTOR SURVEY ASSIGNMENT

<b>Date</b>	09-12-2019	<b>Our Ref No.</b> D19007752MFSH
<b>Accident Date</b>	06-12-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA1279G	<b>Third Party Vehicle.</b> SMM4782C
<b>Survey Location</b>	291 KAKI BUKIT AVENUE 1 SHUN LI INDUSTRIAL PARK	
<b>Contact Person.</b>	JUSTIN EE	
<b>Contact No.</b>	67458800/ 84384642	<b>Fax No.</b> 67414140
<b>Survey Type</b>	DIRECT SETTLEMENT: PLEASE VERIFY DAMAGE CONSISTENCY, DAMAGE VERY MINOR. REPAIR COST ON HIGH SIDE, WO	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

### FOR DIRECT SETTLEMENT

**Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.**

#### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	BW WORKSHOP SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JASON TEA CHEE KIAT	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.