

NATIONAL Assessment Centre Services: [ver 1 Jan'03] MMA 119164746-01

Date In: 16/12/19 09:07	Job description	Date & Time Completed	Done by
Ref No: MA/INC19022047/h4	SAS e-filing		
Veh No: SJP 5723L	E-mail (within 3hrs, AIC 2hrs)		
DDA: 14/12/19 17:00	1-Motor Claim Form	MT11076000-001	17/12/19 09:02
TP / Reporting Only	1-Motor W/O (within: OD 2hrs, TP 4hrs)		
	1-Photo Uploaded		
TP insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: () Tel: () Fax: ()

TP Particulars: Vch No: Railing INC () / Non-INC ()

Owner / Driver: () Tel: ()

Policy No: () Period: () Cover Type: ()

Confirmed by: () Date: () Time: ()

Insured/Driver Liability: () % [Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%]

Year of Registration: () Warranty: YES () / NO ()

Excess: (\$) Loading: \$1,000 () / \$2,000 ()

General Remarks:

() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repolar.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (INC to phone: 6788 6616)

1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

MMA1909373

Client's Particulars:	Invoice Preparation Checklist	Am (5)	Am (1)
Driver/Owner:	1) AR: Accident Reporting (\$30);	30.00	
Contact No:	2) DA: Damage Assessment (\$100); INC (\$10)	80.00	
Damaged Portion:	3) TP: Towing Fee \$40/\$45		
QC Checked by (Engr-In-Charge):	4) FT: Follow-Through Survey \$120		
Auditors' Comments:	5) PT: Follow-Through Survey (Resurvey) \$30		
Ref: 1	For claiming against INC Only (wef 10 Jan 2005)		
11/3/3	6) TR: Re-Inspection \$75		
	7) NI: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	ON:		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (Non INC) against INC \$20		
	9) N12: Idao Mobile \$0		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2019 09:07
Date Of Accident	14/12/2019 17:00
Exact Location Of Accident	SIMEI RD SLIP RD INTO PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP5723L
Insured/Policyholder	
Name Of Registered Owner	CHU CHERH SING
NRIC No	S1231878B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82286617
Alternative Phone No	OFFICE-82286617

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109811579
Cover Note Number	

Driver

Name of Driver	CHU CHERH SING
NRIC No	S1231878B
Date Of Birth	23/01/1957
Occupation	OUTDOOR
Date Of Driving Pass	24/12/1980
Driving Experience	38 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82286617
Fax Number	
Contact Number	OFFICE-82286617
Email Address	NOEMAIL

Address	BLK 334 UBI AVE 1 #02-801
Postcode	400334
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG UBI NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7479999 - FAX NO: 67453410
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191214/2155

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	RAILING
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PIE

Rolling

A

Lost Control

Sime: Rd

A = SJP 5723 L.

Refer to Police Report T/ 20191214 / 2155

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MMA 119164746 Vehicle Registration No: SJP 5723L
Name (as shown in NRIC) : chu cherh Sing NRIC/FIN/Passport No : 51231878B
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : 8228 6617
Email Address : _____
Date of Accident : 14/12/19 Time of Accident : 17:00
Place of Accident : Simei Rd slip Rd into PIE
Insurance Company: NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend Revert from own Damage to Reporting
Only

Policyholder / Drivers Signature
Date:

18/12/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date: 18/12/19.



**SINGAPORE
POLICE FORCE**



T/20191214/2155

1 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20191214/2155

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/12/2019 19:46	Vide Report No.: G/20191214/0165	Station Diary No.: 31
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: CHU CHERH SING			Address: APT BLK 334 UBI AVENUE 1 #02-801 SINGAPORE 400334	
ID Type / ID No.: NRIC NO / S1231878B			Contact No.: Home/Office:	Mobile: 82286617
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 62	Date of Birth: 23/01/1957	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: PRIVATE HIRE DRIVER			Driving Licence Information: Class: 3,4,5 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/12/2019 17:00	Type of Location: Slip road
Location: Along Road 1 SIMEI ROAD				
Simei Road x slip road into PIE				
Weather: Raining	Road Surface: Wet		Road Speed Limit:	
Traffic Flow:	Traffic Control:		Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJP5723L	Car	HYUNDAI	HD AVANTE 1.6 A	Silver	Slightly Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJP5723L	NTUC Income Insurance Co-Operative Limited	5109811579	23/05/2019	27/03/2020



**SINGAPORE
POLICE FORCE**



T/20191214/2155

2 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20191214/2155

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHU CHERH SING	ID No.	S1231878B
Related Vehicle	NIL	Contact No.	82286617
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

This report was lodged as instructed by Traffic Police vide G/20191214/0165:

On 14/12/2019 at about 1700hrs, I was driving along Simei Road and negotiating a left bend at a slip road heading into PIE(Tuas). It was raining and wet at that time. Out of a sudden, I felt that I lost control of the car. The car skidded, faced backwards and flipped and landed on its left side. Several members of public came to help out. I was brought out to safety, together with two of my passengers. Police and ambulance came to the scene. No one was conveyed to hospital.



**SINGAPORE
POLICE FORCE**



T/20191214/2155

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

3 of 3

Report No. T/20191214/2155

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 MUHAMMAD HAMIZAN BIN RITWAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
14/12/2019 19:46

Officer In Charge Of Case:
TP / GIT /
Sgt 3 MARIAH BINTE ZAKARIA
Contact No.: 65476433

Classification Of Case:

Authentication Stamp
NP168



Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	14/12/2019 09:04							
Vehicle No.(For Motor)	SJP5723L	Certificate Number								
Search										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5109811579		CHU CHERH SING	51231878B	GPC	drivo CLASSIC	SJP5723L	SJP5723L	23/05/2019	27/03/2020
Continue										

Claim Handling

Accident MT/1076000

Policy No.	S109811579	Vehicle No.	SJP5723L	GST Registration No.	
Certificate No.					
Policyholder Name	CHU CHERH SING	Cover Type	drive CLASSIC	Policyholder NRIC	S12318788
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)		Loading	0
Contact No.(Mobile)	82286617	Special Remark		Contact No.(Home)	
Email Address		TCA	= No Yes	eCode	No
KFK	= No Yes	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	Yes
Accident Details					
Report Date	17/12/2019 08:57	Accident Report Within 24 hrs	Yes	Accident Type	Others
Date of Accident	14/12/2019	Time of Accident hh:mm	17:00	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	SIMEI RD SLIP RD INTO PIE				
Total Excess Applicable					
Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	2,000.00	TP Standard Excess	1,500.00		
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess	0				
Total OD Excess Applicable	2000.00	Total TP Excess Applicable	1,500.00		
Benefits					
GST Registered Information					
GST Registered	No	GST Registration Date			
GST Registration No.		GST Status Verified	Yes		
Modification History					
Policyholder Mailing Address					
Address 1	BLK 334 #02-801	Address 2	UBI AVENUE 1	Address 3	SINGAPORE 400334
Address 4		Address Type	Singapore address	Post Code	400334
Unit No.		Related Policy Number	S109811579		
OI Driver Info					
Driver Name	CHU CHERH SING	Driver Type	Main Driver	Driver DOB	23/01/1957
Unnamed driver Name		Driver NRIC	S12318788	Driving Experience	38
Register Date of Driver License	24/12/1990	Driver Age	62	Contact No.(Home)	
Contact No.(Mobile)	82286617	Contact No.(Office)		Address 3	SINGAPORE 400334
Address 1	BLK 334 #02-801	Address 2	UBI AVENUE 1	Post Code	400334
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	Yes = No	Driver Vehicle No.		Driver Insurer Company	
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes = No		

Modification History

Claim 001

New

Claim Type *	OD-MD	Insured Name	CHU CHERH SING	Insured NRIC	S12318788
Contact No.(Mobile)	82286617	Contact No.(Home)	83482906	Contact No.(Office)	
Email Address	stephenchuc@gmail.com	OI Vehicle Number	SJP5723L	TP Vehicle Number	RAILIN
Claim Description	SJP5723L / RAILING ON 14 Dec 2019			Name of Preferred Workshop	0
Preferred Workshop	0	Insured Liability	Partially at Fault		
Workshop Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	Received
Date Registered				Claim Close Date	17/12/2019 08:59
Report Taken By				Date Received	17/12/2019
					OD Excess Collected by Workshop

Attachment

Accident No.	MT/1076000	Claim No.	001		
Last Doc. Received	* Yes No	Upload Date	17/12/2019 09:02		
Path *		Category *	Confidential	Urgency *	Desc
Choose File	No file chosen	Clear	Please Select	NO	Normal
Choose File	No file chosen	Clear	Please Select	NO	Normal
Choose File	No file chosen	Clear	Please Select	NO	Normal
Choose File	No file chosen	Clear	Please Select	NO	Normal
Choose File	No file chosen	Clear	Please Select	NO	Normal
Choose File	No file chosen	Clear	Please Select	NO	Normal
Message Read		Clear	Please Select	NO	Normal
Attachment List					

Attachment	Uploaded By/Date	Category		Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:02	NRIC/ Driving License	Y	Normal	NRIC/ Driving License 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:02	NRIC/ Driving License	Y	Normal	NRIC/ Driving License 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:02	SAS		Normal	SAS 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:02	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:01	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:01	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:01	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:01	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:01	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:01	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:00	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:00	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:00	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:00	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:00	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 09:00	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 08:59	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 08:59	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 08:59	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 08:59	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 08:59	Photos		Normal	Photos 2019-12-17
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 17 Dec 2019 08:59	Photos		Normal	Photos 2019-12-17

Video List

Uploads By/Date

Folder Date

File Name

Source

Display in New Window Scan and uploading

ASSIGNMENT (IDAC)

By CSO: Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motorcycle ()
 - b) Bicycle ()
 - c) Tricycle ()
- 2) Vehicle hit:
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govt Property ()
(e.g. signpost, barrier, road side)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other ()
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case:
 - a) Stolen ()
 - b) Damage found when recovered ()
- 8) Fire:
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor: 1) Vehicle Information

Veh No: **SJP 5723 L** Date: **28 Mar 2009**
 Type: **Car** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / **Truck** / Trailer or
 Make & Model: **Hyundai Avante 1.6** (159)
 Colour: **Silver** Transmission Type: **Manual**
 Eng/No: **91036**
 C/No: **KMHOU 41BR 9 U 726 467**
 Gen. Cond: Good / **OK** / Poor / Burnt or
 Steering: **OK** / Jammed / Leaked / Burnt or
 Brake: **OK** / Jammed / Leaked / Burnt or
 Mod: **Nil** / STD A/Rim or
 Tyre Size: F: **185/65 R15** - **GY**
 R: **LION SPORT**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **As above**

Front		Rear	
R/Bal.	5 mm	R/Bal.	6 mm
L/Bal.	5 mm	L/Bal.	6 mm

Parallel Import: Yes / **No**
 Repair Type: **LS** / LBI
 No of Repair Days: **9**
 D.O.I: **16/12/2019**
 Towed-In: **Yes** / No
 Towing Required: **Yes** / No
 Vehicle in Idac: **Yes** / No
 Time: **4.05pm**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govt Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started

Time completed

By CSO

By AS

By Police Operation Completed Time

MOTOR CAR (Frt)

Front Portion

Vehicle No: **SJP 57232**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	MLS		
1002	991887	Frt Number Plate Base	MLS		
1003	991889	Frt Number Plate Garnish	W		
1004	991300	Frt Bumper	BR		
1005	992341	Frt Bumper Clips	NEC	6	
1006	991325	Frt Bumper Bracket		2	
1007	991462	Frt Bumper Side Retainer	LH+RH DIS	2	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	W		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	SCR R		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	CRA		
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	RW		
1097	995072	Frt LH Fender Inner Panel	BT R		
1098	995147	Frt LH Fender Lamp Emblem	NEC		
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CRA		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim	W		
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			3 6076
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen LH Frame	DD R		
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

Continued (5/00)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Stained (09) Discolored (10) Broken (11) Excessively (12) Missing
(13) Torn (14) Unfinished (15) Not Working

MOTOR CAR (LH)

SECTION 1A0

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (N/C)

205

Left Portion

Vehicle No: SJP 5723 L

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror	BR		
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH	BUC		
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	DD		
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass Sticker	NEC		
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel	BUC		
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper	CUT		
1142	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1186	990247	Sticker			
		Rear LH Wheel Rim	CUT		
		" " " Tyre			

No of Items:

Assessor:

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ALUMINUM

(1) Replace (✓) (2) Repair (X) (3) Check (✓)
(4) Not Consistent (NC)

313

Vehicle No: SJP 5723 L

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber	BT	/	
1373	991944	Frt LH Shock Absorber Mounting	NEC	/	
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	DIS	/	
1376	995199	Frt LH Knuckle Arm Bearing	NEC	/	
1377	995178	Frt LH Lower Arm	BT	/	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod	BT	/	
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage	BT	/	
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

Assessor: _____

Original copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 878B

Vehicle Details

Vehicle No.: SJP5723L
Vehicle to be Exported: No
Intended Deregistration Date: 18 Dec 2019
Vehicle Make: HYUNDAI
Vehicle Model: HD AVANTE 1.6 A
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: G4FC9U629152
Chassis No.: KMHDU41BR9U726467
Maximum Power Output: 89.7 kW (120 bhp)
Open Market Value: \$11,974.00
Original Registration Date: 28 Mar 2009
First Registration Date: 28 Mar 2009
Transfer Count: 2
Actual ARF Paid: \$90.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Mar 2024
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$12,763.00
COE Rebate Amount: \$10,910.00
Total Rebate Amount: \$10,910.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Dec 2019

OK

Claim Handling

Task Transfer Exit

Accident MT/1076000

LOS SAL SUB

Policy No.	5109811579	Vehicle No.	SJP5723L	GST Registration No.	
Certificate No.					
Policyholder Name	CHU CHERH SING			Policyholder NRIC	S1231878B
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	82286617	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KPK	No Yes	TCA	No Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	Yes

Accident Details

Report Date	17/12/2019 08:57	Accident Report Within 24 hrs	Yes	Accident Type	Others
Date of Accident	14/12/2019	Time of Accident hh:mm	17:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	SIMEI RD SLIP RD INTO PIE				

Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	2,000.00	TP Standard Excess	1,500.00		
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess	0.00				
Total OD Excess Applicable	2,000.00	Total TP Excess Applicable	1,500.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 334 #02-801	Address 2	UBI AVENUE 1	Address 3	SINGAPORE 400334
Address 4		Address Type	Singapore address	Post Code	400334
Unit No.		Related Policy Number	5109811579		

OI Driver Info

Driver Name	CHU CHERH SING	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S1231878B	Driver DOB	23/01/1957
Register Date of Driver License	24/12/1980	Driver Age	62	Driving Experience	38
Contact No.(Mobile)	82286617	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 334 #02-801	Address 2	UBI AVENUE 1	Address 3	SINGAPORE 400334
Address 4		Address Type	Singapore address	Post Code	400334
Unit No.					
Does he own a Singapore Registered car?	Yes No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes No
-------------------------------------	------	-------------	--------

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Yap Chee Ling

LOS SAL SUB

Claim Type	OD-MD	Insured Name	CHU CHERH SING	Insured NRIC	S1231878B
Contact No.(Mobile)	82286617	Contact No. (Home)	63482906	Contact No. (Office)	
Email Address	stephenchucs@gmail.com	OJ Vehicle Number	SJP5723L	TP Vehicle Number	RAILING
Claim Description	SJP5723L / RAILING ON 14 Dec 2019			Name of Preferred Workshop	0
Preferred Workshop	0				
Product Realisation	Yes	Preferred Repair Option	income to assign workshop	Insured Liability report	Partially received
Date Registered	17/12/2019 09:03	Claim Close Date		Date Received	17/12/2019 00:00
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make	HYUNDAI	Vehicle Model	AVANTE	Engine Capacity	
Date of	28/03/2009	Classis No.	KMHDM41BR0U726467		

Registration

Towing

Required * ☒ Yes ☐ No

Type of Tender *

Own Damage

IDAC/Workshop

Name NATIONAL ASSESSMENT CENTRE

Windscreen

Parts & Labour

Cost

Market

Value(\$)

Vehicle in IDAC *

☒ Yes ☐ No

Assessor Name *

SIMON

Parallel Import *

☐ Yes ☒ No

Survey Current Status

IDAC/Workshop Location

51 UBI AVENUE 1 #01-25 PAYA

Total Loss *

☐ Yes ☒ No

Scrape Value(\$)

Economical Repair Value(\$)

Remark

REMARK: NO OF REPAIR DAYS: 9 DAYS. 1X FRT LH FENDER EMBLEM - REPLACE. 1X FRT RH WHEEL RIM - REPLACE. 1X FRT WINDSCREEN LH FRAME - REPAIR. 1X REAR LH DOOR STICKER - REPLACE. 1X REAR LH WHEEL RIM - REPLACE. 1X FRT LH TIE ROD - REPLACE. 1X FRT LH BRAKE DISC ROTOR - UNCONFIRM. 1X FRT LH BRAKE PIPE - UNCONFIRM. 1X FRT LH BRAKE HOSE - UNCONFIRM. 1X FRT LH BRAKE SENSOR WIRE - UNCONFIRM. 1X SPECTACLES HOLDER - UNCONFIRM.

Remark for

Supplementary

Damage Listing

Find a Part

root	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
ABSORBER	3	32200501	NUMBER PLATE GARNISH (FRONT)	1	Replace	X
ACCELERATOR	4	16000101	BUMPER (FRONT)	1	Replace	X
ACTUATOR	5	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
ADVERTISEMENT STICKER	6	16001301	BUMPER BRACKET (FRONT LEFT)	1	Unconfirm	X
AIR BAG	7	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Unconfirm	X
AIR BLOWER	8	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
AIR COMPRESSOR	9	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
AIR CON	10	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
AIR CON (VAN)	11	16005901	BUMPER SPONGE (FRONT)	1	Unconfirm	X
AIR COOLER	12	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR DISTRIBUTOR	13	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	X
AIR FILTER	14	149001	BONNET	1	Repair	X
AIR FLOW	15	243014	ENGINE LOWER COVER	1	Replace	X
AIR GRILLE	16	25400102	FENDER (FRONT LEFT)	1	Replace	X
AIR HORN	17	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Repair	X
AIR INTAKE	18	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
AIR RESONATOR BOX	19	43600102	TYRE (FRONT RIGHT)	1	Unconfirm	X
AIR THROTTLE BODY AND SENSOR	20	23306701	DOOR VIEW MIRROR (FRONT LEFT)	1	Replace	X
ALARM	21	35500701	ROCKER PANEL (LEFT)	1	Replace	X
ALTERNATOR	22	23300203	DOOR (REAR LEFT)	1	Replace	X
ALUMINIUM PANEL - SIDE	23	23306103	DOOR RUBBER (REAR LEFT)	1	Unconfirm	X
AMPLIFIER	24	356009	ROOF PANEL	1	Repair	X
ANTENNA	25	16000102	BUMPER (REAR)	1	Replace	X
ANTI ROLL	26	42000101	TAIL LAMP (LEFT)	1	Unconfirm	X
APRON	27	43600103	TYRE (REAR LEFT)	1	Unconfirm	X
ARCH	28	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Replace	X
ARM REST	29	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Replace	X
ASH TRAY	30	30000101	KNUCKLE ARM (FRONT LEFT)	1	Replace	X
AUTO CLUTCH	31	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Replace	X
AUTO COOLER PIPE	32	30500101	LOWER ARM (FRONT LEFT)	1	Replace	X
AUTO CRUISE MOTOR	33	23600101	DRIVE SHAFT (FRONT LEFT)	1	Unconfirm	X
AUTO TRANSMISSION	34	15700801	BRAKE CALIPER (FRONT LEFT)	1	Unconfirm	X
AXLE	35	401028	STEERING RACK & PINION	1	Unconfirm	X
BACK REST (M/C)	36	401021	STEERING CROSS MEMBER	1	Unconfirm	X
BACK SEAT	37	12800101	ANTI ROLL BAR (FRONT)	1	Unconfirm	X
BALANCER	38	12800401	ANTI ROLL BAR LINK (FRONT)	1	Replace	X
BATTERY	39	36600103	SHOCK ABSORBER (REAR LEFT)	1	Unconfirm	X
BEADING (M/C)	40	36600603	SHOCK ABSORBER MOUNTING (REAR LEFT)	1	Unconfirm	X
BELT COVER (M/C)	41	30000103	KNUCKLE ARM (REAR LEFT)	1	Unconfirm	X
BELT TENSIONER	42	30000203	KNUCKLE ARM BEARING (REAR LEFT)	1	Unconfirm	X
BODY	43	30500103	LOWER ARM (REAR LEFT)	1	Unconfirm	X
BODY (M/C)	44	13700102	AXLE BEAM (REAR)	1	Unconfirm	X
BOLT CAP (M/C)						
BOLT HEAD COVER (M/C)						
BONNET						
BOOT						
BOX (M/C)						
BOX BRACKET (M/C)						
BOX CARRIER (M/C)						
BOX DOOR						
BOX STAINER (M/C)						

Save Submit